



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 01
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#

008415 combine
7010

HRS PIN/EIN
X HAJ202553

WARRANTY DATE HRS

SEGMENT# 1 5 64051 L. COMBINE 06/26/23 06/26/23

FLAGSHIP COMBINE INSPECTION

18.00 18.00

COMPLAINT:

FLAGSHIP COMBINE INSPECTION

CORRECTION:

Completed inspection and went through it with the customerBA

ADDITIONAL DESCRIPTION:

1. FLAGSHIP COMBINE INSPECTION (L. COMBINE)

HRS
18.00

Quantity

=====
x1
=====
18.00

ZK10 .1 LB METRIC
METRIC AND GR5 FINE THREAD

1 1.30 1.30

11008006

PARTS 1.30
SEGMENT TOTAL==> 1.30

SEGMENT# 2 S 64057 L.COMBINE WA 06/26/23 07/11/23

FLAGSHIP COMBINE INSPECTION WASH

COMPLAINT:

FLAGSHIP COMBINE INSPECTION WASH

ADDITIONAL DESCRIPTION:

1. FLAGSHIP COMBINE INSPECTION WASH (L.COMBINE
WA)

HRS
8.00

Quantity

=====
x1
=====

CONTINUED ON PAGE 02

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to their customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 02
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
008415	combine		X HAJ202553		
	7010				
				8.00	

SEGMENT# 3 S 64051 NA 06/29/23 07/06/23

Running checks

COMPLAINT:

- Elevator chain loose
- Tailings belt jumping

CORRECTION:

- tightened elevator chain and tailings belt

BA 07/06/23

LABOR	84.50
11008006	
SEGMENT TOTAL==>	84.50

SEGMENT# 4 5 64051 NA 06/29/23 07/08/23

Hydraulic Tests

1.00 1.00

COMPLAINT:

- Adjust lube pressure
- Adjust control pressure

CORRECTION:

- Adjusted lube and control pressure

LABOR	169.00
11008006	
SEGMENT TOTAL==>	169.00

SEGMENT# 5 5 64051 NA 06/29/23 06/29/23

Electrical System

2.00 2.00

COMPLAINT:

- RH front flasher burnt out
- Check into GPS

CORRECTION:

- removed screws out of cover, removed cover and removed

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are a non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 03
Account #	Phone #	Inv #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#	combine	HRS	PIN/EIN	WARRANTY DATE	HRS
008415	7010		X HAJ202553		
bulb					
- bulb was burnt out so put new bulb in and put cover back on					
- tested and works					
BA 06/29/23					
529068		BULB	1	5.66	5.66
				PARTS	5.66
				LABOR	42.25
11008006				SEGMENT TOTAL==>	47.91

SEGMENT# 6 S 64051 NA	06/29/23	06/29/23			
Feeder Wear Strips					
<u>COMPLAINT:</u>					
Worn right through					
<u>CORRECTION:</u>					
- ratchet strapped feeder chain up					
- removed old wear strips					
- installed new wear strips					
- tightened feeder chain					
- put feeder gearbox back on and hooked up					
- also did the elevator drive chain on this segment that took 35 mins					
BA 06/29/23					
86638209		STRIP	4	42.42	169.68
				PARTS	169.68
				LABOR	253.50
11008006				SEGMENT TOTAL==>	423.18

SEGMENT# 7 S 64051 NA	06/29/23	06/29/23
Feeder Gearboxes		

CONTINUED ON PAGE 04

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to release the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 05
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#

008415 combine
7010

HRS PIN/EIN
X HAJ202553

WARRANTY DATE HRS

- ratchet strapped the frame up
- removed frame adjuster
- installed new frame adjuster
- put the new concaves in
- set pinch point
- welded the rear concave frame where was cracked took 20 mins

BA 07/06/23

86980964	LINK, CONNECTIN	1	217.32	217.32
			PARTS	217.32
			LABOR	507.00
11008006	SEGMENT TOTAL==>			724.32

SEGMENT#10 S 64051 NA 06/29/23 07/06/23

Cone

COMPLAINT:

- Cone has holes
- half moon Hole worn through and bolts missing

CORRECTION:

- weld 2 patches in cone and filled in 2 little holes where last guy burnt through

BA 07/06/23

11008006	LABOR	309.27
	SEGMENT TOTAL==>	309.27

SEGMENT#11 S 64051 NA 06/29/23 06/29/23

Front Bearing, Cast Housing, & Mounting Plate

COMPLAINT:

Front plate broke around both bottom bolt holes and dented

CORRECTION:

CONTINUED ON PAGE 06

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. hereby releases from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 06
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#

008415 combine
7010

HRS PIN/EIN
X HAJ202553

WARRANTY DATE HRS

- put front concaves in and put 2 2x4 blocks on front concaves
- lifted concaves up until could not turn no more
- used 2 ratchet straps on each side of combine to hold rotor back
- removed the 4 bolts holding front plate on
- removed bolt and spacer on end of rotor shaft
- used a pry bar and pried the plate off
- removed plate
- removed rotor kidney from old plate and removed old bearing
- bearing had a bit of play in it
- installed new bearing and put kidney on new plate
- put front plate back on and got longer bolts and the update kit plates for the bolt holes
- installed plates and tightened up
- tightened bolt on end of rotor shaft
- silicone half moon and installed
- got bolts for half moon as lots were missing
- silicone around kidney to plate
- loosened ratchet straps and lowered concaves
- removed wood blocks and installed back 2 concaves

BA 07/06/23

ZK10	.1 LB METRIC	4	1.30	5.20
	METRIC AND GR5 FINE THREAD			
51529068	PLATE	2	100.48	200.96
86508354	NUT	4	7.77	31.08
86981489	BOLT	4	34.24	136.96
87324171	BEARING, BALL	1 N	147.74	147.74
	PARTS			521.94

CONTINUED ON PAGE 07

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 07
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
008415	combine		X HAJ202553		
	7010				
11008006				LABOR	845.00
				SEGMENT TOTAL==>	1366.94

SEGMENT#12 S 64051 NA	06/29/23 06/29/23				
Rotor Cage					
<u>COMPLAINT:</u>					
-Broken and hole worn					
-Vanes missing					
<u>CORRECTION:</u>					
- welded cage and straightened cage where broke and welded all back up					
- welded in 8 different spots					
- installed 2 vanes that were missing					
BA 07/06/23					
100016	NUT	6	.99		5.94
140219	WASHER	6	8.48		50.88
87106338	BOLT	6	7.37		44.22
87717924	STIFFENER	2	53.88		107.76
	PARTS				208.80
	LABOR				339.69
11008006				SEGMENT TOTAL==>	548.49

SEGMENT#13 S 64051 NA	06/29/23 06/29/23				
Drive Chain, Sprockets, And Tensioner Rod Assembly					
<u>COMPLAINT:</u>					
Chain worn right out					
<u>CORRECTION:</u>					
- did on segment 04					
BA 06/29/23					
87470737	CHAIN	1	159.27		159.27
CONTINUED ON PAGE 08					

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Wayburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 08
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#

008415 combine
7010

HRS PIN/EIN
X HAJ202553

WARRANTY DATE HRS

11008006

PARTS 159.27
LABOR 3.38
SEGMENT TOTAL==> 162.65

SEGMENT#14 S 64051 NA 06/29/23 06/30/23

Bottom Boot & Middle Divider

COMPLAINT:

Boot worn a hole

CORRECTION:

- did on segment 16

BA 06/30/23

SEGMENT#15 S 64051 NA 06/29/23 06/30/23

Elevator Chain, Paddles, & Connectors

COMPLAINT:

Chain loose. Adjust

CORRECTION:

- tightened chain on segment 16

BA 06/30/23

11008006

LABOR 3.38
SEGMENT TOTAL==> 3.38

SEGMENT#16 S 64051 NA 06/29/23 06/29/23

Bottom Sprocket & Key Way

COMPLAINT:

Lots of play on sprocket

CORRECTION:

- removed bolts nd flange, loosened lock collar, removed

bearing

- removed bolts out of boot and took out connector link on

CONTINUED ON PAGE 09

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymond 306-746-2288
Watrous 306-946-3387
Wayburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 09
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
008415 combine X HAJ202553

chain

- removed bottom boot and removed sprocket and key
- was and sprocket were slopped right out
- shaft was good still
- installed new sprocket and key
- when had boot off i welded a patch on where the hole was worn through
- after got patch all welded in, put a coat of black paint on it
- took 1 hour to weld the patch in and clean it all up
- when waiting for the boot to cool down i welded up the half moon for the cone
- welded 3 patches in it as it was thin
- once done i painted it
- took an hour and 20 mins to weld it
- put bottom boot back on and put new bearing on and tightened all up
- put new s pins in connector link and tightened chain and that took 10 mins

BA 06/30/23

170012	KEY	1	9.31	9.31
23442R1	#550 S PIN	4	2.93	11.72
87283436	SPROCKET	1	186.06	186.06
87605593	BEARING	1	135.82	135.82
	PARTS			342.91
	LABOR			718.25
11008006	SEGMENT TOTAL==>			1061.16

SEGMENT#17 S 64051 NA 06/29/23 06/30/23
Tailings Drive Belt & Alignment Of The Pulleys

CONTINUED ON PAGE 10

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Thank You!
We Appreciate Your Business

Leading The Way In A Thriving Agricultural Community!



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina	306-565-2405
Assiniboia	306-642-5991
Chamberlain	306-638-4516
Moose Jaw	306-694-1800
Raymore	306-746-2288
Watrous	306-946-3387
Weyburn	306-842-2629
Windthorst	306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 10
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
008415 combine 7010		X HAJ202553		

COMPLAINT:

pulley is loose and will slide right off

CORRECTION:

- aligned all pulleys and installed belt

BA 06/30/23

11008006

LABOR	84.50
SEGMENT TOTAL==>	84.50

SEGMENT#18 S 64051 NA 06/29/23 07/05/23

Tailings Housing For Cracks and/or Holes

COMPLAINT:

Lots of holes

CORRECTION:

- welded 4 holes that were worn through
- after done welding, grinded it down so door can go on
- painted after

BA 07/05/23

11008006

LABOR	338.00
SEGMENT TOTAL==>	338.00

SEGMENT#19 S 64051 NA 06/29/23 07/05/23

Tailings Top Gearbox

COMPLAINT:

Mount cracked

CORRECTION:

- grooved out crack and welded
- painted once cooled
- BA 07/05/23

11008006

LABOR	126.75
SEGMENT TOTAL==>	126.75

CONTINUED ON PAGE 11

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 11
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
008415 combine 7010		X HAJ202553		
SEGMENT#20 5 64051 NA	06/29/23	06/29/23		
Auger Trough Doors			.15	.15
<u>COMPLAINT:</u> Wrong pin installed on returns				
SEGMENT#21 5 64051 NA	06/29/23	06/29/23		
Stationary Knives, Assembly & In Proper Position.			2.00	2.00
<u>COMPLAINT:</u> Knives missing and bent				
<u>CORRECTION:</u> removed stationary knife assembly and replaced knives and reinstalled knife assembly				
87106692	KNIFE SECTION	14	9.53	133.42
			PARTS	133.42
			LABOR	338.00
11008006		SEGMENT TOTAL==>		471.42
SEGMENT#22 5 64051 NA	06/29/23	06/29/23		
Grain Tank For Leaks & Loose Hardware			2.00	2.00
<u>COMPLAINT:</u> Hole in hopper above rotor Bracket and bolt bent for hopper cover				
QM50A	5 MIN EPOXY	1	11.29	11.29
120117	BOLT	1 N	16.37	16.37
			PARTS	27.66
			LABOR	338.00
11008006		SEGMENT TOTAL==>		365.66
SEGMENT#23 5 64051 NA	06/29/23	06/29/23		

CONTINUED ON PAGE 12

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Estimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 12
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#

008415 combine
7010

HRS PIN/EIN
X HAJ202553

WARRANTY DATE HRS

Unload Incline Auger

3.00 3.00

COMPLAINT:

- Lots of play on splines
- Plug stripped on gearbox

CORRECTION:

- removed drain plug and drained oil and was about 2 liters of water in it
- so after finding that much water i pulled off the side plate and flushed the gearbox out with break clean until it was clean
- drilled through plug and used an extractor and removed stripped plug
- silicone side plate and re installed
- have to put oil in yet

BA 06/29/23

86557412

PLUG

1

12.87

12.87

PARTS

12.87

LABOR

507.00

11008006

SEGMENT TOTAL==>

519.87

SEGMENT#24 S 64051 NA

06/29/23 06/29/23

Air Intake System & Hose Clamps

COMPLAINT:

Filter plugged solid and need to clean aspirator out and check flap

CORRECTION:

- removed air filters and threw them in the garbage as was plugged solid
- removed canaster on back side of the air box
- the flap in canister was missing so that was what was

CONTINUED ON PAGE 13

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
• Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
• An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
• Estimates are for the items specifically identified in the estimate only, and are non-binding.
• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repair performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assinibola 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 13
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
008415 combine 7010		X HAJ202553		
causing filters to plug				
- ordered new canister as can not just get the flap				
- once new one came in i installed and tightened hose				
clamps and put new filters in				
- aspirator tube was clean				
BA 07/05/23				
619585C91	SEAL	1	47.27	47.27
86997386	BUSHING	1	8.11	8.11
86998331	VALVE, CHECK	1 N	129.37	129.37
86998332	FILTER, AIR	1	112.32	112.32
86998333	FILTER, AI	1	207.57	207.57
87106692	KNIFE SECTION	1	9.38	9.38
	PARTS			514.02
	LABOR			169.00
11008006	SEGMENT TOTAL==>			683.02

SEGMENT#25 5 64051 NA	06/29/23 06/29/23			
Engine & Oil Filter Lines For Leaks		4.00	4.00	
<u>COMPLAINT:</u>				
Engine oil drain leaking and a couple leaks Has to be				
washed first to see what is leaking				
EHC1GL	ENVIRO CHARGE	1	.88	.88
1971726C1	BREATHER	1	27.49	27.49
76980JXYCA	COOLANT 3.79L	1	18.20	18.20
	Coolant Conventional Premix			
87105048	DRAINCOCK/TAP S	1	116.11	116.11
	PARTS			162.68
	LABOR			476.58
11008006	SEGMENT TOTAL==>			639.26

CONTINUED ON PAGE 14

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to this customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Authorized By

X

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 14
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS
008415 combine X HAJ202553

SEGMENT#26 S 64051 NA 06/29/23 06/29/23

Coolant System, Including Hose Clamps

COMPLAINT:

Not a drop of coolant in reservoir and sensor must not work as never went off

CORRECTION:

- removed old sensor and found out why there was no coolant in tank as sensor was broken around the hole so was leaking out
- installed new sensor and tested it to make sure it would work
- after I dumped a 4 liter jug of coolant in it to fill it

BA 07/05/23

87377459	SENSOR	1 N	162.25	162.25
			PARTS	162.25
			LABOR	253.50
11008006			SEGMENT TOTAL==>	415.75

SEGMENT#27 S 64051 NA 06/29/23 07/08/23

Radiator & All Coolers

COMPLAINT:

Rads need to be blown out

CORRECTION:

Blow out rads as they were full

11008006			LABOR	169.00
			SEGMENT TOTAL==>	169.00

SEGMENT#28 S 64051 NA 06/29/23 06/29/23

PTO Gearbox Sump For Leaks

6.00 6.00

COMPLAINT:

CONTINUED ON PAGE 15

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 15
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
008415 combine 7010		X HAJ202553		
Seal leaking behind chopper drive pulley				
<u>CORRECTION:</u>				
Replaced seal.BA				
272778	O-RING	1	6.77	6.77
965.471	COTTER PIN Sm	2	.31	.62
			PARTS	7.39
			LABOR	1014.00
11008006			SEGMENT TOTAL==>	1021.39

SEGMENT#29 S 64051 NA 06/29/23 06/29/23

oil and maintenance

COMPLAINT:

The following oils and filters are to be replaced:

- Engine Oil & Filter(s)
- Engine Air Filters
- Fuel Filters
- Engine Crankcase Breather
- PTO Gearbox Oil & Filters
- Hydraulic filters only
- Upper & Lower Unloader Gearbox Oils
- Recirculating Air & Cab Filters

CORRECTION:

- Engine Oil & Filter(s); changed
- Engine Air Filters; changed
- Fuel Filters; changed
- Engine Crankcase Breather ; changed
- PTO Gearbox Oil & Filters; changed
- Hydraulic filters only; changed
- Upper & Lower Unloader Gearbox Oils ; changed
- Recirculating Air & Cab Filters ; changed

CONTINUED ON PAGE 16

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the item specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 16
Account #	Phone #	Inv #
Ship Via		Purchase Order #
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
008415	combine		X HAJ202553		
	7010				
JB					
EHCFLT1	EHC CHARGE	5	.50		2.50
EHCFLT2	EHC CHARGE	3	1.00		3.00
EHCOIL	ENVIRO CHARGE	50	.05		2.50
17301181	O-RING	1	36.84		36.84
254353A1	ELEMENT FILTER	1	178.89		178.89
471	SILICONE BLACK	1	19.08		19.08
51508555	FILTER HYDRAUL	1	169.69		169.69
5801856862	FILTER	1	130.76		130.76
74645001US	15W40 BULK	27	5.39		145.53
77400001US	ULTRACTION BULK	23	5.86		134.78
84058793	FILTER, CAB	1	117.96		117.96
84217229	FILTER, AIR	1	94.23		94.23
84346773	FILTER, ENGINE	1	92.86		92.86
84348882	CARTRIDGE, FUEL	1 O	39.11		39.11
84523925	FILTER, HYDRAUL	1	84.33		84.33
84597064	FILTER, FUEL	1	57.70		57.70
	PARTS				1309.76
	LABOR				1352.00
11008006	SEGMENT TOTAL==>				2661.76

SEGMENT#30 5 64047 N/A	06/26/23 06/26/23	
Boost pressure sensor faults		
COMPLAINT:		
Boost pressure sensor faults		
11008006	LABOR	189.28
	SEGMENT TOTAL==>	189.28

***** WORK ORDER TOTALS *****
CONTINUED ON PAGE 17

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.
* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.
* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
* An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
* Estimates are for the items specifically identified in the estimate only, and are non-binding.
* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business



Box 460 • 100 Second Street South
Davidson, SK S0G 1A0
Phone: 306-567-3074 • Fax: 306-567-5435
www.youngs.ca



Regina 306-565-2405
Assiniboia 306-642-5991
Chamberlain 306-638-4516
Moose Jaw 306-694-1800
Raymore 306-746-2288
Watrous 306-946-3387
Weyburn 306-842-2629
Windthorst 306-224-2110

Ship To: IN STORE PICKUP

Invoice To:

Branch DAVIDSON		
Date 07/13/23	Time 09:25:30 (O)	Page 17
Account #	Phone #	Inv #
Ship Via	Purchase Order #	
Tax ID #		
		Salesperson 823

SERVICE PRELIMINARY

STK#/FLEET#
008415 combine
7010

HRS PIN/EIN
X HAJ202553

WARRANTY DATE HRS

PARTS	4117.69
LABOR	8740.68
shop supplies	300.00
10-40 Ser Comb	2199.00
SUB TOTAL==>	15357.37
PST 6%	.39
GST 5%	767.93
	16125.69

* I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. is hereby released from any and all claims for loss and/or damage not caused by the negligence of Young's Equipment Inc.

* It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment Inc. is working on, and/or in possession of the above-noted equipment.

* Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.

* An express mechanic's lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment Inc. reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

* Estimates are for the items specifically identified in the estimate only, and are non-binding.

* Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.

X

Authorized By

Leading The Way In A Thriving Agricultural Community!

Thank You!
We Appreciate Your Business