

Number	Type	Date Open	Date Closed	Kilometres	Clr	HoursClosed	Fuel Usage	Clr	Fault	Repairer / Notes	Cost / Invoice
R-7899	Tyre	09/07/2024								9042 Carroll's Tyres CUTS IN TYRES STILL OK TO OPERATE WILL CONTINUE TO MONITOR	\$0.00
S-7551	B	01/13/2026	01/22/2026	0		28,500				Internal Workshop - Field Service ACTUALLY DONE AT 28298 HRS	\$0.00
S-7393	A	10/21/2025	10/24/2025	0		28,250				HOSE POWER CAME TO SITE AND REPLACED MULTIPLE HOSES. REPLACED ENGINE AIR CLEANER LID. REPLACED BUCKET TEETH .	\$0.00
S-7284	C	09/10/2025	08/28/2025	0		28,000				ACTUALLY DONE AT 28060 HRS	\$0.00
R-7539	Windscreen washers	06/10/2024	08/21/2025			28,301				8346 A Grade Auto Repair Steph from SAY electrical has repaired whilst at workshop	\$0.00
S-7022	A	06/10/2025	06/09/2025	0		27,870				Internal Workshop - Field Service Internal Workshop - Field Service Main hyd hose from pump to control valve leaking. Had to purchase from hastings deering as they have different hose tails. Tom changed hoses and o rings. Washed down and checked for leaks. Topped up oil.	\$0.00
R-8292	HYD Hose	01/24/2025	01/24/2025			27,694				Internal Workshop - Field Service Un stuck rails and moves now also attached arm rest that was	\$0.00
R-8132	Seat	11/07/2024	12/09/2024			27,550				9452 jammed behind seat.	\$0.00
R-7983	Steps	09/25/2024	12/03/2024			27,516				9198 Internal Workshop - Fabrication Bent straight again Internal Workshop - Field Service Pulled off bucket crowd pipe that was cracked and sent to workshop	\$0.00
R-8099	Hydraulic leak	10/26/2024	11/29/2024			27,500				9377 to be welded up then refit pipe	\$0.00
S-6692	B - 500	12/02/2024	11/29/2024	0	27,500	5					\$0.00
S-6593	A - 250	10/15/2024	10/16/2024			27,250	2				\$0.00
R-7898	flashing light	09/07/2024	09/20/2024			27,130				9041 agrade Flashing light fitted by a grade. Internal Workshop - Field Service 2x idler pulleys seized up and broke belt. Sourced 3x pulleys and new belt from hastings Deering and fitted.	\$0.00
R-7944	Idler Pulley	09/17/2024	09/17/2024			27,130				Internal Workshop - Field Service Had boilys weld on bolts to arm and guard around fitting on dog bone	\$0.00
R-7901	Grease line	09/07/2024	09/17/2024			27,101				9048 to protect from rocks.	\$0.00
S-6505	C - 1000	09/05/2024	09/04/2024	0	27,000	1				Internal Workshop - Field Service ACTUALLY DONE AT 27031HRS Internal Workshop - Field Service Replaced seat and 1x support shaft for armrest/control assembly,	\$0.00
R-7618	Seat	06/24/2024	07/26/2024	0		26,845				8454 supplied by Hastings	\$0.00
S-6358	A - 250	07/04/2024	07/12/2024	0	26,750	2				SERVICE REALLY DONE AT 26755HRS	\$0.00
R-7387	Grease	04/10/2024	07/02/2024			26,727				7997 Internal Workshop - Field Service Replaced grease fitting and line now taking grease.	\$0.00
R-7604	Grease line	06/24/2024	06/24/2024	0		26,678				hosepower Hose power repaired	\$0.00
R-7388	Coolant leak	04/10/2024	06/14/2024			26,612				7996 A Grade Auto Repair Leaking hose on evaporator. Tightened up and left covers off to air out.	\$0.00
R-7386	Window washer	04/10/2024	06/04/2024			26,563				7998 A Grade Auto Repair Repaired by a grade auto Internal Workshop - Field Service New reverse beeper fitted by Tom. Fitted new UHF hand piece and	\$0.00
R-6796	Reverse Beeper	11/23/2023	06/04/2024			26,563			0 7352, 8232	magnetic base. Details attached on invoice.	\$0.00
S-6263	B - 500	05/27/2024	05/25/2024	0	26,500	5					\$0.00
R-7432	Park brake	04/19/2024	05/13/2024			26,430				Internal Workshop - Field Service Found Park brake actuator to be leaking. Ordered new one from hastings. Fitted new one and adjusted brake travel. Tested on slope and stall test both passed.	\$0.00
R-7595	Bonnet	06/20/2024	05/06/2024			26,187				A Grade Auto Repair Agrade auto found all the control box all corroded. Replaced all corroded components. Full details attached on invoice.	\$0.00
S-6189	A - 250	04/12/2024	04/10/2024	0	26,250	2					\$0.00
S-5910	C - 1000	11/08/2023	11/10/2023	0	26,000	1				Welded in new adapter mounts on corner off bucket. replaced all adapters with bolt on ones and all new teeth with extra 16mm plates replaced all segments on bucket and all new heal plates re-skinned the floor New step made up and fitted on lhs	\$0.00
R-6935	Bucket Crowd	11/09/2023	11/09/2023			25,914				replaced plastic panel that holds park brake knob Hastings Deering Failed PPRV. Replaced PPRV Valve as per invoice.	\$0.00

R-5349	Fluid leak	10/06/2022	09/27/2023	0	25,932	0	5434, 6128, 6	Other. Check for any oil / fluid leaks. Oil leaking rear side area of hyd valve bank again Steer relief valve Coolant heater tap small leak	\$0.00
R-5657	Hydraulic leak	12/19/2022	09/01/2023	0	0	0	5826, 6470	Internal Workshop - Field Service Other. Hydraulic hoses for damage, splits & leaks. Small leak rh boom lift hose Hose man to rework. Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months. Broken park break handle ...will need to make plate to re attach to dash Broken adaptors and heel plate gone on bottom of bucket and needs boily work	\$0.00
S-5818	A - 250	09/22/2023	08/25/2023	0	25,750	1	0	T/c filler cap needs replacing	\$0.00
S-5577	B - 500	06/13/2023	07/11/2023	0	25,568	5	0	fixed split coolant hose	\$0.00
S-5423	A - 250	04/12/2023	05/17/2023	0	25,500	5	0		\$0.00
R-6154	Coolant hose	04/26/2023	04/26/2023		25,232		0	Ordered new hose and hose clamps from Hastings and replaced hose/ refilled coolant	\$0.00
R-5445	Bucket adaptors	11/04/2022	03/21/2023	0	24,559		0	5569, 5689, 5	Internal Workshop - Fabrication REPAVED ALL BUCKET SEGMENTS WITH 50MM THICK ONES. RE- WELDED CORNER ADAPTERS. WORK DONE BY CRAIG AND DANNY.
R-5951	Bucket	03/07/2023	03/07/2023		25,057		0	Internal Workshop Replaced faulty bucket joy stick supplied by Hastings. Jay did on site. A Grade Auto Repair A/c operation in middle of day is poor. A Grade found dirty cabin filter, blocked evaporator and evaporator fins bent. Replaced air con filter, cleaned evaporator and straightened fins.	\$0.00
R-5876	Air con	02/21/2023	03/03/2023	0	25,055		0	6065, 6110	Invoice attached.
R-5310	Oil leak	10/11/2022	02/15/2023	0	24,971		0	5459	Other. Check for any oil / fluid leaks. Small leak from hose at steer hmu
R-5259	Door handle	10/07/2022	02/15/2023		24,971		0		door release from outside back of cab needs a handle someone will cut there hand grabbing the wire
R-5258	Valves	10/07/2022	02/15/2023		24,971		0	5408	right steering snub valve leaking needs re seal
R-4177	E Stop	04/06/2022	02/15/2023	0	24,971		0	4426, 5521, 6	Other. Emergency stop button. Not fitted. Internal Workshop - Field Service Changed out steering right snub valve as it was leaking Called out hydraulink to change leaking steering hose Replaced transmission to rear diff lip seal, yoke bolt came loose and was leaking Changed bucket teeth and checked adaptors Changed door release cable for shutting door
									No sample bottles so no samples taken
S-5282	C - 1000	02/14/2023	02/15/2023	0	24,971	1	0		Need to head back and clean down machine and check leaks on control valve also clean from previous leaks . A Grade Auto Repair NO POWER TO UHF. A Grade found fuse blown; replaced fuse and reassembled.
R-5744	UHF Radio	01/19/2023	01/24/2023	0	24,889		0	5945	Tested okay. Invoice attached.
R-5791	Bucket, Cutting Edge	01/09/2023	01/09/2023				0		Internal Workshop - Fabrication Craig & Danny - Remove bucket from loader. Repair mount where dog bone joins onto bucket. Remove and replace 7 x cutting edges. Straighten bent dog bone. Weld outer adaptors to bucket. *Dust seals need to be replaced on dog bone.
S-5173	B - 500	12/15/2022	12/14/2022	0	24,783	3	0		Internal Workshop - Field Service Still need to git door cable.
R-5330	Grease	10/10/2022	11/03/2022	0	24,535		0	5449, 5451	Other. All nipples & pins taking grease. Grease system fault
R-5307	Cutting Edge	10/10/2022	10/21/2022	0	24,487		0	5450, 5522	Other. Check bucket cutting edge, teeth, underside of adaptors & side plates for wear. 1 cutting edge missing
R-5266	Auto Greaser	10/03/2022	10/21/2022	0	24,487		0	5407, 5433, 5	Other. Auto greaser pot level. Warning flashing at indicator unit has 1/4 tank grease
R-5170	Teeth	09/21/2022	10/21/2022	0	24,487		0	5363, 5428	Other. Check bucket cutting edge, teeth, underside of adaptors & side plates for wear. Bucket teeth adaptors loose again
R-4831	Bucket Teeth	07/29/2022	10/21/2022	0	24,487		0	5098	missing
R-4800	Headlights	07/29/2022	10/21/2022	0	24,487		0	5099	Other. Lights (blinkers, brakes & headlights). Both lower head lights keep coming loose
R-4424	Tyre	06/03/2022	10/21/2022	0	24,487		0	4690	Other. Check tyre condition. RHF damaged by steel in stockpile.
R-4127	Wipers	04/06/2022	10/21/2022	0	24,487		0	4425, 5114	Other: Windscreen wipers inoperable.

S-4918	B - 500	09/20/2022	10/07/2022	0	24,477	6	0	no fitting to adapt to grease pod, needs topping up looks like low level fault active right steering snub valve leaking needs re seal (R-5258). door release from outside back of cab needs a handle someone will cut there hand grabbing the wire (R-5259). Other. Check for any oil / fluid leaks. Leak from hyd valve bank area again Hastings Deering resealed valve	\$0.00
R-4799	Oil leak	08/01/2022	08/09/2022	0	24,269		0	5107 bank and Jay fitted.	\$0.00
R-4587	Valves	06/30/2022	07/22/2022	0	24,193		0	4899 Other. Fluid leaks. Small leak rh steer relief valve. Jay: Steering stop valve leaking. Other. Fluid leaks. Hyd oil leak at control valve bank. Hastings replaced all o'rings in valve bank and	\$0.00
R-4400	Hydraulic oil	05/31/2022	07/20/2022	0	24,193		0	4659 topped up oil. Not Working. Other: Major Concerns (Take pics). Bucket intermittently self actuating to tip load poss side effect of leak at valve bank only started 3/5/22 Hastings replaced the 2 x relief valves on bucket ram	\$0.00
R-4270	Bucket	05/05/2022	07/20/2022	0			0	4531 cylinder and resealed valve.	\$0.00
R-4276	Lights	05/04/2022	07/12/2022	0	24,250		0	4521 Other. Lights, horns, gauges & buzzers. Rh park light inop Porters replaced at last A service in July.	\$0.00
S-4623	A - 250	06/08/2022	07/12/2022	0	24,250	3	0		\$0.00
R-4285	Pins	04/28/2022	05/24/2022	0	23,993		0	4498 Automatic grease contractor came out as a warranty job and replaced lines going to bucket cylinder.	\$0.00
R-4273	Bucket	05/04/2022	05/24/2022	0	23,993		0	4522 Automatic grease contractor came out as a warranty job and replaced lines going to bucket cylinder.	\$0.00
R-4197	Hydraulic hose	04/21/2022	04/29/2022	0		0	0	4465, 4466, 4. Other. Fluid leaks. Hyd hose small leak. Repaired. Replaced water pump and coolant.	\$0.00
S-4389	C - 1000	03/25/2022	03/24/2022	0	23,855	2	0	Replaced all 4 x tyres supplied by Porters.	\$0.00
R-4913	Grease pump	08/13/2018	08/13/2018				0	Groeneveld Repaired grease pump when owned PGH.	\$0.00