



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EGGE ENVIROMENTAL FARM/GRINDSTONE GRAIN CORP
339 ENG HRS
252 SEP HRS

Invoice To: WARRANTY REC - CLAAS
.
. TT 99999
United States

Branch N. BATTLEFORD		
Date 10/30/25	Time 10:23:11 (O)	Page 01
Account No WARRA002	Phone No	Inv No W03416
Ship Via INSP 404920869	Purchase Order	
Tax ID No	887067502	
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

SEGMENT# 1 S 190 NA 10/21/25 10/21/25
#8 CUTTERBAR DRIVE BELT TENSIONER PULLEY - CC#404940512

COMPLAINT:

CUTTERBAR TENSIONER PULLEY TO CLOSE TO DRIVE PULLEY

CAUSE:

NOT CORRECT SETTING

CORRECTION:

REPOSITIONED CUTTERBAR TENSIONER PULLEY AS NOT TO RUB ON
DRIVE PULLEY

ADDITIONAL DESCRIPTION:

REPOSTION CUTTERBAR TENSIONER PULLEY AS NOT TO RUB ON DRIVE
PULLEY

****OBTAIN MACHINE REPORT AND TAKE PICS AND EMAIL ALL TO
CHUCK***

	LABOR	60.15
10800000	SEGMENT TOTAL==>	60.15

SEGMENT# 2 S 190 NA 10/21/25 10/21/25
#9 FRONT ATTACHMENT CLUTCH - CLAAS CLAIM #404941883

COMPLAINT:

LEAKING FRONT ATTACHMENT CLUTCH

CAUSE:

LEAKING O-RINGS.FAILED PT # 2192810

CORRECTION:

REMOVED, DISASSEMBLED, RESEALED, ASSEMBLED AND INSTALLED
FRONT ATTACMENT CLUTCH. TIGHTENED BELT.TESTED OPERATION..OK

ADDITIONAL DESCRIPTION:

RESEAL LEAKING FRONT ATTACHMENT CLUTCH

****TAKE PICS AND EMAIL ALL TO CHUCK***

CONTINUED ON PAGE 02

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EGGE ENVIROMENTAL FARM/GRINDSTONE GRAIN CORP
339 ENG HRS
252 SEP HRS

Invoice To: WARRANTY REC - CLAAS
.
. TT 99999
United States

Branch N. BATTLEFORD		
Date 10/30/25	Time 10:23:11 (O)	Page 02
Account No WARRA002	Phone No	Inv No W03416
Ship Via INSP 404920869		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
001046 LEXION 8700 8700	339 252	C8910940		
2192810	O-RING	RETAIL	26.97	
		2	18.78	37.56
26570253	BUSHING	RETAIL	279.22	
		1	200.71	200.71
4787471	SEALING RI	RETAIL	133.74	
		1	99.00	99.00
	SEALING RING			
4787731	SEALING RI	RETAIL	61.41	
		1	45.29	45.29
	SEALING RING			
		PARTS		382.56
		LABOR		701.85
10800000		SEGMENT TOTAL==>		1084.41

SEGMENT# 3 S 190 NA 10/21/25 10/21/25

#11 2-SPEED GEARBOX - CLAAS CLAIM #404941885

COMPLAINT:

LEAKING 2-SPEED GEARBOX WIPER SEAL

CAUSE:

WEAKING WIPER SEAL.PT# 4699330

CORRECTION:

REPLACED LEAKING WIPER SEAL ON 2-SPEED GEARBOX

ADDITIONAL DESCRIPTION:

REPLACE LEAKING WIPER SEAL ON 2-SPEED GEARBOX

TAKE PICS AND EMAIL ALL TO CHUCK

4699330	WIPER SEAL	RETAIL	55.72	
		1	39.36	39.36
		PARTS		39.36
		LABOR		240.63
10800000		SEGMENT TOTAL==>		279.99

CONTINUED ON PAGE 03

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EGGE ENVIROMENTAL FARM/GRINDSTONE GRAIN CORP
339 ENG HRS
252 SEP HRS

Invoice To: WARRANTY REC - CLAAS
.
. TT 99999
United States

Branch N. BATTLEFORD		
Date 10/30/25	Time 10:23:11 (O)	Page 03
Account No WARRA002	Phone No	Inv No W03416
Ship Via INSP 404920869	Purchase Order	
Tax ID No	887067502	
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

SEGMENT# 4 S 190 NA 10/21/25 10/21/25
#19 CRUISE PILOT BEARINGS - CLAAS CLAIM #404941889

COMPLAINT:

NOISE IS HEARD IN THE BEARINGS WHEN TURNING THE SHAFT
FAILED PT# 5188240

CAUSE:

BEARINGS FAILED
FAILED PT# 5188240

CORRECTION:

REMOVED FAILED CRUISE PILOT BEARINGS. GREASED AND INSTALLED
NEW BEARINGS.

ADDITIONAL DESCRIPTION:

REPLACE FAILED CRUISE PILOT BEARINGS
TAKE PICS AND EMAIL ALL TO CHUCK

5188240	FLANGE BEA	RETAIL	142.12	
		2	105.19	210.38
	FLANGE BEARING			
		PARTS		210.38
		LABOR		501.32
10800000		SEGMENT TOTAL==>		711.70

SEGMENT# 5 S 190 NA 10/21/25 10/21/25
#23 RUBBER BLANKET - CLAAS CLAIM #404941915

COMPLAINT:

RH SIDE OF RUBBER BLANKET IS NOT SECURED

CAUSE:

RH SIDE RUBBER BLANKET CLIP IS BROKEN

CORRECTION:

REPLACE BROKEN RUBBER BLANKET CLIP, INSPECTED THE REST.

CONTINUED ON PAGE 04

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EGGE ENVIROMENTAL FARM/GRINDSTONE GRAIN CORP
339 ENG HRS
252 SEP HRS

Invoice To: WARRANTY REC - CLAAS
.
. TT 99999
United States

Branch N. BATTLEFORD		
Date 10/30/25	Time 10:23:11 (O)	Page 04
Account No WARRA002	Phone No	Inv No W03416
Ship Via INSP 404920869		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
001046 LEXION 8700	339	C8910940		
8700	252			
FAILED PT#2331320				
<u>ADDITIONAL DESCRIPTION:</u>				
REPLACE 1 BROKEN CLIP				
TAKE PICS AND EMAIL ALL TO CHUCK***				
2331320	CLIP	RETAIL	14.85	
		1	10.49	10.49
		PARTS		10.49
		LABOR		60.15
10800000		SEGMENT TOTAL==>		70.64

SEGMENT# 7 S 190 NA 10/21/25 10/22/25
#28 GRAIN TANK - CLAAS CLAIM #404941918

COMPLAINT:

RH SIDE REMOVABLE PANEL IN GRAIN TANK ABOVE CONTERSHAFT
LEAKING CANOLA ON TO CONTERSHAFT AND PULLEY

CAUSE:

RH SIDE GRAIN TANK PANEL HAS A GAPS.

CORRECTION:

REMOVED PANEL, CLEANED THE EDGES OF THE HOLE AND INSPECTED
PANEL. FOUND PANEL IS LITTLE BENT, THE SIDE EDGES OF THE
PANEL ARE SLIGHTLY CURVED OUTWARDS. STRAIGHTENED PANEL AND
INSTALLED IN GRAIN TANK.

ADDITIONAL DESCRIPTION:

REMOVABLE PANEL IN GRAIN TANK ABOVE THRESHING VARIABLE
SPEED PULLEY LEAKING CANOLA ON TO PULLEY
TAKE PICS AND EMAIL ALL TO CHUCK

	LABOR	240.63
10800000	SEGMENT TOTAL==>	240.63

SEGMENT# 8 S 190 NA 10/21/25 10/21/25

CONTINUED ON PAGE 05

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EGGE ENVIROMENTAL FARM/GRINDSTONE GRAIN CORP
339 ENG HRS
252 SEP HRS

Invoice To: WARRANTY REC - CLAAS
.
. TT 99999
United States

Branch N. BATTLEFORD		
Date 10/30/25	Time 10:23:11' (O)	Page 05
Account No WARRA002	Phone No	Inv No W03416
Ship Via INSP 404920869	Purchase Order	
Tax ID No	887067502	
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339 C8910940		
	8700	252		

#29 GRAIN TANK SET TUBE - CLAAS CLAIM #404941952

COMPLAINT:

BENT RH SIDE SET TUBE, BRACE FOR BUBBLE UP AUGER IS BENT

CAUSE:

SET TUBE SHOCK ATTACHMENT POINT BENT

FAILED PT#29260901

CORRECTION:

REPLACED BENT RH SIDE SET TUBE, ADJUSTED BUBBLE UP AUGER

CONTROL ARM AND TESTED.

ADDITIONAL DESCRIPTION:

REPLACE BENT RH SIDE SET TUBE, BRACE FOR BUBBLE UP AUGER IS BENT

TAKE PICS AND EMAIL ALL TO CHUCK

29260901	SET TUBE	RETAIL	1401.33	
		1 N	1007.32	1007.32
		PARTS		1007.32
		LABOR		1163.07
10800000		SEGMENT TOTAL==>		2170.39

SEGMENT# 9 S 190 NA 10/21/25 10/22/25

#34 AUTO GREASER -CLAAS CLAIM #404941956

COMPLAINT:

LEAKING AT GREASE BLOCK ON REAR AXLE

CAUSE:

WEAKENED HOLLOW BOLT WHICH CONNECTED GREASE SUPPLY LINE TO THE DISTRIBUTOR

CORRECTION:

CLEANED DISTRIBUTOR AND LINES FROM GREASE AND DIRT. REMOVED

HOLLOW BOLT AND DISCONNECTED GREASE SUPPLY LINE. CLEANED AND

INSPECTED BOLT, LINE AND DISTRIBUTOR. INSTALLED WASHER,

CONTINUED ON PAGE 06

X

Authorized By



Lloydminster
Hwy 16 West & Range Road 21
Box 11336, T9V 3B6
Ph: 780-875-8010

North Battleford
Hwy 16 East & East Hill Road
Box 1778, S9A 3W8
Ph: 306-445-8010 F: 306-445-8011

Vegreville
14426 Hwy 16 Service Road
Box 310, T9C 1R3
Ph: 780-632-3246 F: 780-632-3247

Ship To: EGGE ENVIROMENTAL FARM/GRINDSTONE GRAIN CORP
339 ENG HRS
252 SEP HRS

Invoice To: WARRANTY REC - CLAAS
.
. TT 99999
United States

Branch N. BATTLEFORD		
Date 10/30/25	Time 10:23:11 (O)	Page 06
Account No WARRA002	Phone No	Inv No W03416
Ship Via INSP 404920869		Purchase Order
Tax ID No		887067502
		Salesperson 222

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
001046	LEXION 8700	339	C8910940		
	8700	252			

CONNECTED GREASE LINE AND TIGHTENED HOLLOW BOLT.
ADDITIONAL DESCRIPTION:
GREASE LINES LEAKING AT GREASE BLOCK ON REAR AXLE
TAKE PICS AND EMAIL ALL TO CHUCK

	LABOR	200.53
10800000	SEGMENT TOTAL==>	200.53

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	1650.11	
LABOR	3168.33	
SUB TOTAL==>	4818.44	
GST 5%	240.93	
INTERNAL TOTAL	5059.37	

X

Authorized By