

## D6T Dozer

## Description

| Description     | Date              | hours      | Completed By   | MWO#        |
|-----------------|-------------------|------------|--|-------------|
| General service | 21-Sep            | 4594 hours | serviced engine oil and filter, fuel filters, air filters, transmission oil and filter   |             |
|                 |                   |            | hydraulic oil and filter, all final drive oils, mount front working lights, repair doors   |             |
|                 |                   |            | clean out all stump pans, replace hoses to blade and install butterfly connectors  |             |
| General Service | April 2 2013      | 4911       | change oil and filter inner and outer air filters fuel filter  |             |
| General service | Oct 28 2013       | 5277       | Service engine oil and filter, fuel filters, air filter, Remove broken bolts from grille weld up latches and hinges  |             |
|                 |                   |            | hard mount 2- way radio  |             |
| General Service | Nov 4 2014        | 5454       | weld new chain loops on dozer blade  |             |
| General service | April 29 2017     | 5988       | Service engine oil and filters:fuel filters; air filter, Replace sender in fuel gauge, Replace a/c belt, Replace wiper blades on both doors, tighten tracks  |             |
|                 |                   |            | flipped center cutting edges and replace corner bits,  |             |
| General service | June 11 2017      | 6273       | Changed engine oil   |             |
| General Service | October 25 2017   | 6880       | Service engine oil and filters:fuel filters; air filter, Service transmission oil and filter, Service hydraulic  |             |
|                 |                   |            | oil and filters, Service final drive oils, grease job, change corner bits, Replace equalizer bar   |             |
| General service | July 17 2018      | 7811       | Changed engine oil   |             |
| General service | November 6 2018   | 8242       | Changed engine oil   |             |
| General service | November 20 2018  | 8306       | Changed fuel filters   |             |
| General Service | November 27 2018  | 8448       | Removed shims C-frame and dozer blade trunions to tighten the blade up.Installed new cutting edge  |             |
|                 |                   |            | Installed new hydraulic tank breather.Reinstalled the sterio as it was falling out of the roof.  |             |
| Install Tracks  | April 01 2019     | 8613       | Installed old chains with the new pads onto the unit. Installed new quick connect fitting for blade tilt. Removed the transmission shift solenoid valve bank and cleaned out dirt. Replaced solenoid #4 and reinstalled valve bank. Replaced break accumulator. ( Dan Verklan) | 206         |
| General Service | May 24 2019       | 8680       | Completed a 2000hr service. (Dan V)  |             |
| General service | July 23 2019      | 9064       | Removed blade tilt cylinders and took them to Del-west to get them resealed. Went and got the cylinders  |             |
|                 |                   |            | from Del-west and installed them. Tested the blade tilt then topped up hydraulic oil. Everything is good (taylor)  | 501         |
| U/C + Oil pump  | Nov 12 2019       | 9170       | Removed undercarrisge took at all broken bolts changed over from system one to conventinal UC, installed new rollers, sagments   |             |
|                 |                   |            | and tracks.Changed oil pump didn't have all the updated pieces had to wait for updated parts. Installed new pump and elbow   |             |
|                 |                   |            | tightened all bolts to spec.(Taylor Jones)   |             |
| General Service | Dec 7 2019        | 9181       | Rental checklist serviced new exhaust new ripper teeth.Replaced e frame pins replaced belts (Tim Carr)   | 954         |
| General Service | May 20 2020       | 9280       | Changed engine oil and filter, changed both fuel filters, changed both final drive oils, checked over unit found bolts for the tranny  | 862         |
|                 |                   |            | filter guard fell out, installed new bolts, greased unit. (Taylor)   |             |
| General Service | June 5 2020       | 9313       | Speaker in the 2 way isnt working- replaced the 2 way with a different unit, install a proper antenna, installed the backing plate   | 590         |
|                 |                   |            | on the blades pivot pin. (Dan V)   |             |
| 2000HR Service  | January 15 2021   | 9828       | 2000Hrs Changed engine oil filters and sampled.Changed trans oil and filters(Sampled)/Checked magnet bottom screen.Changed   | 1307        |
|                 |                   |            | hyd oil and filters (Sampled)/Changed both fuel filters load tested both batterys Changed both engine air filters Greased hard bar.  |             |
|                 |                   |            | Changed cab air filters Changed fuel cap new eather bottle Had electrical issues found no power in fuse box when remopving found   |             |
|                 |                   |            | water inside removed batteries and fuse panelcleaned out battery box and removed all fuses blew out fuse slots and used grease   |             |
|                 |                   |            | on all exposed parts reinstalled and all tested good.Tied all battery cables and lose wires in designated spots,no windshield wash   |             |
|                 |                   |            | unhooked all lines at pump and blew all lines out rehooked all lines and all tested good.Shimed bottom rear pins on ripper left and  |             |
|                 |                   |            | right made all greased nipples take grease.Drained and refilled both left and right final drives.Removed shims from both sides of  |             |
|                 |                   |            | C-Fram.Removed shims from blade and replaced one hyd hose (Tanner N)   |             |
| Repairs         | March 22 2021     | 9853       | Replaced all lights with LED lights on unit tested and all work (Shawn L)  | 3026        |
| Repairs         | April 13 32021    | 9903       | Removed new lights installed old dull ones Repaired back up alarm that was fully off machine repair hydraulic leak on tilt of blade  | 3045        |
|                 |                   |            | was a lose fitting (Shawn L)   |             |
| Service         | April 26 2021     | 9967       | Changed Engine oil and filters (Dan)   |             |
| Repairs         | May 12 2021       | 10074      | Went switched out RH wiper motor replaced with new one (Taylor Jones)  | 1429        |
| 250 Hr Service  | June 18 2021      | 10220      | Changed engine oil and filters (Gary)  |             |
| Repairs         | September 02 2021 | 10470      | Mystery Coolant Leak - Opened up the engine bay doors and saw coolant staining on and around the water valve for the heater  | 2046        |
|                 |                   |            | core. Found a ground wire has rubbed a hole through the coolant line and checked for leaks. Found the accessory power stays  |             |
|                 |                   |            | on after you shut the key off. Tested the ignition, its functioning normally. Removed the fuse panel to test the main solenoid and   |             |
|                 |                   |            | the starter relay. They are both good. Tested the wiring harness unhooked from the ignition switch and the fuse box. I had   |             |
|                 |                   |            | continuity between wire 307 & 308. I believe these 2 have rubbed through to the ground. (Dan Verklan)  |             |
| Service         | September 11 2021 | 10483      | Change fuel filter, change engine oil nad filter (Dan Myles)   |             |
| 500 Hr Service  | November 08 2021  | 10732      | Changed Engine oil and Engine oil filter (Dan V)   | 700         |
| 2000 Hr Service | January 25 2022   | 10872      | Get unit ready for the crusher. Completed 2000 hour service. Removed hyd tank, cleaned up mounting bolt holes. Installed hyd oil   | 2974 & 2975 |
|                 |                   |            | tank, installed bolts to secure tank to the frame. Replaced A/C pump. Recharged A/C system. Removed the tranny oil pump,   |             |
|                 |                   |            | installed tranny pump. Replaced the starter with a cat reman one. Resealed the R.H outer canon guide cap. Put new AST 30 into  |             |
|                 |                   |            | the canon rservoir. Removed the R.H track frame. Replaced both pivot shaft bushings. Re-installed track frame. Put new AST 30  |             |
|                 |                   |            | in both pivot shaft reservoirs. Replaced the 24-12V convertor and replaced the plug for the convertor on the wiring harness. Replaced  |             |
|                 |                   |            | the master switch. Replaced the floor mat. Wired th two way radio to ignition power. Repaired the pivot point on the operator seat.  |             |
|                 |                   |            | Removed the exhaust stack and straightened it out, reinstalled stack. Repaired the worn out bolt holes on the hyd tank cover. Wally  |             |

[illegible]