



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Equipment: B1408

Work Order #: 47752
 Date: 06/24/24

Completed Date: 07/31/24

Year: 2013
 Make: KENWORTH
 Model: T800
 Odometer: 619,002
 Hours: 22,214

Serial Number: 1XKDD40X4DR959708

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...		De Jager, Brodie	19.00	60.00	1,140.00
LABOUR INTERNAL (PVT ...		Bursey, Justice	18.00	60.00	1,080.00
LABOUR INTERNAL (PVT ...		Sabado, Paul	20.00	60.00	1,200.00
LABOUR INTERNAL (PVT ...		Kreutz, Ben	2.50	60.00	150.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
971370, CAP, KINGPIN	1.00	15.23	15.23
WL10107, OIL FILTER	1.00	45.29	45.29
WF10123, SPIN-ON FUEL FILTER	1.00	51.99	51.99
FS20172FLG, FUEL/WATER SEPERATOR	1.00	40.87	40.87
65523, SHOCK ABSORBER	2.00	88.83	177.66
CFR19501, FILTER, CAB AIR	1.00	11.34	11.34
359XL, STINGER CUT RESISTANT GLOVE XL	2.00	9.83	19.66
13-7042, 5/8 AXLE DRIVE STUD	8.00	6.31	50.48
R005960, DOWELL FLANGE	8.00	1.67	13.36
109-524, 5/8NF NYLOCK	1.00	1.58	1.58
250-70-18X, STRAP KIT, SPL250	3.00	27.26	81.78
TAS65219RMAN, STEERING, REMAN GEAR	1.00	1,670.88	1,670.88
571.LD322CA17.1, CAM MARKER LED LIGHT CLEAR LIGHT ONLY	1.00	25.63	25.63
DLP3092S, DRAG LINK	1.00	180.81	180.81
WLTOB, WHEEL TORQUE, 33.0 MM/ 1-5/16 RED	2.00	.77	1.54
KL-TF2840, DEXRON VI/MERC LV 946ML	4.00	12.93	51.72
13-7042, 5/8 AXLE DRIVE STUD	1.00	6.31	6.31
GKT1008, GASKET, 5/8" AXEL	2.00	6.72	13.44
1229W1661, WASHER, WHEEL STUD	16.00	1.67	26.72
51068, FILTER, OIL DIFF MERITOR	1.00	5.22	5.22
RKPKT2, POKET INSERT KIT	1.00	66.99	66.99
RK-10605, BUSHING PIN KIT	1.00	92.61	92.61
382-8036, SEAL, WHEEL STEER AXLE	2.00	57.99	115.98
330-3024, GASKET, HUBCAP	2.00	3.92	7.84
85070, STEER AXEL SHOCK/GABRIEL	2.00	35.53	71.06
802569BXW, ROTOR-HD	2.00	256.41	512.82
K129276BXW, KIT BRAKE PAD - DISC BRAKES	1.00	262.01	262.01
817134, WASHER-RETAINER	1.00	4.38	4.38
10W30CHEVBLK, 10W30 CHEVRON DELO 600 ADF SAE	40.00	7.91	316.40

1) B SERVICE

Changed oil/filters and greased and inspected. - Justice(3)

2) VIBRATION

Inspected and found faulty steering box, will need to order parts when parts is open. - Justice(.5)

Swapped out main driveline with M52. - Paul(2)

Drained power steering fluid box out, installed new one, filled up and tested, took steering wheel off and adjusted. -



PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Paul(4.5)

Went for test drive with Brodie, found front end to be vibration at 85-100. - Paul(1.5)

Road test truck, had vibration at 90-95. Pulled unit into shop, checked ride height, all good, checked over unit, everything looks good. Jacked up front end, removed hubs to inspect bearings, bearing were all good, cleaned up. - Brodie(8)

Reassembled everything, installed new rotors and pads on both side, torqued wheel and road tested, unit all good. - Brodie(8)

3) 50% CLEARANCE LIGHT OUT

Different style light thats hardwired in, will need to order parts. - Justice(.5)

Replaced clearance light - Paul(1.5)

4) SHIFT KNOB LOOSE

Tightened shifter knob. - Justice(.5)

5) PS FIRST SHOCK

Torched out shock and installed new. - Justice(1)

6) DS 2ND SHOCK

Torched out shock and installed new. - Justice(1)

7) 1ST DIFF NEEDS RESEALED

Removed driveline and axles, pulled airlines and unbolted diff, fought diff to get it unstuck and removed. Broke 1 bolt for airline bracket, removed power divider from diff to access broken bolt, heated bolt with torch and slowly worked it out, cleaned up all mating surfaces, installed power divider with new origs. Will need new diff bolts, ordered when parts is open before diff can be installed. Cleaned up work area, put tools away and complete paperwork - Justice(10.5)

Assisted putting diff back in,. - Ben(2.5)

Cleaned up diff, applied silicon and bolted up diff, installed axle, bolted up driveline, filled up diff. - Paul(10)

8) PS KING PIN CAP

Installed new king pin cap - Paul(.5)

10) CAB FILTER

Replaced cab filter. - Justice(.5)

Total Labor	3,570.00
Total Parts	3,941.60
Total Returns	.00
Total Sublet	.00
Shop Supplies	178.50
Invoice Total	7,690.10



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Equipment: B1408

Work Order #: 34495
 Date: 07/21/22

Completed Date: 07/21/22

Year: 2013
 Make: KENWORTH
 Model: T800
 Odometer: 543,121
 Hours: 20,571

Serial Number: 1XKDD40X4DR959708

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...	1) SERVICE CALL SERVICE CALL TO MILE 156 ON ALASKA HIGHWAY NORTH OF PINK MOUNTAIN. REMOVE AND REPLACE EXHAUST BELLOWS. INSTALLED NEW GASKET ON DPF INLET. PERFORMED B SERVICE. GREASED UNIT AND FIFTH WHEELS. DIFF #1 INPUT AND OUTPUT LEAKING. CHECKED LEVEL STARTING TO GET LOW. ALSO REPAIRED A COOLANT LEAK THAT WAS JUST STARTING REMOVED COMPRESSION CLAMP AND INSTALLED GEAR CLAMP	Rea, Jacob	14.00	60.00	840.00
LABOUR INTERNAL (PVT ...	2) DIFF #1 INPUT AND OUTPUT SEALS LEAKING RE AND RE INPUT SEAL. TOP OFF DIFF	Rea, Jacob	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	-REPLACED LEAKING OUTPUT SEAL	Debre, Matthew	2.00	60.00	120.00
LABOUR INTERNAL (PVT ...	3) INPUT SEAL DIFF #2 LEAKING REPLACED LEAKING INPUT SEAL #2 DIFF	Debre, Matthew	2.00	60.00	120.00
LABOUR INTERNAL (PVT ...	4) STUB SHAFT BAD REPLACE STUB SHAFT	Debre, Matthew	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	5) ALL WORK LIGHTS NEED REPLACED REPLACE WORK LIGHTS	Debre, Matthew	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	6) FIFTH WHEEL RISERS WORN OUT REMOVED FIFTH WHEEL	Debre, Matthew	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	-REMOVE FIFTH WHEEL, CLEAN RAILS OFF. INSTALL NEW SIDE, LOCKING CYLINDER RISERS AND REUSED OLD PLATE	Rea, Jacob	3.00	60.00	180.00
LABOUR INTERNAL (PVT ...	7) EXHAUST LEAKS GO THROUGH ALL EXHAUST. REPLACED GASKETS AND CLAMPS OF POSSIBLE PROBLEM AREAS	Rea, Jacob	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	8) CHECK OVER UNIT CHECK OVER ENTIRE UNIT AND MAKE LIST OF REPAIRS	Rea, Jacob	1.00	60.00	60.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
TRSY759DRM, TRAXON SYNTHETIC 75W-90 205L DRUM	5.00	7.57	37.85
RK106061, SLIDE BASE REBUILD KIT	1.00	247.45	247.45
RK106894, RISE FOR ILS SLIDE, 10" HEIGHT	1.00	737.40	737.40
H4651ST, LIGHT, HIGH BEAM	1.00	20.23	20.23
SSP1369, BRAKE PAD, AIR DISC KNORR SK7000	1.00	114.95	114.95
DUHP54BLK, ENGINE OIL, DURON UHP 5W-40 BULK	40.00	5.25	210.00
RK106891, KIT, ILS BKT REPLACEMENT 7"	1.00	535.89	535.89
WL10107, OIL FILTER	1.00	46.59	46.59
K37-1029, FILTER, FUEL	1.00	52.84	52.84



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Parts

Description	Quantity/Hours	Price/Rate	Amount
WF10123, SPIN-ON FUEL FILTER	1.00	64.69	64.69
20002, LUCAS OIL STABILIZER	2.00	42.40	84.80
2866636CUM, GASKET, 4" AFM DEVICE	3.00	15.59	46.77
KW65410320, BELLOW, EXHAUST	1.00	193.75	193.75
2866337CUM, GASKET, 5" AFM DEVICE	3.00	16.80	50.40
90-0012, CLAMP, V BAND 4"	3.00	18.66	55.98
105629, BLACK GORILLA TAPE	1.00	13.71	13.71
5-280X, 1710 FULLROUND U JOINT	1.00	54.95	54.95
63611-5, LAMP, CLEAR LED 4" SQUARE	3.00	84.50	253.50
A11205X2728, PINION SEAL	1.00	81.52	81.52
A11205A2731, SEAL	1.00	83.30	83.30
1701A55001C154M, DRIVE LINE, REAR	1.00	1,366.13	1,366.13
90-0013, CLAMP, V BAND 5"	2.00	19.86	39.72
4304023, PLUG, TRANS FILL	1.00	16.49	16.49
AS2729, Diff. output seal, front & cntr diff.	1.00	82.59	82.59
XAM24, BASE S/A 5TH WHEEL- 51"	1.00	1,104.13	1,104.13

1) SERVICE CALL

SERVICE CALL TO MILE 156 ON ALASKA HIGHWAY NORTH OF PINK MOUNTAIN. REMOVE AND REPLACE EXHAUST BELLOWS. INSTALLED NEW GASKET ON DPF INLET. PERFORMED B SERVICE. GREASED UNIT AND FIFTH WHEELS. DIFF #1 INPUT AND OUTPUT LEAKING. CHECKED LEVEL STARTING TO GET LOW. ALSO REPAIRED A COOLANT LEAK THAT WAS JUST STARTING REMOVED COMPRESSION CLAMP AND INSTALLED GEAR CLAMP

2) DIFF #1 INPUT AND OUTPUT SEALS LEAKING RE AND RE INPUT SEAL. TOP OFF DIFF

-REPLACED LEAKING OUTPUT SEAL

3) INPUT SEAL DIFF #2 LEAKING REPLACED LEAKING INPUT SEAL #2 DIFF

4) STUB SHAFT BAD REPLACE STUB SHAFT

5) ALL WORK LIGHTS NEED REPLACED REPLACE WORK LIGHTS

6) FIFTH WHEEL RISERS WORN OUT REMOVED FIFTH WHEEL

-REMOVE FIFTH WHEEL, CLEAN RAILS OFF. INSTALL NEW SIDE, LOCKING CYLINDER RISERS AND REUSED OLD PLATE

7) EXHAUST LEAKS GO THROUGH ALL EXHAUST. REPLACED GASKETS AND CLAMPS OF POSSIBLE PROBLEM AREAS

8) CHECK OVER UNIT CHECK OVER ENTIRE UNIT AND MAKE LIST OF REPAIRS

Total Labor	1,680.00
Total Parts	5,595.63
Total Returns	.00
Total Sublet	.00
Shop Supplies	84.00



PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

Invoice Total 7,359.63



PVT Energy Group Inc.
 93-721071 Range Road 53
 County of Grande Prairie, AB, T8X 0N4
 Phone: 780-830-0045
 Fax: 780-830-5164

Equipment: B1408

Work Order #: 33502

Date: 05/16/22

Completed Date: 05/19/22

Year: 2013
 Make: KENWORTH
 Model: T800
 Odometer: 578,939
 Hours: 19,722

Serial Number: 1XKDD40X4DR959708

Labor

Category	Description	Mechanic	Quantity/Hours	Price/Rate	Amount
LABOUR INTERNAL (PVT ...	SERVICE CALL	Rea, Jacob	6.50	60.00	390.00
LABOUR INTERNAL (PVT ...	BSERVICE	Rea, Jacob	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	RODS	Rea, Jacob	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	YOKE	Rea, Jacob	3.00	60.00	180.00
LABOUR INTERNAL (PVT ...	RODS *CAL*	Baranowski, Lee	2.00	60.00	120.00
LABOUR INTERNAL (PVT ...	BSERVICE *CAL*	Baranowski, Lee	3.00	60.00	180.00
LABOUR INTERNAL (PVT ...	CLAMP *CAL*	Baranowski, Lee	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	FOG LIGHTS *CAL*	Baranowski, Lee	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	MUDFLAP *CAL*	Baranowski, Lee	.50	60.00	30.00
LABOUR INTERNAL (PVT ...	LIGHT *CAL*	Baranowski, Lee	1.50	60.00	90.00
LABOUR INTERNAL (PVT ...	WINDSHIELD	Peterson, Ryan	.50	60.00	30.00
LABOUR INTERNAL (PVT ...	SHAFT	Rea, Jacob	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	YOKE	Rea, Jacob	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	CLUTCH BRAKE	Rea, Jacob	.50	60.00	30.00
LABOUR INTERNAL (PVT ...	BATTS	Rea, Jacob	1.00	60.00	60.00
LABOUR INTERNAL (PVT ...	BUMP STOP	Rea, Jacob	.50	60.00	30.00
LABOUR INTERNAL (PVT ...	SHAFT	Rea, Jacob	.50	60.00	30.00

Parts

Description	Quantity/Hours	Price/Rate	Amount
DW1164-30, WINDSHIELD, L/H T800 KW	1.00	40.00	40.00
GA31S, BATTERY, 1200 CA SCREW POST	4.00	113.77	455.08
DUHP54BLK, ENGINE OIL, DURON UHP 5W-40 BULK	45.00	5.25	236.25
C83-1036, STOP, AXLE	1.00	111.04	111.04
N2620-C, BRACKET, ANTI-SAIL MUDFLAP	1.00	13.45	13.45
FF5825NNFLG, FILTER, FUEL	1.00	56.68	56.68
24X24, 24X24 MUDFLAP BLACK	1.00	19.95	19.95
WL10107, OIL FILTER	1.00	46.59	46.59
Q347367FLG, CAP, POWER STEERING	1.00	16.72	16.72
WF10500, FUEL FILTER	1.00	55.61	55.61
C83-1055, STOP-REAR AXLE	2.00	140.74	281.48
WA10009, RADIAL AIR FILTER	2.00	80.38	160.76
839310, BUSHING	4.00	76.39	305.56
SPL170-4X, U-JOINT KIT SPL 170	2.00	109.58	219.16
170-70-18X, STRAP KIT, SPL170	2.00	20.70	41.40
170-4-721-1X, YOKE, DIFFERENTIAL END, SPL170 SERIES	1.00	261.17	261.17
10094142, CENTERBEARING ASSEMBLY	1.00	96.95	96.95
KIT2638, KIT, NUT AND WASHER	1.00	28.45	28.45
26240, THREADLOCK, RED	1.00	30.95	30.95
C65-1009, ROD ASSY TORQUE	2.00	530.31	1,060.62
SB200, CLUTCH BRAKE 2PC	1.00	36.20	36.20
250-70-18X, STRAP KIT, SPL250	2.00	18.95	37.90

BSERVICE REQUEST



PVT Energy Group Inc.
93-721071 Range Road 53
County of Grande Prairie, AB, T8X 0N4
Phone: 780-830-0045
Fax: 780-830-5164

- (1)SERVICE CALL - CANFOR RD, REAR DIFF TORQUE ROD MOUNTING BOLTS BROKE OFF. INSTALLED NEW BOLTS. STUB SHAFT BETWEEN DIFF 1 & 2 DAMAGED. REMOVED SHAFT & HAD DRIVER BRING TRUCK BACK.
- (2)BSERVICE - COMPLETED.
- (4)TORQUE RAD BUSHINGS - REMOVED TORQUE RODS ON DIFF #2, WENT TO CHANGE BUSHINGS BUT FOUND BAD WEAR, REPLACE.
- (5)DRIVE SIDE WINDSHIELD - REPLACED.
- (6)CLUTCH BRAKE -
- (7)FLEX PIPE MISSING -
- (8)DS RED AIR CLEANER LIGHT - REPLACED.
- (9)PS LOWER AMBER AIR BOX LIGHT OUT - REPLACED.
- (10)PS RED AIR BOX LIGHT - REPLACED.
- (11)REAR DIFF YOKE -
- (12)FOG LIGHTS - REPLACED.
- (13)DS MUDFLAP IN FRONT OF CHAINS - R&R'D.
- (14)BATTS - REPLACED ALL 4.
- (15)REAR DIFF BUMP STOPS - REPLACED.

Total Labor	1,620.00
Total Parts	3,611.97
Total Returns	.00
Total Sublet	.00
Shop Supplies	81.00
Invoice Total	5,312.97



9607 - 111 Street
Grande Prairie, AB T8V 4E5

INVOICE

Invoice No.: 26344
Date: 09/15/2022

Sold to:
Performance Vac & Tank Services Ltd
Box 783
Grande Prairie, AB T8V 3R5

PO# 39924
Insurance Co.
Adjuster
Claim #

Business No.: 81641 9246

Description	Tax	Amount
Loose Kenworth Hood Unit B1408		
R&I Hood Components for Repairs		
Repair Hood Latch Mounts		
Repair RH Fender		
Repair LH Fender		
New Part - Hood Corner and Latch Plates		
Repair RH Grille and Reinforce Both Corners		
Refinish Hood Complete		
LABOR -Repair	G	3,300.00
LABOR -Refinish	G	1,200.00
PARTS	G	135.00
PAINT MATERIALS	G	640.00
BODY MATERIALS	G	880.00
HAZARDOUS FEE	G	8.00
Subtotal:		6,163.00
G - GST 5%		
GST		308.15
Big Rig Collision Grande Prairie Ltd. GST: #81641 9246		
Big Rig Collision Grande Prairie Ltd. Phone: (780) 532-1996 Fax: (780) 532-8033	Total Amount	6,471.15
Comment:	Amount Paid	0.00
	Amount Owing	6,471.15