



Vehicle History Summary

Fleet #	
Registration	
Make	Kenworth
Model	SAR T409 6x4
VIN / Chassis #	6F500000EA452484
Build Date	2014

Date	Reading / Units	Type / Repairer Notes	Repairer
17/11/2025		transmission rebuild R-19442	Truck Transmission Pty Ltd
17/10/2025		tie rod R-18355 replace when putting gearbox back in please	Simon Wade (Mechanic)
07/10/2025	8,438,710 kms 710,526 hrs	repairs R-19001 CLUTCH KIT - GEN EATON 2050 MAN ADJ PD REAR SEAL KIT - ISX GASKET - SHIFT LEVER HOUSING EATON GASKET (LID) SHIFT BAR HOUSING	multispares
06/10/2025		fuel tank minor leak R-18707 will re book Ausec for welding	Jake Doughty (Mechanic)
06/10/2025		rear structure leaking R-19035	Blake's Torque & Tinker
03/10/2025		gearbox removal R-19034 removed gear box	Blake's Torque & Tinker
29/09/2025		fuel tank leak R-19125	Internal
23/09/2025		A service repairs R-18540	Simon Wade (Mechanic)
19/09/2025		Reverse Light Switch R-18723 noted thanks re book next A service if not sooner	Simon Wade (Mechanic)
15/09/2025		Bonnet strap R-18978	Internal
12/09/2025	8,438,710 kms 710,526 hrs	clutch R-18727 Repair clutch Bring in truck Removed clutch linkages Rebuild arm Replaced outer adjuster Adjusted clutch road test truck Ok	A&C Heavy Repairs Pty Ltd
12/09/2025	8,438,710 kms 710,526 hrs	clutch re adjustment R-18725 Worked with Andrew on clutch linkage repair and re adjustment.	Blake's Torque & Tinker
11/09/2025	8,438,710 kms 710,526 hrs	LEVER CLUTCH, LEVER CLUTCH CONTROL R-18720 LEVER CLUTCH LEVER CLUTCH CONTROL	multispares
10/09/2025	860,468 kms	B - 30k S-13839 B SERVICE NEXT B - 890,468	Blair Wade
09/09/2025		no fault R-18517 No fault found	Blair Wade
29/08/2025		batteries R-18648	

Date	Reading / Units	Type / Repairer Notes	Repairer
		New batteries installed	
27/08/2025	8,438,710 kms 710,526 hrs	HUB CAP - STEER R-18619 HUB CAP - STEER	multispares
25/08/2025	8,438,710 kms 710,526 hrs	N70ZZH MF Century R-18609 N70ZZH MF Century	A2R Batteries & Performance
21/08/2025	843,871 kms 71,052 hrs	After-treatment issue R-18663 Complaint: After-treatment issue Cause: Seized dosing injector and outdated ECM calibration Correction: 21/8/25 - Assessed the vehicle. - Scanned fault codes and found active after-treatment codes. - Followed troubleshooting procedures and completed a click test. - Determined the truck needs to come to the workshop for further tests. - Vehicle arrived at K & C Workshop. - Connected diagnostic tool and found active fault codes related to the 'NOx inlet sensor, data valid but above normal operating range'. - Inspected the exhaust system and SCR, found no signs of the inlet NOx sensor. - Attempted to find troubleshooting information through Cummins Insight, but nothing was available. - Used Cummins QuickServe Online to access ECM information. - The ECM did not list this fault code. - Reviewed wiring diagrams, but nothing listed the inlet NOx sensor. - Found troubleshooting steps and followed them. - This involved removing the AdBlue dosing injector to confirm correct dosing. - Due to the dosing injector being seized in the exhaust, I had to remove that section of the exhaust. - While removing the exhaust, the V-bands were also seized and broke apart, requiring replacement. - Removed the seized injector and performed a dosing override test, which tested good. - Re-fitted the exhaust and secured the wiring. - Consulted with Cummins for support, and they informed me that a calibration and update were required. - Cummins had to come to the site to perform this. - All tests were successful.	K&C autos
18/08/2025		trailer tyre R-18553	Metro tyres
17/08/2025		Registration O-3799	
14/08/2025	855,130 kms	A - 15/30 days S-13531	Simon Wade (Mechanic)
14/08/2025		STEER HUB COVER R-18543 INSTALL NEW N/S AXLE 1 HUB COVER AND REFILL OIL	Simon Wade (Mechanic)
13/08/2025	843,871 kms 71,052 hrs	repairs R-18524 SEAL - CR SCOTSEAL CLASSIC (TOOL FIT) HUB CAP GASKET - 6 HOLE 5.5"PCD DRIVE AXLE GASKET - 8 STUD BRAKE DRUM - 16.5X5 CAST 10 STUD 285PCD CAST DRUMS BRAKE DRUM - MERITOR L/W 285PCD 5" KW LIGHT WEIGHT	multispares
01/08/2025	850,073 kms	brake check R-18373 Check and adjust steer brakes Test run and check brakes-ok	Simon Wade (Mechanic)
31/07/2025		Exhaust R-18271 Replace exhaust flex and clamps	Simon Wade (Mechanic)
31/07/2025		oil leak R-18312 Install new turbo drain gasket	Simon Wade (Mechanic)
31/07/2025	8,438,710 kms 710,526 hrs	BEARING SET CONE & CUP, SEAL - CR SCOTSEAL CLASSIC (TOOL FIT) R-18365 BEARING SET CONE & CUP SEAL - CR SCOTSEAL CLASSIC (TOOL FIT)	multispares
31/07/2025	8,438,710 kms 710,526 hrs	BEARING SET CONE & CUP, SEAL - CR SCOTSEAL CLASSIC (TOOL FIT) R-18367 BEARING SET CONE & CUP BEARING SET CONE & CUP SEAL - CR SCOTSEAL CLASSIC (TOOL FIT)	multispares
30/07/2025	849,256 kms	n/s fuel tank R-18244 Remove n/s fuel tank and send to austec Install top fuel tank breather and insert Install fuel tank Repair n/s fuel tank light wiring	Simon Wade (Mechanic)
29/07/2025		ringfeeder R-18243 Dismantle and clean/lubricate ringfeder Check operation - ok	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
28/07/2025	843,871 kms 71,052 hrs	Corroded connector R-18220 Assessed vehicle - Connected computer to scan fault codes. - Found multiple fault codes relating to after treatment. - Checked wiring and found corroded connector, which was removed and replaced. - Checked wiring to coolant level sensor due to an inactive code; wiring seemed fine. - Jake will replace the sensor as a precaution. - Checked wiring to throttle pedal and over engine; all seemed fine. - Erased fault codes. - Customer will test drive once the fuel tank is put back in.	K&C autos
23/07/2025	846,586 kms	Exhaust flex R-18195 Install new exhaust flex with clamps and gaskets	Simon Wade (Mechanic)
23/07/2025	846,586 kms	throttle position sensor R-18196 Install new throttle position sensor	Simon Wade (Mechanic)
23/07/2025	843,871 kms 710,526 hrs	ADBLUE FILTER - IN TANK, ADBLUE TANK MAGNET - WITH STRAINER R-18205 ADBLUE TANK MAGNET - WITH STRAINER ADBLUE FILTER - IN TANK	multispares
22/07/2025	843,871 kms 71,052 hrs	HUB CAP GASKET - 6 HOLE 5.5"PCD, HUB CAP - STEMCO STD ALLOY FRONT 6 HOLE, LINED SHOE KIT - MERITOR 23000LB Q+ 5" R-18208 LINED SHOE KIT - MERITOR 23000LB Q+ 5" HUB CAP - STEMCO STD ALLOY FRONT 6 HOLE HUB CAP GASKET - 6 HOLE 5.5"PCD	multispares
21/07/2025	843,871 kms 71,052 hrs	THROTTLE POSITION SENSOR - WM526 CUMMINS R-18184 THROTTLE POSITION SENSOR - WM526 CUMMINS	multispares
18/07/2025	847,987 kms	cabin shocks R-18173 Install 2 x new cabin shocks	Simon Wade (Mechanic)
10/07/2025	844,841 kms	A - 15/30 days S-13388 Front bumper bar support cracked Rear main leak Pto hose out leaking Through shaft has play O/s first axle o/s booster dented Cab shocks wet Diesel tank leaking Drag link needs replacing booked in next week Dump pipe hanger rubbers need replaced Window tint drivers and passenger windows needs replacing Stone chip direct line of sight drivers window Passenger window cracked 15cm 1 out of 2 dash globe for air temp gauge blown	Jacob Rennex-Apprentice Mechanic
10/07/2025		clearance light R-18097 13 clearance lights fixed	
02/07/2025		engine oil R-18055 10 ltrs added	Jake Doughty (Mechanic)
28/06/2025	828,594 kms	Steering wheel R-17843 Install new steering wheel	Simon Wade (Mechanic)
26/06/2025	8,215,538 kms 710,526 hrs	DRAGLINK ASSEMBLY R-18024 DRAGLINK ASSEMBLY	multispares
25/06/2025	821,553 kms	bug deflector R-17997 Reglue bug deflector	Simon Wade (Mechanic)
19/06/2025	8,215,538 kms 710,526 hrs	BRAKE DRUM - MERITOR L/W 285PCD 7", LINED SHOE KIT - MERITOR BLK 23000LB Q+ R-17964 LINED SHOE KIT - MERITOR BLK 23000LB Q+ BRAKE DRUM - MERITOR L/W 285PCD 7"	multispares
18/06/2025	8,215,538 kms 710,526 hrs	GASKET - TURBO OIL DRAIN R-17939 GASKET - TURBO OIL DRAIN	multispares
17/06/2025		coolant R-17935 Clamps tightened on bottom radiator hose	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
10/06/2025	8,215,538 kms 710,526 hrs	SERVICE BRAKE CHAMBER TYPE 20 R-18083 SERVICE BRAKE CHAMBER TYPE 20	multispares
04/06/2025	8,215,538 kms 710,526 hrs	SLACK ADJ MANUAL- 28SPL - 5.5" & 6.5" R-17857 SLACK ADJ MANUAL- 28SPL - 5.5" & 6.5"	multispares
29/05/2025		trio leaking R-17823 INSTALL NEW O/S TRIO VALVE	Simon Wade (Mechanic)
29/05/2025	828,594 kms	trio valve R-17820 INSTALL NEW O/S TRIO VALVE	Simon Wade (Mechanic)
21/05/2025		air leaks R-17764 Repair air manifold at fire wall Install new one way valve at o/s chassis	Simon Wade (Mechanic)
15/05/2025	8,215,538 kms 710,526 hrs	fuel filter, oil filter, water filter R-17667 FUEL FILTER - ISX CR FUEL/WATER FILTER - 10 MICRON LONGLIFE OIL FILTER	multispares
15/05/2025		fuel tank leaking R-17427 All issues been fixed	
14/05/2025		adblue R-17461	Simon Wade
14/05/2025		fuel tank leak R-17476	Blair Wade
12/05/2025	826,928 kms	Air leaks R-17559 Move 1 airline mounted to fire wall internal and external Install 1 new protection valve o/s above front diff	Simon Wade (Mechanic)
29/04/2025		engine oil R-17416 Install engine oil	Blair Wade
09/04/2025	820,553 kms	A - 15/30 days S-13679	Blair Wade, Simon Wade
02/04/2025		Air Leak R-17381 Repair and replace broken air fitting to trailer axle 2 n/s booster	Simon Wade (Mechanic)
27/03/2025		drivers window R-17204 Got fixed	Blair Wade
26/03/2025		drivers window reg R-17298 INSTALL NEW DRIVERS WINDOW REG	Simon Wade (Mechanic)
21/03/2025	816,182 kms	A - 15/30 days S-13678	Blair Wade, Simon Wade
21/03/2025	816,182 kms	drivers window reg R-17259 Install new drivers window reg Install 2nd hand door control module from att042 Dull noise on buzzer	Simon Wade (Mechanic)
19/03/2025		Fire extinguisher R-17247 Install new 9kg fire extinguisher	Simon Wade (Mechanic)
19/03/2025	815,793 kms	Clearance Lights R-17246 Repair wiring to 2 tank lights Install 2 new tank led lights Make and install bin light earth strap to chassis	Simon Wade (Mechanic)
12/03/2025		engine oil R-17218 Install 4ltr engine oil	Simon Wade (Mechanic)
11/03/2025		welding R-17202 bin welded by Sloanebuilt trailers	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
11/03/2025		engine oil R-17201 install 4ltr engine oil	Simon Wade (Mechanic)
05/03/2025		engine oil R-17168 Install 5ltr engine oil	Simon Wade (Mechanic)
26/02/2025		wiper motor R-17004 Install new wiper motor	Simon Wade (Mechanic)
26/02/2025		level valve R-16506 Replaced air bag and level valve	Simon Wade (Mechanic)
26/02/2025		air con R-17002 air con repaired by K&C auto	Simon Wade (Mechanic)
26/02/2025		air con R-17003 air con repaired by K&C auto	Simon Wade (Mechanic)
24/02/2025		engine oil R-16845 Install 5 ltr engine oil	Simon Wade (Mechanic)
19/02/2025	808,692 kms	A - 15/30 days S-12929 A SERVICE NEXT B - 822,000 - No2 O/S Slack Adjuster	Blair Wade
13/02/2025	807,399 kms	wiper motor R-16801 INSTALL NEW WIPER MOTOR	Simon Wade (Mechanic)
12/02/2025	814,685 kms 710,526 hrs	wiper motor wiring R-17230 MOTOR - WIPER	Gilbert and Roach
10/02/2025		Air Leak R-16793 Repaired air leak at rear of trailer	Simon Wade (Mechanic)
10/02/2025		air leak tyre R-16792 tyre repaired by all tyres aus	
10/02/2025		new tyres T-3397 EV1122516 4 STM 450.00 FITTED POS 7-8-9-10 ATT128 9-2-25 ZTD TYRE DISPOSAL 4 STM 27.50 110.00	All Tyres Australia
21/01/2025	802,908 kms	A - 15/30 days S-12836 A SERVICE NEXT B - 822,000	Blair Wade
20/01/2025		air R-16542 Install new foot brake valve	Blair Wade
20/01/2025		adblue R-16553 Install new adblue sender/pickup	Blair Wade
20/01/2025		air leak, R-16551 Install new rear airbag levelling valve	Blair Wade
20/01/2025		air leak, R-16547 Install new rear airbag levelling valve	Blair Wade
19/12/2024		dog tyres R-16464 Tyres replaced by all tyres aus	Simon Wade (Mechanic)
17/12/2024	797,258 kms	A - 15/30 days S-12756 Repair leaking hose on steering box. Will need 2nd drive axle brakes next service.	Christopher Watson-Mechanic
09/12/2024	793,809 kms	adjust brakes R-16382	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
09/12/2024		Adjust steer axle brakes oil usage R-16384 Oil consumption already noted	Simon Wade (Mechanic)
09/12/2024	796,213 kms 710,526 hrs	drive tyres T-3291 EV11225EDM67 4 STM 459.00 FITTED POS 3-4-5-6 FLEET ATT128 ZTD TYRE DISPOSAL 4 STM 27.50 110.00	All Tyres Australia
04/12/2024	796,213 kms 710,526 hrs	King pin & bushes R-16442 L11-KG931R KING PIN KIT - STEMCQ QWIK (3 BOLT CAP) R838D 598.29 598.29 1 1 57L1209 TIE ROD END - LHS D134H2 71.68 71.68 1 1 57L1210 TIE ROD END - RHS D134F1 71.68 71.68 1 1 57L2212 DRAGLINK ASSEMBLY R879G4 684.06 684.06 6 6 57Y0602 BUSH - SHACKLE/SPRING - THREADED D103J5 20.61 123.66 2 2 57Y0502 SHACKLE PIN - REAR THREADED D105E4 31.33 62.66 4 4 57Y0524 SHACKLE PIN - THREADED D105E6 51.29 205.16 2 2 K09-RPL20 UNI JOINT RPL20 D306C1 228.34 456.68 2 2 K09-RPL25 UNI JOINT RPL25 D306D2 291.17 582.34 1 1 57Y3104P KIT - REAR ENGINE MOUNT U TYPE GAFF POLY D302G3 452.18 452.18 2 2 57Y3026 SHOCK ABSORBER - MERITOR H410C1 134.76 269.52	multispares
29/11/2024	792,479 kms	King pin & bushes R-16367 Stripped down hub assemblies on steer axle found wheel bearing have case hardening coming apart. R&R king pin assemblies. R&R tie rod ends R&R drag link assemble. R&R all steer shackle pins and bushes. R&R steer wheel bearings/ hub seals pack with new grease. R&R rear engine mount. R&R 1st drive shocks. R&R all mudflaps. Remove rear tail shaft and jack shaft. R&R uni's and refit to truck. Remove stainless wrap from front bar then sand and polish bar	Christopher Watson-Mechanic
29/11/2024	792,479 kms	B - 30k S-12687	Christopher Watson-Mechanic
28/11/2024		rear front axle R-16427 U-BOLT-FRONT AXLE 4 4 89.79 85.30 1 341.20 2 2 204A05B3 K169-147-126CA NUT-3/4NFNYLDEEPNUT8	Gilbert and Roach
27/11/2024		bearings R-16432 F25-45280/45220 ATT128 BEARING SET CONE & CUP D101E2 42.40 84.80 2 2 L03-CR35066 ATT128 SEAL - CR SCOTSEAL CLASSIC (TOOL FIT) D101E6	multispares
20/11/2024		ringfeeder R-16351 Make up socket to be able to remove ringfeder from truck, Remove ringfeder and rebuild it. Refit to truck and test operation	Christopher Watson-Mechanic
19/11/2024	792,478 kms	A - 15/30 days S-12664 This vehicle has been taking off the road until all the following repairs have been carried out, Excessive movement in kingpins, Excessive movement in all tie rod ends and drags link ends, Excessive movement in steer shackle pins and bushes, Excessive movement in 4x tail shaft uni's, 1st drive torque rod bushes worn out, New shock on N/S 1st drive, Excessive movement in ringfeder, Rear engine mounts worn out,	Christopher Watson-Mechanic
29/10/2024		coolant , R-16179 install heater core	Simon Wade (Mechanic)
29/10/2024		drive faults R-16184 shocks replaced steering box reco by direct power steer	Simon Wade (Mechanic)
22/10/2024	782,762 kms	A - 15/30 days S-12543 A SERVICE NEXT B - 783,167	Blair Wade
22/10/2024	731,441 kms 19,377 hrs	inspect coolant leak R-15268 New heater core installed	Simon Wade
02/10/2024		diff torque rod bushes R-15992 Replace 4 bushes	Blair Wade
02/10/2024		steer shocks R-15991 Replace with New shocks and rubbers	Blair Wade
02/10/2024		power steering box R-15990	Blair Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
27/09/2024	775,566 kms	Install new power steer box inlet sensor wiring R-16000 connected to Insite & retrieved ECM image Engaged auto electrician to complete repairs	Cummins South Pacific Pty Ltd
26/09/2024	777,566 kms	Parts O-3647 Sensor - Exhaust Temp - Grey Plug	multispares
25/09/2024	775,566 kms	leak steering box R-15962 Install reco exchange steering box by Direct power steering Install new power steer oil and filter Test run and check re straighten steering wheel Install new steer axle shocks Install new main fanbelt and a/c fanbelt	Blair Wade, Simon Wade
25/09/2024	775,566 kms	A - 15/30 days S-13677	Blair Wade, Simon Wade
25/09/2024	777,566 kms	shock bushes R-15627 Install new steer shocks	Simon Wade
25/09/2024		steering box R-15948 Supply recon SAR409 steering box	Direct Power Steering Service
25/09/2024		Parts O-3648 Drive Belt - Dayco	multispares
24/09/2024		Parts O-3623 2 x Shock Absorbers	multispares
18/09/2024	775,566 kms	engine oil R-15907 Install 5 ltr engine oil	Simon Wade (Mechanic)
17/09/2024	775,566 kms	Front Tailshaft R-15852 Install new rpl25 front tailshaft uni Install new gear box yoke and nut from truck trans Re install tailshaft and tension all tailshaft bolts	Christopher Watson-Mechanic, Simon Wade
17/09/2024		Parts O-3645 Gearbox Yoke & gearbox yoke nut	
05/09/2024		manifold gaskets R-15941 repair gasket manifold	multispares
20/08/2024		trailer tyres T-3123 Fitted 4 x Greentour 11R22.5 149/146K GDM601	All Tyres Australia
20/08/2024	760,010 kms	A - 15/30 days S-12310 A SERVICE NEXT B - 783,167 New centre bearing	Blair Wade
23/07/2024	740,826 kms 19,526 hrs	check tyres R-15384 Tyres were replaced with new tyres on drive	
15/07/2024	753,167 kms	B - 30k S-12311 B SERVICE NEXT B - 783,167 New centre bearing	Blair Wade
15/07/2024	753,167 kms	C - 100k/ Annual S-12306 C SERVICE NEXT B - 783,167 New centre bearing	Blair Wade
15/07/2024	752,755 kms	Tailshaft centre bearing R-15554 Install new tailshaft centre bearing Install 4 x new tailshaft bolts behind centre bearing Install 2 x new tailshaft centre bearing carrier bolts/nuts	Blair Wade, Simon Wade
01/07/2024	747,513 kms	7 pin female plug R-15485 Replaced 7 pin socket	Blair Wade
17/06/2024	741,888 kms	A - 15/30 days S-12214	Blair Wade

Date	Reading / Units	Type / Repairer Notes	Repairer
A SERVICE			
07/06/2024	739,611 kms	puncture repair T-3083 GK Denney Tyres Coffs Harbour 1 x tyre position 7 1 x puncture repair pos 8	
23/05/2024		coolant leak R-15270 Install new electric heater tap on fire wall Install new wiring harness to electric heater tap Install 2 x new 5/8 silicone heater hose to heater core	Simon Wade
14/05/2024	725,395 kms	A - 15/30 days S-12080 service completed Clearance light replaced steering box leaking-Monitor Heater control valve	Blair Wade
14/05/2024	725,595 kms	B - 30k S-12081 Service completed	Blair Wade
08/05/2024		coolant leaking R-15174 Install new 5/8 coolant hose from top tap to heater module Remove and check all coolant supply piping and check for leaks	Simon Wade
03/05/2024	721,696 kms	axle shocks R-15132 Install new axle 2 o/s shock	Blair Wade
03/05/2024	721,696 kms	front tyres R-15131 Install 2 x new steer tyres	Blair Wade
29/04/2024		puncture repair R-15117 completed	
17/04/2024	718,176 kms	heater taps R-14887 Install 2 x new heater taps and p-clamp Install new coolant	Simon Wade (Mechanic)
16/04/2024	718,176 kms	clutch adjust R-14888 Adjust clutch and clutch brake	Simon Wade (Mechanic)
15/04/2024	718,176 kms	A - 15/30 days S-11992 service completed o/s axle 2 slack adjuster adjusted clutch- done Simon gearbox filter leak - done Simon	Simon Wade
12/04/2024	717,120 kms	Check oil, check tyres R-15005	
28/03/2024	713,995 kms	blinker stalk, wiper motor wiring R-15124 replaced blinker stalk repaired wiring to wiper motor	Phillip Axisa
25/03/2024	712,593 kms	heater tap leaking R-14971 on repair 14887	
22/03/2024	712,618 kms	coolant leak/losing coolant R-14967 checked and repaired	
21/03/2024		radiator cap R-14706 Install new radiator cap and 5 ltr coolant	Simon Wade (Mechanic)
20/03/2024		compressor hose R-15154 completed	Hydraulink
19/03/2024	711,019 kms	A - 15/30 days S-11911 service completed	Blair Wade
15/03/2024		inspect air leak R-15142 leak repaired	
28/02/2024		air conditioner R-15138	

Date	Reading / Units	Type / Repairer Notes	Repairer
28/02/2024		Hydraulic oil R-14570 Install 40 ltr of hydraulic oil	Blair Wade
28/02/2024	703,248 kms	check tyres R-14571 Install new axle 2 tyres x4 Install 2 x runout tyres axle 4 n/s	Blair Wade
20/02/2024	700,376 kms	A - 15/30 days S-11812 Service Completed	Blair Wade
19/02/2024		sentinel screen R-14445 Mount and install sentinel to above driver storage area Wire power to sentinel to accessory power	Simon Wade (Mechanic)
14/02/2024		Air leak, trio leaking R-15136 replaced trio valve male and female, replaced airline in drawbar	
07/02/2024		bonnet mirror R-14389 re install mirror	Simon Wade (Mechanic)
06/02/2024		air line R-14742 Blair replaced hose with simon as had hole/rub through problem fixed	Blair Wade
06/02/2024		Air hose leaking R-14761 blair replaced air hose problem fixed	Blair Wade
06/02/2024		Air hose leaking R-14743 blair and simon replaced hose problem fixed	Blair Wade
02/02/2024		bonnet mirror R-14760 replaced mirror assembly	Simon Wade
30/01/2024	693,083 kms	A - 15/30 days S-11740 Service completed	Simon Wade (Mechanic)
29/01/2024	693,083 kms	B - 30k S-11744 Service completed	Simon Wade (Mechanic)
25/01/2024		a/c R-14295 air con fixed at ace auto	Simon Wade (Mechanic)
23/01/2024		bald tyre on float R-14331 repair tyre	Simon Wade (Mechanic)
22/01/2024		a/c R-14303 a/c done by ace auto	Simon Wade (Mechanic)
22/01/2024		replaced trio valve R-14757 replaced trio valve replaced air line in a frame	Blair Wade
19/01/2024		Airconditioner, air hoses, replaced trio valve R-14759 Aircon fixed by ace auto blair replaced trio valve blair replaced air hose in a frame as had hole in line	Ace Air Auto Electrical, Blair Wade
18/01/2024	691,248 kms	air conditioner faulty R-14444 replace number 6 & 8 hose assemblies clean out evaporator core and replace worn out blower fan regas,add dye solution & test	Ace Air Auto Electrical
15/01/2024		fuel leak R-14581 fuel overfilled leaking out breather	Simon Wade (Mechanic)
15/01/2024		adblue R-14578 Clean adbluew lines	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
15/01/2024		inspect fuel leak R-15138 fuel leak repaired	
12/01/2024		fuel leak R-14580 Fuel has been overfilled coming out breather	Simon Wade (Mechanic)
11/01/2024		Air leak R-14732 trios replaced and	
10/01/2024		air leak R-14583 replace trio valve	Simon Wade (Mechanic)
03/01/2024		bin light out R-14084 repaired wiring	Simon Wade (Mechanic)
30/12/2023	700,376 kms	Airbags, Bolts, brake drums & linings, Clutch, Hub seal, hydraulic filter, slack adjusters, steer shocks, trios, Valve R-14264 20/12/2023 Replaced 3rd axle n/s & o/s slack adjusters tightened tailshaft & jackshaft bolts replace n/s & o/s axle brakes 2nd & 3rd axle Replaced 2nd axle n/s hub seal Replaced 3rd axle n/s shock Replaced 2nd n/s airbags x 4	Blair Wade, Simon Wade, Jacob Rennex-Apprentice Mechanic
20/12/2023		a/c R-14356 repaired a/c by ace auto	Ace Air Auto Electrical
18/12/2023	688,122 kms	A - 15/30 days S-11659 Service completed Repair list attached	Simon Wade (Mechanic)
15/12/2023	687,312 kms	airconditioning faulty R-14023 Low on gas,degas pressures Labour to evac,regas,add dye solution,washdown replace damaged pclamp	Ace Air Auto Electrical
20/11/2023		diesel tank, hub seal leak, hydraulic filter, steer tyre, tailshaft unis, Trailing arm bushes R-13872 All repairs done & completed	Blair Wade, Simon Wade, Jacob Rennex-Apprentice Mechanic
17/11/2023	678,436 kms	wiper- blade R-13931 install 2 new wiper blades	Blair Wade
15/11/2023	677,330 kms	wiper blades R-13868 Replace both wipers	Blair Wade
15/11/2023	678,059 kms	A - 5k/ 21 days S-11561 Service completed	Simon Wade (Mechanic)
14/11/2023		runout tyres T-2975 Fitted 2 x runout tyres	Blair Wade
14/11/2023		wiper blades R-13642 Blair replaced wiper blades	Corey Lonergan
01/11/2023		Faulty air conditioner R-13820 Checked over system ,works fine Replaced clearance light on step	BSC Auto Electrical Pty Ltd
30/10/2023	675,324 kms	tighten gear knob R-13772 Tighten with loctite	Blair Wade
27/10/2023		Parts O-3246 canvas seatcover-right x 1	multispares
20/10/2023		wiper blades R-13898 Replaced	Corey Lonergan
17/10/2023	671,154 kms	beacon R-13703 Install new roof beacon and rewire Install new beacon switch in dash.	Simon Wade (Mechanic)

Date	Reading / Units	Type / Repairer Notes	Repairer
16/10/2023	671,154 kms	A - 5k/ 21 days S-11468 service completed	Simon Wade (Mechanic)
16/10/2023	671,154 kms	adjust clutch brake, Gear knob R-13683 Clutch adjusted to right spot-tested Tightened gear knob	Blair Wade
15/10/2023		damaged underun R-13766 Truck both sides and trailer	
05/10/2023		Parts O-3212 window regulator control x 1	Gilbert & Roach
04/10/2023	667,748 kms	Air Brake Switch R-13639 removed leaking switch & Replaced with new	Blair Wade
27/09/2023		faulty UHF R-13512 Replaced head unit and head deck(2nd hand) as was not working	
19/09/2023	662,916 kms	faulty UHF R-13538 Install new lower UHF head unit	Simon Wade (Mechanic)
12/09/2023	662,120 kms	adjust clutch R-13558 performed clutch lift off test	Blair Wade, Jacob Rennex-Apprentice Mechanic
12/09/2023	662,120 kms	B - 20k S-11377 Service completed	Simon Wade
12/09/2023	662,120 kms	A - 5k/ 21 days S-11376 Service completed	Simon Wade
07/09/2023		check over R-13545 completed	A&C Heavy Repairs Pty Ltd
07/09/2023	660,871 kms	reflective tape, safety stickers R-13489 completed	Jacob Rennex-Apprentice Mechanic
04/09/2023		steer hub bearings R-13418 Install new n/s and o/s steer hub bearings and seals and grease Adjust bearings and test run and check	Simon Wade (Mechanic)
24/08/2023		brakes wobble, steering issue R-13410 Found fault intermittent inspected foot valve removed valve piston,lube and reassemble	A&C Heavy Repairs Pty Ltd
18/08/2023		Parts O-3119 Brake drums x 4 Lined shoe kits x 2 Bush-tow eye x 2 LED rear stop/tail lamp x 1	multispares
07/08/2023		Bypass Hose R-13354 completed	Hydraulink
07/08/2023		Parts O-3100 JAS Oceania 6 x lights for truck 4 for stock	
04/08/2023		Parts O-3117 5 x LED amber side markers	multispares
04/08/2023		Parts O-3116 2 x headlight insert with park LED 7"	multispares
04/08/2023		Parts O-3118 2 x high beam 7" LED	multispares

Date	Reading / Units	Type / Repairer Notes	Repairer
03/08/2023	650,000 kms	maintenance R-13216 Replaced kemworth bag Headlights / high beam replaced Cab vents replaced had to cut old ones out Air leak fitting replaced Full check over done Had to get parts	Corey Lonergan
01/08/2023		clearance light bracket R-13358 completed	sloanebuilt Trailers
01/08/2023		bin floor, light bracket, welding chassis cracks R-13356 Completed	sloanebuilt Trailers
31/07/2023		inspection R-13099	A&C Heavy Repairs Pty Ltd
30/07/2023		adaptors, quick couplers R-13293 Completed	Hydraulink

Signed: _____
 Name: _____
 Date: _____