



## Vehicle History Summary

|                 |                   |
|-----------------|-------------------|
| Fleet #         |                   |
| Registration    |                   |
| Make            | Kenworth          |
| Model           | K200              |
| VIN / Chassis # | 6F5000000CA448005 |
| Build Date      | 2012              |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer                                   |
|------------|-----------------|---|--|
|            |                 | <b>Engine Break Switch</b> R-19215  | Internal                                   |
|            |                 | <b>No right Indicator on Dash</b> R-19380   | Internal                                   |
|            |                 | <b>Reverse camera</b> R-19324   | K&C autos                                  |
|            |                 | <b>12 volt sockets</b> R-19304  | K&C autos                                  |
|            |                 | <b>Ice Pack Operation</b> R-19303   | Internal                                   |
|            |                 | <b>passenger side mirror</b> R-19266  | Internal                                   |
|            |                 | <b>Both side Mirrors</b> R-19265  | Internal                                   |
|            |                 | <b>Cab Ram Repair</b> R-19405   | Internal                                   |
| 14/11/2025 | 1,163,220 kms   | <b>h4 led headlights</b> R-19450<br>INSTALL NEW H4 LED HEADLIGHTS   | Simon Wade ( Mechanic )                    |
| 14/11/2025 |                 | <b>Rubber seal on door</b> R-19425<br>Reglue door seal  | Simon Wade ( Mechanic )                    |
| 13/11/2025 |                 | <b>Seal come out door trim</b> R-19413<br>Re glue door seal   | Simon Wade ( Mechanic )                    |
| 12/11/2025 |                 | <b>Torn Interior door seal</b> R-19401<br>Re glue door seal   | Simon Wade ( Mechanic )                    |
| 12/11/2025 |                 | <b>I face cradle charger missing</b> R-19392<br>Charging cable and cradle replaced 12/11/2025   | Internal                                   |
| 30/10/2025 |                 | <b>air leak</b> R-19033<br>repaired during A service  | Internal                                   |
| 29/10/2025 | 49,634 kms      | <b>A - 15/30 days</b> S-14304<br>Gearbox top hat leaking compressor mount leaking sump gasket leaking front diff input shaft seal leaking L/H cab ram leaking Truck needs under body wash Turn table needs replacing, worn and damaged, needs replacing asap. | Blake's Torque & Tinker                    |
| 24/10/2025 |                 | <b>air con, Cruise control</b> R-19032  | Internal                                   |
| 16/10/2025 | 1,037,035 kms   | <b>A - 15/30 days</b> S-14287   | ETHAN WOOLNOUGH                            |
| 01/10/2025 | 1,037,035 kms   | <b>B - 30k</b> S-14241  | A&C Heavy Repairs Pty Ltd, ETHAN WOOLNOUGH |
| 01/10/2025 | 37,035 kms      | <b>A - 15/30 days</b> S-14240   | Simon Wade ( Mechanic )                    |

| Date       | Reading / Units             | Type / Repairer Notes  | Repairer                |
|------------|-----------------------------|--|-------------------------|
| 26/09/2025 | 1,163,220 kms<br>20,318 hrs | <b>repairs</b> R-18776<br><br>Travel to job site for truck not building up air. start truck and check for leaks, found wire line popped out of joiner, refit airline. truck built up air. when truck got back to yard, replaced 1/2" joiner and made hose abit longer.   | Blake's Torque & Tinker |
| 26/09/2025 |                             | <b>air not building</b> R-18782  | Blake's Torque & Tinker |
| 26/09/2025 |                             | <b>hub oil leak</b> R-18786<br><br>repair completed  | Blake's Torque & Tinker |
| 26/09/2025 |                             | <b>cabin step</b> R-18778<br><br>will be fixed tonight   | Blake's Torque & Tinker |
| 30/08/2025 | 1,163,220 kms<br>20,318 hrs | <b>new tyres</b> T-3611<br><br>WALKER WLAKE 235/75R17.5 143/141J WTX1 (STEER/TRAILER) FITTING TRUCK TYRE Disposal - Truck Tyre ROAD SERVICE  | Eagle Truck Centre      |
| 11/08/2025 | 1,021,126 kms               | <b>front diff centre</b> R-18446<br><br>Install new diff centre from Truck Trans to front diff Install reco Through shaft and new seal to front diff Install new o/s and n/s hub bearings and seals complete to front diff Install new diff and hub oils to front diff Test run and check over. No noises or vibrations - ok                                   | Simon Wade ( Mechanic ) |
| 01/08/2025 |                             | <b>A - 15/30 days</b> S-13456<br><br>AIR FILTER OIL FILTER   | multispares             |
| 31/07/2025 |                             | <b>Diff</b> R-18276<br><br>Diff booked for replacement   | Simon Wade ( Mechanic ) |
| 31/07/2025 |                             | <b>check over engine</b> R-18292<br><br>Tune and check done by Western Diesel  | Simon Wade ( Mechanic ) |
| 31/07/2025 | 1,163,220 kms<br>20,318 hrs | <b>BRAKE DRUM - 16.5" X 6" 285PCD 10S STEER</b> R-18246<br><br>BRAKE DRUM - 16.5" X 6" 285PCD 10S STEER  | multispares             |
| 31/07/2025 |                             | <b>Diff</b> R-18277<br><br>Diff booked for replacement   | Simon Wade ( Mechanic ) |
| 31/07/2025 | 1,163,220 kms<br>20,318 hrs | <b>CHROMESAFE 33MM ROUND PUSH FIT</b> R-18364<br><br>CHROMESAFE 33MM ROUND PUSH FIT  | multispares             |
| 28/07/2025 | 1,163,220 kms<br>20,318 hrs | <b>REPAIRS</b> R-18221<br><br>LINED SHOE KIT - MERITOR 23000LB Q+ 6" R839F CR SCOTSEAL CLASSIC MICRO V BELT - GATES FLEETRUNKER DRIVE BELT TRANSMISSION FILTER FUEL FILTER - 13.7MIC FILTER ONLY - OIL/WATER - TURBO 2000 BEARING SET CONE & CUP STEERING FILTER - PAPER TYPE BEARING SET CONE & CUP HUB NUT KIT - STEER FRONT HUB & DRUM ASSY - 10STUD 285PCD | multispares             |
| 30/06/2025 | 1,163,220 kms<br>20,318 hrs | <b>FUEL FILTER - 13.7MIC, FUEL FILTER (KW) EGR 30 MICRON, FUEL/WATER FILTER - 50MIC STD</b> R-18046<br><br>FUEL FILTER - 13.7MIC FUEL/WATER FILTER - 50MIC STD FUEL FILTER (KW) EGR 30 MICRON  | multispares             |
| 30/06/2025 | 1,163,220 kms<br>20,318 hrs | <b>HOSE INTERCOOLER CONVOLUTED 4" X 7"</b> R-18045<br><br>HOSE INTERCOOLER CONVOLUTED 4" X 7"  | multispares             |
| 26/05/2025 | 1,163,220 kms               | <b>POWER ISSUE</b> R-17819<br><br>INSTALL NEW MAIN AND PRE FUEL FILTERS INSTALL NEW ENGINE CRANKCASE FILTER INSTALL NEW AIR FILTER(FOUND 2 BIRDS AND NEST) TEST RUN AND CHECK - OK   | Simon Wade ( Mechanic ) |
| 29/04/2025 |                             | <b>TRIANGLES</b> R-17428   | Blair Wade              |

| Date       | Reading / Units             | Type / Repairer Notes   | Repairer                    |
|------------|-----------------------------|---|-----------------------------|
|            |                             | install new triangles   |                             |
| 27/03/2025 | 1,014,078 kms               | <b>starter motor</b> R-17224  | multispare                  |
|            |                             | STARTER MOTOR - DELCO REMY 39MT 11T   |                             |
| 19/03/2025 | 1,139,488 kms               | <b>A - 15/30 days</b> S-12865   | Blair Wade                  |
|            |                             | A SERVICE   |                             |
| 18/03/2025 | 1,139,488 kms<br>20,318 hrs | <b>VDO 3 TERMINAL</b> R-17287   | multispare                  |
|            |                             | VDO 3 TERMINAL  |                             |
| 11/03/2025 |                             | <b>Gearbox</b> R-17196  | Simon Wade ( Mechanic )     |
|            |                             | install new pressure switch   |                             |
| 10/03/2025 | 1,111,111 kms<br>20,318 hrs | <b>Intercooler hose &amp; clamps</b> R-17227  | multispare                  |
|            |                             | HOSE INTERCOOLER CONVOLUTED 4" X 7"   |                             |
| 10/03/2025 | 1,139,488 kms<br>20,318 hrs | <b>starter motor</b> R-17223  | multispare                  |
|            |                             | STARTER MOTOR - 12V 11T 39MT DUAL EARTH   |                             |
| 05/03/2025 |                             | <b>steering check</b> R-17174   | Simon Wade ( Mechanic )     |
|            |                             | Check all suspension from front to rear No fault found Found issue is super single tyres following tyre grooves in road   |                             |
| 04/03/2025 | 1,139,488 kms<br>20,318 hrs | <b>cap radiator</b> R-17280   |                             |
|            |                             | CAP RADIATOR - 16PSI  |                             |
| 03/03/2025 |                             | <b>beacon switch</b> R-17067  | Simon Wade ( Mechanic )     |
|            |                             | Install new beacon switch   |                             |
| 03/03/2025 |                             | <b>beacon switch</b> R-17066  | Simon Wade ( Mechanic )     |
|            |                             | Install new beacon switch   |                             |
| 12/02/2025 | 1,011,747 kms               | <b>rear diff</b> R-18245  | Blair Wade                  |
|            |                             | REMOVAL - Diagnose Rear Diff With Excessive Back Lash - Drain Oil (Found Contaminated Oil) - Remove Both Axles, Hubs & Tyres - Remove Brake & Electrical Lines - Remove Jack Shaft - Remove Diff INSTALLATION - Clean Up Diff Housing - Install Diff With Threebond - Install All Brake & Electrical Lines - Refit Axles, Hubs & Tyres - Refilled Both Diffs & Installed Jack Shaft |                             |
| 12/02/2025 | 1,011,747 kms               | <b>B - 30k</b> S-13452  | Blair Wade                  |
|            |                             | B SERVICE NEXT B - 1,041,747  |                             |
| 04/02/2025 | 1,111,111 kms<br>20,318 hrs | <b>front diff centre</b> R-17228  | Truck Transmission Pty Ltd  |
|            |                             | DIFF DANA - DCDL REBUILD DIFF CENTRE AS PER JOB# 28530  |                             |
| 20/11/2024 |                             | <b>trailer tyres</b> T-3275   |                             |
|            |                             | Fitted 8 x Evergreen 11R22.5 146/143L EDM67 - ON/OFF ROAD - POS 3-4-5-6-7-8-9-10 4 x Tyre Disposals NO KMS NOTED  |                             |
| 12/11/2024 |                             | <b>diff noise</b> R-16252   | Simon Wade ( Mechanic )     |
|            |                             | Awaiting parts  |                             |
| 12/11/2024 |                             | <b>diff noise</b> R-16248   | Simon Wade ( Mechanic )     |
|            |                             | Awaiting parts  |                             |
| 01/11/2024 | 1,011,562 kms               | <b>A - 15/30 days</b> S-12614   | Christopher Watson-Mechanic |
|            |                             | Cruise control switches inop. Electric horn inop. No switch for beacon lights.  |                             |
| 30/04/2024 |                             | <b>spray nozzle</b> R-14566   |                             |

| Date       | Reading / Units | Type / Repairer Notes  | Repairer                         |
|------------|-----------------|--|----------------------------------|
|            |                 | replaced sprayer nozzle  |                                  |
| 05/04/2024 |                 | <b>New Tyres</b> T-3054<br>8 x Evergreen drive tyres positions 3 to 10   | All Tyres Australia              |
| 04/04/2024 |                 | <b>prestart</b> R-14854<br>checked when brought into shop and pulled off the road for multiple issues with truck and 3rd axle diff   | Jacob Rennex-Apprentice Mechanic |
| 27/03/2024 | 1,020,237 kms   | <b>A - 15/30 days</b> S-11936<br>Service completed Blinker repaired 2 x shocks cab rams leaking-monitor  | Blair Wade                       |
| 27/03/2024 |                 | <b>indicator</b> R-14796<br>replaced indicator as was waterlogged and had not working problem resolved by replacement  | Simon Wade                       |
| 15/03/2024 |                 | <b>Jaw kit</b> R-15145<br>completed  | sloanebuilt Trailers             |
| 28/02/2024 |                 | <b>Airconditioner</b> R-14568<br>Replaced air con control panel in cab dash Truck to be booked for air con repair  | A&C Heavy Repairs Pty Ltd        |
| 28/02/2024 |                 | <b>drivers door window control</b> R-14567<br>Inspect window operation numerous times Unable to fault at time of inspection  | A&C Heavy Repairs Pty Ltd        |
| 28/02/2024 |                 | <b>Heater control operation, indicator, water jets, window switches</b> R-14592<br>completed   | A&C Heavy Repairs Pty Ltd        |
| 22/02/2024 |                 | <b>Parts</b> O-3424<br>Control-HVAC DELPHI COE   | Gilbert and Roach                |
| 21/02/2024 |                 | <b>Parts</b> O-3473<br>1 zx suzi coil long tail  | multispares                      |
| 20/02/2024 |                 | <b>turntable adjustment</b> R-14782<br>sent to sloanebuilt for repair and adjustment completed and problem solved  | sloanbuilt trailers              |
| 15/02/2024 |                 | <b>Registration</b> O-3372   |                                  |
| 15/02/2024 | 999,065 kms     | <b>A - 15/30 days</b> S-11845<br>service completed Needs Repair seat recliner lever as coming apart Needs Heater control unit Replaced heater tap<br>windscreen washers repaired adjusted clutch and linkages Roadtested truck for knock in drive train-noise is damaged<br>shocks reported last service, still waiting on repair approval | A&C Heavy Repairs Pty Ltd        |
| 02/02/2024 |                 | <b>too hot</b> R-14341<br>noted  | Simon Wade ( Mechanic )          |
| 31/01/2024 |                 | <b>label</b> R-14339<br>install nhvr label   | Simon Wade ( Mechanic )          |
| 31/01/2024 |                 | <b>label</b> R-14340<br>install new nhvr label   | Simon Wade ( Mechanic )          |
| 24/01/2024 |                 | <b>blinker</b> R-14268<br>repaired light mount   | A&C Heavy Repairs Pty Ltd        |
| 23/01/2024 |                 | <b>Fluids</b> R-14092<br>noted   | Simon Wade ( Mechanic )          |
| 23/01/2024 |                 | <b>too hot</b> R-14330<br>noted  | Simon Wade ( Mechanic )          |
| 18/01/2024 |                 | <b>Parts</b> O-3294  | Gilbert and Roach                |

| Date       | Reading / Units | Type / Repairer Notes  | Repairer  |
|------------|-----------------|--|---|
|            |                 | FD20-2111-4PSI- switch-pressure 4PSI x 2   |   |
| 18/01/2024 |                 | <b>water leak</b> R-14250<br>Resealed all beacons,horns and clearance lights on roof   | Jacob Rennex-Apprentice Mechanic                  |
| 17/01/2024 | 997,400 kms     | <b>A - 15/30 days</b> S-11711<br>completed   | A&C Heavy Repairs Pty Ltd                         |
| 17/01/2024 |                 | <b>hot air</b> R-14296<br>install new gear stick boots   | Simon Wade ( Mechanic )                           |
| 12/01/2024 | 997,929 kms     | <b>maintenance</b> R-14038<br>Wired lights fixed brakes works fine Seat bolt missing had to adjusted works fine New globs in cab and new fuse  | Corey Lonergan                                    |
| 11/01/2024 |                 | <b>flat drive tyres</b> R-14046<br>Install runout tyre axle 2 n/s  | Jacob Rennex-Apprentice Mechanic                  |
| 08/01/2024 |                 | <b>repair turntable</b> R-14098<br>Adjust turntable  | A&C Heavy Repairs Pty Ltd                         |
| 08/01/2024 |                 | <b>label</b> R-14240<br>install nhvr label   | Simon Wade ( Mechanic )                           |
| 08/01/2024 |                 | <b>label</b> R-14241<br>install label  | Simon Wade ( Mechanic )                           |
| 08/01/2024 |                 | <b>label</b> R-14242<br>install label  | Simon Wade ( Mechanic )                           |
| 21/12/2023 |                 | <b>Parts</b> O-3281<br>1 x Valve   | Gilbert and Roach                                 |
| 15/12/2023 | 955,755 kms     | <b>B - 30k</b> S-11643<br>service completed  | A&C Heavy Repairs Pty Ltd                         |
| 13/12/2023 |                 | <b>book</b> R-14225<br>rerplaced by chris  | Simon Wade ( Mechanic )                           |
| 11/12/2023 | 995,267 kms     | <b>engine brake operation</b> R-14005<br>Found no power to steering wheel controls 7 no horn working. found fuse blown,replaced,checked all works ok now   | Jacob Rennex-Apprentice Mechanic                  |
| 30/11/2023 |                 | <b>broken side step</b> R-14169<br>repair step   | Simon Wade ( Mechanic )                           |
| 24/11/2023 |                 | <b>interior light</b> R-14096<br>replace fuse  | Simon Wade ( Mechanic )                           |
| 24/11/2023 |                 | <b>lubes</b> R-14095<br>Coolant topped up Noted  | Simon Wade ( Mechanic )                           |
| 24/11/2023 |                 | <b>interior light</b> R-14093<br>replace fuse  | Simon Wade ( Mechanic )                           |
| 21/11/2023 | 993,322 kms     | <b>O/S bottom step</b> R-13883<br>Made angle bracket up to hold bottom step  | Jacob Rennex-Apprentice Mechanic                  |
| 17/11/2023 |                 | <b>Knock in motor</b> R-13876<br>Inspected engine for truck A&C Heavy-found cracked injector rocker shaft replaced rocker shaft & rockers retension 7 Hrs DLTL- Rocker lever shaft snapped,snapped bolts removed 7.5 Hrs | A&C Heavy Repairs Pty Ltd, DLTL Haulage & Repairs |
| 17/11/2023 | 992,364 kms     | <b>B - 20k</b> S-11621   | A&C Heavy Repairs Pty Ltd                         |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer                         |
|------------|-----------------|---|----------------------------------|
|            |                 | Service completed   |                                  |
| 31/10/2023 |                 | <b>faulty wipers, Gearbox Oil Leak, lens</b> R-13622  | A&C Heavy Repairs Pty Ltd        |
|            |                 | Been monitored  |                                  |
| 30/10/2023 |                 | <b>drive shocks, Intercooler pipes, reverse lights, Spot Lights</b> R-13687                 | A&C Heavy Repairs Pty Ltd        |
| 27/10/2023 | 989,702 kms     | <b>adjust clutch &amp; clutch brake</b> R-13814   | A&C Heavy Repairs Pty Ltd        |
|            |                 | found clutch extremely high with no freeplay,adjusted freeplay,adjusted clutch brake        |                                  |
| 16/10/2023 |                 | <b>Parts</b> O-3220   | multispares                      |
|            |                 | 4 x shock absorbers   |                                  |
| 13/10/2023 |                 | <b>Parts</b> O-3219   | multispares                      |
|            |                 | transmission filter assy  |                                  |
| 12/10/2023 | 988,919 kms     | <b>A - 5k/ 21 days</b> S-11456  | A&C Heavy Repairs Pty Ltd        |
|            |                 | Service completed Repair list attached  |                                  |
| 22/09/2023 |                 | <b>Parts</b> O-3188   | multispares                      |
|            |                 | combo switch  |                                  |
| 15/09/2023 |                 | <b>Air conditioner</b> R-13517  |                                  |
|            |                 | Air conditioning fixed by BSC Auto  |                                  |
| 12/09/2023 |                 | <b>Air conditioner</b> R-13501  | BSC Auto Electrical Pty Ltd      |
|            |                 | found gas level to be low,inspected for leaks-all okay regassed with oil & dye              |                                  |
| 01/09/2023 | 983,720 kms     | <b>clearance light</b> R-13394  | Jacob Rennex-Apprentice Mechanic |
|            |                 | replaced 2 x clearance lights and wiring straightened steps on d/s tightened all grab rails |                                  |
| 30/08/2023 |                 | <b>clutch adjustment, Dash globes, faulty wipers, water leak</b> R-13549                    | A&C Heavy Repairs Pty Ltd        |
|            |                 | completed   |                                  |
| 30/08/2023 | 983,720 kms     | <b>A - 5k/ 21 days</b> S-11346  | A&C Heavy Repairs Pty Ltd        |
|            |                 | Service completed   |                                  |
| 30/08/2023 | 983,720 kms     | <b>Resealing for leaks</b> R-13420  | Jacob Rennex-Apprentice Mechanic |
|            |                 | Needs further resealing done  |                                  |
| 18/08/2023 |                 | <b>Parts</b> O-3146   | multispares                      |
|            |                 | 4 x mudflaps 330L x 605W plain white  |                                  |
| 14/08/2023 |                 | <b>window washers</b> R-13276   |                                  |
|            |                 | replaced  |                                  |
| 02/08/2023 | 980,000 kms     | <b>A - 5k/ 21 days</b> S-11265  | A&C Heavy Repairs Pty Ltd        |
|            |                 | A service completed   |                                  |
| 31/07/2023 |                 | <b>Repairs</b> R-13235  | DLTL Haulage & Repairs           |
| 24/07/2023 |                 | <b>Parts</b> O-3093   | multispares                      |
|            |                 | suzi coil short tail x 1 suzi coil long tail x 1  |                                  |
| 21/07/2023 | 988,788 kms     | <b>A - 5k/ 21 days</b> S-11227  | A&C Heavy Repairs Pty Ltd        |
|            |                 | Service completed   |                                  |
| 30/05/2023 |                 | <b>Parts</b> O-2986   | multispares                      |
|            |                 | 1 x radiator cap  |                                  |
| 18/05/2023 | 972,168 kms     | <b>C - 100k/ Annual</b> S-11032   | A&C Heavy Repairs Pty Ltd        |

| Date       | Reading / Units | Type / Repairer Notes  | Repairer                  |
|------------|-----------------|--|---------------------------|
|            |                 | Annual completed Kenworth dash globes needed,interior cabin light door cover AB and annual done together See attached                              |                           |
| 18/05/2023 | 972,168 kms     | <b>B - 20k</b> S-11031<br>Completed AB and Annual done together See attached   | A&C Heavy Repairs Pty Ltd |
| 18/05/2023 | 972,168 kms     | <b>A - 5k/ 21 days</b> S-11030<br>A,B,and annual service done together Paperwork is attached Left in filthy manner by Driver,Jacob reported to Rob | A&C Heavy Repairs Pty Ltd |
| 03/05/2023 | 972,120 kms     | <b>A - 5k/ 21 days</b> S-10994<br>service completed  | Simon Wade                |
| 24/03/2023 | 964,273 kms     | <b>sump</b> R-12875<br>completed   | Sean (Mechanic)           |
| 24/03/2023 | 964,273 kms     | <b>Gearbox Warranty</b> R-12863<br>Completed   | A&C Heavy Repairs Pty Ltd |
| 21/03/2023 |                 | <b>Parts</b> O-2889<br>1 x pressure switch   | Gilbert and Roach         |
| 21/03/2023 | 964,833 kms     | <b>A - 5k/ 21 days</b> S-10866<br>Service completed  | Simon Wade                |
| 07/03/2023 |                 | <b>Fault codes</b> R-12868<br>completed  | Ace Air Auto Electrical   |
| 03/03/2023 |                 | <b>Parts</b> O-2892<br>supply air fittings   | Hydraulink                |
| 23/02/2023 | 964,003 kms     | <b>A - 5k/ 21 days</b> S-10774<br>service completed  | A&C Heavy Repairs Pty Ltd |
| 17/02/2023 |                 | <b>Registration</b> O-2793   |                           |
| 31/01/2023 | 963,299 kms     | <b>New tyres</b> T-2765<br>4 x tyres positions 3,4,5,6 4 x disposals   | All Tyres Australia       |
| 25/01/2023 |                 | <b>Parts</b> O-2764<br>clutch lit spigot bearing   |                           |
| 24/01/2023 | 963,274 kms     | <b>A - 5k/ 21 days</b> S-10667<br>Completed No Faults recorded   | Simon Wade                |
| 20/01/2023 |                 | <b>Refit gearbox</b> R-12630<br>to be completed by Simon & boys  | A&C Heavy Repairs Pty Ltd |
| 19/01/2023 |                 | <b>Parts</b> O-2754<br>lever clutch control lever clutch shaft spacers   | Gilbert and Roach         |
| 13/01/2023 |                 | <b>Gearbox jumping out</b> R-12624<br>Removed rear structure & repaired oil leak lift truck on hoist removal                                       | A&C Heavy Repairs Pty Ltd |
| 17/12/2022 |                 | <b>clutch brake</b> R-12600<br>completed   | A&C Heavy Repairs Pty Ltd |
| 07/12/2022 |                 | <b>Parts</b> O-2734<br>exhaust clamps & exhaust stack  | multispare                |
| 21/11/2022 | 952,658 kms     | <b>New top batteries</b> R-12535<br>2 x batteries installed-top  | Simon Wade                |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer   |
|------------|-----------------|---|--|
| 14/11/2022 | 952,273 kms     | <b>Batteries</b> R-12504<br>completed   | Simon Wade   |
| 11/11/2022 |                 | <b>Not starting</b> R-12520<br>parked at side of office Located flat batteries  | Ace Air Auto Electrical  |
| 13/10/2022 |                 | <b>Parts</b> O-2656<br>4 x hub washer kit 4 x lock nut-inner 4 x lock nut-outer | multispare   |
| 13/10/2022 |                 | <b>Parts</b> O-2657<br>2 x seal-stemco voyager drive                            | multispare   |
| 12/10/2022 | 953,218 kms     | <b>maintenance</b> R-12496<br>completed   | A&C Heavy Repairs Pty Ltd, Simon Wade                          |
| 07/10/2022 | 953,268 kms     | <b>B - 20k</b> S-10386<br>completed Repair list attached                        | A&C Heavy Repairs Pty Ltd, DLT L Haulage & Repairs, Simon Wade |
| 06/10/2022 |                 | <b>Parts</b> O-2654<br>1 x shield mud flap                                      | Gilbert & Roach  |
| 26/09/2022 | 951,918 kms     | <b>Fault codes, Throttle</b> R-12481<br>Faulty wiring found                     | Cummins South Pacific Pty Ltd                                  |
| 24/09/2022 |                 | <b>Parts</b> O-2630<br>4 x single mesh flags                                    | multispare   |
| 26/08/2022 |                 | <b>Squeak at Belt area</b> R-12403<br>completed                                 | A&C Heavy Repairs Pty Ltd                                      |
| 25/08/2022 |                 | <b>Parts</b> O-2661<br>Filler cap seal tube oil filler                          | Cummins South Pacific Pty Ltd                                  |
| 25/08/2022 |                 | <b>horton inop</b> R-12402<br>completed   | A&C Heavy Repairs Pty Ltd                                      |
| 12/08/2022 | 940,922 kms     | <b>Wheel alignment</b> R-12439<br>completed                                     | pro axle   |
| 11/08/2022 | 942,191 kms     | <b>oil gauge</b> R-12401<br>Completed   | A&C Heavy Repairs Pty Ltd                                      |
| 11/08/2022 |                 | <b>Parts</b> O-2605<br>90Degree elbow   | Hydraulink   |
| 11/08/2022 |                 | <b>Parts</b> O-2603<br>bolts & flat washers x 20 each 136164                    | Bolts & Industrial Supplies                                    |
| 10/08/2022 |                 | <b>Parts</b> O-2604<br>2 x mudflaps   | Gilbert and Roach  |
| 09/08/2022 | 940,956 kms     | <b>suzi coil isolation mount</b> R-12400<br>completed                           | Simon Wade   |
| 27/07/2022 |                 | <b>compressor hose</b> R-12325<br>Completed                                     | Hydraulink   |
| 26/07/2022 | 939,248 kms     | <b>Fault codes oil pressure</b> R-12399<br>completed                            | Cummins South Pacific Pty Ltd                                  |
| 06/07/2022 | 937,017 kms     | <b>front diff</b> R-12317   |  |



| Date       | Reading / Units | Type / Repairer Notes   | Repairer                      |
|------------|-----------------|---|-------------------------------|
|            |                 | see attached invoice 1091   |                               |
| 29/06/2022 |                 | <b>New tyres</b> T-2657<br>4 x new tyres position 7,8,9,10 3 disposals  | All Tyres Australia           |
| 10/06/2022 |                 | <b>B - 20k</b> S-10199<br>completed   |                               |
| 27/05/2022 | 925,626 kms     | <b>C - 100k/ Annual</b> S-10086<br>completed  | A&C Heavy Repairs Pty Ltd     |
| 27/05/2022 | 925,626 kms     | <b>A - 5k/ 21 days</b> S-10110<br>completed Repairs list attached   | Jayden Haule                  |
| 25/05/2022 | 924,539 kms     | <b>Trailer plug</b> R-12215<br>completed  | Corey Lonergan                |
| 24/05/2022 |                 | <b>Parts</b> O-2458<br>suzi coil Invoice 5012302 suzi coil and trailer plug invoice 5015617229.78                       | multispare                    |
| 16/05/2022 | 921,364 kms     | <b>trailer light plug, wiring</b> R-12206<br>completed  | Simon Wade                    |
| 13/05/2022 |                 | <b>Parts</b> O-2445<br>tapered-pin cartridge  | Gilbert and Roach             |
| 13/05/2022 |                 | <b>guards, torque rod bushes</b> R-12179<br>completed   | A&C Heavy Repairs Pty Ltd     |
| 06/05/2022 | 917,939 kms     | <b>Black smoke underload, EGP sensor, EGR Valve</b> R-12140<br>completed  | Cummins South Pacific Pty Ltd |
| 03/05/2022 |                 | <b>DPF Cleaning</b> R-12205<br>Western filters  | Western Filters               |
| 22/04/2022 |                 | <b>Parts</b> O-2431<br>ROYANS Cummins DPF ASSY  |                               |
| 27/03/2022 | 911,587 kms     | <b>A - 5k/ 21 days</b> S-9950<br>completed  | Andrew Grindrod               |
| 25/03/2022 | 911,587 kms     | <b>B - 30k</b> S-9951   | Andrew Grindrod               |
| 25/03/2022 |                 | <b>Defects</b> R-12046  | A&C Heavy Repairs Pty Ltd     |
| 07/03/2022 |                 | <b>A - 5k/ 21 days</b> S-9949<br>completed  | Jayden Haule                  |
| 16/02/2022 |                 | <b>Registration</b> O-2346  |                               |
| 15/02/2022 | 891,917 kms     | <b>B - 30k</b> S-9091<br>completed  | Simon Wade                    |
| 14/02/2022 | 891,917 kms     | <b>A - 5k/ 21 days</b> S-9090<br>Completed B service same night   | Simon Wade                    |
| 14/02/2022 |                 | <b>Defects</b> R-10915<br>see attached for defects Also installed 15 wheel nut covers installed 40 wheel nut indicators | Simon Wade                    |
| 28/01/2022 |                 | <b>Not starting</b> R-12035<br>New battery isolator   | Ace Air Auto Electrical       |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer                    |
|------------|-----------------|---|-----------------------------|
| 28/01/2022 |                 | <b>Maint. Repairs</b> R-11955<br>Completed  | Andrew Grindrod, Simon Wade |
| 24/01/2022 |                 | <b>A - 5k/ 21 days</b> S-9191<br>Manually generated 5000 km service                         | Blair Wade, Simon Wade      |
| 24/01/2022 |                 | <b>Maint. Repairs</b> R-11945<br>Completed  |                             |
| 20/01/2022 |                 | <b>A - 5k/ 21 days</b> S-9170<br>Manually generated 5000 km service                         |                             |
| 20/01/2022 |                 | <b>A - 5k/ 21 days</b> S-9117<br>A service  | Andrew Grindrod             |
| 13/01/2022 |                 | <b>Maint. Repairs</b> R-11937<br>Done   | Andrew Grindrod             |
| 13/01/2022 |                 | <b>Maint. Repairs</b> R-11928<br>Install new n/s & o/s wipers                               | Simon Wade                  |
| 20/12/2021 |                 | <b>Maint. Repairs</b> R-11899<br>Replaced   | Corey Lonergan              |
| 15/12/2021 |                 | <b>Maint. Repairs</b> R-11883<br>Change engine oil and filter Sample engine oil for testing | Simon Wade                  |
| 15/12/2021 |                 | <b>Maint. Repairs</b> R-11889<br>completed  | Andrew Grindrod             |
| 14/12/2021 |                 | <b>Maint. Repairs</b> R-11890<br>completed  | Andrew Grindrod             |
| 10/12/2021 |                 | <b>Maint. Repairs</b> R-11855<br>Ace Air  |                             |
| 09/12/2021 |                 | <b>Maint. Repairs</b> R-11863<br>see attached   | Andrew Grindrod             |
| 26/11/2021 |                 | <b>Maint. Repairs</b> R-11792<br>see attached A & C Heavy Haulage repaired                  | Simon Wade                  |
| 13/11/2021 |                 | <b>C - 100k/ Annual</b> S-9310<br>Manually generated 100000 km service                      | Simon Wade                  |
| 13/11/2021 |                 | <b>Maint. Repairs</b> R-11747<br>Replaced wiper motor inop Ch3ck operation ok               |                             |
| 13/11/2021 |                 | <b>Maint. Repairs</b> R-11644<br>Air leaks in cab,under floor,RH side chassix               | Andrew Grindrod             |
| 13/11/2021 |                 | <b>A - 5k/ 21 days</b> S-9254<br>Manually generated 5000 km service                         |                             |
| 13/11/2021 |                 | <b>B - 30k</b> S-9274<br>B Service Manually generated 30000 km service                      | Andrew Grindrod             |
| 12/11/2021 |                 | <b>A - 5k/ 21 days</b> S-9232<br>A service  | Andrew Grindrod             |
| 08/11/2021 |                 | <b>B - 30k</b> S-9275   |                             |

| Date       | Reading / Units | Type / Repairer Notes  | Repairer        |
|------------|-----------------|--|-----------------|
|            |                 | Manually generated 30000 km service  |                 |
| 29/10/2021 |                 | <b>A - 5k/ 21 days</b> S-9277<br>A service                                     | Andrew Grindrod |
| 05/10/2021 |                 | <b>A - 5k/ 21 days</b> S-9642<br>done  | Andrew Grindrod |
| 21/09/2021 |                 | <b>Maint. Repairs</b> R-11627<br>air leak at governor valve                    | Andrew Grindrod |
| 13/09/2021 |                 | <b>A - 5k/ 21 days</b> S-9650<br>A service                                     | Andrew Grindrod |
| 09/09/2021 |                 | <b>Maint. Repairs</b> R-11255<br>changed                                       | Mark Gloster    |
| 09/09/2021 |                 | <b>Maint. Repairs</b> R-11393<br>gfixed  | Simon Wade      |
| 09/09/2021 |                 | <b>Maint. Repairs</b> R-11238<br>checked                                       | Mark Gloster    |
| 09/09/2021 |                 | <b>Maint. Repairs</b> R-11307<br>changed                                       | Mark Gloster    |
| 27/08/2021 |                 | <b>B - 30k</b> S-9673<br>B Service - Manually generated 30000 km service       | Simon Wade      |
| 27/08/2021 |                 | <b>A - 5k/ 21 days</b> S-9691<br>A & B done together                           | Simon Wade      |
| 20/08/2021 |                 | <b>A - 5k/ 21 days</b> S-9730<br>see attached                                  |                 |
| 12/08/2021 |                 | <b>New</b> T-2484<br>done  | Simon Wade      |
| 16/07/2021 |                 | <b>Maint. Repairs</b> R-11397<br>done  | Andrew Grindrod |
| 16/07/2021 |                 | <b>A - 5k/ 21 days</b> S-9761<br>A service                                     | Andrew Grindrod |
| 08/07/2021 |                 | <b>A - 5k/ 21 days</b> S-9769<br>A service                                     | Simon Wade      |
| 25/06/2021 |                 | <b>Maint. Repairs</b> R-11329<br>Muffler,stack clamp & mounting bracket fitted |                 |
| 22/06/2021 |                 | <b>Maint. Repairs</b> R-11301<br>changed                                       |                 |
| 19/06/2021 |                 | <b>A - 5k/ 21 days</b> S-9363<br>A service                                     |                 |
| 10/06/2021 |                 | <b>Maint. Repairs</b> R-11277<br>installed                                     |                 |
| 25/05/2021 |                 | <b>A - 5k/ 21 days</b> S-9407<br>A service                                     |                 |

| Date       | Reading / Units | Type / Repairer Notes  | Repairer                |
|------------|-----------------|--|-------------------------|
| 21/05/2021 |                 | <b>Maint. Repairs</b> R-11582<br>completed   |                         |
| 17/05/2021 |                 | <b>Maint. Repairs</b> R-11559<br>completed   |                         |
| 17/05/2021 |                 | <b>Maint. Repairs</b> R-11575<br>completed   |                         |
| 14/05/2021 |                 | <b>B - 30k</b> S-9414<br>B Service - Manually generated 30000 km service   | Simon Wade              |
| 13/05/2021 |                 | <b>Maint. Repairs</b> R-11222<br>??  |                         |
| 07/05/2021 |                 | <b>A - 5k/ 21 days</b> S-9442<br>A service   | Simon Wade              |
| 06/05/2021 |                 | <b>Maint. Repairs</b> R-11203<br>completed   |                         |
| 27/04/2021 |                 | <b>Maint. Repairs</b> R-11204<br>completed   | Simon Wade              |
| 16/04/2021 |                 | <b>A - 5k/ 21 days</b> S-9484<br>completed   | Simon Wade              |
| 12/04/2021 |                 | <b>Maint. Repairs</b> R-11560<br>completed   |                         |
| 08/04/2021 |                 | <b>Maint. Repairs</b> R-11202<br>accelerator pedal,,blowing smoke  | Jayden Haule            |
| 31/03/2021 |                 | <b>Maint. Repairs</b> R-11200<br>engine oil 43 litres coolant 60 litres  |                         |
| 30/03/2021 |                 | <b>Maint. Repairs</b> R-11201<br>completed   |                         |
| 23/03/2021 |                 | <b>Maint. Repairs</b> R-11198<br>cpmpleted   | Brandon McKinnon        |
| 23/03/2021 |                 | <b>Maint. Repairs</b> R-11199<br>removed and resealed all  |                         |
| 05/03/2021 |                 | <b>A - 15/30 days</b> S-8124<br>completed completed engine valve adjustment removed & replaced shift cables Found exhaust leaks @ egr pipes and broken clamp off rear of turbo | James Hendry (Mechanic) |
| 05/03/2021 |                 | <b>A - 5k/ 21 days</b> S-9545<br>A service   |                         |
| 19/02/2021 |                 | <b>Registration</b> O-2010   |                         |
| 13/02/2021 | 765,107 kms     | <b>drive axle guards</b> R-9710<br>done  |                         |
| 13/02/2021 |                 | <b>Parts</b> O-2049<br>cables,rod assy clutch link   | multispares             |
| 13/02/2021 |                 | <b>Maint. Repairs</b> R-10986  |                         |

| Date       | Reading / Units | Type / Repairer Notes  | Repairer                    |
|------------|-----------------|--|-----------------------------|
|            |                 | Completed  |                             |
| 09/02/2021 |                 | <b>A - 5k/ 21 days</b> S-9776  |                             |
|            |                 | A service  |                             |
| 09/02/2021 | 763,947 kms     | <b>B - 40k</b> S-8077  | Simon Wade ( Mechanic )     |
|            |                 | completed  |                             |
| 09/02/2021 | 763,944 kms     | <b>low coolant fault</b> R-9676  | Ace Air Auto Electrical     |
|            |                 | completed  |                             |
| 09/02/2021 | 763,947 kms     | <b>A - 15/30 days</b> S-8070   | Simon Wade ( Mechanic )     |
|            |                 | completed  |                             |
| 09/02/2021 |                 | <b>Parts</b> O-2046  | multispare                  |
|            |                 | gasket-shift lever housing eaton rags  |                             |
| 09/02/2021 |                 | <b>B - 30k</b> S-9773  |                             |
|            |                 | B service  |                             |
| 09/02/2021 |                 | <b>Maint. Repairs</b> R-11026  |                             |
|            |                 | Completed  |                             |
| 03/02/2021 |                 | <b>Batteries, bunk fan, dog box, engine light on, loss of power, oil pressure gauge, Side step, spot light, UHF antenna</b> R-9608 | Simon Wade ( Mechanic )     |
| 03/02/2021 |                 | <b>Maint. Repairs</b> R-11014  |                             |
|            |                 | Completed  |                             |
| 21/01/2021 |                 | <b>trailer wheel lock switch</b> R-9558  | Simon Wade ( Mechanic )     |
|            |                 | completed  |                             |
| 21/01/2021 |                 | <b>Maint. Repairs</b> R-10989  |                             |
|            |                 | Completed  |                             |
| 14/01/2021 |                 | <b>Maint. Repairs</b> R-10959  |                             |
|            |                 | Completed  |                             |
| 14/01/2021 |                 | <b>Weight change</b> R-9642  | Sydney Truck and Machinery  |
|            |                 | completed  |                             |
| 23/12/2020 | 715,825 kms     | <b>Batteries, drive tyres</b> R-9439   | James Hendry (Mechanic)     |
|            |                 | completed  |                             |
| 14/12/2020 |                 | <b>Parts</b> O-1844  | multispare                  |
|            |                 | Low coolant sensor   |                             |
| 14/12/2020 |                 | <b>A - 15/30 days</b> S-7922   | Simon Wade ( Mechanic )     |
| 03/12/2020 |                 | <b>Steps</b> R-9375  | Simon Wade ( Mechanic )     |
|            |                 | completed  |                             |
| 24/11/2020 |                 | <b>New tyres</b> T-2288  | Southwest Car & Truck Tyres |
|            |                 | 3 x tyres 3 x disposals  |                             |
| 23/11/2020 | 745,331 kms     | <b>A - 15/30 days</b> S-7841   | Simon Wade ( Mechanic )     |
|            |                 | completed  |                             |
| 23/11/2020 |                 | <b>Parts</b> O-1784  | multispare                  |
|            |                 | 512895 diff lock kit   |                             |
| 16/11/2020 |                 | <b>power divider</b> R-9374  | James Hendry (Mechanic)     |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer                    |
|------------|-----------------|---|-----------------------------|
|            |                 | kit-shift cylinder power divider Completed  |                             |
| 13/11/2020 |                 | <b>Parts</b> O-1779<br>belt tensioner assy  | multispares                 |
| 05/11/2020 | 739,443 kms     | <b>check engine light, fan belt cracked, horton fan</b> R-9035<br>completed                 | Simon Wade ( Mechanic )     |
| 05/11/2020 |                 | <b>Weighbridge</b> O-1805<br>weighbridge ticket   | sloanebuilt Trailers        |
| 02/11/2020 |                 | <b>Parts</b> O-1658<br>Fan drive kit  | Gilbert & Roach             |
| 02/11/2020 |                 | <b>A - 15/30 days</b> S-7760  | Simon Wade ( Mechanic )     |
| 28/10/2020 |                 | <b>New tyres</b> T-2276<br>4 x tyres  | JK Vella Earthwerx Pty Ltd  |
| 28/10/2020 |                 | <b>Parts</b> O-1696<br>sensor-EGR pressure  | multispares                 |
| 28/10/2020 |                 | <b>Parts</b> O-1699<br>belt   | multispares                 |
| 27/10/2020 | 736,596 kms     | <b>faults</b> R-9149<br>completed   | Ace Air Auto Electrical     |
| 23/10/2020 |                 | <b>runout tyre</b> T-2280<br>1 x runout tyre(stock)   | Southwest Car & Truck Tyres |
| 21/10/2020 | 734,787 kms     | <b>Airbag, Tyres</b> R-9073<br>completed  |                             |
| 20/10/2020 |                 | <b>air con belt, UHF aerial broken</b> R-9000   | Simon Wade ( Mechanic )     |
| 20/10/2020 | 734,787 kms     | <b>A - 15/30 days</b> S-7693<br>completed   | Simon Wade ( Mechanic )     |
| 12/10/2020 |                 | <b>check engine light, Coolant leak</b> R-9072<br>completed                                 | James Hendry (Mechanic)     |
| 07/10/2020 | 731,434 kms     | <b>B - 40k</b> S-7670<br>completed  | Simon Wade ( Mechanic )     |
| 07/10/2020 |                 | <b>diff pinion seal leak, rear structure leaking</b> R-8989                                 | Simon Wade ( Mechanic )     |
| 30/09/2020 |                 | <b>Misc</b> O-1639<br>Get The Look Graphics & signage                                       |                             |
| 24/09/2020 |                 | <b>cabin lift ram, driver window switch, front cab shock, front diff pinion seal</b> R-8937 | Simon Wade ( Mechanic )     |
| 24/09/2020 |                 | <b>A - 15/30 days</b> S-7622<br>completed   | Simon Wade ( Mechanic )     |
| 23/09/2020 | 726,699 kms     | <b>air conditioner operation</b> R-9071<br>Completed Truckelec                              |                             |
| 11/09/2020 |                 | <b>Parts</b> O-1565<br>Alloy bkt to suit Axis 22 C&A Mobile                                 |                             |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer                     |
|------------|-----------------|---|------------------------------|
| 08/09/2020 |                 | <b>Parts</b> O-1601<br>oring diff lock piston cover piston oring piston cover   | Truck Transmission Pty Ltd   |
| 07/09/2020 | 724,060 kms     | <b>A - 15/30 days</b> S-7553<br>completed   | Simon Wade ( Mechanic )      |
| 07/09/2020 |                 | <b>belt tensioner, cabin shock leaking, cab lift ram leaking</b> R-8835   | Simon Wade ( Mechanic )      |
| 04/09/2020 |                 | <b>drive axle gaskets, intake tube isolation rubbers</b> R-8852<br>completed  | Simon Wade ( Mechanic )      |
| 28/08/2020 |                 | <b>Load lights</b> R-8796<br>completed  | Ace Air Auto Electrical      |
| 19/08/2020 | 718,987 kms     | <b>A - 15/30 days</b> S-7472<br>completed   | Simon Wade ( Mechanic )      |
| 19/08/2020 |                 | <b>auto greaser lines, cabin ram leaking, fire extinguisher, first aid kit, front diff</b> R-8736<br>Fire extinguisher & first aid kit put in truck 18/8/2020 | Simon Wade ( Mechanic )      |
| 12/08/2020 |                 | <b>Parts</b> O-1457<br>micro v belts gaskets  | multispare                   |
| 10/08/2020 |                 | <b>Parts</b> O-1563<br>belt tensioner assy also credit attached   | multispare                   |
| 05/08/2020 |                 | <b>Parts</b> O-1562<br>floor mats   | multispare                   |
| 05/08/2020 |                 | <b>Parts</b> O-1561<br>temp sender water trallier control valve valve hadley pinion seal kit  | multispare                   |
| 02/08/2020 |                 | <b>exhaust leak, radiator hose, turntable</b> R-8710<br>completed   | James Hendry (Mechanic)      |
| 01/08/2020 |                 | <b>Truckwash</b> O-1451<br>prime mover wash   | Narellan Truck Wash Services |
| 24/07/2020 | 705,672 kms     | <b>susie coil</b> R-8644<br>completed   | Simon Wade ( Mechanic )      |
| 22/07/2020 | 705,672 kms     | <b>anderson plug, drawbar puller, trailer plug</b> R-8598<br>completed  | Simon Wade ( Mechanic )      |
| 21/07/2020 | 705,672 kms     | <b>ice pack motor, isolation rubbers</b> R-8577   | Simon Wade ( Mechanic )      |
| 21/07/2020 | 705,672 kms     | <b>park brake handpiece, temp sender, wiring</b> R-8586<br>completed  | Simon Wade ( Mechanic )      |
| 21/07/2020 | 705,672 kms     | <b>A - 15/30 days</b> S-7348<br>completed   | Brandon McKinnon             |
| 20/07/2020 |                 | <b>Parts</b> O-1379<br>sensor-coolant temperature   | multispare                   |
| 18/07/2020 |                 | <b>air conditioner, checkover &amp; repairs, turntable</b> R-8708<br>completed 17/7/2020 4522 8 hrs 18/7/2020 4523 12 hrs                                     | James Hendry (Mechanic)      |
| 17/07/2020 | 704,991 kms     | <b>Wheel alignment</b> R-8563<br>completed  | Sydney Trucks and Machinery  |

| Date       | Reading / Units | Type / Repairer Notes   | Repairer                      |
|------------|-----------------|---|-------------------------------|
| 17/07/2020 |                 | <b>Parts</b> O-1380<br>prime mover wash   | Narellan Truck Wash Services  |
| 17/07/2020 |                 | <b>Parts</b> O-1382<br>checker plate & cutting  | Neverland Holdings PTY LTD    |
| 16/07/2020 |                 | <b>steer axle, studs &amp; nuts</b> R-8709<br>completed   | James Hendry (Mechanic)       |
| 12/07/2020 |                 | <b>driveline vibration, service of engine,adjust valves</b> R-8707<br>completed                 | James Hendry (Mechanic)       |
| 10/07/2020 |                 | <b>faults</b> R-8519<br>completed   | Ace Air Auto Electrical       |
| 08/07/2020 |                 | <b>Parts</b> O-1288<br>Anthonys Auto Upholstery custom made mattress sleeper                    |                               |
| 07/07/2020 |                 | <b>Parts</b> O-1310<br>chrome pogo stick  | multispare                    |
| 06/07/2020 | 700,694 kms     | <b>weight scales</b> R-8561<br>completed  | Simon Wade ( Mechanic )       |
| 04/07/2020 |                 | <b>Parts</b> O-1309<br>shim 20 thou x 7   | multispare                    |
| 03/07/2020 | 700,679 kms     | <b>AIR DRYER ASSEMBLY, Compressor, Diff, Engine</b> R-8435<br>completed engine complete rebuild | Brandon McKinnon              |
| 03/07/2020 | 700,679 kms     | <b>B - 40k</b> S-7346<br>completed  | Brandon McKinnon              |
| 01/07/2020 |                 | <b>Parts</b> O-1293<br>paint-300 apex red   | Cummins South Pacific Pty Ltd |
| 01/07/2020 |                 | <b>Parts</b> O-1292<br>wiring harness   | Cummins South Pacific Pty Ltd |
| 25/06/2020 |                 | <b>Parts</b> O-1271<br>digital gauge dual input blue tooth                                      | sloanebuilt Trailers          |

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_