

Nov D07-5

Quantum Power Products Inc.
10903 92 Avenue
Grande Prairie, AB T8V 3J3, CA
service@quantuminc.ca
(780) 539-4258



Invoice: DRAFT INV
Date: 11/7/2024

Bill To
Fraction Energy Services
Lot 30 - 61027 Hwy 672
Sexmsith, AB T0H 3C0, CA
P: (780) 567-3900

Remit Payment To
Quantum Power Products Inc
10903 92 Avenue
Grande Prairie, AB T8V 3J3, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
2227	Net 60	DRAFT INV	Accounts Payable		D9184006727

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Load Bank

Cause: Customer request

Labor	Correction:	3.00000	\$170.00	\$510.00
-------	-------------	---------	----------	----------

AC Generator / AC Generator / Find 2 batteries and connect in series.
Check oil, coolant, and air filter.
Remove front panels.
Connect load bank cables to main breaker box.
Find controller power wires and put on a toggle switch.
Swap fitting on regulator and connect NG supply line.
Install ball valve inside enclosure for NG bleed.
Start unit and let it run through warm up cycle.
Confirm oil pressure and battery charging.
Once up to temp, put under load, work up to 80% for an hour.
Anything over 80% load would cause it to go down on under frequency.
Also seems to be a supply fuel problem as it is the same across all units.
Take off load and let unit cool down, then shut down.
Bleed off NG and remove supply line and fitting.
Disconnect load bank cables, remove toggle switch, and put panel back together.
Disconnect batteries to use on the next unit.

Defects:
E-stop missing
Both batteries missing
All control toggle switches missing, need at least 1 for DSE power
Unused wiring in panel should be removed
Cold start aids recommended for winter
Customer declined repairs at this time - Completed: 11/6/2024

Subtotal \$510.00

Inspection

Labor	Generator Inspection (250 Hour): Generator Maintenance Checklist	2.00000	\$170.00	\$340.00
-------	--	---------	----------	----------

Subtotal \$340.00

Unit: D9184006727 S/N#: 18105C11003
Zenith CIPR105Z
Engine: 660.19 Hours

Labor	\$850.00
Shop Supplies & ENV Fee	\$55.25
Pre-Charge Subtotal	\$905.25
GST (5% of \$905.25)	\$45.26
Total	\$950.51

Payment shall be made in full by purchaser for all services and repair work performed by Quantum Power Products Inc. and for any parts, components, engines, and products furnished to purchaser. You understand and agree that we make no warranties of any kind unless expressed in writing. Any warranties on the parts and accessories sold hereby are made by the manufacturer. Payment shall be made at the time of completion of the repair and service work. If credit is extended to purchaser, purchaser agrees to pay all cost and expenses, including reasonable attorney's fees, incurred by Quantum Power Products Inc. in collecting any amount due to Quantum Power Products Inc. from the purchaser. Any invoice which is past due shall bear interest until paid at the rate of 1.5% per month. net 30 days from date of purchase. Quantum Power Products Inc. will not be held responsible for loss or damage to the vehicle, including but not limited to its engine or parts in case of fire, theft, accident, negligence, gross negligence, or any other cause. This invoice is due 30 days following the invoice date, otherwise a late fee will be assessed.

Thank You for keeping your account current.

GST# 703871673RT0001

Customer Signature: _____

Printed Name: _____ Date: _____



FRACTION
Division of Green Energy Services

UNIT NUMBER: 6727

MILEAGE: 660 Hrs

DATE: July 9/25

MECHANICS COMMENTS

TECH

LOOK OVER + REPAIR

T.R.

ACTIVE HOURS - 660 Hrs

T.R.

SERVICE DUE - N/A.

FUEL - N/A.

INLET - N/A.

OUTLET - N/A.

PANEL - N/A.

- Replaced Estop Switch
- Replaced batteries.
- Replaced toggle switches, controller now has power
- Removed excess wiring

MECHANIC: Tristen Robinson

HOURS: 5

MECHANIC:

HOURS:

MECHANIC:

HOURS: