

		WO Date Created	Date Scheduled	Beginning Meter Reading	End M Read
30988	Demob/clean for auction	14-Nov-25	14-Nov-25	10262	
-	1 Demob/clean for auction				
30955	Replace blown hose	11-Nov-25	11-Nov-25		
-	1 Replace blown hose				
30894	250hr Service	05-Nov-25	05-Nov-25	10212	
250h	nr Service				
30708	Track worn out	03-Oct-25	03-Oct-25	10057	
-	1 Track worn out				
30686	Fit rock screen/hammer	02-Oct-25	02-Oct-25		
	Fit rock screen/hammer				
30632	Replace engine oil hose	29-Sep-25	29-Sep-25	1010	
-	Replace engine oil hose				
30560	Repair coolant leak at header tank	17-Sep-25	17-Sep-25	9973	
-	Repair coolant leak at header tan	nk			
30546	2000hr Service	16-Sep-25	16-Sep-25	9954	
2000	Ohr Service				
30410	Replace cutting edge bolts	19-Aug-25	19-Aug-25	9810	
-	Replace cutting edge bolts				
30269	Replace blown hose	22-Jul-25	22-Jul-25		
1	1 Replace blown hose				
30255	250 hour service	17-Jul-25	17-Jul-25	9698	
250h	nr Service				



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	
30005	EGR/Coolant leak	12-Jun-25	12-Jun-25	9503		
	1 EGR/Coolant leak					
29971	500 hour service	05-Jun-25	05-Jun-25	9475		
500	hr Service					
29525	Engine derate fault Diagnosed NRS valve intermittent fault	12-Mar-25	12-Mar-25	9325		
	1 Replace NRS Valve					
29524	Install crusher bucket	11-Mar-25	11-Mar-25	9325		
	1 Install crusher bucket					
29427	Reseal leaking stick cylinder	25-Feb-25	25-Feb-25	9316		
	1 Reseal leaking stick cylinder					
29255	Replace blown hydraulic hose	23-Jan-25	23-Jan-25	9257		
	1 Replace blown hydraulic hose					
29221	Reseal leaking quick connects	17-Jan-25	17-Jan-25	9251		
	1 Reseal leaking quick connects					
29141	Replace rusted out tail pipe	06-Jan-25	06-Jan-25			
	1 Replace rusted out tail pipe					
29094	Pressure Vessel Inspection	12-Dec-24	12-Dec-24			
	1 Pressure Vessel Inspection					
29086	Replace fire extinguishers	11-Dec-24	11-Dec-24			
	1 Replace fire extinguishers					
29052	Diagnose engine fault	03-Dec-24	03-Dec-24	9238		
	1 Diagnose engine fault					



Notes						
Pin 1 Reinstall upper boom cylinder pin 25 Nov-24 25 Nov-24 9194 250 Nour service 25 Nov-24 25 Nov-24 9194 250 Nov-24 25 Nov-24 9167 1 Inspect hydraulic oil leak 20 Nov-24 13 Nov-24 13 Nov-24 13 Nov-24 14 Nov-24 15 Nov-24 Nov						Notes
250 hour service 25-Nov-24 25-Nov-24 9194 250hr Service 28983 Inspect hydraulic oil leak 20-Nov-24 20-Nov-24 9167 1 Inspect hydraulic oil leak 13-Nov-24 13-Nov-24 13-Nov-24 13-Nov-24 1 1 Replace sieve bucket teeth 13-Nov-24 13-Nov-24 1 1 Replace sieve bucket teeth 1 2	29037		29-Nov-24	29-Nov-24	9227	
250hr Service 28983 Inspect hydraulic oil leak 20-Nov-24 20-Nov-24 9167	1	. Reinstall upper boom cylinder pin				
28983 Inspect hydraulic oil leak 20-Nov-24 20-Nov-24 9167 1 Inspect hydraulic oil leak 28943 Replace sieve bucket teeth 13-Nov-24 13-Nov-24 1 Replace sieve bucket teeth 28871 Quick connect fittings leaking 07-Nov-24 07-Nov-24 1 Quick connect fittings leaking 28763 Install shears 17-Oct-24 17-Oct-24 1 Install shears 17-Oct-24 17-Oct-24 28757 Inspect slow tilt bucket 09-ration 1 Inspect slow tilt bucket operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	29001	250 hour service	25-Nov-24	25-Nov-24	9194	
1 inspect hydraulic oil leak 28943 Replace sieve bucket teeth 13-Nov-24 13-Nov-24 1 Replace sieve bucket teeth 28871 Quick connect fittings leaking 07-Nov-24 07-Nov-24 1 Quick connect fittings leaking 17-Oct-24 17-Oct-24 1 install shears 17-Oct-24 17-Oct-24 1 install shears 17-Oct-24 17-Oct-24 17-Oct-24 28757 Inspect slow tilt bucket 17-Oct-24 17-Oct-24 operation 1 inspect slow tilt bucket operation 1 inspect slow tilt bucket operation 28633 1000 hour service 11-Sep-24 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	250h	r Service				
28943 Replace sieve bucket teeth 13-Nov-24 13-Nov-24 1 Replace sieve bucket teeth 28871 Quick connect fittings leaking 07-Nov-24 07-Nov-24 1 Quick connect fittings leaking 28763 Install shears 17-Oct-24 17-Oct-24 28757 Inspect slow tilt bucket operation 17-Oct-24 17-Oct-24 operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 16-Aug-24 16-Aug-24 28550 Replace leaking quick connect fittings 16-Aug-24 18-Jul-24 28469 250 hour service 18-Jul-24 18-Jul-24	28983	Inspect hydraulic oil leak	20-Nov-24	20-Nov-24	9167	
1 Replace sieve bucket teeth 28871 Quick connect fittings leaking 07-Nov-24 07-Nov-24 1 Quick connect fittings leaking 28763 Install shears 17-Oct-24 17-Oct-24 1 Install shears 10-Oct-24 17-Oct-24 17-Oct-24 28757 Inspect slow tilt bucket operation 1 Inspect slow tilt bucket operation 1 Inspect slow tilt bucket operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 250 hour service 18-Jul-24 18-Jul-24 250hr Service	1	. Inspect hydraulic oil leak				
28871 Quick connect fittings leaking 07-Nov-24 07-Nov-24 1 Quick connect fittings leaking 28763 Install shears 17-Oct-24 17-Oct-24 28757 Inspect slow tilt bucket operation 17-Oct-24 17-Oct-24 operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24	28943	Replace sieve bucket teeth	13-Nov-24	13-Nov-24		
1 Quick connect fittings leaking 28763 Install shears 17-Oct-24 17-Oct-24 1 Install shears 28757 Inspect slow tilt bucket operation 1 Inspect slow tilt bucket operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	1	. Replace sieve bucket teeth				
1 1 1 1 1 1 1 1 1 1	28871	Quick connect fittings leaking	07-Nov-24	07-Nov-24		
1 Install shears 28757 Inspect slow tilt bucket operation 1 Inspect slow tilt bucket operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	1	. Quick connect fittings leaking				
1 1 1 1 1 1 1 1 1 1	28763	Install shears	17-Oct-24	17-Oct-24		
operation 1 Inspect slow tilt bucket operation 28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	1	. Install shears				
28633 1000 hour service 11-Sep-24 11-Sep-24 1000hr Service 1000hr Service 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 18-Jul-24 18-Jul-24 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service 18-Jul-24 18-Jul-24	28757		17-Oct-24	17-Oct-24		
1000hr Service 28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	1	Inspect slow tilt bucket operation				
28550 Replace quick connect fittings 16-Aug-24 16-Aug-24 1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	28633	1000 hour service	11-Sep-24	11-Sep-24		
1 Replace leaking quick connect fitting 28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	1000	hr Service				
28469 250 hour service 18-Jul-24 18-Jul-24 250hr Service	28550	Replace quick connect fittings	16-Aug-24	16-Aug-24		
250hr Service	1	. Replace leaking quick connect fitt	ing			
	28469	250 hour service	18-Jul-24	18-Jul-24		
28360 Replace blown hose 19-Jun-24 19-Jun-24	250h	r Service				
	28360	Replace blown hose	19-Jun-24	19-Jun-24		
1 Repair blown hose	1	. Repair blown hose				



		WO Date	Date	Beginning	End Meter		
28200	Repair EGR fault code	Created 18-Apr-24	Scheduled 18-Apr-24	Meter Reading	Reading	l	
		18-Apr-24	18-Apr-24			l	
	1 Repair EGR fault					ı	
28136	500 hour service	09-Apr-24	09-Apr-24				
500	hr Service						
27969	Service defects	22-Feb-24	22-Feb-24			ı	
	1 Replace oil cap o'ring						
	2 Reseal RH cab window						
27943	250 hour service	13-Feb-24	13-Feb-24				
250	hr Service					_	
27941	Bucket repairs	12-Feb-24	12-Feb-24				
	1 Bucket repairs						
27928	Replace harness	08-Feb-24	08-Feb-24			ı	
	1 Replace stick harness						
	2 Replace tilt bucket harness						
27778	Replace engine oil/filter after bad sample	20-Dec-23	20-Dec-23				
	1 Replace engine oil/filter after bac	d sample					
27753	Bucket repairs	18-Dec-23	18-Dec-23			ı	
	1 Replace floor and wear strips					-	
	2 Replace U/S hydraulic hoses						
27676	Replace blown tilt hose	28-Nov-23	28-Nov-23				
	1 Replace blown tilt bucket hose					Ī	
27674	Replace load rollers	27-Nov-23	27-Nov-23				
	1 Replace u/s load rollers					1	



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27673	Replace cutting edge	27-Nov-23	27-Nov-23			
:	1 Replace cutting edge					
:	2 Geplace GP bucket tips					
27621	2000hr service	16-Nov-23	16-Nov-23	7941		
2000	Ohr Service					
27465	Inspect/ repair minor coolant leak from radiator core	09-Oct-23	09-Oct-23	7744		
:	1 Inspect/ repair minor coolant leak	from radiator co	re			
27464	Replace worn tilt bucket cutting edge	09-Oct-23	09-Oct-23	7744		
:	1 Replace worn tilt bucket cutting e	dge				
27415	250hr service	25-Sep-23	25-Sep-23	7693		
250h	nr Service					
27309	Replace U/S Stick cylinder hoses	04-Sep-23	04-Sep-23			
	1 Replace U/S Stick cylinder hoses					
27234	Repair blocked tilt bucket grease points	14-Aug-23	14-Aug-23			
:	1 Repair blocked tilt bucket grease p	points				
27221	500hr service	09-Aug-23	09-Aug-23	7445		
500h	nr Service					
27215	repair cracked visionlink bracket on cabin	09-Aug-23	09-Aug-23	7430		
	1 repair cracked visionlink bracket o	n cabin				
27194	12 Monthly pressure vessel inspection	01-Aug-23	01-Aug-23	7395		
12 N	Nonthly pressure vessel inspection					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
27103	Reseal leaking Stick cylinder	12-Jul-23	12-Jul-23			
	1 Reseal leaking Stick cylinder					
27029	Defects from service	28-Jun-23	28-Jun-23			
	1 oil cap o-ring					
	2 broken mirror rhs					
	3 Radiator hose					
	4 Cracked bucket pin boss					
	5 Hyd hoses in pump room					
	6 Battery clamps					
26978	250hr Service	19-Jun-23	19-Jun-23	7200		
250	hr Service					
26926	Gaurd rail	02-Jun-23	02-Jun-23	7118		
	1 Guard rail					
26919	cutting edge	01-Jun-23	01-Jun-23	7111		
	1 Edge turn					
26914	Upgrade GPS to 5G Modem	30-May-23	30-May-23			
	1 5G Modem					
26887	Tilt bucket repairs	25-May-23	25-May-23	6975		
	1 Crack repairs					
26886	Belly guard bolts	25-May-23	25-May-23	6975		
	1 Belly guard bolts					
26885	Quick fitting	25-May-23	25-May-23	6975		
	1 Quick connect					



Body Wo Date of Schoduled						 *
1 Edge 26813 1000hr service 28-Apr-23 28-Apr-23 28-Apr-23 21-Apr-23 21-Apr-23 21-Apr-23 6918 21-Apr-23 21-Apr-23 6918 21-Apr-23 21-Apr-23 6918 21-Apr-23 21-Apr-23						Notes
26813 1000hr service 28-Apr-23 28-Apr-23 28-Apr-23 1000hr Service 26798 Bucket not taken grease 21-Apr-23 21-Apr-23 6918 1 Bucket not taken grease 17-Feb-23 17-Feb-23 6737 1 fault code 26559 250hr Service 09-Feb-23 09-Feb-23 6693 250hr Service 26533 GPS harness 25-Jan-23 25-Jan-23 1 GPS 1 figher cracked 19-Jan-23 12-Jan-23 1 Ripper cracked 25-Jan-23 11-Jan-23 1 Hose 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 1 Hose 26493 Crack in ripper 1 1-Jan-23 11-Jan-23 1 Hose 26491 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26492 Bucket repairs 14-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 06-Dec-22 1-Dec-22 1-Dec	26884	Cutting edge	25-May-23	25-May-23	6975	
1000hr Service 26798 Bucket not taken grease 21-Apr-23 21-Apr-23 6918 1 Bucket not taken grease 26585 Engine fault code 17-Feb-23 17-Feb-23 6737 1 fault code 26599 250hr Service 09-Feb-23 09-Feb-23 6693 250hr Service 26533 GPS harness 25-Jan-23 25-Jan-23 75-Jan-23 75-Jan-2	1	L Edge				
26798 Bucket not taken grease 21-Apr-23 21-Apr-23 6918 1 Bucket not taken grease 26585 Engine fault code 17-Feb-23 17-Feb-23 6737 1 fault code 26599 250hr Service 09-Feb-23 09-Feb-23 6693 250hr Service 26533 GPS harness 25-Jan-23 25-Jan-23 1695 26493 Crack in ripper 12-Jan-23 12-Jan-23 17-Jan-23 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 11-Jan-23 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 6518 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 08-Dec-22 06-Dec-22 06-Dec-22 06-Dec-22	26813	1000hr service	28-Apr-23	28-Apr-23		
1 Bucket not taken grease 26585 Engine fault code 17-Feb-23 17-Feb-23 6737 1 fault code 26559 Sohr Service 09-Feb-23 09-Feb-23 6693 250hr Service 26533 GPS harness 25-Jan-23 25-Jan-23 25-Jan-23 1 GPS 26493 Crack in ripper 12-Jan-23 12-Jan-23 12-Jan-23 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 14-Jan-23 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 6518 26430 Bucket repairs 14-Dec-22 14-Dec-22 6470 26421 GR fault 08-Dec-22 08-Dec-22 6470 26407 SOOhr service 06-Dec-22 06-Dec-22 06-Dec-22	1000	hr Service				
26585 Engine fault code 17-Feb-23 17-Feb-23 6737 1 fault code 26559 250hr Service 09-Feb-23 09-Feb-23 6693 250hr Service 26533 GPS harness 25-Jan-23 25-Jan-23 26493 Crack in ripper 12-Jan-23 12-Jan-23 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 15-Dec-22 1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 06-Dec-22	26798	Bucket not taken grease	21-Apr-23	21-Apr-23	6918	
Fault code 250hr Service 250hr Service 250hr Service 250hr Service 250hr Service 2533 6693 250hr Service 2533 698 harness 25-Jan-23 25-J	1	Bucket not taken grease				
26559 250hr Service 250hr Service 26533 GPS harness 25-Jan-23 1 GPS 26493 Crack in ripper 12-Jan-23 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 1 Bucket repairs 14-Dec-22 08-Dec-22 6470 1 EGR fault 08-Dec-22 06-Dec-22 06-Dec-22 26407 500hr service 06-Dec-22 06-Dec-22	26585	Engine fault code	17-Feb-23	17-Feb-23	6737	
250hr Service 26533 GPS harness 25-Jan-23 25-Jan-23 Span-23 Sp	1	L fault code				
26533 GPS harness 25-Jan-23 25-Jan-23 1 1 GPS 26493 Crack in ripper 12-Jan-23 12-Jan-23 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 1 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 1 1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 10-Dec-22 10-	26559	250hr Service	09-Feb-23	09-Feb-23	6693	
1 GPS 26493 Crack in ripper 12-Jan-23 12-Jan-23 12-Jan-23 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 14-Jan-23 1 Hose 1 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 14-Dec-22 1 Bucket repairs 14-Dec-22 08-Dec-22 6470 26421 EGR fault 08-Dec-22 06-Dec-22 06-Dec-22 26407 S00hr service 06-Dec-22 06-Dec-22 06-Dec-22	250h	r Service				
26493 Crack in ripper 12-Jan-23 12-Jan-23 1 1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 1 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 14-Dec-22 1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 06-Dec-22	26533	GPS harness	25-Jan-23	25-Jan-23		
1 Ripper cracked 26487 Blown hose at tilt 11-Jan-23 11-Jan-23 19-Dec-22 19-Dec-22 6518 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 19-Dec-22 14-Dec-22	1	L GPS				
26487 Blown hose at tilt 11-Jan-23 11-Jan-23 1 Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 1 Bucket repairs 46421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22	26493	Crack in ripper	12-Jan-23	12-Jan-23		
Hose 26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 06-Dec-22	1	L Ripper cracked				
26451 Change thumb wheel direction 19-Dec-22 19-Dec-22 6518 1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 0	26487	Blown hose at tilt	11-Jan-23	11-Jan-23		
1 Thumb wheel 26439 Bucket repairs 14-Dec-22 14-Dec-22 1 Bucket repairs EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22	1	L Hose				
26439 Bucket repairs 14-Dec-22 14-Dec-22 1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22 06-Dec-22	26451	Change thumb wheel direction	19-Dec-22	19-Dec-22	6518	
1 Bucket repairs 26421 EGR fault 08-Dec-22 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22	1	Thumb wheel				
26421 EGR fault 08-Dec-22 6470 1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22	26439	Bucket repairs	14-Dec-22	14-Dec-22		
1 EGR fault 26407 500hr service 06-Dec-22 06-Dec-22	1	Bucket repairs				
26407 500hr service 06-Dec-22 06-Dec-22	26421	EGR fault	08-Dec-22	08-Dec-22	6470	
	1	L EGR fault				
500hr Service	26407	500hr service	06-Dec-22	06-Dec-22		
	500h	r Service				



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26400	Replace grease nipples in hitch	05-Dec-22	05-Dec-22	6452		
1	Hitch grease nipples					
26341	Bucket cutting edge	17-Nov-22	17-Nov-22	6357		
1	Cutting edge					
26330	Hyd oil leak at stick crane valve bleeder	14-Nov-22	14-Nov-22	6334		
1	crane valve bleeder					
26250	250hr service	10-Oct-22	10-Oct-22			
250h	r Service					
26247	Replace front window	06-Oct-22	06-Oct-22			
1	Replace front window					
26184	Damaged rhs window	15-Sep-22	15-Sep-22			
1	Damaged rhs window					
26165	Engine fault code	08-Sep-22	08-Sep-22	6047		
1	Fault code - egr					
26112	2000hr service	19-Aug-22	19-Aug-22	5942		
1000	hr Service					
26058	Replace Track Chain Ass with new	03-Aug-22	03-Aug-22	5993		
1	Remove and Replace worn Track	Link Ass with new	E&S Track L			
26048	Repair gps mount	29-Jul-22	29-Jul-22			
1	Product link mount					
26038	GET Side cutter guard bolts	26-Jul-22	26-Jul-22			
1	GET Side cutter guard bolts					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
26009	750hr service	13-Jul-22	13-Jul-22		5773	
250l	nr Service					
26007	Grease hitch	13-Jul-22	13-Jul-22			
	1 Grease hitch					
26003	Replace flashing light	13-Jul-22	13-Jul-22			
	1 Replace flashing light					
25885	Inspect final drive leak	30-May-22	30-May-22			
	1 Final drive leak					
25847	12 Monthly pressure vessel inspection	20-May-22	20-May-22			
12 N	Monthly pressure vessel inspection					
25813	500hr service	11-May-22	11-May-22			
500l	nr Service					
25783	Replace belt and tensioner	04-May-22	04-May-22			
	1 Replace belt and tensioner					
25720	Replace worn bucket teeth	12-Apr-22	12-Apr-22			
	1 Replace worn bucket teeth					
25685	Inspect track chains for wear	05-Apr-22	05-Apr-22			
	1 Inspect track chains					
25639	Inspection	23-Mar-22	23-Mar-22			
	1 Inspection					
25630	Inspect engine fault codes	18-Mar-22	18-Mar-22			
	1 Inspect engine fault codes					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25618	250hr service	17-Mar-22	17-Mar-22		5257	
250h	r Service					
25575	Repair handrail	28-Feb-22	28-Feb-22	5189		
1	Repair handrail					
25564	Replace alternator and batteries	23-Feb-22	23-Feb-22			
1	Replace batteries and alternator					
25523	Repair grease lines	14-Feb-22	14-Feb-22			
1	Repair grease lines					
25492	Replace bucket GET	03-Feb-22	03-Feb-22	5084		
1	Replace bucket GET					
25458	Stick cylinder repair	24-Jan-22	24-Jan-22			
1	Stick cylinder repair					
25453	Repair eng hood	21-Jan-22	21-Jan-22	5033		
1	Repair eng hood					
25445	Turn cutting edge	19-Jan-22	19-Jan-22	5018		
1	Turn cutting edge					
25429	1000hr service	13-Jan-22	13-Jan-22	4988	5021	
1000	hr Service					
25425	Clean out radiator	13-Jan-22	13-Jan-22	4975		
1	Clean out radiator					
25351	Repair 2way	23-Nov-21	23-Nov-21			
1	Repair 2way					
25323	750hr service	12-Nov-21	12-Nov-21		4526	
250h	r Service					



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
25310 I	Inspect final drive oil leak	09-Nov-21	09-Nov-21	4745		
1	Inspect final drive oil leak					
25194	Inspect track master link	22-Sep-21	22-Sep-21			
1	Inspect track master link					
25158	500hr service	07-Sep-21	07-Sep-21		4500	
500hr	Service					
25089	Hyd oil leak	10-Aug-21	10-Aug-21			
1	Hyd oil leak					
25073	Diaognose low power	04-Aug-21	04-Aug-21	4260		
1	Low engine power					
25057	250hr service	27-Jul-21	27-Jul-21			
250hr	Service					
25055 I	Repair tilt cylinder retainer	27-Jul-21	27-Jul-21	4221		
1	Repair tilt cylinder retainer					
25008	ELC Extender - bad sample	02-Jul-21	02-Jul-21	4104		
1	ELC Extender - bad sample					
25007	replace faulty grease nipple	01-Jul-21	01-Jul-21	4104		
1	replace faulty grease nipple					
24991	Replace GET	18-Jun-21	18-Jun-21	4066		
1	Replace GET					
24962	4000hr service	02-Jun-21	02-Jun-21	3997	4014	
2000hi	r Service					
24869	Repair stick cylinder oil leak	05-May-21	05-May-21			
1	Repair stick cylinder oil leak					



Notes
1 Top up coolant 24811 Replace blocked air cleaners 19-Apr-21 19-Apr-21 1 Replace blocked air cleaners 24773 250hr service 09-Apr-21 09-Apr-21 3750 3755 250hr Service 24689 Install compaction wheel 08-Mar-21 08-Mar-21 1 Install compaction wheel 24651 Check operation of A/C 18-Feb-21 18-Feb-21 3579 1 Check operation of A/C 24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536 3536
24811 Replace blocked air cleaners 19-Apr-21 19-Apr-21 1 Replace blocked air cleaners 24773 250hr service 09-Apr-21 09-Apr-21 3750 3755 250hr Service 24689 Install compaction wheel 08-Mar-21 08-Mar-21 1 Install compaction wheel 18-Feb-21 18-Feb-21 3579 24651 Check operation of A/C 18-Feb-21 18-Feb-21 3579 24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 18-Feb-21 18-Feb-21 3579 24584 500 hr service 02-Feb-21 02-Feb-21 3536 3536
1 Replace blocked air cleaners 24773 250hr service 09-Apr-21 09-Apr-21 3750 3755 250hr Service 24689 Install compaction wheel 08-Mar-21 08-Mar-21
24773 250hr service 09-Apr-21 09-Apr-21 3750 3755 250hr Service 24689 Install compaction wheel 08-Mar-21 08-Mar-21
250hr Service 24689 Install compaction wheel 08-Mar-21 08-Mar-21 1 Install compaction wheel 24651 Check operation of A/C 18-Feb-21 18-Feb-21 1 Check operation of A/C 24650 Repair flashing light 18-Feb-21 18-Feb-21 1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536
24689 Install compaction wheel 08-Mar-21 08-Mar-21 1 Install compaction wheel 24651 Check operation of A/C 18-Feb-21 18-Feb-21 3579 1 Check operation of A/C 24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536 3536
1 Install compaction wheel 24651 Check operation of A/C 18-Feb-21 18-Feb-21 3579 1 Check operation of A/C 24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 18-Feb-21 3579 24584 500 hr service 02-Feb-21 02-Feb-21 3536
24651 Check operation of A/C 18-Feb-21 18-Feb-21 3579 1 Check operation of A/C 24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536
1 Check operation of A/C 24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536 3536
24650 Repair flashing light 18-Feb-21 18-Feb-21 3579 1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536 3579 3536 3536
1 Repair flashing light 24584 500 hr service 02-Feb-21 02-Feb-21 3536 3536
24584 500 hr service 02-Feb-21 02-Feb-21 3536 3536
500hr Service
24498 103 inspection 08-Jan-21 08-Jan-21
1 103 inspection
24463 Replace lock 14-Dec-20 14-Dec-20
1 Replace lock
24428 12 Monthly pressure vessel 10-Dec-20 10-Dec-20 inspection
12 Monthly pressure vessel inspection
24393 250hr Service 26-Nov-20 26-Nov-20 3363 3363
250hr Service



	EAGLS? SESTE EAGUAGE.							
		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes		
24382	Replace cracked windscreen - Job Cost PH106.100.045	23-Nov-20	23-Nov-20					
	1 Replace cracked windscreen - Job	Cost PH106.100.0)45					
24343	Repair hammer circuit - NG28229 Westrac	16-Nov-20	16-Nov-20	3247	3247			
:	1 Repair hammer circuit					Westrac repaired invoice NG28229		
24314	Replace grease gun	06-Nov-20	06-Nov-20					
:	1 Replace grease gun							
24309	Hammer set up	05-Nov-20	05-Nov-20	3246				
:	1 Hammer set up							
24122	Replace faulty tilt bucket cable	14-Sep-20	14-Sep-20					
:	Replace faulty tilt bucket cable							
23987	1000hr Service	10-Aug-20	10-Aug-20	2997	2997			
1000	Ohr Service							
23935	Test fit and set up grab bucket	30-Jul-20	30-Jul-20	2982				
	1 Test and set up grab bucket					Test fit and set up grab bucket		
23907	Replaced globe in flashing light	22-Jul-20	22-Jul-20	2755				
	Replaced globe in flashing light							
23575	Inspect machine	25-May-20	25-May-20	2732				
	1 Inspect machine							
23432	Replace out of date seat belt	11-May-20	11-May-20					
	1 Replace out of date seat belt							
23388	Repaired missing grease nipple in tilt bucket	01-May-20	01-May-20	2729				
	1 Repaired missing grease nipple in	tilt bucket						



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
23354	250hr Service	29-Apr-20	29-Apr-20	2701	2732	
2501	nr Service					
23042	Set up for mine site	17-Feb-20	27-Feb-20			
	1 Safety					17/02 Fit bowless fuel filter 19/02 Change fuel sep filter housing, fab & install new fuel lines. 20/02 Fit safety decals & paint steps 21/02 Replace travel beeper with squawker.
	2 Inspection & maintenance					14/02 Clean machine 17/02 Complete 103 inspection
	3 GET					26/02 Change out cutting edge - 2466hrs
22951	500hr Service	13-Jan-20	13-Jan-20	2401	2441	
	1 500hr Service					30/01 Completed 2441hrs - D Martin
22913	Replace hyd fittings on bucket ram	13-Dec-19	13-Dec-19	2338		
	1 Replace hyd fittings on bucket rar	m				13/12 Bucket repaired by Westrac, oill leak at fitting replace with new fitting.
22849	250hr Service	29-Nov-19	29-Nov-19	2244	2284	
	1 250hr Service					4/11 Completed 2284HRS - M Gardner
22804	November Maintenance Work Order	01-Nov-19	01-Nov-19			
	1 GET/Attachments					19/11 cutting edges
22775	Inspect bucket pin- retaining plate broken (warranty)	05-Nov-19	05-Nov-19	2140		
	1 Inspect bucket pin- retaining plate	e broken (warrant				
22658	2000hr Service	25-Sep-19	25-Sep-19	1918	2009	
22563	Aug maintenance work order	01-Aug-19	01-Aug-19			
	1 GPS work					15/8 Re-pin tilt cable



		WO Date Created	Date Scheduled	Beginning Meter Reading	End Meter Reading	Notes
22548	250hr Service	09-Aug-19	09-Aug-19	1712	1752	
	1 250hr Service					
22459	Commission machine	28-Jun-19	28-Jun-19			
	1 Body work					25/06 - Re-shim bucket hitch 26/06 - Fit circle hand rails, weld facing to bucket face & install centre pin 2/7 Fit Company logos 8/7 Sand & paint front panel
	2 GET work					25/06 Turn cutting edge 26/06 remove cutting edge 3/7 Fit edge to tilt bucket
	3 Safety work					27/6 Install reflective & safety decals. 28/6 Pressure Vessel checks - Adept 2/7 Paint tow points red. Fit safety decals. Fit burst protection & segregation work. Whip check hoses. Double insulate battery leads. 3/7 Fit door alarm 4/7 Fit turbo & manifold wrap 12/7 Fit new FOPS to cab. Fit turbo & exhaust lagging
	Inspection & service work					4/7 Assist Westrac with inspection.
	5 GPS work					5/7 Westrac install hyd components for GPS update.