

XW93BU SERVICE HISTORY



VIN: 1FVJHYD19LLLU1970

DATE	KM/HRS	DESCRIPTION	LOCATION	COST
	660000	NEXT SERVICE DUE (MINOR)		
13/05/2026	636185	REPLACE LEAKING INPUT SHAFT SEAL REAR DIFF	DAIMLER GEELONG	1031.46
13/05/2026	636185	REPLACE ALL BRAKES ON DRIVE AXLES	DAIMLER GEELONG	1854.98
20/04/2026	631114	MAJOR C SERVICE COMPLETED	DAIMLER GEELONG	2890.77
11/02/2026	615571	RADIATOR FAILED, REPLACE WITH NEW RADIATOR	DAIMLER GEELONG	8143.91
7/01/2026	601518	600,000KM M2 SERVICE AND ENGINE TUNE	DAIMLER GEELONG	5343.85
12/11/2025	585793	REPLACE SIEZED FAN HUB AND WINDSCREEN	BRISBANE DAIMLER	5700.45
29/09/2025	573669	570,000 KM SERVICE	DAIMLER GEELONG	1001.88
18/07/2025	540712	VEHICLE DERATE DUE TO NOX SENSOR (REPLACED)	DAIMLER GEELONG	1652.06
18/07/2025	540712	LEAKING WHEEL SEAL RHF REPLACED	DAIMLER GEELONG	
18/07/2025	540712	REPLACE LEAKING SUMP GASKET	DAIMLER GEELONG	
11/07/2025	540689	540,000 KM SERVICE	DAIMLER GEELONG	2886.76
11/07/2025	540689	REPLACE LEAKING INJECTOR PASS THROUGH SEAL IN #3	DAIMLER GEELONG	
24/04/2025	510973	BOTH HEADLIGHTS REPLACED WITH NEW	DAIMLER GEELONG	3154.84
24/04/2025	510973	510,000 KM M1 SERVICE	DAIMLER GEELONG	1186.43
17/12/2024	451334	REPLACE LEAKING LH REAR AXLE SEAL	DAIMLER GEELONG	399.67
17/12/2024	451334	REPLACE FOG LIGHT IN BUMPER BAR	DAIMLER GEELONG	617.67
17/12/2024	451334	REPLACE FAULTY NOX SENSOR	DAIMLER GEELONG	3379.75
8/11/2024	451334	REPLACE LEAKING FOG LIGHT IN BUMPER	DAIMLER GEELONG	679.44
7/10/2024	430763	REPLACE NOX SENSOR	DAIMLER GEELONG	1691.26
9/09/2024	419739	420000 KM SERVICE	DAIMLER GEELONG	347.97
9/09/2024	419739	REPLACE EXHAUST GASKET UNDER CAB (EXTRA SOOT)	DAIMLER GEELONG	
5/07/2024	390553	390000 KM SERVICE	DAIMLER GEELONG	1899.26
5/07/2024	390553	REPLACE FRONT CAB MOUNTS	DAIMLER GEELONG	
5/07/2024	390553	FRONT BRAKE PAD REPLACEMENT	DAIMLER GEELONG	
16/02/2024	327447	REPLACE FRONT SPRING BUSHES	DAIMLER GEELONG	1259.54
25/01/2024	327447	REPLACE BOTH REAR DRIVE AXLE BRAKES	DAIMLER GEELONG	1689.03
20/01/2024		SERVICE CONTRACT EXPIRED	DAIMLER GEELONG	
21/07/2022		ALL SERVICES ON CONTRACT UNTIL 20-1-24	DAIMLER GEELONG	
20/07/2022	129887	130000 KM SERVICE	WILSON BOLTON	CONTRACT
20/07/2022	129887	REPLACE FRONT BUMPER BAR (DAMAGED PRIOR PURCHASE	WILSON BOLTON	CONTRACT
1/07/2022		REMOTE TIPPER HYDRAULICS FITTED	GD FULTON WORKSHOP	800
1/07/2022		HYDRAULIC TANK ENLARGED FOR TIPPER WORK	GD FULTON WORKSHOP	750
23/06/2022		RECOMMENDED 30,000KM INTERVALS FOR TIPPER WORK	WILSON BOLTON	
23/06/2022	114703	PURCHASED TRUCK FROM WILSON BOLTON HORSHAM	WILSON BOLTON	
		FURTHER INFO GREG @ GD FULTON 0488 233 926		