

Mouvement 101741

Date 28-10-2025

Client

Machine ML04KL0001628 R60CR-9A Intervention Révision 3467h+rep faisceau

N° Demande 0

Libellé	Quantité	Prix unitaire	Montant
Frais de port			32.80
Main d'oeuvre	14.00	95.00	95.00
Déplacement	1.00	15.00	15.00
Prise en charge	1.00	40.00	40.00
Fourniture Huile 10W-15W	82.00	4.80	4.80
Fourniture Huile 90 fongibles	3.00	4.80	4.80
			66.50
TOTAL FRAIS			1892.30
Y21N1-00011 BEACON LAMP ASSY(12V)	1.00	662.37	662.37
Y71ML-03930 STRIKER	1.00	32.17	32.17
Y31RF-10250 ELEMENT-RETURN	1.00	54.71	54.71
YXJAU-00894 V-BELT	1.00	67.36	67.36
Y11M9-90260 V-BELT	1.00	22.60	22.60
YXJAU-01138 FUEL FILTER	1.00	21.77	21.77
YXJAU-01515 filter	1.00	48.79	48.79
YXJAU-01190 OIL FILTER	1.00	91.24	91.24
Y31MH-20520 ELEMENT	1.00	45.69	45.69
YXKAN-00030 AIR FILTER REC	2.00	19.67	39.34
Y11S7-40120 ELEMENT-PRIMARY(OUT)	1.00	43.60	43.60
Y11S7-40130 ELEMENT-SAFETY(IN)	1.00	33.24	33.24
PIECES DETACHEES			1162.88
TOTAL GENERAL			3055.18

3666,21 TTC