

Job Item Detail Report for All Customer Job Items
Customer LIFT04 LIFT TRUCK SPECIALISTS P/L (ASSETS)
Contact NICK CLARK
Telephone 53392084

Plant ID	LTS 348	Make	KOMATSU	Model	FD25T-17
Last Job	1/09/2025	Serial	334419	Engine	

Date	29/06/2021	Inv	114003	Job	216118	Meter	10673	Order	
Desc	Breakdown				Bill To	LIFT04			

Stock and Alternate Stock Codes	Qty	Description	
LTS S920 hours 10673			
SCR 33131			
Possible alternator issue			
PM service if required			
Replaced alternator, belt and battery			
10058762	1.00	Vee Belt	0.00
E05	1.50	Engine Oil	0.00
17937	1.00	FUEL FILTER	0.00
343801	1.00	Oil filter	0.00
3042173	1.00	AIR FILTER Outer	0.00
DXA487	1.00	Alternator	0.00
4053	7.60	Labour - Tony Benson	0.00
6030	1.00	Battery N70ZZLN	0.00
			0.00

Date	6/04/2022	Inv	117189	Job	219172	Meter	10950	Order	
Desc	Service				Bill To	LIFT04			

Stock and Alternate Stock Codes	Qty	Description	
PM Service & Safety inspection			
LTS S920 hours 10950			
SCR: 35263			
Steven Barnett 0448 453 328			
Replaced sump plug as was stripped			
E05	1.50	Engine Oil	0.00
343801	1.00	Oil filter	0.00
17937	1.00	FUEL FILTER	0.00
3042173	1.00	AIR FILTER Outer	0.00
3978897	1.00	AIR FILTER - INNER	0.00
CL1	1.00	Chain Lube	0.00
GC1	1.00	Grease EP	0.00
AW12	1.00	12mm Sump Plug	0.00
4053	1.50	Labour - Tony Benson	0.00
			0.00

Date	8/12/2022	Inv	120194	Job	221884	Meter	11287	Order	
Desc	Service				Bill To	LIFT04			

Stock and Alternate Stock Codes	Qty	Description	
PM Service & Safety inspection			
LTSS920 hours 11287			
SCR:37187			

Job Item Detail Report for All Customer Job Items
Customer LIFT04 LIFT TRUCK SPECIALISTS P/L (ASSETS)
Contact NICK CLARK
Telephone 53392084

Steve 0448 453 328 confrimed 6/12/22

replace stripped sump plug

con	1.00	Consumables / Waste Levy	0.00
343801	1.00	Oil filter	0.00
17937	1.00	FUEL FILTER	0.00
3042173	1.00	AIR FILTER Outer	0.00
3978897	1.00	AIR FILTER - INNER	0.00
4053	2.50	Labour - Tony Benson	0.00
			0.00

Date 15/12/2022 Inv 120282 Job 222161 Meter 1 Order
Desc Parts Internal Bill To LIFT04

Stock and Alternate Stock Codes	Qty	Description
- Change Sticker Label to LTS 348 - 15-12-22		
		0.00

Date 20/07/2023 Inv 122817 Job 224607 Meter 11547 Order
Desc Breakdown Bill To LIFT04

Stock and Alternate Stock Codes	Qty	Description
---------------------------------	-----	-------------

-Contact Steve Barnett to arrange onsite visits before attending steve.barnett@stawellgoldmine.com

BREAKDOWN & PM

LTS 348 hours 11547

SCR38528

Dale 0407 060 843/ 5358 9271

Advised unit needs an alternator, has no output

Attended site and installed new alternator and

compelted PM Service

-20/7/23 the sump plug has been leaking - new plug required at next service

-20/7/23Trunion bush are very worn to be replaced

con	1.00	Consumables / Waste Levy	0.00
DXA487	1.00	Alternator	0.00
343801	1.00	Oil filter	0.00
E05	1.50	Engine Oil	0.00
3042173	1.00	AIR FILTER Outer	0.00
3978897	1.00	AIR FILTER - INNER	0.00
GC1	1.00	Grease EP	0.00
CL1	1.00	Chain Lube	0.00
4100	4.00	Labour	0.00
			0.00

Date 22/02/2024 Inv 125573 Job 227174 Meter 11806 Order
Desc Service Bill To LIFT04

Stock and Alternate Stock Codes	Qty	Description
---------------------------------	-----	-------------

-Contact Steve Barnett to arrange onsite visits before attending steve.barnett@stawellgoldmine.com

-20/7/23Trunion bush are very worn to be replaced

PM Service & Safety inspection

Job Item Detail Report for All Customer Job Items
Customer LIFT04 LIFT TRUCK SPECIALISTS P/L (ASSETS)
Contact NICK CLARK
Telephone 53392084

LTS 348 hours 11806

SCR:38769

Steve 0448 453 328

Replaced sump plug

343801	1.00	Oil filter (FPS-170B)	0.00
E05	1.50	Engine Oil	0.00
3042173	1.00	AIR FILTER Outer FA-159	0.00
3978897	1.00	AIR FILTER - INNER	0.00
R16BP1	1.00	Sump Plug M16X1.5	0.00
4101	2.00	Labour - Mitch Hodder	0.00
			0.00

Date 4/11/2024 Inv 129117 Job 230268 Meter 12063 Order
 Desc Service Bill To LIFT04

Stock and Alternate Stock Codes	Qty	Description
---------------------------------	-----	-------------

-Contact Steve Barnett to arrange onsite visits before attending steve.barnett@stawellgoldmine.com

-20/7/23Trunion bush are very worn to be replaced

PM Service & Safety inspection

LTS 348 hours 12063

SCR:42139

Justin Cheyne 0409 954 334/5358 1022

-Noted at Service 4/11/24

-Counter weight to come off to do truinion bushes, no bushes left

-Carraige need shimmming as has lots of movement

-Sump plug thread is bad and needs repair , sump will need to come out

-All bushed and king pins worn

E05	1.50	Engine Oil	0.00
H05	0.60	Hydraulic oil AWH 68 5L	0.00
343801	1.00	Oil filter (FPS-170B)	0.00
3042173	1.00	AIR FILTER Outer FA-159	0.00
4101	3.50	Labour - Mitch Hodder	0.00
			0.00

Date 1/09/2025 Inv 133808 Job 230647 Meter 1 Order
 Desc Workshop Internal Bill To LIFT04

Stock and Alternate Stock Codes	Qty	Description
---------------------------------	-----	-------------

Workshop

Converted to POR SJ85

Job closed with current costings

6030	1.00	Paint Komatsu -LTS 348	0.00
			0.00