



## EX19 - EX19-KOBELCO SK350LC-10 EXCAVATOR

---

Location: 191 GEORGE ST, SCORESBY

Serial#: YC14405133

Hour/Odometer: 6241.4

Next Service: 6500

### Maintenance History

---

| Type            | Date       | Comments  |
|-----------------|------------|---|
| REPAIRS         | 29/05/2026 | Seat air suspension broken (Incab lighter) doesn't work as sold   |
| REPAIRS         | 19/05/2026 | OIL FILTER & OIL FILTER FUEL  |
| REPAIRS         | 17/04/2026 | Fit new batteries   |
| PARTS           | 18/03/2026 |   |
| SERVICE         | 4/11/2025  | 500hr Service   |
| REPAIRS         | 7/10/2025  | Blown Hose replacement.   |
| REPAIRS         | 20/09/2025 | Bucket Repairs  |
| REPAIRS         | 26/06/2025 | Repl Light Relay  |
| REPAIRS         | 19/06/2025 | EX19 Service Hours 5015 Needs 2 new working lights, needs new 24v 5pin relay, cutting edge needs flipping with new bolts and nuts, rhs rear main door needs replacing, lhs rear panel needs replacing.  |
| REPAIRS         | 22/04/2025 | 5000 SERVICE  |
| REPAIRS         | 13/02/2025 | ON INSPECTION OF MACHINE FOUND LOOSE CHECK VALVE ON BRAKE SPOOLS, BLOWN O-RINGS BOTH FRONT & BACK CARRIED OUT WORK TO REMOVE & REPLACE DAMAGED O-RING & TORQUE LOOSE CHECK VALVES TESTED MACHINE AFTER WORK COMPLETED - FOUND OK CUSTOMER TO MONITOR FOR FURTHER ISSUES AFTER REPAIRS WORK CARRIED OUT ON LHS DRIVE MOTOR |
| EXTERNAL REPAIR | 7/01/2025  | 4000hr service and tramming fault   |
| EXTERNAL REPAIR | 12/12/2024 | Cutting edge replace  |
| DAMAGES         | 11/11/2024 | Damaged panels  |
| SERVICE         | 30/10/2024 | 500hr service   |
| REPAIRS         | 20/09/2024 | Cutting edges   |

|                  |            |  |
|------------------|------------|--|
| EXTERNAL REPAIR  | 9/07/2024  | 3000hr Service   |
| RECORD 360       | 1/11/2023  | Record 360   |
| SERVICE          | 31/10/2023 | 500hr service  |
| REPAIRS          | 14/09/2023 | Grease nipples blocked   |
| EXTERNAL REPAIR  | 29/08/2023 | Leaking quick hitch Enzed  |
| REPAIRS          | 23/08/2023 | Stick to bucket grease nipple not asking grease  |
| RECORD 360       | 23/08/2023 | Record 360   |
| EXTERNAL REPAIR  | 12/07/2023 | 2000hr Service   |
| REPAIRS          | 2/05/2023  | bucket edge replacement @1690hrs DBF2536X12X114-1 M24X83 PLOW BOLTS X20 M24 NUTS X20   |
| SERVICE          | 10/02/2023 | 1500hr service @1475.4hrs  |
| OTHER            | 5/07/2022  | risk assessment  |
| EXTERNAL SERVICE | 17/05/2022 | 1,000hr service (Melbourne tractors) @1021hrs  |
| PARTS            | 11/05/2022 | parts for grease gun - coupling, flex and level  |
| REPAIRS          | 10/12/2021 | 10/12/21@671hrs Noise coming from dipper stick to boom area, machine has been greased and no difference made (Geoff) Contact Melbourne tractors for inspection   |
| SERVICE/REPAIR   | 27/10/2021 | Cab - control loose objects, seat belts, windscreens, windscreen washer, visibility, rear view mirrors, and seat function. : Service has been completed but change filter and oil is flashing up on screen |
| SERVICE/REPAIR   | 27/10/2021 | reset service hr meter schedule  |
| SERVICE/REPAIR   | 15/09/2021 | Mud bucket cutting edge requires turning Tracks require adjustment   |
| SERVICE/REPAIR   | 1/07/2021  | 500hr service  |
| SERVICE/REPAIR   | 7/06/2021  | Grease point at dipper arm to boom right side not taking grease  |