

This live tracking will be terminated at: 12 Feb 2027 23:59

+
-



i

Location: RIDING BOUNDARY RD, RAVENHALL

Serial#: KMTWA120HJA010671

Hour/Odometer: 9564

Next Service: 10000

Maintenance History

Type	Date	Comments
REPAIRS	1/06/2026	Rhs battery not secured down Suppression system needs recharging
EXTERNAL REPAIR	22/05/2026	ac compressor failed
PARTS	1/05/2026	Hydraulic hose
EXTERNAL REPAIR	30/04/2026	Rotate Front tyres to back on unit WL09, fit loan tyre to position 4, Take off tyre sent for a Repair
PARTS	30/04/2026	Lamp
PARTS	24/04/2026	Service Kit
REPAIRS	16/04/2026	DPF fault code
PARTS	15/04/2026	2 x Batteries
PARTS	24/03/2026	Cutting edge and hardware
REPAIRS	23/03/2026	Cab door not opening and fault code with bucket float
PARTS	16/03/2026	Cabin door cable

EXTERNAL REPAIR	12/03/2026	Blown hydraulic hose onsite repair
PARTS	10/03/2026	O rings
PARTS	3/03/2026	Dosing unit components
PARTS	2/03/2026	Service filter kit
PARTS	25/02/2026	
REPAIRS	18/12/2025	Lights
REPAIRS	17/12/2025	Cutting edges and light upgrade
SERVICE	28/11/2025	8500hr service
REPAIRS	17/11/2025	Repl Boom to Bucket Hook Up Pins & Bushes
REPAIRS	10/10/2025	Heal plates need replacing
SERVICE	7/08/2025	WL09 SVC
REPAIRS	17/04/2025	SERVICE KIT
REPAIRS	5/03/2025	BATTERY FIXES
REPAIRS	7/02/2025	WL09 OIL CAP
REPAIRS	12/12/2024	Bucket cutting edge is worn Inspection wheel arch hard to open right hand side
EXTERNAL SERVICE	10/12/2024	7000hr service
REPAIRS	30/09/2024	Park brake switch
REPAIRS	20/09/2024	Bonnet hinges seized and fan bracket broken
SERVICE	19/09/2024	500 hr service
REPAIRS	19/09/2024	Auto level on bucket
REPAIRS	13/09/2024	RHS engine bay door extremely hard to open (Luke aware) Drivers door-cannot open door from inside
REPAIRS	21/08/2024	LO3 Code differential pressure sensor
EXTERNAL REPAIR	9/07/2024	Broken Grease lines
REPAIRS	17/05/2024	Repair step
REPAIRS	29/04/2024	RHS engine bay door extremely hard to open
REPAIRS	22/02/2024	Grease pump unit
SERVICE	9/02/2024	6000hr service
RECORD 360	9/01/2024	Record 360
REPAIRS	22/08/2023	R/H Headlight not working
REPAIRS	14/08/2023	Grease system not working
REPAIRS	14/08/2023	Music radio has no reception
RECORD 360	14/08/2023	Record 360
DAMAGES	9/08/2023	Few light broken lights
REPAIRS	4/08/2023	Door not opening properly when hopping out the loaded
PARTS	3/07/2023	Missing fuel cap

REPAIRS	21/06/2023	bucket cutting edges to be replaced parts ordered from G.E.T. AUSTRALIA
REPAIRS	7/06/2023	Not starting
EXTERNAL SERVICE	26/05/2023	500hr service komatsu 30/05/23
EXTERNAL SERVICE	6/05/2022	N/S/R tyre u/s
SERVICE/REPAIR	11/04/2022	Step U/S, R/H guard assy wont open, wear plate under bucket not fitted, grease line right side loader arm leaking
SERVICE/REPAIR	10/03/2022	Grease line damaged at Z bar area
SERVICE/REPAIR	25/02/2022	Turn cutting edges
SERVICE/REPAIR	22/02/2022	Check air con not cold
EXTERNAL SERVICE	10/02/2022	5,000hr Service Air con not efficient
EXTERNAL SERVICE	25/01/2022	Air Con N/W
SERVICE/REPAIR	6/10/2021	Key broken off in door