

This live tracking will be terminated at: 15 May 2030 09:55

+
-



Location: ELDER ST SOUTH (AREA 2), HEATHERTON

Serial#: VATZ0454LZB032132

Hour/Odometer: 408.1

Next Service: 7500

Maintenance History

Type	Date	Comments
REPAIRS	3/06/2026	Hitch release doesn't work. assold
REPAIRS	28/05/2026	Heater and aircon both don't work, only fan. Suspension in seat is stuffed. assold
EXTERNAL REPAIR	28/05/2026	replace plug for fly pos sensor parts ordered cant return parts ex Germany will keep for stock assold
REPAIRS	27/05/2026	repair coolant leak , fan belt
PARTS	22/05/2026	PARTS - 14MM METRIC DOWTY SEAL
REPAIRS	13/05/2026	Fly wheel sensor fault
PARTS	6/05/2026	Machine speed sensor
PARTS	6/05/2026	Hose fittings and clamps
REPAIRS	6/05/2026	Coolant expansion bottle
REPAIRS	6/05/2026	Supply and fit faulty isolator

PARTS	1/05/2026	Rebuild set
PARTS	27/04/2026	E stop
REPAIRS	27/04/2026	Replace blown hyd hose
PARTS	2/04/2026	Cutting edges and hardware
EXTERNAL REPAIR	16/03/2026	Air conditioning faulty
PARTS	13/03/2026	Pressure switch
PARTS	2/03/2026	
EXTERNAL REPAIR	25/02/2026	A/C not working
REPAIRS	19/02/2026	SERVICE
REPAIRS	13/02/2026	LOCKWASHER RIBBED SPRING M10
REPAIRS	13/02/2026	Servo control + Freight costs
REPAIRS	13/02/2026	RETAINER CLIP
REPAIRS	13/02/2026	Plain compression ring
REPAIRS	13/02/2026	CABLE TIES
PARTS	27/01/2026	Gas spring.
REPAIRS	27/01/2026	New cutting edge
PARTS	27/01/2026	Engine oil.
REPAIRS	8/12/2025	Tyre replacement
REPAIRS	24/11/2025	Tyre replacement
SERVICE	6/10/2025	7000hr SVC
REPAIRS	13/08/2025	Repl GET Bolts
REPAIRS	21/07/2025	Input Module #1 Fault
REPAIRS	8/07/2025	Rings / Bolts / Couplings
REPAIRS	10/06/2025	Repl Driveshaft
REPAIRS	23/04/2025	BLOWN GREASE LINE FIXES
EXTERNAL REPAIR	24/03/2025	SERVICE KIT
REPAIRS	27/02/2025	AIRCON GAS
REPAIRS	20/01/2025	
REPAIRS	31/12/2024	
PARTS	6/11/2024	Pump regulator leaking
RECORD 360	31/10/2024	Record 360 inspection
EXTERNAL REPAIR	23/10/2024	Air conditioner not working
SERVICE	17/10/2024	6000hr service
REPAIRS	11/10/2024	relief valve

REPAIRS	19/09/2024	Cutting Edges and bolts U/S
PARTS	23/08/2024	Loader forks
PARTS	28/06/2024	MCV Leak
RECORD 360	30/04/2024	Record 360
REPAIRS	24/04/2024	Reverse camera not working
REPAIRS	13/03/2024	Light blown
REPAIRS	12/03/2024	Grease fault on lower boom
REPAIRS	23/02/2024	Crank and cam sensor fault
REPAIRS	22/02/2024	Hydraulic hose leaks
REPAIRS	12/02/2024	Air con not working No music radio
REPAIRS	5/02/2024	Loadrite not working
EXTERNAL SERVICE	14/12/2023	Bucket movement from Weld it to site
REPAIRS	9/11/2023	Stuck bucket locking pin
EXTERNAL REPAIR	23/10/2023	Blown hose
REPAIRS	13/07/2023	Hydraulic Leak
REPAIRS	16/05/2023	Machine won t start
REPAIRS	12/05/2023	Horn not working and mirror missing
REPAIRS	10/05/2023	Bucket link arm grease line u/s Machine no power, no throttle 16/5/23
REPAIRS	4/05/2023	Coolant low top up
REPAIRS	3/05/2023	C/O wiper blades
SERVICE	1/05/2023	5,500 hr service
REPAIRS	17/04/2023	18/4/23 5597hrs Pumps transferring hyd oil into splitter box Replace cutting edges
SERVICE/REPAIR	28/09/2022	Auto grease pot not taking grease
OTHER	5/07/2022	risk assessment
REPAIRS	16/06/2022	Engine hatch hard to open Left mirror u/s Cutting edges require replacement\ dash screen n/w 5,500hr service due Change hyd oil Dash display unit not working at times
EXTERNAL SERVICE	17/08/2021	Hydraulic bucket hose leaking
PARTS	30/09/2020	service kit, sample bottle, hydraulic oil & axle and gear oil
PARTS	30/09/2020	angle cutter x 2 & knife x 2
PARTS	16/09/2020	radiator filler cap
PARTS	17/07/2020	angle cutter x 2, knife x 2
SERVICE/REPAIR	8/04/2019	WL06@4057HRS CARRY OUT 500HR TYPE SERVICE AS PER LIEBHERR SCHEDULE LABOUR \$446.25 PARTS \$
SERVICE/REPAIR	8/04/2019	8/4/2019 - WL06 @ 4057 HRS HYDRAULIC OIL LOSS/HORN N/W CLEAN UNDER MACHINE, OPERATE FOR .5HRS AND CHECK FOR SOURCE OF LEAK. FOUND LEAK

@ HIGH PRESSURE - HOSE FITTING AT HYDRAULIC MOTOR - TENSION FITTINGS
- TEST ALL OK. REPAIR HORN WIRING & TEST

FOUND SYSTEM LOW ON GAS. RECOVERED GAS & PRESSURISED SYSTEM,
PRESSURE HELD, VACUUM SYSTEM VACUUM HELD. CHARGED SYSTEM TO MAN
SPEC. RESET CONTROLLER CHECKED OPERATION PRESSURES TRAVEL PARTS
LABOUR \$340.00

SERVICE/REPAIR 16/02/2019

WL06@3910HRS 20.11.18-CHECK OVER MACHINE, A/C NOT COLD HORN
MUFFLED - TUNE FOR NOW THEN REPLACE 22.11.18-BEACON N/W REPLACE
FUSES X 2 SOURCE NEW HORN & FIT & TEST OK LABOUR \$255.00

SERVICE/REPAIR 20/11/2018

WL06 at 3475hrs. Travel to Old dandy rd - found fuel system contaminated.
Returned loader to Hallam.Drain. Carry out Major Service - Change all oils,
Filters, Fan belt Replace x2 Hydraulic hoses Wash down machine Fill Auto greaser,
Check operation. * Note: hydraulic oils not changed - (samples) 2000 hr type kit
x1 Eng. Oil Delo 400 30lts Hyd. hose x2 Hyd. Oil.(basic 100) 50lts

SERVICE/REPAIR 21/06/2018

WL06 at 3379hrs. Repair beacon N/W (Globe) Scales N/W Adjust proxy switch for
scales Check hyd. oil (level is OK) Check pump hose. leaking.(will repair when
machine is serviced next.) Globe Hi 70W 24V x1

SERVICE/REPAIR 10/05/2018

WL06 at 2914hrs. Hydraulic loss?? Inspect for loss - needs pump hose replaced
at rear.

SERVICE/REPAIR 18/01/2018

WL06 at 2671hrs. Repair grease lines + tap new threads for grease nipples + Z
bar.

SERVICE/REPAIR 20/10/2017

WL06 at 2274hrs - 24/4/17 - Check grease nipple, Elbow broken. Remove for
sample - to EnZed for parts. Could not match up-or parts EnZed. Due in 26/4/17
- Back to site and refit nipples/elbows. 26/4/17 - To EnZed-Grease fittings - to
site to fit next elbow. Machine not starting, Battery isolator not making contact -
clean contacts - fuse 10amp blown to starter relay. 2/6/17 WL06 at 2354hrs -
Repair grease nipple + plug Zbar - Replace fuse.

SERVICE/REPAIR 24/04/2017

WL06@2194hrs carry out 500hr type service, fit new uhf radio, repair hyd leak
o/s/f cylinder service parts \$952.00 labour \$

SERVICE/REPAIR 24/02/2017

PARTS

31/01/2017

WL06 s/fit new UHF radio and voltage reducer

WL06 at 2194hrs - 500hrs type service + hydraulic leak O/S/F wheel area. Check
auto grease points. Machine ID Decals WL06 UHF Radio U/S

SERVICE/REPAIR 24/01/2017

WL06 s/fit new cutting edges and hardware Parts \$1455.00

SERVICE/REPAIR 24/11/2016

WL06@1746hrs carry out Major 2,000hr type service.... change oils and filters,
engine, transmission, front and rear diffs, splitter box, sample all compartments,

SERVICE/REPAIR 16/06/2016

turn cutting edges, replace fuel cap, wiper blade assy, fill auto greaser, manually
grease joints as some not getting grease, repair hyd. oil leak l/h front, supply and
fit 2x new Batteries, clean all terminals and cables, repair rotating beacon wiring,

SERVICE/REPAIR 14/06/2016

WL06@1746hrs carry out machine inspection

SERVICE/REPAIR 1/06/2016