

This live tracking will be terminated at: 15 Dec 2028 23:59

+  
-



i

Location: ELDER ST SOUTH (AREA 2), HEATHERTON

Serial#: 1FVHF0CY4ELFV4805

Hour/Odometer: 10356.6

Next Service: 500

## Maintenance History

---

Type	Date	Comments
REPAIRS	3/06/2026	replace hour meter
REPAIRS	2/06/2026	Toolbox severely rusted and lid falling apart Due for 500 Hr Service assold
REPAIRS	5/04/2026	A/C faulty
EXTERNAL REPAIR	11/03/2026	A?C not working
PARTS	5/03/2026	water pump
PARTS	25/02/2026	Air cooled heat exchanger
PARTS	24/02/2026	Heat Exchanger
REPAIRS	16/02/2026	B service and diff oils.. windows not working.. ac not working.. fuel and adblue gauge not working.. clean truck inside
REPAIRS	13/02/2026	SWITCH ROCKER
REPAIRS	6/02/2026	Swivel

REPAIRS	6/02/2026	service
REPAIRS	4/02/2026	PIPE FITTINGS
REPAIRS	2/02/2026	HAND BRAKE NOT WORKING
REPAIRS	27/01/2026	Leaking Hydraulic hose repairs
REPAIRS	12/09/2025	fan belt and tensioner
EXTERNAL REPAIR	16/12/2024	Leaking water pump
REPAIRS	1/07/2024	Flat batteries, battewries U/S
SERVICE	22/02/2024	Minor service
REPAIRS	13/02/2024	Bonnet spring not working on latch properly
REPAIRS	6/02/2024	Door lock not working
REPAIRS	6/02/2024	Passenger side beacon needs globe
REPAIRS	6/02/2024	Small spring on bonnet catch
REPAIRS	1/02/2024	Waterpump not working
REPAIRS	12/01/2024	L/H flashing light not working
REPAIRS	12/01/2024	No spray fitting L/H rear lower
REPAIRS	11/01/2024	Hour metre not visable
REPAIRS	28/11/2023	Drivers window stuck down
REPAIRS	9/10/2023	Stuck spray fitting
REPAIRS	18/05/2023	Get vehicle ready for roadworthy and site ready
REPAIRS	10/03/2023	Right side window n/w Left side front wheel bearing hub cover plug missing, dirt contamination