

This live tracking will be terminated at: 10 Nov 2026 12:45

+
-



i

Location: 191 GEORGE ST, SCORESBY

Serial#: KMTWA120THA010653

Hour/Odometer: 8751

Next Service: 9500

Maintenance History

Type	Date	Comments
REPAIRS	27/05/2026	Carried out software update to repair low power fault codes present - MT Mechanical
REPAIRS	22/05/2026	Transmission oil overfull
PARTS	23/03/2026	Cap and cover
SERVICE	16/03/2026	1000hr service
PARTS	13/03/2026	Handle washer and lock
PARTS	12/03/2026	New edge plate
PARTS	27/02/2026	hyd hose and fittings
PARTS	25/02/2026	
REPAIRS	23/02/2026	BOLTS + WASHER
REPAIRS	16/02/2026	SERVICE
REPAIRS	13/02/2026	BOLT + NUT

REPAIRS	13/02/2026	SERVICE
REPAIRS	11/02/2026	Hydraulic components
REPAIRS	5/02/2026	Engine locked up
REPAIRS	21/01/2026	New battery.
PARTS	20/01/2026	Bolts / Washers
REPAIRS	21/11/2025	Rubber Sides
REPAIRS	22/10/2025	Repl EGR Cooler
OTHER	17/10/2025	Transport from Point Wilson to Heatherton.
SERVICE	1/10/2025	Service
REPAIRS	1/10/2025	Fit GET
REPAIRS	1/10/2025	Repl Seat Belt
REPAIRS	11/09/2025	4 NEW TYRES
REPAIRS	29/08/2025	Repl Heel Plates
SERVICE	25/08/2025	8000hr Service
REPAIRS	21/08/2025	Repl Door Cable
REPAIRS	25/07/2025	Repl Blower Motor - didn't need to be done
REPAIRS	30/06/2025	7500hr SVC
REPAIRS	28/04/2025	PUNCTURE REPAIR
SERVICE	26/03/2025	SERVICE KIT
REPAIRS	20/03/2025	NEW CUTTING BOLTS AND EDGES
REPAIRS	11/03/2025	CUTTING EDGES & BOLTS
REPAIRS	10/02/2025	
REPAIRS	7/02/2025	REPLACE BLOWN HOSE ON WL08
PARTS	21/01/2025	
DAMAGES	19/12/2024	Guards and steps bent Steering column lock useless
REPAIRS	13/11/2024	Aircon fan not working
REPAIRS	11/11/2024	Cutting edges
REPAIRS	11/11/2024	Right step bent, no climate control Low coolant (amber) showing. Coolant level to top mark.
SERVICE	30/10/2024	500hr service
REPAIRS	29/10/2024	Grease fittings
REPAIRS	17/10/2024	Front diff overfilling
RECORD 360	4/09/2024	Record 360
REPAIRS	7/08/2024	Broken Grease line
REPAIRS	7/08/2024	6000hr Service and repairs
REPAIRS	9/07/2024	Grease pot unit not working

REPAIRS	7/06/2024	Pre start faults - grease line has fallen off Two way radio not working
EXTERNAL REPAIR	15/05/2024	Flat tyre
REPAIRS	22/03/2024	Grease pump not working
REPAIRS	22/02/2024	Grease pot sight glass
REPAIRS	29/01/2024	Radio not working.
RECORD 360	19/12/2023	Record 360
EXTERNAL REPAIR	27/11/2023	Loadmaster recalibration
SERVICE	16/11/2023	500hr Service
PARTS	21/06/2023	ORDER NEW CUTTING EDGES AND HARDWARE FOR STOCK WL08
REPAIRS	16/06/2023	UHF hand piece not working
EXTERNAL SERVICE	26/05/2023	5000hr service komatsu wed 31/06/23
REPAIRS	16/05/2023	Bucket cylinder grease line damaged and nipple broken
SERVICE	23/02/2023	4750 hr service
REPAIRS	7/12/2022	isolator switch n/w at times @4844hrs
OTHER	5/07/2022	risk assessment