



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch		ATHABASCA		*REPRINT*	
Date	07/15/25	Time	20:03:10 (B)	Page	01
Account No.	INT02	Phone No.		Invoice No.	W23098
Ship Via		Purchase Order			
				Salesperson	252

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717 1E0D450XHBC381511	11/01/14	
	D450	456		

SEGMENT# 1 C A2 NA 06/17/25 06/17/25 .50 HRS
Replace cab filters

COMPLAINT:

4 years since last change

CORRECTION:

Remove cab filters and blow out filter box.
Install new filters and mark with hours.

ADDITIONAL DESCRIPTION:

Quote both cab filters

AH115833	FILTER	1	151.20	151.20
H220870	AIR FILTER	1	88.96	88.96
	PARTS			240.16
	LABOR			103.50
10100002	46001202	SEGMENT TOTAL==>		343.66

SEGMENT# 2 C A2 NA 06/17/25 06/17/25 .50 HRS
Replace fuel filters

COMPLAINT:

Not marked

CORRECTION:

Remove fuel filters and install new filters and bleed system.

ADDITIONAL DESCRIPTION:

Quote both fuel filters

EF100	ENVIRO FEE	1	1.00	1.00
EF50	ENVIRO FEE	2	.50	1.00
RE522878	FILTER ELEME	1	69.15	69.15
RE541922	Filter Element	1	69.10	69.10
R113565	PACKING	2	9.29	18.58

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch ATHABASCA		
Date 07/15/25	Time 20:03:10 (B)	Page 02
Account No. INT02	Phone No.	Invoice No. W23098
Ship Via	Purchase Order	
		Salesperson 252

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14	
	D450	456			
				PARTS	158.83
				LABOR	103.50
10100002	46001202			SEGMENT TOTAL==>	262.33

SEGMENT# 3 C A2 NA 06/17/25 06/17/25
Change engine oil and filter 1.00 HRS

COMPLAINT:

Machine sat without use. Need to change.

CORRECTION:

Drain engine oil and install new filter and oil.

Fill with 15w40 engine oil to spec.

Mark filter with hours.

ADDITIONAL DESCRIPTION:

Quote engine oil and filter

EF200	ENVIRO FEE	1	2.00	2.00
EF40	ENVIRO FEE	1	.40	.40
EF50	ENVIRO FEE	1	.50	.50
RE504836	OIL FILTER	1	40.13	40.13
R502513	SEAL	1	10.79	10.79
TY26673	4L 15W-40+50	1	39.03	39.03
	Plus-50 II Oil 15W40 CK4/SN			
TY26679	20L 15W40 +50	1	168.84	168.84
	Plus-50 II Oil 15W40 CK4/SN			
			PARTS	261.69
			LABOR	207.00
10100002	46001202		SEGMENT TOTAL==>	468.69

SEGMENT# 4 C A2 NA 06/17/25 06/17/25
Replace hydraulic filters 1.75 HRS

COMPLAINT:

CONTINUED ON PAGE 03

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch ATHABASCA			
Date 07/15/25	Time 20:03:10 (B)	Page 03	
Account No. INT02	Phone No.	Invoice No. W23098	
Ship Via		Purchase Order	
		Salesperson 252	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14	
	D450	456			

Not marked

CORRECTION:

Remove old hydraulic filters and install new ones and top up hydraulic oil.

Mark filters with hours.

ADDITIONAL DESCRIPTION:

Quote all hydraulic filters

128449	FILTER	1	150.91	150.91
	Hydraulic Filter			
AT318160	OIL FILTER	1	214.67	214.67
EF100	ENVIRO FEE	1	1.00	1.00
	PARTS			366.58
	LABOR			362.25
10100002	46001202	SEGMENT TOTAL==>		728.83

SEGMENT# 5 C A2 NA 06/17/25 07/10/25 .50 HRS

Replace engine air filters

COMPLAINT:

Past service interval

CORRECTION:

Remove engine air filters and install new and mark hours.

ADDITIONAL DESCRIPTION:

Quote both engine air filters

AFH203878	Electric Motor	1 N	1149.00	1149.00
AT300487	FILTER ELE	1	124.85	124.85
AT314583	FILTER ELE	1	78.28	78.28
	PARTS			1352.13
	LABOR			103.50
10100002	46001202	SEGMENT TOTAL==>		1455.63

CONTINUED ON PAGE 04

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch ATHABASCA		
Date 07/15/25	Time 20:03:10 (B)	Page 04
Account No. INT02	Phone No.	Invoice No. W23098
Ship Via		Purchase Order
		Salesperson 252

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14	
	D450	456			

SEGMENT# 6 C A2 NA 06/17/25 06/17/25

Replace canvas 2.00 HRS

COMPLAINT:

Holes in canvas, very little adjustment.

One was all ready change last fall in the field.

CORRECTION:

Remove right hand canvas.

Find that the idler roller bearings are gone.

Remove idler and bring to town.

Remove snap rings and end up having to weld out the bearings.

Install new bearings and snap rings.

install roller and torque to spec

Install new canvas and connector slats and hardware.

Tension to spec.

Run and re-tension to spec.

ADDITIONAL DESCRIPTION:

Quote one canvas and joiner strips.

AXE14731	Flat Belt	1	1556.73	1556.73
AXE50068	Ball Bearing	2	50.79	101.58
H169640	SCREW	7	3.70	25.90
H216391	Bar	2	86.58	173.16
N70171	Snap Ring	2	12.24	24.48
14M7528	LOCK NUT	7	1.40	9.80
34M7141	SPRING PIN	1	3.09	3.09

PARTS 1894.74

LABOR 414.00

10100002 46001202 SEGMENT TOTAL==> 2308.74

CONTINUED ON PAGE 05

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By

DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch		ATHABASCA	
Date	Time	Page	
07/15/25	20:03:10 (B)	05	
Account No.	Phone No.	Invoice No.	
INT02		W23098	
Ship Via		Purchase Order	
		Salesperson	
		252	

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14
	D450	456		

SEGMENT# 7 C A2 NA 06/17/25 06/17/25

Replace all cutter bar wear plates

6.00 HRS

COMPLAINT:

missing and damaged shoes and brackets - 5 hours

Will need to set knives after repair. - 1 hour

CORRECTION:

move each gard bolts and install new holders.

to install the A&i skid plates.

Find that the rear curl is not formed correctly.

End up having to grind out the back curl and every pad to correct and then install

This is why it took extra time.

Install as needed and in proper orientation.

ADDITIONAL DESCRIPTION:

Quote all bottom skid plates

Quote retaining brackets

A-H231521	Shoe	23 N	37.61	865.03
A-H231522	Shoe	4 N	59.35	237.40
A-H241108	Bracket	60 N	19.13	1147.80
FRT	FREIGHT	1	51.00	51.00
H231523	SHOE	2 N	42.44	84.88
03M7192	BOLT	10	2.49	24.90
03M7194	BOLT	10	3.54	35.40
14M7296	FLANGE NUT	20	3.22	64.40

PARTS 2510.81

LABOR 1680.84

10100002	46001202	SEGMENT TOTAL==>	4191.65
----------	----------	------------------	---------

SEGMENT#	8	C	A2	NA	06/17/25	06/17/25
----------	---	---	----	----	----------	----------

Planetary oil

1.50 HRS

CONTINUED ON PAGE 06

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By _____



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch ATHABASCA		Page 06	
Date 07/15/25	Time 20:03:10 (B)		Invoice No. W23098
Account No. INT02	Phone No.	Purchase Order	
Ship Via		Salesperson 252	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14	
	D450	456			

COMPLAINT:

Change Planetary Oils

CORRECTION:

Drain both final drives and fill with 80w90 gear oil to spec.

ADDITIONAL DESCRIPTION:

ote oil for planetaries

10	ENVIRO FEE	1	.10	.10
EF40	ENVIRO FEE	1	.40	.40
TY26815	4L 80W90GEAROIL	1	53.47	53.47
TY6296	1L 80W-90	1	16.51	16.51
	PARTS			70.48
	LABOR			310.50
10100002	46001202	SEGMENT TOTAL==>		380.98

SEGMENT# 9 C A2 NA 06/17/25 07/09/25

Travel to Customers

2.00 HRS

COMPLAINT:

Travel to customers to complete repairs.

17.5 Hours = 2 trips = 2 hours

ADDITIONAL DESCRIPTION:

Load and travel out to Brian's July9/25

Get more parts as needed and travel out to farm. July 10/25
July 11/25

Travel back to Brian's to install the rotary screen motor.

Note that there is three times traveling.

10100002	46001202	LABOR	414.00
SEGMENT TOTAL==>			414.00

SEGMENT#10 C A2 NA 06/17/25 07/11/25

CONTINUED ON PAGE 07

I
err
pa
Lie
con
stor

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE



Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch ATHABASCA			
Date 07/15/25	Time 20:03:10 (B)	Page 07	
Account No. INT02	Phone No.	Invoice No. W23098	
Ship Via		Purchase Order	
		Salesperson 252	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14	
	D450	456			

Service truck Fee- \$250.00

COMPLAINT:

Service truck Fee- \$250.00

SEGMENT#11 C A2 NA 06/17/25 07/10/25

Rotary Screen

COMPLAINT:

C 520825.16

High Current code.

CORRECTION:

Preform test needed for code.

Find that the motor is failed.

Order in new motor.

Drive back out to Brian's and install new rotary screen motor.

And install drive chain. And run test to make sure all is good.

Return and complete work order.

10100002

46001202

LABOR	710.01
SEGMENT TOTAL==>	710.01

SEGMENT#12 C A2 NA 06/17/25 07/10/25

Oil leak on Header Hyd Motor

COMPLAINT:

There is a oil leak on header hydraulic motor.

CORRECTION:

Clean up oil around motor and gear box.

Run unit and can not locate a leak.

Note that the motor was off and reconditioned.

I think that it was residual from before. Because it never

CONTINUED ON PAGE 08

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By

pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By



DEERLAND EQUIPMENT

2101 - 48 Avenue
Athabasca, AB T9S 0B8
(780) 675-2256 • Fax: (780) 675-3844
www.deerland.ca



JOHN DEERE

Ship To: BRIAN BAHRY Internal Repair

Invoice To: ATHABASCA INTERNAL USE
AB

Branch ATHABASCA			
Date 07/15/25	Time 20:03:10 (B)	Page 08	
Account No. INT02	Phone No.	Invoice No. W23098	
Ship Via		Purchase Order	
		Salesperson 252	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
0381511B	D450 SP WINDROWER	717	1E0D450XHBC381511	11/01/14	
	D450	456			

got washed off when they took it out to lend.
Brian will watch and make sure its not leaking, and let us know.

10100002	46001202	LABOR	20.70
		SEGMENT TOTAL==>	20.70

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	6855.42	
LABOR	4429.80	
SERV VEH #1	250.00	
INTERNAL TOTAL	11535.22	

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express Mechanic's Lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing.

X

Received By