



Vehicle History Detail

Fleet #	
Registration	
Make	DAF
Model	TRUCK
VIN / Chassis #	XLRTTM430LG323712

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
24/07/2026	619,157 kms	DECOMMISSION R-65853 Another set of two batteries replaced on XO23CH			\$231.00
30/03/2026	1 kms	C - 100K/365Days S-27351 C SERVICE	GILBERT & ROACH - 10		\$3,717.69
02/12/2025		TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2624 Inspection carried out on the truck respectively as per the Job card description			\$154.00
23/11/2025	588,478 kms	ENGINE DERAT R-52529	GILBERT & ROACH - 10		\$4,597.60
22/11/2025	588,452 kms	A - 10K/90Days S-26257 A service completed ☒	GILBERT & ROACH - 10		\$1,327.72
07/11/2025	587,415 kms	MARKER PLATES R-51856 Replace MARKER PLATES			\$133.36
29/10/2025	576,555 kms	DERATING R-52513 Replace DPF exhaust	GILBERT & ROACH - 10		\$892.95
20/10/2025	576,533 kms	DPF FAULT R-50802			\$2,082.44
20/10/2025	576,249 kms	B - 20K/180Days S-25512 B SERVICE Replaced top plate of the fifth wheel.	GILBERT & ROACH - 10		\$1,006.40
30/09/2025	569,631 kms	DERATING R-50164			\$154.00
19/09/2025		CRACKED WINDSCEEN R-48159	SOUTHWEST AUTOGLASS - 10		\$880.00
14/09/2025	545,560 kms	ENGINE OVER HEATING R-49252 Pulled out radiator and intercooler and sent for cleaning and inspection replace radiator and thermostat . Done replace radiator and thermostat and power steering stick . . Done Final inspection done check all the clamps check all the coolant hose . check coolant level. check for coolant leak. Drive test done. check for high temperature it's good. Done	GILBERT & ROACH - 10		\$12,372.70

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/09/2025	545,560 kms	A - 10K/90Days S-24743 A SERVICE replaced steer tyres			\$385.00
10/09/2025	545,560 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2443 Annual inspection done			\$0.00
08/09/2025	557,412 kms	B - 20K/180Days S-24297 B SERVICE			\$921.53
20/08/2025	557,412 kms	CHECK TYRE R-48158			\$1,508.01
04/08/2025	549,270 kms	A - 10K/90Days S-23931			\$154.00
24/07/2025	509,334 kms	FUEL CROSSOVER HOSE R-46999 XO23CH fabricate cross bar and bypass fuel from tank A to tank B	SWAN HYDRAULICS PTY LTD - 10		\$1,262.25
19/07/2025	905,334 kms	Fault T-12922 Replace drive tyres with new Roadone. Done			\$308.00
10/07/2025	509,334 kms	B - 20K/180Days S-23526 B service completed ☒ Repair air leaks done clean fuel tank bleeder . Done			\$914.18
30/06/2025	509,334 kms	AIR LEAK, FAULT REPORT, FUEL TANK ISSUES, REVERSE LIGHT R-46373 Repair air leak Repair broken wire for reverse light			\$154.00
24/06/2025	545,020 kms	Broken Spring R-44471 Replace RS Spring Packs . Done Replace rear axle worn tyres with new haulster. Done Check over . Done XO23CH KM(545020)			\$0.00
28/05/2025	519,496 kms	A - 10K/90Days S-22622 A service done			\$231.00
07/05/2025	434,711 kms	FAULT REPORT, LIGHT R-43434 Replace Light on bull bar drivers side . Done			\$154.00
01/05/2025	506,215 kms	C - 100K/365Days S-22089 C service completed Annual inspection done Replace Knock sensor . Done			\$1,438.02
30/04/2025	434,711 kms	NOX SENSOR R-43082 Replace knock sensor done			\$154.00
03/04/2025	494,017 kms	BATTERY BOX, FAULT REPORT, OVERHEATING R-41902	GILBERT & ROACH - 16		\$1,976.01
03/04/2025	494,017 kms	FAULT REPORT, OVERHEATING R-40688 Tested Bluetooth and the mic is operating fine. Turned down mic gain as it was too high. - Topped up coolant, unable to see any leaks - Ordered new Nox sensor			\$693.00
03/04/2025	456,234 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2245 Annual inspection done			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
02/04/2025	494,017 kms	A - 10K/90Days S-21595 - Handbrake alarm inop			\$308.00
18/03/2025	1,096,032 kms	BULLBAR INDICATORS INOP R-41123 Checked bullbar indicator, all ok			\$38.50
10/03/2025	434,711 kms	B - 20K/180Days S-21093 B service completed ☒			\$760.18
14/02/2025	470,836 kms	A - 10K/90Days S-20626 A service done found out from spring shackle bush worn			\$154.00
31/01/2025	454,000 kms	MISSFIRE, OIL LEAK R-38968	GILBERT & ROACH - 10		\$28,521.61
23/01/2025	460,410 kms	B - 20K/180Days S-20254 B service completed ☒			\$1,010.25
16/01/2025	457,214 kms	FAULT REPORT R-38616 Replace tail light RS . Done			\$77.00
28/11/2024	453,866 kms	A - 10K/90Days S-19228			\$231.00
01/11/2024	440,979 kms	FAULT REPORT R-36377			\$544.04
31/10/2024	440,921 kms	B - 20K/180Days S-18629 1. Carried out B service 2. Replaced broken fitting of wiper washer hose			\$756.47
10/10/2024	430,602 kms	A - 10K/90Days S-18236			\$231.00
16/09/2024	419,521 kms	FAULT REPORT R-34028 Replaced windscreen washer hose adaptor			\$192.13
16/09/2024	419,612 kms	WATER PUMP LEAKING R-33133			\$2,542.19
12/09/2024	418,421 kms	B - 20K/180Days S-17659 Completed B service			\$756.47
11/09/2024	417,376 kms	FAULT REPORT, WINDSCREEN CRACKED R-32894	SOUTHWEST AUTOGLASS - 10		\$880.00
30/08/2024	411,940 kms	AIR LEAK, FAULT REPORT R-32204			\$183.34
30/08/2024	411,940 kms	A - 10K/90Days S-17379 A service carried out on the truck respectively as per the job card description.			\$308.00
12/08/2024	203,360 kms	C - 100K/365Days S-16823 C service done			\$3,631.07
17/07/2024	392,429 kms	FAULT REPORT R-30848 Replaced suzi coil with a new one.			\$154.00
16/07/2024	392,394 kms	FAULT REPORT R-30135 RESET ALL ABS SENSORS AND TESTED , ALL ABS WARNING WENT OUT			\$154.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/07/2024	1 kms	A - 10K/90Days S-15837	KJS FLEET MAINTENANCE - 10		\$132.00
28/05/2024	367,366 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-1642 c/o inspection JOBCARD WAS NOT FILLED OUT OR SIGNED - JOB COMPLETED ON THE 08/06 SIGNED OFF BY STEPH			\$0.00
28/05/2024	375,254 kms	FAULT REPORT R-27759 WENT INTO GILBERT AND ROACH FOR REPAIRS			\$77.00
28/05/2024	377,604 kms	B - 20K/180Days S-14973 c/o service			\$1,253.07
21/05/2024	377,321 kms	ENGINE MALFUNCTION R-27431 engine light was on for low oil level , top up oil level to full and fault cleared itself			\$308.00
10/05/2024	367,394 kms	WARRANTY R-28758 ALL PARTS REPLACED UNDER WARRANTY BY GILBERT & ROACH	GILBERT & ROACH - 10		\$1,222.10
06/05/2024	367,435 kms	COOLANT LEAK R-24717 NILESH INSPECTED VEHICLE AND STATED THAT COOLANT LEAKING FROM HEAD TRUCK HAS GONE INTO GILBERT AND ROACH HUNTINGWOOD FOR REPAIRS. CHECK OVER TRUCK BEFORE RETURN TO WORK	GILBERT & ROACH - 10		\$154.00
08/04/2024		NEW T-4702 SUPPLY AND FIT TYRES AS NEEDED PLEASE SEE ATTACHED INVOICE	WESTERN SUBURBS TYRE SERVICE PTY LTD		\$1,560.00
08/04/2024	265,616 kms	NEW T-7720 SUPPLY AND FIT TYRES AS NEEDED PLEASE SEE ATTACHED INVOICE	WESTERN SUBURBS TYRE SERVICE PTY LTD		\$2,420.00
14/03/2024	367,361 kms	A - 10K/90Days S-13410 A serves completed Coolant leaking from the gasket head			\$308.00
21/02/2024	357,456 kms	B - 20K/180Days S-13025			\$439.24
21/02/2024	357,456 kms	FAULT REPORTS R-23855 - Removed tyres and inspected rotors, no deep cracks found. Within specs. - Drivebelts checked by Steve - Carried out puncture repair on LH 3rd axle inner tyre			\$531.30
03/02/2024	358,074 kms	BATTERIES R-23053 replace both battery's at pace and check charge rate after repair carried out			\$1,273.49
17/01/2024	1 kms	A - 10K/90Days S-12379 MAINTENANCE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$242.00
04/01/2024	2,033,600 kms	FAULT REPORT R-21218 LIGHT BULBS REPLACED ON SERVICE MUDGUARDS AND WIPHER BLADES ON ORDER Drive to Pace Replaced both wiper blades Replaced P/S rear mudguard top cover Replaced D/S rear mudguard top cover			\$154.00
21/12/2023	333,723 kms	B - 20K/180Days S-11840 B SERVICE CARRIED OUT BY VINCE WIPHER BLADES AND 2 TOP REAR MUDGUARDS ON ORDER			\$1,343.90

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
07/12/2023	333,723 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-1342 INSPECTION CARRIED OUT BY VINCET BERRY(NO GEARBOX LOGIN)			\$0.00
22/11/2023	1 kms	A - 10K/90Days S-11377 MAINTENANCE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$242.00
27/10/2023		A - 10K/90Days S-10939	KJS FLEET MAINTENANCE - 10		\$121.00
27/10/2023	309,200 kms	C - 100K/365Days S-10875			\$1,410.13
10/10/2023	301,975 kms	FUEL TANK STRAP R-18532 REPLACE FUEL TANK STRAP, RUBBER AND PINS			\$77.00
26/09/2023		A - 10K/90Days S-10386 SERVICE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$121.00
31/08/2023	285,115 kms	FAULT REPORT R-17226 Repair RHS madguard damage done			\$77.00
31/08/2023	285,115 kms	B - 20K/180Days S-9924 B SERVICE COMPLETE DONE			\$747.24
18/08/2023	1 kms	A - 10K/90Days S-9637 SERVICE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$121.00
02/08/2023	1 kms	A - 10K/90Days S-9432 SERVICE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$121.00
19/07/2023	1 kms	A - 10K/90Days S-9209 (A) SERVICE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$121.00
11/07/2023	262,507 kms	MUDFLAP, MUDGUARD R-12011 Replaced LHS Mudguard Installed New 1st axle mudflaps Tightened Fuel tank straps			\$570.15
07/07/2023		NEW T-6012 TYRES SUPPLIED AND FITTED BY WST - PLEASE SEE THE ATTACHED INVOICE	WESTERN SUBURBS TYRE SERVICE PTY LTD		\$2,160.00
04/07/2023		A - 10K/90Days S-9006	KJS FLEET MAINTENANCE - 10		\$440.00
24/06/2023	662,211 kms	RUNOUT T-4512 Drive to pace for truck have damage tyre rear LHS inner remove tyre drive to work shop fit good runout tyre back to pace fit tyre done Note all drive tyre and rims need replace			\$0.00
23/06/2023	203,360 kms	A - 10K/90Days S-8741 (A) SERVICE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$242.00
05/05/2023		A - 10K/90Days S-7879			\$121.00
04/04/2023	221,236 kms	REPAIRS R-12880 Replace air dryer filters new one done Replace power steering filter new one done			\$591.39

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
04/04/2023	221,236 kms	B - 20K/180Days S-7422 B SERVICE COMPLETE DONE CABIN FILTER ALSO REPLACED			\$30.22
08/03/2023	210,211 kms	A - 10K/90Days S-7024 MAINTENANCE CARRIED OUT BY KJS			\$242.00
16/02/2023	200,417 kms	C - 100K/365Days S-6660 C SERVICE COMPLETE DONE Dryer filters not available steering filter not available Broken madguard front LHS			\$521.15
24/01/2023		CRACKED WINDSCREEN R-20225 WINDSCREEN REPLACED BY SOUTHWEST AUTOGLASS	SOUTHWEST AUTOGLASS - 10		\$1,507.00
24/01/2023	190,114 kms	MUDGUARD R-10352 Replaced all damaged fuel tank rubbers Replace LHS spotter mirror Replace mug guard top on rear axle			\$2,021.70
12/01/2023	184,055 kms	A - 10K/90Days S-6102 Carryout A Srevice as per check sheet. DONE. RHS fuel tank J bracket rubber damage. Wimd screen has multiple cracks. LHS rear view mirror damage. LHS &RHS rear mudguards worn and got hole.			\$0.00
12/01/2023	182,991 kms	EXTERNAL REPAIR R-36128 REPAIRS CARRIED OUT BY GILBERT AND ROACH UNDER WARRANTY.	GILBERT & ROACH - 10		\$0.00
15/12/2022	173,457 kms	TRAILER ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-654			\$0.00
15/12/2022	173,457 kms	B - 20K/180Days S-5705 B SERVICE COMPLETE DONE Rear RHS mudguards worn-out			\$473.36
02/11/2022	1 kms	A - 10K/90Days S-5029			\$0.00
25/10/2022	150,652 kms	WHEEL ALIGNMENT T-11800 PRO-AXLE TO CARRY OUT WHEEL ALIGNMENT. JOB COMPLETED. INVOICE RECIEVED.	PRO-AXLE SMITHFIELD		\$660.00
28/09/2022	1 kms	A - 10K/90Days S-4448	KJS FLEET MAINTENANCE - 16		\$220.00
24/09/2022	137,317 kms	TYRE REPLACEMENTS T-10015 JOB COMPLETED, INVOICE RECIEVED.	WESTERN SUBURBS TYRE SERVICE PTY LTD		\$1,873.00
03/08/2022	1 kms	A - 10K/90Days S-4636 MAINTENANCE CARRIED OUT BY KJS	KJS FLEET MAINTENANCE - 10		\$55.00
97 Records				Total:	\$105,540.55