



Vehicle History Detail



Fleet #	DOZ1
Registration	
Make	Caterpillar
Model	D8T
VIN / Chassis #	CAT00D8TCJJ501376 / JJ501376T00D8T

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		body repairs R-2720	Internal Workshop		\$920.00
06/03/2026	8,014 hrs	solenoid R-2689 Replace Rh hydronic steering solenoid	Internal Workshop		\$408.44
16/02/2026	8,014 hrs	D - 2000hrs S-1122 Removed skid plates washed all bottom of engine an gearbox from underneath, washed skid plates Drop final drive/hub oils, took oil samples and replaced drive/hub oils Dropped and replaced engine oil took oil sample replaced engine oil filter Replaced both hydraulic oil filters took sample of hydraulic oil Took coolant samples Put seat back Put skid plates back Kane replaced RH steering solenoid	Internal Workshop		\$1,647.12
19/06/2025		hydraulic hoses R-2262 REPLACED HOSE AND FILL WITH HYDRAULIC OIL	Internal Workshop		\$1,444.41
28/01/2025	7,659 hrs	A - 250hrs S-878 CARRY OUT 250H SERVICE INSPECT AND REPAIR ELECTRICAL JOYSTICK			\$1,384.40
10/12/2024		Electrical R-2111	Internal Workshop		\$453.16
19/09/2024	7,626 hrs	CALLOUT R-1829 - Inspected oil pressure fault - Checked plug/wiring going to sensor - Oil pressure resting as it should and code inactive - Took oil sample as requested - Operator worked machine for day and had no issue.	Steady Contracting		\$341.00
17/09/2024		Parts Only R-1790 SUPPLIED RIPPER TYNE PARTS			\$1,740.20
06/09/2024	7,495 hrs	Electrical R-1764 - Travel from Weipa to Jardine - Remove belly guards and side pannels - Remove electrical/battery cables to access starter motor - Remove and refit new starter motor - Rewire start relay - Refit belly guards and panels - Test machine - Replace transmission oil	Steady Contracting		\$8,584.29

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
05/09/2024	7,545 hrs	Electrical R-1759 - Travel up to Jardine - Inspect low voltage fault - Found alternator failed main bearing and worn bushes - Check battery and they had failed due to alternator - Travel back to Weipa 21/08/24 - Travel to Jardine - Fit new alternator - Fit new starter relay - Fit new main power relay and tighten up bogie pin covers - Drop belly guards to change out 2x trans hoses - Run up and check oil - Check alternator is charging - Fit new batteries - Travel back to Weipa	Steady Contracting		\$17,641.18
09/08/2024	7,510 hrs	B - 500hrs S-808 CARRIED OUT 500HR SERVICE REPLACED FINAL DRIVE OIL REPLACED ENGINE OIL AND FILTERS REPLACED FUEL FILTERS REPLACED TRANS FILTER REPLACED AIR FILTER REPAIRED EXHAUST TENSIONED TRACKS GREASED AS REQUIRED	Steady Contracting		\$6,365.33
10/07/2024		CALLOUT R-1617 TRAVEL TO JARDINE AND REPLACE TRANSMISSION LINE.TEST OPERATION AND FILL WITH TRANS OIL. REFIT BASH PLATES	Steady Contracting		\$7,944.86
24/06/2024		Safety Equip R-1554	Internal Workshop	16195418	\$197.93
21/06/2024	7,316 hrs	Electrical R-1458 DIAGNOSE AND REPAIR INTERMITTANT ENGINE STOPPING.TRANCE FAULT TO FAULTY MAIN POWER RELAY. REPLACED RELAY AND SECURE WIRING.TEST OK. TENSIONED TRUNNION BOLTS	Internal Workshop		\$3,983.78
30/05/2024	7,210 hrs	COOLING SYSTEM R-1477 REMOVE AND REPLACE COOLANT LINE FABRICATED BY CGD. FILL COOLANT AND BLEED SYSTEM.TEST RUN TO TEMPERATURE OK.	Internal Workshop		\$345.50
30/05/2024	7,205 hrs	Engine R-1447 Work shop labour CAT D8T Dozer 7205hrs Travel to agget creek. To replace fan belt and idler, found another idler bearing failed. Travel back to Georgetown. Machine new spacer for idler Get new bearings for idler. Travel back to site. Fit fan belt and idlers.	Internal Workshop		\$4,328.54
16 Records				Total:	\$57,730.14