

E05-1



# WORK ORDER

DATE: Nov 8 2202	ODOMETER:
EQUIPMENT: BC 2	HOURS: 3672

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Fuel gauge not working.	3672	Nov 8/2022

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Troubleshoot and repair wire connection going to the fuel sender gauge in tank.		5



# WORK ORDER

DATE: June 7/ 2022	ODOMETER:
EQUIPMENT: BC 2	HOURS: 3565

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Hose leaking	3565	June 7/2022

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Changed out worn O ring on pump drive motor.		3



# WORK ORDER

DATE: March 17/2022	ODOMETER:
EQUIPMENT: BC 2	HOURS: 3556

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Get small leaks repaired. Leaking valve cover gasket. Hose on pump leaking. Travel pump leaking at fitting.	3556	Mar/22/22

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Remove valve cover gasket and change out with new, intall new gaskets for glow plug seals and new o rings on injector caps.  Remove pump and install new O Rings on pump valve body.  Install new hose for travle motor.  clean unit up and get ready for sale.		18



# WORK ORDER

DATE:	Jan 29/2021	ODOMETER:	
EQUIPMENT:	BC 2	HOURS:	3467

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Service unit	Jan 29/2021	Jan29/2021

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Change engine oil and filter change fuel filter change inline fuel filter. Grease unit.	8	

PART DESCRIPTION	PART NUMBER	QTY.	COST	OIL/COOLANT USED	Unit	QTY.	COST
oil filter	B34	1	\$ 6.21	COOLANT	Ltr		
fuel filter	BF 1257	1	#N/A	DURON 10/40	Ltr	10	\$ 65.00
				DURON 0/30			
				DURATRAN	Ltr		
				HEAVY DUTY ATF			
				TRAXON 75/90	Ltr		
				TRAXON 80/140	Ltr		
				TRAXON CD50	Ltr		
				HYDREX XV ALL SEASON	Ltr		
				VALPAR ISO46	Ltr		
				JD HYGUARD TRANS OIL			
				WERGEN SPECIAL GEAR OIL			
				PRODURO TO-4+10W	Ltr		
				PRODURO TO-4+30W	Ltr		
				PRODURO TO-5+50W	Ltr		
				TURBOFLO R&O 68			
				BRAKE FLUID			
				DIESEL			



# WORK ORDER

DATE: Aug 10/2020	ODOMETER:
EQUIPMENT: BC2	HOURS: 3342

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Unit running out of hyd power when loaded up.	3342	Aug 25/2020

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Remove cover assy to gain acces to hyd drive belt. Tighten up pump drive belts and idler, pully. Test out unit and seems to be good now.  Replace cabin fiter replace air filter. Wash and grease unit.		5

PART DESCRIPTION	PART NUMBER	QTY.	COST	OIL/COOLANT USED	Unit	QTY.	COST
				COOLANT	Ltr		
				DURON 10/40	Ltr		
				DURON 0/30			
				DURATRAN	Ltr		
				HEAVY DUTY ATF			
				TRAXON 75/90	Ltr		
				TRAXON 80/140	Ltr		
				TRAXON CD50	Ltr		
				HYDREX XV ALL SEASON	Ltr		
				VALPAR ISO46	Ltr		
				JD HYGUARD TRANS OIL			
				WERGEN SPECIAL GEAR OIL			
				PRODURO TO-4+10W	Ltr		
				PRODURO TO-4+30W	Ltr		
				PRODURO TO-5+50W	Ltr		
				TURBOFLO R&O 68			
				BRAKE FLUID			
				DIESEL			



# WORK ORDER

DATE:	Nov 19 2019	ODOMETER:	
EQUIPMENT:	BC2	HOURS:	3162

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Quick attach worn out. Boom support arms are loose in the bores. Tilt cylenders have play in rod end. Go over unit	3162	Dec12 2019

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Install new pins and bushings on tilt cylender rod ends. Install all new Bob Tech parts for quick attach. Remove boom arm suport lineage bars and take them to Davis Mechine for meching re- install them back on unit with new pins Install new Egr cooler hose and clamps on egr valve. Tap out grease zerk holes in boom so they can take a zerk. Strighten out gril guard for rad. Install new head light and get reverse lights working. Remove ac pump change belt and re install. Install coolant drain plug adapter kit with new hose and clamps.		41

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
		\$ 1,350.00	COOLANT DURON 10/40 DURON 0/30 DURATRAN HEAVY DUTY ATF TRAXON 75/90 TRAXON 80/140 TRAXON CD50 HYDREX XV ALL SEASON VALPAR ISO46 JD HYGUARD TRANS OIL WERGEN SPECIAL GEAR OIL PRODURO TO-4+10 PRODURO TO-4+30 PRODURO TO-4+50 TURBOFLO R&O 68 BRAKE FLUID DIESEL		



# WORK ORDER

DATE: May 28/2020	ODOMETER:
EQUIPMENT: BC 2	HOURS: 3269

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Track fell off Front window wiper blade . And weather strip.		May28 2020

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Install track back on skid steer. Replace window wiper on unit and fix weather strip on door.		2

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
			COOLANT DURON 10/40 DURON 0/30 DURATRAN HEAVY DUTY ATF TRAXON 75/90 TRAXON 80/140 TRAXON CD50 HYDREX XV ALL SEASON VALPAR ISO46 JD HYGUARD TRANS OIL WERGEN SPECIAL GEAR OIL PRODURO TO-4+10 PRODURO TO-4+30 PRODURO TO-4+50 TURBOFLO R&O 68 BRAKE FLUID DIESEL		



# WORK ORDER

DATE: Nov 19 2019	ODOMETER:
EQUIPMENT: BC2	HOURS: 3162

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
1000 HR PM	3162	Nov27 19

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Change engine oil and engine filter Change fuel filter Change hyd charge filter Change hyd oil and hyd filter Clean hyd fluid screen Change case drain filters check hyd reservoir breather Change coolant Change primary and secondary air filters Change both cab filters Check hydro motor carrier oil check battery Check drive sprockets and tracks Grease mechine	10	

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
B34	1	\$ 6.21	COOLANT	12	
BT8840MPG	1	\$ 9.67	DURON 10/40	10	
7025626	1	\$ 74.56	DURON 0/30		
6992337	1	\$ 74.56	DURATLAN	20	
BF1257	1	\$ 17.34	HEAVY DUTY ATF		
RS5741	1	\$ 37.28	TRAXON 75/90		
RS5742	1	\$ 18.14	TRAXON 80/140		
PA5618	1	\$ 33.84	TRAXON CD50		
PA5625	1	\$ 26.94	HYDREX XV ALL SEASON		
7012314	2	\$ 149.12	VALPAR ISO46		
			JD HYGUARD TRANS OIL		
			WERGEN SPECIAL GEAR OIL		
			PRODURO TO-4+10		
			PRODURO TO-4+30		
			PRODURO TO-4+50		
			TURBOFLO R&O 68		
			BRAKE FLUID		
			DIESEL		



Developments Ltd.

# WORK ORDER

DATE:	Nov 6 2019	ODOMETER:	
EQUIPMENT:	BC2	HOURS:	3160

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Track change	3160	Nov 6 2019

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Change out summer tracks for winter ones.	2	



# WORK ORDER

DATE: t 17 2019			
EQUIPMENT:	BC 2 190 Skidsteer	ODOMETER:	
		HOURS:	3147

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Unit will crank over and then blow 30 amp fuse and will not start	3147	Oct 17 201

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Troubleshoot unit and found faulty fuel shut off solenoid. Changed solenoid		3

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
Solenoid	1	324.43	COOLANT		
O ring	1	4.15	DURON 10/40		
			DURON 0/30		
			DURATRAN		
			HEAVY DUTY ATF		
			TRAXON 75/90		
			TRAXON 80/140		
			TRAXON CD50		
			HYDREX XV ALL SEASON		
			VALPAR ISO46		
			JD HYGUARD TRANS OIL		
			WERGEN SPECIAL GEAR OIL		
			PRODURO TO-4+10		
			PRODURO TO-4+30		
			PRODURO TO-4+50		
			TURBOFLO R&O 68		
			BRAKE FLUID		
			DIESEL		

# WORK ORDER — KH DEVELOPMENTS LTD

DATE: 8.7.19	FLEET #: BC2
MACHINE: BOBCAT T190	ODOMETER:
WRITTEN BY:	HOURS: 3055

PROBLEM OR FAULT	HOURS COMPLETED	DATE REPAIR COMPLETED
HYDRAULIC OIL LEAK	3055	9.7.19

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
REMOVED CONTROL VALVE AND RESEALED TILT AND BOOM CONTROL VALVE.		16



# WORK ORDER - KH DEVELOPMENTS LTD

DATE: 20.6.19	FLEET #: BC2
MACHINE: BOBCAT T190	ODOMETER:
WRITTEN BY:	HOURS: 3039

PROBLEM OR FAULT	HOURS COMPLETED	DATE REPAIR COMPLETED
REPLACE IDLER PULLEY AND DRIVE BELT	3039	21.6.19

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
INSTALLED NEW DRIVE BELT AND IDLER PULLEY. SET UP DRIVE BELT TENSION		5

