

E05-2



# WORK ORDER

DATE: Feb 10/2022	ODOMETER:
EQUIPMENT: D 2	HOURS: 5339

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Complete undercarage on unit. (both sides)	5339	Feb10/2022

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
R and R undercarage. And perform all tasks welding extra when tracks are off.  Complete undercarage changed out everything.	160	

PART DESCRIPTION	PART NUMBER	QTY.	COST	OIL/COOLANT USED	Unit	QTY.	COST
COMPLETE UNDERCARGAGE			#####	COOLANT	Ltr		
				DURON 10/40	Ltr		
				DURON 0/30			
				DURATRAN	Ltr		
				HEAVY DUTY ATF			
				TRAXON 75/90	Ltr		
				TRAXON 80/140	Ltr		
				TRAXON CD50	Ltr		
				HYDREX XV ALL SEASON	Ltr		
				VALPAR ISO46	Ltr		
				JD HYGUARD TRANS OIL			
				WERGEN SPECIAL GEAR OIL			
				PRODURO TO-4+10W	Ltr		
				PRODURO TO-4+30W	Ltr		
				PRODURO TO-5+50W	Ltr		
				TURBOFLO R&O 68			
				BRAKE FLUID			
		DIESEL					



# WORK ORDER

DATE: April 29/2021	ODOMETER:
EQUIPMENT: D2	HOURS: 5294

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Unit over heating and leaking oil.	5294	April29/2021

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Check into over heating issue, found leaking hose that the fan was blowing oil into the rad plugging up rad fins and causing a over heat problem.  Replace hose and spit rads to clean out fins, top up with coolant and check over. Units seems to be working fine now.	10	

PART DESCRIPTION	PART NUMBER	QTY.	COST	OIL/COOLANT USED	Unit	QTY.	COST
				COOLANT	Ltr	10	\$ 24.70
				DURON 10/40	Ltr		
				DURON 0/30			
				DURATRAN	Ltr		
				HEAVY DUTY ATF			
				TRAXON 75/90	Ltr		
				TRAXON 80/140	Ltr		
				TRAXON CD50	Ltr		
				HYDREX XV ALL SEASON	Ltr		
				VALPAR ISO46	Ltr		
				JD HYGUARD TRANS OIL			
				WERGEN SPECIAL GEAR OIL			
				PRODURO TO-4+10W	Ltr		
				PRODURO TO-4+30W	Ltr		
				PRODURO TO-5+50W	Ltr		
				TURBOFLO R&O 68			
				BRAKE FLUID			
				DIESEL			



# WORK ORDER

DATE:	June 8 2020		
EQUIPMENT:	D2	HOURS:	5087

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Right side sprocket segments broke off. Turbo feed line leaking.	5087	June8/2020

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Remove segments from sprocket and drill and tap brocken bolts out of carrier. Install new bolts and torque to spec.  Install new turbo feed line on unit.		12

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
bolts	25	\$45.50	COOLANT		
turbo hose and o rings	1	\$105.68	DURON 10/40		
			DURON 0/30		
			DURATRAN		
			HEAVY DUTY ATF		
			TRAXON 75/90		
			TRAXON 80/140		
			TRAXON CD50		
			HYDREX XV ALL SEASON		
			VALPAR ISO46		
			JD HYGUARD TRANS OIL		
			WERGEN SPECIAL GEAR OIL		
			PRODURO TO-4+10		
			PRODURO TO-4+30		
			PRODURO TO-4+50		
			TURBOFLO R&O 68		
			BRAKE FLUID		
			DIESEL		



# WORK ORDER

DATE: May 26/2020	ODOMETER:
EQUIPMENT: D2	HOURS: 5056

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Batterys not holding charge		May 25/2020

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Replace batterys	3	

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
Battery	2	\$230.00	COOLANT DURON 10/40 DURON 0/30 DURATRAN HEAVY DUTY ATF TRAXON 75/90 TRAXON 80/140 TRAXON CD50 HYDREX XV ALL SEASON VALPAR ISO46 JD HYGUARD TRANS OIL WERGEN SPECIAL GEAR OIL PRODURO TO-4+10 PRODURO TO-4+30 PRODURO TO-4+50 TURBOFLO R&O 68 BRAKE FLUID DIESEL		



Developments Ltd.

# WORK ORDER

DATE: March 4/2020	ODOMETER:
EQUIPMENT: D2	HOURS:

PROBLEM OR FAULT	HRS COMPLETED	DATE COMPLETED
Battery's not charging.		

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
Trouble shoot charging system and found cables to be at fault. Remove cables and install new ones. Check charging system and it seems to be charging good now. (28.2 volts)		6

PARTS USED	QTY.	COST	OIL/COOLANT USED	QTY.	COST
			COOLANT DURON 10/40 DURON 0/30 DURATRAN HEAVY DUTY ATF TRAXON 75/90 TRAXON 80/140 TRAXON CD50 HYDREX XV ALL SEASON VALPAR ISO46 JD HYGUARD TRANS OIL WERGEN SPECIAL GEAR OIL PRODURO TO-4+10 PRODURO TO-4+30 PRODURO TO-4+50 TURBOFLO R&O 68 BRAKE FLUID DIESEL		

# WORK ORDER

# KH DEVELOPMENTS LTD

DATE:13.2.19	FLEET #: D2
MACHINE: JD750J	ODOMETER:
WRITTEN BY:	HOURS: 4979

PROBLEM OR FAULT	HOURS COMPLETED	DATE REPAIR COMPLETED
<p>FATIGUE CRACKS ON BLADE.                      WINTER SERVICE. CHANGE ENGINE OIL AND FILTER. CHANGE FUEL FILTER AND FUEL WATER SEPERATOR. CHECK BATTERY FLUID LEVEL AND CLEAN TERMINALS.CHANGE PRIMARY AND SECONDARY AIR FILTERS. CHANGE INNER AND OUTER FINAL DRIVE OILS. CHECK TRACK FRAME PIVOT BUSHING OIL LEVEL. CHANGE CAB FILTERS AND RECIRCULATING FILTER.                      VALVE LASH ADJUSTMENT TO BE DONE BY BRANDT.                      BOTTOM ROLLER #2 ON RHS NEEDS REPLACING.</p>	4981	14.3.19

CORRECTIVE ACTION	SERVICE HOURS	REPAIR HOURS
<p>TAKE OFF PANS AND GUARDS. WASHED OFF.                      REMOVED BLADE FROM C-FRAME. CLEANED AND WASHED PINS AND BOSSES SO AS THEY CAN BE INSPECTED FOR WEAR.                      CLEANED UP PINS, BOSSES, AND MOUNTS ON BLADE AND PREPARED FOR WELDING REPAIRS.                      RENTED AIR ARC FROM UNITED RENTALS. GUAGED OUT THE CRACKED JOINTS AND WELDED BACK UP.REFITTED BALDE BACK ONTO MACHINE.</p>	29.5	5
<p>CHANGED ENGINE OIL AND FILTER.                      CHANGED FUEL FILTER AND FUEL/WATER SEPERATOR.                      CHANGED AIR FILTERS.                      CHANGED CAB FILTERS.                      CHANGED INNER AND OUTER FINAL DRIVE OILS.                      CHECKED TRACK FRAME PIVOT OIL BUSHING LEVELS.                      CHANGED COOLANT.                      REPLACE STARTING ETHER BOTTLE.</p>	12	34.5
<p>REPLACED UPPER AND LOWER RADIATOR HOSES.</p>		4
<p>REMOVED EXHAUST AND HOOD TO BE READY FOR BRANDT TO COMPLETE VALVE ADJUSTMENT.</p>		6
<p>VALVE LASH ADJUSTMENT COMPLETED.</p>		3
<p>REMOVE EXHAUST MANIFOLD AND REPLACE GASKETS AND BOLTS. INSTALL ALL PANELS AND COVERS.                      CHECKED BATTERIES AND CLEANED TERMINALS.</p>	8	8
<p>REPLACED NUMBER 1 RHS TRACK ROLLER                      DETAIL CAB</p>	5.5	
	7	





















