

ECMT Certificate of Compliance of a Trailer(1) with the Technical Safety Requirements

Vehicle Type and Make :	FRUEHAUF	DX33CZ
Vehicle Identification Number (VIN) :	VFKDX33CZA01F0056	

The ²,

- ** ~~Competent validation Services in the country of registration (3) ;~~
- ** ~~Vehicle Manufacturer, or the authoriser Representative of the Manufacturer in the country of registration, or —~~
- ** ~~A combination of the competent validation Services in the country of registration and the vehicle Manufacturer, or the authorised Representative of the Manufacturer in the country of registration, when all the equipment is not fitted by the vehicle Manufacturer (4).~~

hereby confirms that the said vehicle is in compliance with the provisions of respective UNECE Regulations and/or EC Directives, as listed below, and confirms that the particulars entered overleaf are correct.

The trailer is fitted with the following devices :

- Rear protective devices according to UNECE Regulation R.58.01 or as subsequently amended ; or to Directive 70/221/EEC, as amended by Directive 2000/8/EC or as subsequently amended.
- Lateral protection according to UNECE Regulation R73.00 or as subsequently amended ; or to Directive 89/297/EEC or as subsequently amended.
- Lighting and light signaling devices according to UNECE Regulation R48.01 or as subsequently amended ; or to Directive 76/756/EEC, as amended by Directive 97/28EC, or as subsequently amended.
- Rear marking plates (retroreflective) for heavy and long vehicles according to UNECE Regulation R70.01 or as subsequently amended.
- Bracking, including antiblocking systems, according to UNECE Regulation R13.09 or as subsequently amended ; or to Directive 71/320EEC, as amended by Directive 98/12/EC, or as subsequently amended.

Place
AUXERRE

Date
29/07/2010

Signature(s) and stamp(s)

FRUEHAUF S.A.S.

24 à 28 Avenue Jean Mermoz
89002 AUXERRE
Tel. 03 86 94 42 42 - Fax 03 06 48 32 11
RCS AUXERRE SIREN 693 650 194

1. Semi-trailers included
2. Delete inappropriate mentions.
3. For the countries where the Representatives of the manufacturers are not authorised
4. In this case, the first signatory fills in the column on the left, the second signatory fills in the column on the right.