

Freddas

1/14-16 enmore street
north geelong VIC 3215
+61 409582067
admin@freddas.com
freddas.com



Tax Invoice

INVOICE TO
Earth-Tech Civils
Earth-Tech Civils

INVOICE 1094
DATE 24/09/2023
TERMS 14 days
DUE DATE 08/10/2023

DATE		DESCRIPTION	GST	QTY	RATE	AMOUNT
	SERVICE REGULAR	hino WUU725 kms: 600549 fit trailer supply valve	GST	1.50	110.00	165.00
	SERVICE REGULAR	DAF 1JO4ZA kms: 1019227 replace UHF	GST	1	110.00	110.00
	SERVICE REGULAR	Volvo SUE432 kms: 707012 replace UHF	GST	1.50	110.00	165.00

We appreciate your business and look forward to hearing from you soon.


SUBTOTAL	440.00
GST TOTAL	44.00
TOTAL	484.00
BALANCE DUE	A\$484.00

FREDDAS DIESEL & HIRE
BSB: 083-653
ACC: 31-703-5180



Freddas Diesel & Hire

 VENDORS

 Earth-tech civils

 PROCEDURE

Service Doc

33 / 64

Fields completed

Date::
24/06/2023
Filled by matthew fredericks on 26/06/2023, 13:22

Customer name::
EARTH TECH CIVILS
Filled by matthew fredericks on 26/06/2023, 13:22

Make::
HINO
Filled by matthew fredericks on 26/06/2023, 13:22

Model::
GD
Filled by matthew fredericks on 26/06/2023, 13:28

Registration::
WUU725
Filled by matthew fredericks on 26/06/2023, 13:22

Kilometres::
596663
Filled by matthew fredericks on 26/06/2023, 13:23

Components

Lights:

- ☐ Okay at this time
- ☒ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Wiper blades:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Windscreen:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comment:

No value given.

Washer fluid:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Belts/hoses:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Batteries:

- ☐ Okay at this time
- ☒ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Air filter:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☒ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Cabin filter:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Clutch pedal free-play:

- ☐ Okay at this time
- ☒ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Engine oil/level:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☒ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Oil filter/s:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☒ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

PCV filter:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Comments:

No value given.

Fuel filter/s:

- ☐ Okay at this time
- ☐ May require future attention
- ☒ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

NOT SUPPLIED

Filled by matthew fredericks on 26/06/2023, 13:23

P/s fluid/level:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

No value given.

Brake/clutch fluid/leve:

- ☐ Okay at this time
- ☒ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:23

Comments:

LOW FLUID

Filled by matthew fredericks on 26/06/2023, 13:24

Coolant/level:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Transmission oil/level :

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Transfer case oil/ level:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Comments:

No value given.

Diff oil/ level :

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

King pins:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

suspension/drive line:

- ☐ Okay at this time
- ☒ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Turntable:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Comments:

No value given.

Ring feeder:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Comments:

No value given.

Body:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Tyres:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Wheel bearings :

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Check and adjust Brakes:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Lubricate all grease points:

- ☒ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☐ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

Service sticker:

- ☐ Okay at this time
- ☐ May require future attention
- ☐ Requires immediate attention
- ☒ Replaced

Filled by matthew fredericks on 26/06/2023, 13:24

Comments:

No value given.

 COMMENTS

NO FUEL FILTERS SUPPLIED
PLAY IN CENTREBEARING
BATTERY TERMINAL LEAKING/WRONG
TERMINAL/SCREW IN TERMINAL
FRONT SPRING PINS/BUSHES ALL
REAR LEFT SPRING PACK BRACKET
BROKEN/BENT
EXHAUST NEED ATT - HOLES/FALLING APART
EXHAUST LEAK @ MANIFOLD
RADIATOR NEEDS WASH OUT
CLUTCH NEEDS ATT - MASTER CYLINDER
FLUID ALMOST EMPTY (TOPPED UP)
CAB MOUNTS
ENGINE MOUNTS
PASSENGER DOOR INDICATOR NW

Commented by matthew fredericks on 26/06/2023, 13:29



TAX INVOICE

Earth Tech Civils
185 Waurm Ponds Drive
WAURN PONDS VIC 3216

Invoice Date
20 Jul 2023

Account Number
176

Invoice Number
INV-0618

Reference
PO# 754


ABN
56 725 826 103

TN Automotive Electrics
tnautoelectrics@outlook.c
om
32 Albert St
MOOLAP VIC 3224
AUSTRALIA
RTA Authorisation No: AU
50200

Description	Quantity	Unit Price	GST	Amount AUD
Hino Tipper - Replace roof beacon, replace switch, repair wiring. Repair side marker wiring, replace side marker. Repair headlight fault. Replace number plate light globes. Replace batteries. Replace negative terminal, repair cable.	0.00	0.00		0.00
Total Labour Hours	4.50	120.00	10%	540.00
LED Beacon	1.00	140.00	10%	140.00
AC DELCO MF50ZZSLI	2.00	190.00	10%	380.00
Negative battery terminal H/D	1.00	10.00	10%	10.00
58ARM Side Marker	1.00	25.00	10%	25.00
Sundries; Cable Ties, Crimps etc,	1.00	15.00	10%	15.00
			Subtotal	1,110.00
			TOTAL GST 10%	111.00
			TOTAL AUD	1,221.00

Due Date: 31 Aug 2023

Bank Details
TN Automotive Electrics
Bank: CBA
BSB: 063 551 Account: 10556221



PAYMENT ADVICE

To: TN Automotive Electrics
tnautoelectrics@outlook.com
32 Albert St
MOOLAP VIC 3224
AUSTRALIA
RTA Authorisation No: AU 50200

Customer	Earth Tech Civils
Account Number	176
Invoice Number	INV-0618
Amount Due	1,221.00
Due Date	31 Aug 2023
Amount Enclosed	<div>Enter the amount you are paying above</div>