
Moorvale Earthmoving
Asset History Report
KOMATSU PC300-8

Friday, 12 June 2026

W/O No	Description	Complete
MEEEX05		
58222	MEEEX05 6M Fire Suppression InspectionCompleted 05/10/25 by Pyro	5/10/2025
57757	investigate fire suppression fault - Repaired pressure sensor wiring	25/08/2025
57735	carried out 6 monthly brake test W/O: M955801	24/08/2025
57104	washer motor not working and tank spilt	9/08/2025
57088	autolube not greasing	27/07/2025
57078	broken cutting edge bolts	26/07/2025
56643	MEEEX05 EXCAVATOR 500hr SERVICECompleted by: James PalmerHours: 11497Date: 25-07-25	25/07/2025
56916	Blown tilt bucket hose, removed and made another.	18/07/2025
56642	MEEEX05 Replace Leaking Hydraulic Tank Cap	18/07/2025
56877	REPLACE GREASE BLOCK FOR BUCKET	17/07/2025
56718	MEEEX05 Replace Swing Ring SealSeal has popped out	16/07/2025
56720	REPLACE U/S HYD HOSES	15/07/2025
54604	MEEEX05 EXCAVATOR 1250hr SERVICECompleted by: AidenHours: 11428Date: 07/07/25	7/07/2025
56689	MEEEX05 Replace Fuel Filters	4/07/2025
56615	REPLACE AIR FILTERS	1/07/2025
56574	broken bucket cutting edge bolts again - machine at broadlea	27/06/2025
56509	MEEEX05 CMJV Compliance	25/06/2025
56014	broken all bolts on tilt bucket cutting edge.	31/05/2025

W/O No	Description	Complete
54898	MEEEX05 6M Fire Suppression InspectionCOMPLETED 18/04/25	18/04/2025
54584	blown hydraulic hose on bucket	2/04/2025
54006	seat belt alarm going off, disconnected seat belt switch, seat belt still fully functional 5/3/25	6/03/2025
52301	MEEEX05 EXCAVATOR 1000hr SERVICECompleted by: Tom & NathanHours: 11041Date: 03/03/25	3/03/2025
53746	Replace belts	22/02/2025
53687	VEMP AND BRAKE TEST	19/02/2025
53449	pumped up R/H track and smoke bomb cab to find water leak	8/02/2025
51681	A/C faultCompleted BY: ANgus, Nathan and John Date: 18/12/2024	20/01/2025
51627	OIL LEAK ON PUMP Completed by: A Matthews+ M Hills	20/01/2025
51587	Coolant overflow sensor failed	20/01/2025
51372	CRW - PYRO Level two annual inspections - Carborough	20/01/2025
51124	REPLACE BROKEN BUCKET TILT HOSE - IRONBARK	20/01/2025
50092	LHS LOAD ROLLER U/S	20/01/2025
52996	REPL seat belt	19/01/2025
52986	hyd leak on tilt bucket	18/01/2025
52658	Repairs to tilt sensor cable	15/01/2025
46923	AUTO GREASER NOT WORKING GREASE DISTRIBUTION BLOCK U/S - JACK DIAGNOSED	13/01/2025
52835	carried out brake test	13/01/2025
52703	Tilt bucket, changed hydraulic cylinder's around and re routed hydraulic hoses completed 8/1/2025 Aidan Matthews	9/01/2025
52426	right track fallen off.	17/12/2024
52325	boost leak at aftercooler.	13/12/2024
52187	MEEEX05 A/C Fan motor failed	5/12/2024

W/O No	Description	Complete
52057	EXCAVATOR 250hr SERVICECompleted by: angusHours: 10737Date: 02/12/24	3/12/2024
52104	pumped up tracks and washed out radiator - Angus	3/12/2024
50831	EXCAVATOR 500hr SERVICECompleted by:Aidan and Angus Hours:10661hrs Date:15-11-24	15/11/2024
51750	PURCHASE NEW TILT BUCKET	15/11/2024
51704	High engine temps - Washed out coolers - Aidan	14/11/2024
51689	A/C repairs - replaced Compressor, evaporator and dryer - Angus	13/11/2024
51037	REPLACE BLOWN TILT HOSE	11/10/2024
48600	C/O cutting edge	5/10/2024
49872	REPLACE MISSING CUTTING EDGE BOLTS - ENOUGH ORDERED SO THERE IS BOLTS FOR THE CUTTING EDGE FLIP	5/10/2024
50320	RHS TRACK SLACK	5/10/2024
50401	TOP UP GAS ON AC SYSTEM	5/10/2024
46060	WORN CUTTING EDGE	25/08/2024
46725	Track rollers leaking after walking.	25/08/2024
47579	REPAIR GPS SYSTEM	25/08/2024
47620	Free up quick hitch	25/08/2024
48584	REPLACE FINAL DRIVE BUNG. BUNG STOLEN OUT OF EX10	25/08/2024
48949	BCC compliance and brake test	25/08/2024
48992	AC system low on gas	25/08/2024
49780	EXCAVATOR 250hr SERVICECompleted by: JACKHours:10273Date:9/8/24	11/08/2024
49275	CHANGE OUT TILT BUCKET COUPLERS - JACK CAMPBELL 15/7/24	16/07/2024
48388	2000HR service	10/06/2024
48450	EXCAVATOR 2000hr SERVICECompleted by: Jack CHours: 10040Date: 02/06/2024	2/06/2024

W/O No	Description	Complete
47589	SEIZED TILT BUCKET COUPLERS - FREE UP TO REMOVE BUCKET - TOMMY H 22/04/24	23/04/2024
47137	EXCAVATOR 2000hr SERVICECompleted by:Hours:Date:	23/04/2024
47057	tilt hose blown	23/04/2024
46983	Bucket quick hitch faults	23/04/2024
46783	Pyro	23/04/2024
46538	STARTING FAULT, FUEL BLEEDING BACK	23/04/2024
46491	PYRO - EX05 6 monthly service	23/04/2024
46322	SIRE SUPPRESSION LET GO	23/04/2024
46235	FITZROY VEMP	23/04/2024
46026	AC REFRIGERANT LOW - 08/02/24 FILL GAS AND CHECK FOR LEAKS TOMMY H	23/04/2024
43174	Fire Suppression Service Level 2 - Pyro Invoice 00021397	23/04/2024
43060	Recovered Bugged Machine from water sump	23/04/2024
47175	EXCAVATOR 250hr SERVICECompleted by: Mitch B Mick HHours: 9716Date: 30/03/24	11/04/2024
47269	MAIN PIN IN TILT BUCKET SEIZED - FORCED GREASE IN AND FREE UP	5/04/2024
47268	LOOSING ELECTRICAL POWER- FOUND FAULTY ISOLATOR - CHANGED OUT 4/4/24 JACK C	5/04/2024
42847	EXCAVATOR 500hr SERVICECompleted by: Mitch and MickHours: 9545HDate: 16/02/2024	20/02/2024
41852	fire supp ststem discharge	2/01/2024
42801	Low power fault	20/10/2023
39405	Ignition Key lost	20/10/2023
40953	Blow out air filters - inspect leak.	20/10/2023
41412	collect bucket and pin wheel from moorvale south	20/10/2023
41364	tilt bucket circuit fail	20/10/2023
41408	Check uhf poor performancefire supp faultsblown tilt bucket fitting	20/10/2023

W/O No	Description	Complete
41849	A/C Fault.	20/10/2023
41884	Defects: Oil leaks, electrical lights	20/10/2023
41905	Cold start issues.	20/10/2023
41939	Turbo failed, put debris though system	20/10/2023
42786	Fuel tank breather blocked	20/10/2023
43337	Hyd oil leak, tilt hose coupling	20/10/2023
43634	Tilt pilot control valve fail	16/10/2023
42828	Electric power lost 28/8/23 Mitch Buetel - No power fault, test estops, bypass bat- relay, power at 2 relays in cab, bridge out and had cab power to certain circuits	30/08/2023
39958	EXCAVATOR 250hr SERVICE Mick H 22/07/2023 9242H	28/07/2023
40974	Defects List 30-May-23 idler wheel leak 14/02/2023	30/05/2023
37827		30/05/2023
39438	Steel pipe on stick cylinder bent and leaking Schean 28/04/2023 9047H	28/04/2023
39675	Fire suppression Level One	30/03/2023
39287	inspect grease system	13/03/2023
38115	Inspect grease fault	9/03/2023
37557	Demobe from Saraji and Pembroke	9/03/2023
38795	EXCAVATOR 1000hr SERVICE Tom, Justin C 08/03/2023 8975H	8/03/2023
38305	EXCAVATOR 250hr SERVICE Steve D 20/01/2023 8765H	20/01/2023
38157	Replace teeth Aaron 12/01/2023 8765H	12/01/2023
30418	2000hr service kit	16/12/2022
36420	EXCAVATOR 500hr SERVICE Justin C 20/11/2022 8555H	20/11/2022
37229	No commercial radio (31/10 SMU 110885) Repaired Nev 18/11/2022	18/11/2022

W/O No	Description	Complete
37075	Seat u/s needs replacing (26/10 SMU 8482) Test ok checked 18/11/2022	18/11/2022
35225	Saraji pass-out.	18/11/2022
34722	Check engine miss fire.	18/11/2022
34677	Reseal Exhaust Manifold	18/11/2022
33781	Line bore stick and bucket etc	18/11/2022
32712	Fire Suppression 6 Monthly Inspection Completed by: Pyro Dynamics Date: 10/06/2022 Level 2 service	18/11/2022
34400	Replace travel alarm as required. Remove broken bracket and seized mounting bolts. Clean all threads and re-fit as required. Check operation - ok.	6/06/2022
30929	check over, site inspection	1/06/2022
30788	x 2 track rollers need replacing (10/12 SMU 7961) Second back from the dries on both sides	1/06/2022
30428	engine overheat, fan solenoids u/s	1/06/2022
32328	EXCAVATOR 2000hr SERVICE	19/05/2022
32185	EXCAVATOR 250hr SERVICE Aaron M	17/05/2022
31104	Oil leak through tilt hitch	17/01/2022
30367	Cutting edges needs flipping (15/11, SMU 7901	16/12/2021
30309	fire suppression service	16/12/2021
29625	Repair damages GPS Dome	16/12/2021
30722	3 Month brake test Grosvenor	7/12/2021
30274	Cutting edge needs flipping (03,04,05,08/11, SMU 7866 done on Work order 30034	16/11/2021
30034	Cutting edge needs flipping (25/10, SMU 7820	16/11/2021
29852	Needs coolant (red) (12/10, SMU 7757	12/11/2021
29669	Needs hydraulic oil (29/09, SMU 7709	30/10/2021
29946	250hr service	22/10/2021

W/O No	Description	Complete
29670	Needs new horns (29/09, SMU 7709 Replaced faulty low horn	21/10/2021
29851	Needs new air filter (12/10, SMU 7757	18/10/2021
29358	Brake test for grosvenor	7/09/2021
28734	Check over machine get ready for Dawson, fire sup service	24/06/2021
28369	Auto greaser not working (20,22,23,24/03,03/04 SMU 7482)	24/06/2021
28188	grease system faults	24/06/2021
26709	EXCAVATOR 250hr SERVICE @ 7,250 HRs	24/06/2021
28773	Fire Suppression 6 Monthly Inspection	5/06/2021
28171	Cannot get full tilt with bucket due to after market stoppers on bucket (19/03 SMU 7482)	3/06/2021
28170	Water/ Fuel separation light comes on (19/03 SMU 7482)	3/06/2021
28169	Hydraulic cap loose = leaks (19/03 SMU 7482)	3/06/2021
28114	Check over machine for FKG Paint counter weight due to damage, fuel filter sensor	3/06/2021
27784	Two way not transmitting (02/02 SMU 7399)	3/06/2021
27783	A/C struggling to stay cold rear vents don't work at all (02/02 SMU 7399)	3/06/2021
27677	Boom crack test	3/06/2021
27666	Check over offhire Check over for Moranbah North Repair Turbo engine Feed	3/06/2021
27584	EXCAVATOR 500hr SERVICE	11/03/2021
27547	Needs new cutting edge (01,02,03/12 SMU 7272)	2/02/2021
26931	Fire suppression fault (12,15/11 SMU 7148)	21/01/2021
25910	Fire Suppression 6 Monthly Inspection	21/01/2021
26930	Loose hydraulic cap (10,11,12,13,14,15/11 SMU 7130)	30/11/2020
26852	Replace Fuel Cap	30/11/2020
26848	Replace Cutting edge mud bucket	30/11/2020

W/O No	Description	Complete
26805	Fan belt loose - over heated code S02 (1/11 SMU 7122)	30/11/2020
26804	Small leak from quick release fitting- mud bucket (31/10 SMU 7113)	30/11/2020
26648	Coolant Leak refit tilt bucket pin	30/11/2020
25799	EXCAVATOR 1000hr SERVICE @ 7000 Hrs	16/10/2020
24954	Bma inspection get machine ready Paint counter weight mount new gps clamps and tilt hose clamps	30/08/2020
24705	EXCAVATOR 250hr SERVICE @ 6,750 Hrs	6/08/2020
25628	Service Fire Suppression Level 1	26/07/2020
24774	Hydraulic tank cap leaking (13/07 SMU 6661)	20/07/2020
24620	Coolant Leak	10/07/2020
24639	Bucket tooth has hole (03,4,5/07 SMU 6605)	7/07/2020
24448	Crack Test Boom	30/06/2020
23790	Make up guards to go under digger Damaged at coppabella	26/06/2020
23795	Replace front lights	23/06/2020
23116	Repair Fire suppression that went off on the weekend 11/04/20	23/06/2020
22354	Isolater playing up (02/03 SMU 6042)	23/06/2020
18313	Replace leaking quick hitch hoses	23/06/2020
23794	Replace damaged slew pipe	17/06/2020
18298	EXCAVATOR 2000hr SERVICE	11/06/2020
22889	Tracks Worn Out	10/06/2020
22749	EXCAVATOR 500hr SERVICE @ 6,500 Hrs	28/05/2020
18323	Replace worn bucket teeth	28/05/2020
22948	Weld up bucket cracked out	14/05/2020
23052	Gps system fault	12/05/2020

W/O No	Description	Complete
22900	Replace Boom hose	7/05/2020
20295	Replace damaged tilt bucket hoses	6/05/2020
20267	Fire Suppression 6 Monthly Inspection	24/04/2020
21224	Replace worn sieve bucket teeth	17/04/2020
21169	EXCAVATOR 250hr SERVICE @ 6,250 Hrs	12/04/2020
21470	Change blown quick hitch hose	3/04/2020
17774	Plate under cab damaged (27,28,29/08 SMU: 5053)	12/03/2020
20257	Replace failed batteries	3/03/2020
17914	Replace tilt bucket pivot pin & bushes	2/03/2020
18493	Fire Suppression 6 Monthly Inspection	27/02/2020
21798	2000hr service	7/02/2020
17614	RH call sign peeling (18-21,25-28/02, 01,04-07,11,14-16,18-22,25-27,29/03, 08,10-17/04 01-03,07,08,13,16,21,22,27/05 12,24,26/06 29-31/07 01,02,05,06,07,08,09,12,13/08 SMU: 4371)	31/01/2020
21037	Tilt bucket hose fittings	16/01/2020
20716	R&R radiator cap, R&R flashing light	14/01/2020
20534	Remove RH ID sign	8/01/2020