

Rural Municipality of Portage la Prairie									
Asset Repairs									
Public Works and Utility Equipment									
Unit#: 35 2008 John Deere 750J Dozer - Keith / Eric									
Start Date	Finish Date	Hours	Mileage	Input Type	Repaired By	Repair Hours	Repair Cost	Repairs Completed	Comments and Advisory's
2015-01-19	2015-01-19	20,539		Repair	Bart,Jeff,Bruce			remove starter at pit and bring in for testing	
2015-01-23	2015-01-23	20,539		Repair	Bart,Bruce			install starter at pit to bring in	
2015-01-26	2015-01-26	20,540		Repair	Bruce,Bart			change decel linkage, replace cable end at starter,repair l.f. top light	
2015-02-26	2015-02-27	20,600		Repair	Jeff,Bart,Bruce			remove broken roller, inspect all rollers	Advisory's: send to Wpg. Toromont Comments:
2015-03-17	2015-03-18	20,691		Repair	Jeff,Bart,Bruce			oil change, fuel filters, r.h. final dr. oil, fix light wiring, exhaust, change hyd. And trans. Filter,replace fuel pressure sender	
2015-03-30	2015-03-30	20,695		Repair	Bruce,Bart			replace O-ring on cover above starter	
2015-04-13	2015-04-13	20,750		Service	Jeff,Torry			flip cutting edge, install new corner bits	
2015-07-01	2015-07-01	20,980		Service	Jeff, Bart			oil change, fuel filters, air filters, cab filters, inspect for leaks	
2015-07-22	2015-07-22	20,980		Repair	Bart			install new def. louvres	
2015-08-17	2015-08-17	20,990		Repair	Bart, les			change big pin	Advisory's: has good one _now Comments:
2015-10-02	2015-10-02	21,277		Service	Jeff, Bruce			oil change, air filter, cab filter, fuel filter, test espar heater, check lights	
2015-12-03	2015-12-03	21,480		Repair	Bart, Bruce,Keith			check, repair, adjust throttle handle,wire in 12 volt, repair bracket r.h. top of engine, clean out stump pans	
2016-01-22	2016-01-22	21,574		Service	Bart			add hyd. Oil	Advisory's: done at pit Comments:
2016-01-25	2016-01-25	21,577		Repair	Jeff,Bruce,Bart			replace l.h. headlight, re-install washer fluid tank with new pump,fill and test-ok. replace front tilt cylinder manifold(at grill #8E-8916) repair grill mount,lower nose ,oil change,	Advisory's: Rick replaced rear window at this time Comments: tested 12 volt outlet-good
2016-03-22	2016-03-22	21,779		Repair	Bart, Torry			install new l.e.d. headlite, replace front dozer wear plates	
2016-09-01	2016-09-01	21,779		Repair	Bart			re-install l.h. dozer tilt cylinder, replace front hose, Hours estimated	
2016-09-28	2016-09-28	21,800		Service	Bart,Jeff			drag in to begin disassembly	
2016-12-05	2016-12-05	21,800		Repair	Bart,Keith,Jeff,Cliff			BEGIN RE-ASSEMBLY; re-assembled complete hydraulic system after cleaning and rebuilding of all components.	
2017-03-22	2017-03-22	5,983		Repair	Bart,Kyle			check over, clean grease	Advisory's: **this is the NEW #35, J D 750J Comments:
2017-05-28	2017-05-28	6,103		Repair	Jeff, Bart			6000 Hr service, Change hoses, Harmonic Balancer	Advisory's: Checked for leaks; found 2 hyd Comments:
2017-07-03	2017-07-04	6,150		Repair	Bart, Keith			Re-install L hand "C-Frame" pin. Make a new Retainer	Advisory's: Done at Jack Rabbit Comments:
2017-09-12	2017-09-12	6,270		Repair	Bart			Check over heating, Steering Check Foundation	Advisory's: Met Dale from Brandt at Machine Comments: Steering is 'good'
2017-09-19	2017-09-19	6,300		Service	Jeff, Keith			Blow out rads. Verify fan is working properly	
2017-10-11	2017-10-11	6,300		Service	Jeff, Keith			Blow out Rads. Hours estimated.	
2017-10-19	2017-10-19	6,300		Service	Bart, Keith			Blow out rads, Check hydraulic leaks. Hours estimated.	
2017-11-15	2017-11-15	6,500		Service	Bart			500 Hr Service: oil + filter, air filter, fuel filter. Straighten RH Engine Bay Door, Re-install Shims on Cab-Mount	Advisory's: RH Engine Bay Door Comments:
2017-12-19	2017-12-19	6,700		Repair	Jeff			Tighten Loose Door Handle	
2018-04-25	2018-04-25	6,966		Repair	Jeff, Keith			Blow out reads, Air filter, repair engine oil leak	
2018-07-12	2018-07-18	7,120		Repair	Jeff, Evan, Walker			Install reverse fan	Advisory's: multiple codes after install, Jeff diagnose + fix, properly working now Comments:
2018-08-24	2018-08-24	7,156		Service	Jeff, Keith			Clean out AC Rad	
2018-11-22	2018-11-22	7,483		Service	Jeff, Keith, Tyler			Install new air,airhose, repair antifreeze leak	
2018-12-03	2018-12-03	7,500		Service				Oil Change, Tighten cab, new fuel primer pump, tighten tracks	
2018-12-10	2018-12-10	7,551		Repair	Jeff			Put new bolt in proheat, fix small antifreeze leak at degas bottle	
2019-01-06	2019-01-06	8,575		Repair	Jeff			install dozer lift pin, install new bolt to replace bolt that fell out	
2019-01-11	2019-01-11			Service	Jeff, Keith			Tighten Track Pads	
2019-01-17	2019-01-17			Repair				Alternator	
2019-04-17	2019-04-19			Repair	Evan, Cliff, Jeff, Walker			Roller Bolts, track bolts, engine oil leak, hyd oil leak	
2019-05-14	2019-05-14	7,930		Repair	Jeff			Install new upper radiator hose, install coolant 20L	
2019-05-31	2019-05-31	7,957		Repair	Jeff			Install new top roller, tighten 3 track pads, check dozer bushings, install GPS	
2019-07-30	2019-07-30	7,687		Repair	Jeff, Keith			Replace O-Ringon dozer angle hose, fill with 5-40	
2019-10-23	2019-10-23			Repair	Jeff, Evan, Keith			Coolant leak, Repair heater hose line	
2019-11-06	2019-11-06			Repair	Evan			Fix Broken,Burnt wires for ESPAR connect GPS	
2020-05-10	2020-05-10	9,038		Repair	Jeff			Hyd fan pressure hose burst. Replac at pit	
2021-03-01	2021-03-01			Repair	Jeff			Noheat, replace water pump	
2021-05-01	2021-05-01	9,964		Service	Evan			Oil Change, hyd filter, fuel fileters, hyd oil, trans oil, final drives	
2021-06-13	2021-06-13	9,969		Repair	Jeff			Air Pressure, A,C line replaced, Charged	
2021-07-14	2021-07-14	10,113		Repair	Ivan			Replace water pump and coolant	
2021-07-15	2021-07-15	10,113		Repair	Ivan			Replace Thermostat, repair ESPARR hose, burp air	
2021-07-20	2021-07-20	10,117		Service	Ivan			Remove 5# fire extinguisher and install 20# Fire Extinguisher	
2021-09-28	2021-09-28			Repair	Fraser			Remove Blown 1 1/2" hyd hose under cab, order new from Brandt	
2021-09-29	2021-09-29			Repair	Fraser			Install hyd hose under cab	
2021-10-26	2021-10-26			Repair	Fraser			Repair No Start Issue	
2021-11-04	2021-11-04	10,366		Hours	Fraser			Mileage record	
2021-11-10	2021-11-10			Repair	Fraser			Order Parts	
2021-11-18	2021-11-18			Repair	Fraser			Install Thermostat and Coolant Valve	
2021-11-30	2021-11-30			Repair	Fraser			Install Wiper Blade	
2021-12-01	2022-12-01	10,502		Hours					
2021-12-02	2021-12-02	10,428		Hours					
2021-12-02	2021-12-02			Repair	Fraser			Diagnose no heat in cab-replace coolant hoses under cab-repair leak at rad, replace espar water pump and mount properly	
2021-12-08	2021-08-12			Repair	Ron			Replace Damaged Hydraulic Hoses	
2021-12-14	2021-12-14			Repair	Fraser			Replace Hoses / Install Hydraulic Clamp	
2022-01-06	2022-01-06	10,512		Hours					
2022-03-01	2022-03-01			Repair	Cole/Bart			Replaced alternator	
2022-03-01	2022-03-01	10,667		Hours					
2022-03-17	2022-03-17	10,771		Repair/Service	Jordan/Bart			oil and filter chge, all air filters, fuel filters, replaced alt harness and water/fuel seperator harness,	
2022-04-04	2022-04-04	10,802		Hours					
2022-04-22	2022-04-25	10,804		Repair	Cole			Starter removal and replace, changed v-plov to blade	
2022-04-26	2022-04-26			Replace	Keith			LH door wiper motor	
2022-05-02	022-05-02	10,813		Hours					
2022-05-26	2022-05-26	10,820		Repairs	Cole			Removed hose from proheatinstall connection, added coolant, tested	
2022-06-08	2022-06-08	10,867		Repairs	cole R			Replaced fuel cap, trouble-shoot & repair A/C cleaned all rads and coolers, torqued track bolts, checked reversing fan	
2022-06-22	2022-06-22	10,919		Hours	Cole R				
2022-06-23	2022-06-23	10,920		Repair	Brandt			Steering solenoidplaced	
2022-07-04	2022-07-04	10,920		Hours					
2022-08-02	2022-08-02	10,920		Hours					
2022-10-28	2022-10-28	11,004		Repair	Rempel			Service call to north of high bluff Replace leaking turbo oil supply line. Diag starting issues. Tighten loose track pads. change engine oil & filter. change final drive oils, change hydraulic filters and top up with oil. replace cabin air & engine air filters.	
2022-11-28	2022-12-01	11,085		Repairs	Rempel			Service call to pit. Replace starter, low voltage & no crank condition. lift cab, R&R damaged wiring. Reroute hoses & harnesses to prevent future damage. Remove batteries & replace. Repair heater core lines due to no heat in cab. Replace starter with another new. machine starts. run	
2023-01-03	2023-01-03	11,102		Repair	Rempel			Perform trans calibration and record faults. Call Brandt to repair dozer. Grader differential has priority no time to repair.	
2023-01-05	2023-01-05	11,104		Repair	Preston			Replace gear selector switch. Perform transmission calibration.	
2023-02-01	2023-02-01	11,177		Hours					
2023-02-27	2023-02-27	11,263		Service	Rempel			Service call to pit. Perform 250 hr service.	
2023-03-01	2023-03-01	11,271		Hours					
2023-03-08	2023-03-08	11,309		Repair	Rempel			Service call to pit. Top up trans & hydraulic oils. Top up coolant. Troubleshoot leaks. Troubleshoot poor heating.	
2023-03-29	2023-03-29	11,313		Repair	SHOP			Remove blade, remove C frame from machine for crack repair. Quote crossbar and pivot shaft repairs.	
2023-09-25	2023-09-25	11,394		Service				1000 hr service	
2024-01-02	2024-01-02	11,516		Hours	cole				
2024-02-26	2024-02-26	11,633		Service	cole			Change engine dampner. Drain and refill all hydrolic oil	
2024-03-14	2024-03-14	11,666		Repair	cole			Replace bottom rad hose and refill coolant. Check and fill final drives.	
2024-09-18	2024-09-18	11,920		hours	cole				
2024-09-19	2024-09-19	11,922		Service	burke			500 hr service, replaced engine oil / filter, air filter, fuel filters	
2024-10-01	2024-10-01	11,963		Hours					
2024-10-08	2024-10-08	11,988		Repair	Cole			Remove and replace left and right track speed sensors and calibrate/remove and replace gear selector switch and calibrate.	
2024-11-01	2024-11-01	12,112		Hours					
2024-12-02	2024-12-02	12,220		Hours					
2025-07-07	2025-07-07	12,267		hours	cole				
2025-10-01	2025-10-01	12,312		Hours	Angle				
2025-11-03	2025-11-03	12,331		Mileage	Angle				
2025-12-16	2025-12-16	12,342		Repair/Service	cole			remove and replace leaking blade tilt hose, remove and replace all revercing fan hoses, remove and replace muffler.	
2026-01-14	2026-01-14	12,381		hours	cole			Remove and replace all worn hydraulic hoses to reversing fan remove and replace black tilt hose. Test and replace esbar waterpump. Engine oil and filter changed/ fuel filters changed. Hyraulic filters changed and transmission filter.	
2026-01-24	2026-01-24	12,395		Repair	Cole			Repair hydraulic leak at pump. Repair fuse holder at ground side Espar heater. Check and top up all fluids.	
2026-01-24	2026-01-24	12,396		Repair	Sheldon			Wash unit and clean floor.	