

Description	Work Done	Completed
Inspection - Front End Loader	As per work order	09/25/2024
Caterpillar 988H Front End Loader (A service)	As per work order	09/16/2024
Fire Suppression Systems Inspection	Not required	09/10/2024
Inspection - Front End Loader	As per work order	09/10/2024
Inspection - Front End Loader	As per work order	09/03/2024
Inspection - Front End Loader	As per work order	08/27/2024
A/C U/S	Remove & replace A/C compressor & receiver dryer, Gas system	08/24/2024
Inspection - Front End Loader	As per work order	08/13/2024
Caterpillar 988H Front End Loader (B service)	As per work order	08/06/2024
Inspection - Front End Loader	As per work order	08/06/2024
Tilt function U/S	Replace tilt lever in cab	07/29/2024
Inspection - Front End Loader	As per work order	07/23/2024
Inspection - Front End Loader	As per work order	07/16/2024
Inspection - Front End Loader	As per work order	07/10/2024
Inspection - Front End Loader	As per work order	07/09/2024
Wire UHF to stay on without ignition on	Not required	07/23/2024
Caterpillar 988H Front End Loader (A service)	As per work order Marvin Gomez	06/24/2024
Replace Beacon with LED beacon	Beacon replaced	08/07/2024
Inspection - Front End Loader	As per work order	06/18/2024
Electrical faults	checked cab wiring.  located Brocken earth strap and repaired  tested systems ok	
Ordered rear work lights to be replaced. constant power supply requested for 2 way check with Wayne	As per work order	07/23/2024
Hydraulic hose weep near hydraulic filter	Tightened filter assembly	07/08/2024
Inspection - Front End Loader	As per work order	06/12/2024
Inspection - Front End Loader	As per work order	06/04/2024

Caterpillar 988H Front End Loader (D service)	As per work order	05/28/2024
Inspection - Front End Loader	As per work order	05/28/2024
Inspection - Front End Loader	As per work order	05/21/2024
REPAIR CAB FAN/ FILTER & HEATER TAP	ORDERED	05/21/2024
Inspection - Front End Loader	As per work order	05/14/2024
Inspection - Front End Loader	As Per work order	05/07/2024
Caterpillar 988H Front End Loader (A service)	As per work order	04/29/2024
Inspection - Front End Loader	As per work order	04/29/2024
Inspection - Front End Loader	As per work order	04/22/2024
Inspection - Front End Loader	As Per Work Order	04/15/2024
Westrac	Westrac	
FEL00014	FEL00014	
Starter motor fault	Starter motor fault	
11/04/24	11/04/24	04/11/2024
Inspection - Front End Loader	As per work order	04/08/2024
Inspection - Front End Loader	As per work order	04/01/2024
Caterpillar 988H Front End Loader (B service)	As per work order	03/21/2024
Inspection - Front End Loader	As per work order	03/26/2024
A/C fault	A/C GAS-FOUND HIGH PRESSURE PIPE LEAKING & EVAP	
FEL00014	BLOCKED -ADVISED QUBE OF REPAIRS NEEDED BEFORE WE CAN REGAS	02/29/2024
Caterpillar 988H Front End Loader (A service)	As per work order	03/03/2024
Electrical faults	Inspect & repair	03/05/2024
Inspection - Front End Loader	As per work order	03/19/2024
Inspection - Front End Loader	As per work order	03/12/2024
Electrical faults	Electrical faults	03/03/2024
Fire Suppression Systems Inspection	Inspections carried out on a weekly basis	02/20/2024
Inspection - Front End Loader	As per work order	02/26/2024
Air filter supply	Air filter supply	02/13/2024
Repair oil leaks	Trans Hose replace Rocker cover gasket replace	03/03/2024
Inspection - Front End Loader	As per work order	02/19/2024
Inspection - Front End Loader	As per work order	02/13/2024
Inspection - Front End Loader	As per work order	02/06/2024

TOOLING KIBBLE PAD	TOOLING ORDER	01/30/2024
Parts supply	As per work order	02/01/2024
ALTERNATOR FAILURE	ALTERNATOR CHANGED	01/21/2024
DEFECTS	As per work order	03/05/2024
DEFECTS	As per work order	02/01/2024
Inspection - Front End Loader	As per work order	01/30/2024
Inspection - Front End Loader	INSPECTION COMPLETE	01/20/2024
DEFECTS	REF WO-GFN-004-881 FOR ADDITIONAL TASKS AND COMPLETED TASKS	01/24/2024
Inspection - Front End Loader	INSPECTION COMPLETE	01/11/2024
DEFECTS	REF WO-GFN-004-883 FOR ADDITIONAL TASKS	01/24/2024
DEFECTS	REF WO-GFN-004-660 FOR CORRECTIVE ACTION	12/26/2023
ALTERNATOR OVER CHARGING 34V	ALTERNATOR CHANGED OUT MACHINE PLACED BACK IN SERVICE	12/28/2023
Caterpillar 988H Front End Loader (C service)	B SERVICE COMPLETED 21/11/23 C SERVICE COMPLETED 11/1/24	01/11/2024
DEFECTS	2, CRACK ASSESSED, UNABLE TO LOCATE ANY CRACK IN TYNE REMAINING DEFECTS OPENED ON WO-GFN-004-586	12/12/2023
Caterpillar 988H Front End Loader (A service)	REF WO-GFN-004-256 FOR COMPLETION	11/21/2023
DEFECTS	1. NEW WO RAISED FOR OIL LEAK  2. AUTO GREASER ASSESSED, ADJUSTMENT MADE TO TIMING, ASSESSED AS SERVICEABLE  3. LIGHTS CHECKED AS PART OF SERVICE  4. KEY WORKS WHEN TURNING MACHINE OFF	11/21/2023
Caterpillar 988H Front End Loader (B service)	SERVICE COMPLETED	11/21/2023
Caterpillar 988H Front End Loader (A service)	Ref WO-GFN-004-256 B service for completion	11/07/2023

Defects	Auto greaser requires loom oil leak rear rocker cover battery light, poor contact in wiring, rectified	10/15/2023
Caterpillar 988H Front End Loader (A service)	A SERVICE - B.MILLER & A. JOHNSON	10/15/2023
Caterpillar 988H Front End Loader (B service)	completed	09/18/2023
SEAT AIR SWITCH N/W	checked operation, no fault found	09/18/2023
Caterpillar 988H Front End Loader (C service)	completed Josh and Lloyd	09/18/2023
Caterpillar 988H Front End Loader (D service)	completed Josh and Lloyd	09/18/2023
Fire Suppression Systems	still in date	09/19/2023
warning light on dash	changed out hydraulic filter	08/24/2023
Repairs	tested charging circuit no fault found replaced step assembly	08/14/2023
Caterpillar 988H Front End Loader (B service)	completed service	08/14/2023
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet cam	07/08/2023
Rotator will not rotate anti clock wise	repaired wiring next to valve block	07/09/2023
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	07/01/2023
FAULTS	checked charging light fault, replaced fuses repaired auto greaser wiring fitted new revers lights checked dash lights ok	07/01/2023
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	06/08/2023
defects	CHECKED ALL OKAY	06/08/2023
Rear Step RHS / Battery light	Weld rear step RHS and ladder Inspect wiring for battery light flashing	05/04/2023

damage repairs	Fixed broken wires on auto greaser repair r/h steps and grab rail - no fix required replaced alternator washed engine check for leaks	05/04/2023
breakdown	Welded up crack in Tyre Found loose hydraulic hose - tightened	04/10/2023
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet Repair fan circuit oil leak	05/04/2023
damage repairs	New work order created	05/03/2023
Damage repairs	refer 002-770	04/20/2023
REPAIR FORK / REPLACE WIPER	REPLACE FRONT WIPER ARM WELD LEFT FORK (CRACKED TOP REAR)	04/12/2023
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet removed front cover from rotator	03/29/2023
oil leak at rotator	removed drive motor and Brocken bolts	03/15/2023
	refitted drive motor with new bolts	
	made up and fitted new hose	
Caterpillar 988H Front End Loader (A service)	tested oneration refitted front cover plate	03/26/2023
	Service asset as per attached service sheet	
	REPLACED LEAKING FILTER	
DEFECTS	REPAIRED ROTATOR ELECTRICAL FAULT	03/27/2023
	TESTED AUTO GREASER OK	
	ROTATOR STARTS AND STOPS REPAIRED WIRING	
Caterpillar 988H Front End Loader (D service)	Service asset as per attached service sheet	02/19/2023
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	02/19/2023
WELD UP CRACK IN TINE	WELD UP CRACK IN TINE	01/26/2023
Caterpillar 988H Front End Loader (B service)	DUPLICATE OF 002-312 C-SERVICE	01/24/2023
weekly rotator inspection	weekly rotator inspection and grease	12/19/2022
Caterpillar 988H Front End Loader (C service)	DUPLICATE OF 002-316 C-SERVICE	01/24/2023
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet	02/22/2023

Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet  replaced cabin filters  serviced rotator / greased / check over	01/14/2023
Caterpillar 988H Front End Loader (A service)	double up from 002-288  checked engine oil leak, minor	01/16/2023
engine oil leak	cracks in tines to be monitored  seat still to be done  checked reverse lights. auto greaser fault E13	01/14/2023
Chassis and frame	new job opened	01/01/2023
light on dash	checked and replaced hydraulic filters rechecked ok	10/24/2022
weekly	carried out weekly check over	11/15/2022
Caterpillar 988H Front End Loader (B service)	Service asset as per attached service sheet  replaced diff cooler  repaired leaking grease lines	11/24/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet  replaced auto greaser hose  replaced hydraulic hose on load frame  replaced work lights  welded exhaust bracket  replaced dash bulbs  repaired fan speed  replaced heater control  <u>fitted bucket</u>	10/19/2022
minor repairs	replaced r/h rear tail light  replaced front l/h work light  replaced wiper linkage and blade  topped up auto greaser	10/09/2022

More Defects	replace work lights replace wiper linkage and motor replace dash lights replace heater control	10/14/2022
DEFECTS	REPLACED BEACON ADJUSTED AUTO GREASER TIMER SECURED ROTATOR MOTOR REPLACED HEATER TAPS ORDERED WORK LIGHTS ORDERED DASH BULBS	09/19/2022
REPAIRS	as per 001-959	07/10/2022
Caterpillar 988H Front End Loader (D service)	off site for major repairs	04/20/2022
Caterpillar 988H Front End Loader (A service)	Carried out A service	02/15/2022
Caterpillar 988H Front End Loader (B service)	A SERVICE COMPLETED - NEED ENGINE OIL	03/06/2022
Caterpillar 988H Front End Loader (A service)	Carried out A service as required. Following faults recorded and require parts - 2 x Axle Temp Sensors - 288-8390 1 x Hydraulics pressure switch assembly - 376-7257 1 x Trans Temp Sensor - 118-7226 1 x Hydraulic Temp Sensor - 288-8390	01/19/2022
Caterpillar 988H Front End Loader (C service)	Carried out C service a required	12/13/2021
Caterpillar 988H Front End Loader (A service)	Carried out A service as required.	11/28/2021
Carry out weekly rotator inspection	Carry out weekly rotator inspection	04/28/2022
Carry out weekly rotator inspection	Work completed as per work order	11/19/2021
Check and report on free play in the rotator.	Work completed as per work order.	11/19/2021
Caterpillar 988H Front End Loader (B service)	Carried out B Service as per schedule  Check in between trucks nd keeping topper in plant full.	11/19/2021

Caterpillar 988H Front End Loader (A service)	<p>POS 3/4 40% left / POS 1/2 90% left - All 80PSI - Now A service.</p> <p>Replace wiper blades , grease and inspect rotator, 1 bolt loose, spring ashtray failed, replaced.</p> <p>Working lights fitted, first aid placed in cab.</p> <p>Parts used -            Air Filter            Wiper Blades            First aid kit            Oil Filter            Engine oil            Element Filter            Work Lights</p>	10/30/2021
Windscreen	Windscreen replaced by Deans Autoglass	09/24/2021
Rotator INOP	Fit new motor. Fit new spike protection valve & test - all OK	08/11/2021
Hydraulic hose	Hose replaced on service See WO-GFN-000-591	08/10/2021
Caterpillar 988H Front End Loader (D service)	Service completed as per sheet	08/10/2021
Caterpillar 988H Front End Loader (B service)	B service completed at Yaka site	04/22/2021
Rear R/H step repairs	Inspected R/H Step Remove step and weld up Refit step Return to work	05/22/2021
Grease Rotator, check and repair oil leaks x3	Move loader to workshop Remove Front cover Found oil leak at pump motor hose and one leak on valve Remove and reseal leaks Grease unit Check oils Return to work	05/19/2021
Transfer case suction hose leaking.	Suction hose change Trans.  Suction hose x 1	01/29/2021

Hydraulic oil cooler leaking.	Replaced cooler, topped up fluid.  Hydraulic oil cooler x 1	01/29/2021
R/H Tine snapped. L/H Tine cracked.	Replaced tines, torqued. Retorqued 14/05/2021.  Tines x 2	05/14/2021
Caterpillar 988H Front End Loader (B service)	WORK COVERED BY WO-GFN-000-093	05/04/2021
Caterpillar 988H Front End Loader (C service)	C service completed.	06/25/2021
Lights not turning on	Carried out wiring repairs.	06/14/2021
Repair RH step, Repaie wipers	Check R/H lower step mount bolts. Both had pulled through rubber and step was bent. Redrill and change out bolts, reassemble. Remove centre section of step which was rusted and had broken off, fab replacement end to mount, refit to unit, test.	04/08/2021
Hydraulic oil leak	Run and check leak, remove failed hose from unit, return to workshop. Mke up hose to suit from available stock, return and fit, top up oil, run and check. Clean down, return to workshop  25,977 hours  Hose (S/hand) site stock	03/10/2021

Rotator fault	<p>5/3/21 Fuel unit, check grease points (2) not taking grease      Clean out blocked holes, grease all points. Reassemble, check operation</p> <p>6/3/21 Position at work shop, check rotor operation and locking Grease, test, check movement in race bearing (lots)      Return to work, monitor, parts required</p> <p>7/3/21 Return to work shop, remove covers, inspect bearings (inner). Clean and repack, reassemble, grease and test. Return to work, monitor, parts still required</p> <p>18/3/21 In preparation for repairs, clean out hitch release pins to remove. Both seize as have never been operated, will continue to lubricate to attempt to remove. Hitch pins need to be released to remove rotor for repairs</p> <p>21/3/21 Unpack, inspect all received parts, work off list. Move unit to work shop. Support, remove rotator assemble from machine for repairs to ring gear / drive gears.</p> <p>22/3/21 Unpack required parts, inspect and check off      Move machine into work shop, support frame, dismantle front and rear sections of rotor for repairs</p> <p>23/3/21 Clean all parts, change gears, bearings, reassemble. Seal all covers, change over slew ring, torque bolts. Assemble front to rear section of rotator</p> <p>25944 Hours</p>	03/05/2021
Caterpillar 988H Front End Loader (B service)	<p>Carried out 500 hour service      Repair hydraulic line      Refitted rotator</p> <p>26160 Hours</p>	03/24/2021
Repair rotator guard	<p>Position in work shop      Remove front guard from rotator      Clean, check and repair threads, seal and refit cover      Test and check, return to operation</p> <p>25830 Hr</p>	02/26/2021

Caterpillar 988H Front End Loader (B service)	WO-NGF-001-445 25,487 hours 25314 km	01/30/2021
R/H middle step on ladder broken off on one side.	Fitted new step	01/20/2021
Rotator motor & bolts loose/ worn.	Replaced Rotator motor, adjusted bolts, lubricated rotator. 25110 hr	01/04/2021
Caterpillar 988H Front End Loader (C service)	WO-NGF-001-445 25,489 Hours Replaced all hydraulic fittings	01/30/2021
Hydraulic fault	24693 Hr Parts used: 5x hydraulic fittings	12/08/2020
Caterpillar 988H Front End Loader (B service)	WO-NGF-001-445 25,487 hours	01/30/2021

	Carried out 2,000 hour series Replace diff cooler Replace gearbox hose Fitted new steering lube  25,482 hours  Parts 1x 106 - 3969 air filter 1x 326-1644 fuel 1x 1R-1808 oil 3x 222 - 6713 hyd 2x 465-650 hyd 1x 337-5270	01/30/2021
Caterpillar 988H Front End Loader (D service)	250 hour service Filter isolator  24,008 hour  Parts Filter kit	10/29/2020
Caterpillar 988H Front End Loader (C service)	Service asset as per attached service sheet  Remove and replace radiator cores Replace coolant  23,400  Parts Used: Coolant Radiator cores and seals	10/30/2020
Coolant leak replace radiator cores	  Move to workshop, remove covers, clean and dry, pressure test. Locate another coolant leak at a further 3 core assemblies, parts required asap  23,310km	09/10/2020
Coolant Leaks		09/03/2020

Coolant leak	<p>30/8 - run and check coolant leak, top up, locate and move to workshop. Remove all covers to access and locate, clean down, carry out temp repairs. Run and check, re-assemble, return to unit</p> <p>31/8 - move to workshop, remove guards, chain cooling system, remove failed core assemble, clean all surfaces, seal and fit new core. Comp into position, connect lines, fill with coolant. Run and check, wash, refit covers, top up. Warm up, check for leaks, return to operations</p> <p>Km/Hrs 23,285Hr</p> <p>Parts Used Radiator Core 387-4366 x1 Clamps 1P-4278 x12 Hose 106-4572 x8 Seal 61-2431 x6</p> <p><u>Needs 5 more radiator core assemblies</u></p>	08/31/2020
Repair tine	<p>Position at work shop, clean all surfaces, tac into position, weld plate back into position and return to operation</p> <p>23,252Hr</p>	08/26/2020
Start Fault - starter motor	Travel to unit in mill and remove starter motor. fit new started motor. refit covers. machine returned to work	08/20/2020
Oil Leak (Hydraulic)	<p>Return to site after hours, check oil leak and locate. Top up and monitor. Once task completed ( unload, fill topper) remove guards, remove hose, check stock N/A</p> <p>Move hose dimensions, get hose made on site, return and fit. Tie and protect, run and check, top up oil, run and test. Refit covers, rear guards, check for leaks, recheck oil and top up</p>	08/19/2020

Rotator Operation switch, drive gear, bolt	<p>Check switch on cab operation, check new power supply, replace blown fuses, test</p> <p>Check lower rear gear cover loose (missing bolt when bump changes 11.8.20)</p> <p>Clean and inspect, gear retaining bolt loose and damaged threads</p> <p>Replace and reassemble, check where new pump is coming from as it hasn't arrived</p>	08/18/2020
Rotator failed	<p>Position at work shop, remove fan cover, rear gear cover, inspect. Remove pump assembly, found shaft broken. Clean all surfaces, clean up second hand(?) pump, seal and fit. Fit gear, torque retaining bolt, correct hoses, test operation. Seal and fit both covers, grease, return to operation. New pump required</p> <p>Parts used: 1 x second hand rotate pump assembly</p>	08/11/2020
Grease Pod, Oil Leak, High Engine Temp (water)	<p>check engine oil temp running hot, isolate and test, monitor check, unit running cooler - move to work shop, recheck levels, blow out all coolers with compressed air and retest. check grease system, censer has been fitted with two sorts of grease, clean, fill with correct grease 1/3rd full, unit required back in operation continue to fill a/oad during the day, monitor tarp pod completely. remove centre r/h access step, return to work shop, cleane, weld, refit to unit at moviing and top up grease pod</p>	08/09/2020
Oil Leak - Hydraulic Hose	<p>Travel to unit, check oil leak, run and check, remove failed hose, remove cover to access. Get hose made on site, return and fit, tie and protect, fit cover, test for leaks. Top up hyd oil, refit floor mate, fuel, return to workshop. Travel to Kibble pad to diagnose hydraulic leak under cab. Help out loading Kibbles onto truck with hyster loader</p>	07/21/2020
Oil leak	<p>Travel to loader. Found engine fan oil hose had failed. Remove failed hose and park up machine. Return to workshop for parts.</p> <p>Travel to make new hose. Return to machine and fit hose. Ran machine up to temperature and inspected for leaks. Refit access guards. Returned to workshop.</p>	07/18/2020

Rotator Valve Mount - broken	<p>Crack noise in rotator assemble (motor), remove front cover. Found valve mount broken, remove mount, tie into position (temp), refit cover, return to operation</p> <p>Unit available, remove cover , repair mounting threads for cover (2x) clean all surfaces, fit mount, fit and align valve, check clearance. Remove valve and weld mounr, refit valve repair threads and change mount bolts, seal and refit front cover</p>	07/08/2020
Oil leak	<p>Travel to unit, clean and inspect oil leak in hose at center arctic area. Test and monitor to locate, return to workshop once located, order parts</p> <p>Return to workshop, relieve system pressure, remove leaking hose. Clean all surfaces, clean out threads, align and fit new hose. Position and torque clamp bolts, protect all hoses, run and check. Top up oil, wash down, return to work, check for leaks</p>	07/03/2020
Check operation of auto grease system, check points for grease & test	Move into workshop, check operation of grease system, test with manual switch, time and operate, return to work and monitor. Check points receiving grease, parts required	07/05/2020
Check operation of beacon, repair wiring in plug & test.	Check operation, check and repair wiring at plug test, reposition loom, tie and protect	06/08/2020
Check oil leak remove pin / rod clean and inspect ,modified pin to suit put back together test	CHECK OIL LEAK AT HITCH PUN AND PIN MOVING OUT LH DISMANTLE AND CLEAN, MODIFIED TO REASSEMBLE PIN/ROD ASSEMBLE TO RAM, REASSEMBLE AND TORQUE UP, MARK PIN TO MONITOR, RETURN TO WORK	05/26/2020
Replace hydraulic hose	Remove seized bolts in hydraulic clamps. Drain fluid, fit new hose with new o rings and test	05/12/2020
Replace wiper motor ( Front )	<p>TEST OPERATION</p> <p>CHECK POWER SUPPLY</p> <p>DISMANTLE DASH AND CHECK WIPER MOTOR ASSEMBLE</p> <p>REMOVE AND CHANGE OUT MOTOR ASSEMBLE, CONNECT, TEST AND ALIGN ARM ASSEMBLE, REASSEMBLE DASH, REPAIR MOUNT FOR PARK BRAKE SWITCH, TEST, RETURN TO OPERATION. CARRY OUT TASTE DURING OPERATION!! C/O</p> <p>SORE WORK, FILL TOPPER, CONTINUE FIT UP!!</p>	05/04/2020

Rotator locking up	Strip out the front end of rotator, remove all nickel dust mixed with the grease. Replace front cover and seal up, regrease the unit and test	04/27/2020
Oil leak	Inspect oil leak, remove guard, removed failed hose. Travel to MtKeith to make hose, return to Leinster, align and fit hose. Run and check.	04/11/2020
Caterpillar 988H Front End Loader (B service)	B Service on kibble loader, repair amber beacon	04/23/2020
Put rotator gear cover	removed rotator gear cover from hyster, modify it. reattached it to missing rotator gear cover	01/15/2020
Carry out weekly service and inspection.	Carry out weekly service and inspection.	01/01/2020
Repair horn and auto greaser.	Repaired horn and auto greaser	12/16/2019
Carry out weekly service and inspection.	carried out weekly check over replaced alternator	12/16/2019
Not charging		12/13/2019
Check clean and grease rotator gear.	Check clean and grease rotator gear.	12/13/2019
Replace thermostat	Replace thermostat	12/07/2019
Rotator fault	Checked over rotator as the driver said it was moving on its own. Checked and cleaned hydraulic solenoid. Tested OK. Grease rotator.	12/01/2019
Replace coolant	Replace coolant	11/29/2019
Replace pilot pressure pump	Replace pilot pressure pump	11/28/2019
500 hr service	500 hr service as per service sheet	11/28/2019
replace crowd cylinder	replace crowd cylinder	11/17/2019
replace hydraulic filter	replace hydraulic filter	10/30/2019
quick hitch fault	Checked over quick hitch and found hydraulic hose around the wrong way, changed over and tested. OK.	11/04/2019
Hyd leak from rotator control valve block, grease system fault, cracked R/H tyne	checked over tyres cleaned up areas that needed it. check over quick hitch and found hoses that are on the wrong way and changed them around. and tested. tried to use grease system diagnostic tool but needs new software.	11/04/2019
crack in tynes RH side	weld up cracks in tynes	11/27/2019

Carry out 500Hr service	Carried out 500hr service as per sheet attached. Work carried out by Karl from Mader.	10/27/2019
weekly service	Carried out weekly service as per sheet attached.	10/22/2019
Weekly service	Carried out weekly service as per sheet attached.	10/08/2019
Oil leak	Find where the leak is coming from, removed hoses, travelled to MtKeith heavy workshop for hose to be made, travelled back and fitted. Tested all OK.	10/08/2019
250 Hour service	Carried out 250 Hour service as per sheet attached. Flushed out radiator and cleaned.	09/26/2019
Weekly service	Weekly service as per sheet attached. Repaired LH beacon. drained coolant due to possible oil cooler failed and put water and washing powder in. will check in the next few days.	09/23/2019
Call out Charge light coming on dash	Travelled to call out, found charge light bon dash coming on due to build up of dirt on terminal. Removed and cleaned. Tested OK.	09/22/2019
Replace hydraulic filter as requested by Westrac.	Replaced hydraulic oil filter as requested by Westrac	09/15/2019
Weekly service	Carried out weekly service and inspection.	09/15/2019
Steering failed	Travelled to breakdown, checked over steering checked steering diagram before going over to machine. Checked with the driver and had to get Cat to come out. and put gauges on and test ports and found pump failed. Westrac:- checked pump pressures removed and cut filter open and found it full of brass. Machine floated to Westrac Kalgoorlie new pump fitted, hydraulic system flushed.	09/12/2019
No start	When checking over A/C fault noticed it wouldn't start, checked over starting system everything seemed ok. Bypassed starting system and cranked engine over but wouldn't run. Noticed no transmission light on dash to say it was in a gear on neutral. Found fuse to trans ECM failed, replaced fuse Tested Ok.	09/08/2019
A/C not working	checked over a/c fault and found wiring problem around fuse area need further looking over	10/08/2019

Rotator has excessive play	removed cover found that the rotator motor had come loose so removed old bolts and replaced with new ones then refit cover and test all ok	09/01/2019
Carry out 2000 hour service.	Carry out 2000 hour service.	09/07/2019
Repair coolant leak.	Removed and replaced down pipe. removed and replaced coolant hose.	08/17/2019
weekly service	Carried out weekly service as per sheet attached.	08/11/2019
Hydraulic hose leaking RH tilt ram.	Remove and replaced RH tilt cylinder hose.	08/11/2019
250hr service	Carried out 250Hr service as per sheet attached	07/26/2019
Replace drive belt and tensioner	Found strange groove on belt,removed belt and belt tensioner found tensioner had failed. Fitted new tensioner and belt. Tested OK	07/26/2019
Replace leaking transmission hoses	Removed and replaced top transmission hoses. Washed down and tested ok.	07/20/2019
Top up transmission oil due to leaking hose	Top up transmission oil due to transmission hose leaking.	07/17/2019
Weld tyne.	Grind old weld grind out on cracks and weld it. Tyne should be replaced and should be weld properly again, tyne simular to the other side should be fitted. Grind and weld cracks on the spare tyne and replaced it to RHS tyne which has crack. Prepare the fork for welding and fitted new tyne.	07/13/2019
Imperilment controls faulty. Throttle not responding.	Work carried out by Westrac.  Work sheets attached.	07/09/2019
replace hyd oil due to westrac request	Replaced hydraulic oil and filters and checked for operation. Done as requested by Westrac.	07/09/2019
Call out, rotator not working	Travelled to call out, checked over rotator fault, still had kibble on it at 90deg. Once we got kibble off took to workshop to inspect. Removed rotator motor and inspected ok. Found there was no hydraulic flow going to rotator from hydraulic pump. Needs further looking at after Westrac worked on hydraulic system that day.	07/06/2019
Change out left hand tyne	Removed left hand tyne, then replaced with new (repaired tyne) Carried out by Vince Walker	07/08/2019

Find and repair roof leak,oil dip stick keeps popping out and lh cab light dull.	Travel to Kibble pad- check up for all XDR(?) found out that the rod needs to be done in workshop. escort the loader to workshop. removed the roof lining and the roof protector plate to see where the leak is - find out that its coming out of 2 wire grommets to old and not seated properly - replaced with new grommets and put sealant on it. Checked the dipstick - popping out because its to close to the pipe - vibration issue. Crimped the the pipe - checked when the engine on all good. Checked dull light - nothing wrong with it - as bright as the others.	06/29/2019
Windscreen wiper switch failed	Repaired wiring to switch as wipers didn't work at all, then found not all speeds work so replaced wiper switch	07/20/2019
Make and put temporary cover on electrical wirings and component.	Make cover - made up of fly board. Travel to kibble pad and fit so that components & wires will be protected from the rain & mud, while the cat technicians are not finished wiring it and the new cover hasn't arrived yet.	06/27/2019
Investigate on derating and ot starting issue.	Travel to Kibble pad, check on derating issues. Replace air cleaner and fuel filters still derating. while investigating all the loader electrical shutdown. found out that the problem is on the fire suppression system. Try to find out the problem is, couldn't find it. Decided to just to bypass the fire Suppression system so that the loader can be used. start the loader and greased up the rotator( advice the supervisor to get fire suppression electrician to fix the fire suppression issue) - assist greasing and repairs.	06/26/2019
Check for dash warning light	Travel from camp to workshop and grab tools and possible parts needed. Travel to workshop to kibble pad. Check for warning light on dash, find out that its for block hydraulic filter, replace filter, start engine, check warning light and it goes off. Check hydraulic level then travel to camp.  Parts used; 1 x hydraulic filter	06/18/2019
Loader 1000 Hour Service	Carried out service as per attached service sheet.	06/25/2019

Coolant leak	Found radiator hose clamp loose. Tightened up, topped up level and tested OK. Washed down.	05/28/2019
Loader 250 Hour Service	Carried out 250 hour service as service sheet attached	06/02/2019
Check up auto greaser	Check up Auto Greaser and top it up. Check to see if its working.	05/10/2019
	CANNOT CANCEL DUE TO UNPROCESSED INVOICES.  THESE ARE OLD WO'S WITH NO CONFIRMATION WORK HAS BEEN DONE, BUT IT CAN BE ASSUMED DUE TO THE TIMEFRAME BETWEEN CREATED DATE AND NOW.  COMPLETE AS PER SHAUN GRAHAM AND NEIL BALDWIN'S REQUEST	
Replace cooling system hose off water pump	Carry out Weekly inspection as service sheet attached.  Work completed by Josh Hull - Mater	03/05/2020
Loaders - Weekly Inspection		05/04/2019
Call out coolant leak	Traveled to call out. Checked over for coolant leak and found hose going onto heater top leaking due to hose being soft. Cut back hose and refitted. Also found clamp loose on bottom hose of water pump. Needs new hose and clamps. Tested OK	04/29/2019
Loaders - Weekly Inspection	Completed with WO-GFE-009-566	04/26/2019
Loader 500 Hour Service	Carried out 500 hour service as service sheet attached.	04/26/2019
Loader 250 Hour Service	Completed with WO-GFE-009-566	04/26/2019
Inspect coolant leak	Checked over coolant leak and found coolant coming out of over flow as it was filled up at last service.	04/06/2019
Replace A/C heater tap control valve	Drained coolant to carry out work. Once drained, repaired heater taps on the back of water pump. removed heater control model in cab and fitted new one. Filled coolant up, tested OK	04/11/2019
Loaders - Weekly Inspection	Carried out weekly service as service sheet attached.	04/05/2019
Loader 500 Hour Service	Carry out 500 Hour Service as per SHEMS-14-FM-MW085 checklist as per WO-GFE-009-213	03/27/2019
Replace door gas strut	Replace door gas strut	04/01/2019

Repair engine shutdown and not start again fault	Filled fuel tank. Replaced and filled fuel filters.	03/23/2019
Front windscreen wiper not working	Found both front and rear wipers not working. Found no power to both switches. After rewiring diagram I could see there is a common point where the power supply wired splice into each other.  After removing panels I found the splice point was under the cab. Due to the weather and how busy the loader is needed it was easier to pitch up ign power rear switch.  Wired in the power supply, tested OK. Still needs new switch as it wont turn off if you use the water.	03/22/2019
Loaders - Weekly Inspection	Carry out weekly inspection.	03/24/2019
Loader 2000 Hour Service	Carry out 2000 Hour Service as per SHEMS-14-FM-MW085 checklist	03/27/2019
Call Out Axle temp alarm	traveled to call out. Checked what symbol was alarming in CAT book. It is the axle oil temp. Checked temp sensors front and back. Looked OK. Found even at 40 - 50 deg the alarm s still going off. Got driver to keep heat gun with him so he could keep an eye on it.	03/14/2019
Remove and Replace Starter motor	Traveled to breakdown. Picked up starter motor from workshop. Traveled to loader on site. Had Jason turn key while I checked power. Power supply was good. Removed and replaced starter motor. Tested OK.  Parts used; <u>Starter motor</u>	03/14/2019
6 Monthly Service Fire Equipment	Inspect, test and tag fire equipment - CARRIED OUT BY CFS KALGOORLIE	03/15/2019
Inspect Hyd Fault	Go to kibble pad, check for the warning light coming out from dash. Find out that its for hydraulic filter . Bring loader to workshop and replace the hydraulic filter.	02/26/2019
Replace Air cleaner housing	Replaced housing.	03/24/2019

Replace Quick hitch Valve	to kibble pad.  Parts used; Quick hitch valve.	04/08/2019
Replace heater taps	Done on WO-GFE-009-316	04/11/2019
Replace HYD hose as required	CANNOT CANCEL DUE TO UNPROCESSED INVOICES.  THESE ARE OLD WO'S WITH NO CONFIRMATION WORK HAS BEEN DONE, BUT IT CAN BE ASSUMED DUE TO THE TIMEFRAME BETWEEN CREATED DATE AND NOW.  COMPLETE AS PER SHAUN GRAHAM AND NEIL BALDWIN'S REQUEST	03/05/2020
Loader 500 Hour Service	Carry out 500hr Service	02/19/2019
Loaders - Weekly Inspection	Carry out weekly inspection as per sheet	03/05/2019
Loaders - Weekly Inspection	Done with 500hr Service. WO-GFE-008-695	02/18/2019
Replace seized battery isolator	replaced both seized Isolators.	03/27/2019
Inspect and repair damaged fuel tank	Inspect Damage - Drained fuel Liase with Drage boilermaking Cory repaired 08.02.2019	02/08/2019
Inspect rotator and motor	Inspect rotater motor and hosing. Inspected hearing movement and mounting bolts. Inspected for cracks. All ok.	02/05/2019
Inspect auto grease system	Checked over grease system found no fault	01/12/2019
Loaders - Weekly Inspection	Carried out as part of WO-GFE-008-310	01/23/2019
Loaders - Weekly Inspection	parts used; Engine air filter Cab inner air filter Cab outer air filter	02/05/2019
Loader 250 Hour Service	Carried out 250 hour service	01/23/2019

Engine oil leak from filter housing	removed and replaced top gasket on oil filter housing. Tested ok. Washed down.	01/01/2019
Loaders - Weekly Inspection	Carried out Weekly Inspecton.	
Loaders - Weekly Inspection	Work completed by Double R Andrew Halbert 2 hours	12/28/2018
Loaders - Weekly Inspection	Carried out weekly service.	
Loaders - Weekly Inspection	Defects; Rear indicator not working Leak on tilt ram seal	12/23/2018
Loaders - Weekly Inspection	Carried out weekly service	12/14/2018
Loader 1000 Hour Service	Carried out 1000 hour Service. (takes a lot of time because have to do it in between loaders job, just can work on it when they're not using Loaders)  parts used; Hydralaulic Filters 50S Engine Oil Filters Cab Air Filters Engine Air Filters	12/24/2018
inspect grease pump fault	Checked over grease system to see why it keeps flashing red light for fault. Ran test cycle to get grease to grease parts. Ran with no fault, put back into service it faulted, ordered pressure switch, replaced pressure switch tested OK	12/09/2018
Loaders - Weekly Inspection	Carry out weekly service	11/24/2018
Loaders - Weekly Inspection	CARRIED OUT WEEKLY INSPECTION	12/06/2018
Loaders - Weekly Inspection	Completed as part of WO-GFE-007-777	11/17/2018
Replace failed starter motor	Tested starting system and found starter motor had failed. Removed and replaced starter motor - Tested - OK	11/16/2018
Loader 500 Hour Service	500 hr service	11/24/2018
Investigate heater controls	Double R Inspect, leave heater inop. C/out heater core.  Work completed by Double R	02/05/2019

Loaders - Weekly Inspection	Weekly service and washed	11/12/2018
Replace POS 1 tyre due to damage	Replace POS 1 tyre due to run flat with spare r/out tyre Work completed by Kaltire	10/31/2018
Replace Rear cab lights	Replace rear cab lights as keep blowing	11/07/2018
Loaders - Weekly Inspection	completed on WO-GFE-007-642	11/04/2018
Loader 250 Hour Service	Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist	11/06/2018
Remove faulty fire alarm module	Removed faulty fire alarm module	10/02/2018
Loaders - Weekly Inspection	Carried out weekly service Weld cracks on forks	10/19/2018
Loaders - Weekly Inspection	Carried out weekly service Greased rotator nil a/c filets in stock	10/13/2018
Loader 1000 Hour Service	Completed as part of WO-GFE-007-302	09/28/2018
Loaders - Weekly Inspection	Completed as part of WO-GFE-007-327	09/28/2018
Loader 2000 Hour Service	Carry out 2000 Hour Service as per SHEMS-14-FM-MW085 checklist	09/29/2018
Investigate electrical fault with Alternator	Investigate fault, trace to exciter wire, repair and test - OK  Work completed by Double R (Todd)	09/26/2018
Repair broken lh rear grab rail	Removed damaged hand/grab rail Cut out broken section Weld in new section Cleaned up and painted	09/15/2018
Grease system timing fault	Investigate fault. Trace and locate broken wire in artic point. Repair broken wiring	09/30/2018
Fire suppression bottle bracket failed	Removed suppression bottle and wall plate. Fabricated new wall plate and bottle mount. Painted and fit. Fit and secured bottle. Applied grip tape to wall plate.	09/14/2018
Replace Rotator pump	Replace Rotator pump	09/12/2018
Replace ETI Shutdown panel	Replace ETI Shutdown panel	09/10/2018
Investigate rotator pump fault	Investigate Pump fault, locate broken shaft. Remove and replace pump	09/09/2018

Rectify failed Rotator rams and lock for quick hitch	Investigate fault, locate LH Q-Hitch lock ram failed. Weld keeper in place to hold lock bar until new parts arrive. Cut out LH Ram shaft to allow pin to retract in order to remove rotator.  removed what was left of LH ram/pin and removed RHS. Replaced rams and LH pin. Cleaned up bores and valley Assembled and routed hoses in manner that will avoid chafing and being squashed. Tested mostly OK. Found shuttle valve for retracting rams is inop. Will chase up next business day	09/15/2018
6 Monthly Service Fire Equipment	Completed by Cooper Fluid Systems	09/06/2018
Level 2 PEFS Service	Completed by Cooper Fluid Systems	09/06/2018
Loaders - Weekly Inspection	Serviced as part WO-GFE-007-029	09/01/2018
Rectify rotator not rotating	Callout - remove front cover and test - no turning Removed pump and found shaft was broken Replaced pump and test - OK Refit cover	09/02/2018
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	09/23/2018
Loaders - Weekly Inspection	Carry out weekly service as per service sheet attached	09/08/2018
Loader 250 Hour Service	250hr service and repair lights	09/14/2018
Charge light coming on	Investigate and found signal wire end U/S. Removed and made up new lead. Fit and test - OK	08/25/2018
Low coolant	Topped up coolant. Has slight leak in engine bay. Needs checking out next weekly	08/17/2018
Loader 250 Hour Service	CARRY OUT 250HR SERVICE BETWEEN HOPPER REFILLS	08/14/2018
Loaders - Weekly Inspection	Carry out weekly service	08/19/2018
Loader 500 Hour Service	Carried out 500 hour service as per service sheet attached	09/01/2018
Loaders - Weekly Inspection	Completed with WO-GFE-006-578	07/21/2018
Loader 1000 Hour Service	CARRY OUT 1000HR SERVICE	07/21/2018
Repair Rear steps	REPAIR REAR STEPS REPLACE BOTTOM RUNGS	07/18/2018

Loader 250 Hour Service	250 Hour service, repair heater system	07/07/2018
9582 - A/C remove and refit	9582 - A/C remove and refit	05/16/2018
9583 - Gas system	9583 - Gas system - diagnose fault pressure, wiring plug melted.	05/17/2018
Repair rotator control joystick Repair 2 x broken kibbles	Repaired 2 x kibbles; Resecured joystick	06/28/2018
Rotator fault	<p>Rotator slow and nothing - take to Wshop - found ring dry - grease - better - but still nothing. Possible US bearings inside. Un hatched rotator from loader in WS. Stripped down rotator and found top had excessive pin movement. Found leg way missing and caused pin to wear into bushing. One bearing on gear was just about to fault.</p> <p>Got 2 new bearings from Kal (sent up). Replaced bearings, fitted on welded in bolt as leg for shaft. Replaced hyd pump as it was notchy, re assembled rotator, fitted not loader, tested - OK. Rotator need to be sent away for repairs</p>	06/22/2018
Grease Rotator Top up Trans oil	Grease Rotator Top up Trans oil	06/13/2018
Loaders - Weekly Inspection	Carry out weekly service; top up hyd oil; top up grease pod; changed out air filters and a/c filter.	06/27/2018
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	06/17/2018
Replace seat belt	Remove and replace seat belt	09/29/2018
Replace Steer ram hoses	<p>CANNOT CANCEL DUE TO UNPROCESSED INVOICES.</p> <p>THESE ARE OLD WO'S WITH NO CONFIRMATION WORK HAS BEEN DONE, BUT IT CAN BE ASSUMED DUE TO THE TIMEFRAME BETWEEN CREATED DATE AND NOW.</p> <p>COMPLETE AS PER SHAUN GRAHAM AND NEIL BALDWIN'S REQUEST</p>	03/05/2020
Repair damaged step	REPAIR AS PER WO-GFE-006-528	07/18/2018
Loader 500 Hour Service	Carried out 500 Hour service as per service sheet. Note - defects found.	05/28/2018

Repair steering lock out lever	Clout spring and cover mechanism 1x cover 1x spring	05/22/2018
Loaders - Weekly Inspection	WEEKLY SERVICE	06/01/2018
Loader 250 Hour Service	Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist Completed as Part WO-GFE-005-975	05/26/2018
Fill grease pod	FILLED GREASE POD UP	05/06/2018
Replace Rea Trunnion bush Replace Steer rams and pins	Remove and replace trunnion bushes	05/17/2018
Investigate Non Starter / Replace Starter motor	Breakdown. Travel to LNO. Tested and found starter muster had failed. Removed and replaced starter muster - tested - OK	05/06/2018
Repair HYD oil leak	Checked over for leak and found hyd fitting, resealing in engine buy right hand side for rotator	05/03/2018
Inspect and repair FRT W/Lights	Inspect and repair FRT W/Lights Double R	05/01/2018
Investigate and repair A/Con inop	Investigate and repair A/Con inop Double R	05/17/2018
Call Out - Investigate fuel leak and repair	Found fitting on filter head leak, removed and resealed, bled fuel , tested ok	04/29/2018
Loader 2000 Hour Service	Carry out 2000 Hour Service as per SHEMS-14-FM-MW085 checklist	04/29/2018
repair a/c	Inspected and found accumulator has leak - ordered parts Replaced accumulator (hoses all seized) greased - OK Requires refurb - parts on order - booked in for 15 and 16 MAY	04/23/2018
Hyd pump mounting surface leaking	Cleaned pump removed, cleaned surface area, fitted new gasket, refitted pump, tested ok	06/04/2018
rotator binding up	Travel tp pad and inspect Bought to workshop, removed cover - drive and gears okay Lack of grease thoroughly grease	04/08/2018
Loaders - Weekly Inspection	Complete	04/21/2018
Loader 250 Hour Service	250 Hour service	04/13/2018
fill grease pod	Filled grease pod up	03/30/2018
04963 - Top up auto greasing unit.	Top up auto greasing unit.	03/14/2018

04993 - Top up auto grease unit.	Top up auto grease unit.	03/19/2018
04983 - Check rotator for loose parts. Rear plate of rotator, retaining bolts loose. Fit new spring washers to bolts Loctite - tighten.	Check rotator for loose parts. Rear plate of rotator, retaining bolts loose. Fit new spring washers to bolts Loctite - tighten.	03/18/2018
Replace transmission hoses	Drain trans oil Remove and replace leaking trans hose Fill trans Test - OK	06/22/2018
Investigate lift controls intermittent and repair	Investigate and replace ECM	03/28/2018
Loader 500 Hour Service	B Service Replaced leaking fuel line, hard pipe from tank left hand side Inspected main battery isolator fault, need new switch	03/26/2018
Replace RH Tyne and Bolts	Removed and replaced damaged tyre, replaced old bolts	03/24/2018
Repair / Replace Rotator pump	Repair / Replace Rotator pump HOSE EXPRESS	03/27/2018
Repair Tyne	send tyne to Kal for repair	03/23/2018
Repair A/Con	completed under WO-GFE-005-583	05/17/2018
Driver Req. - Auto greaser requires topping up	Completed	03/06/2018
Call out. Directional drive gear come out of housing	Travelled to site and inspected rotator and find had plat had holds directional hear in has come away and gear assembly has come out of housing. Treat to unhitch rotator but right hand pin wouldn't go in. Had to cut short 5mm off pm to un hitch. Once apart inspect why is came out and found bolt had come loose and plate fell away causing gear to come out. Cleaned out bolt hubs and fitter gear after inspection and fitted plate had on. Fitted rotator to loaders then test	03/13/2018
Fill grease pod and inspect rotator motor after it got changed out	Fill grease pod and inspect rotator motor after it got changed out	03/07/2018
Call out. Rotator motor failed	Travelled to working from camp, loader was in yard when I got there. Checked over and found hyd motor had failed. Removed covers and bolt from motor shaft to get gear off. Removed mounting bolts and hoses. Check out found shaft had snapped. Heated gear up to get shaft out. Fitted new motor and plumbed up. Test ok and fitted cover and put into service	03/05/2018

Replace Fuel line	Replace Fuel line MADER	03/26/2018
Investigate A/Con poor	Investigate and top up A/C gas	03/01/2018
Loaders - Weekly Inspection	As above	03/16/2018
Loader 250 Hour Service	250 hour service	03/09/2018
Remove bent RH Tyne	Removed damaged tyre and fit replacement spare tyre	02/24/2018
Loaders - Weekly Inspection	Completed as part 1000 hrs. svc WO-GFE-005-217	02/19/2018
Investigate and repair grease fault	Checked over grease lines to see if lines had leak, Hume found used tested button to clutch pump welded A/C - found pump slightly noisy. It may be sucking in air - needs further looking at	02/09/2018
Loader 1000 Hour Service	1000 hour service	02/28/2018
06986 - Top up auto greasing unit	Top up auto greasing unit	02/04/2018
Loader 250 Hour Service	Carried out service	02/03/2018
Quick hitch and rotator fault	Checked over hyd and electrical system to rotater as rotater is mainly when the hitch button is used	01/25/2018
Grease system fault	Check over grease seal to see to see why it stops pumping Nothing found Clened out and see it fixed	01/24/2018
Loaders - Weekly Inspection	Carried out weekly inspection	01/20/2018
Loader 500 Hour Service	Repaired oil leak at sump Carried out 500 hr svc	01/12/2018
Fill auto grease pod	Top up auto grease unit as required	01/11/2018
Investigate oil leak around sump	Investigate oil leak around sump, Minor Monitor.	01/10/2018
replace ineffective front lights	Replace in effective front lights	01/04/2018
Loaders - Weekly Inspection	Carried out weekly inspection Replaced outer air fittings (engine and A/C) Replaced restriction indicator Topped up batteries and cleaned out	01/04/2018
Loaders - Weekly Inspection	Weekly inspection	12/30/2017
non starting fault	Test - found 6 week old reman starter U/S. Replaced.	12/23/2017
Loader 250 Hour Service	Carry out 250 hour service	12/23/2017
6 Monthly Service Fire Equipment	Carry out 6 month test and inspect	12/18/2017
Inspect Artic Drive shaft	Inspect - OK	12/19/2017
Inspect A/Con Issue	Replaced A/Con Filters, tested ok.	12/03/2017

Replace worn diff filler plug and POS 3 drain plug	Removed and replaced worn plug and oring	01/13/2018
Rotator drive failed	Remove and replace hyd drive -test - ok	12/13/2017
Replace Slew ring on Rotator	Strip rotator Removed bearing Found new bearing in correct move Restored bearing ect Removed and replaced slew ring as required Cleaned up mess after task	02/09/2018
Loaders - Weekly Inspection	Carry out weekly check	12/08/2017
Repair Rotator Pump	Repair Rotator Pump HOSE EXPRESS	12/01/2017
Replace Trans hose	Remove and replace hose trans oil replaced	12/01/2017
Loaders - Weekly Inspection	Weekly insp	12/02/2017
Loader 2000 Hour Service	Carried out 2000 hour service	12/03/2017
Loader 2000 Hour Service	believe issued in error as 2000 hr service completed on WO-GFE-004-654 1.12.17 1 week later.	12/03/2017
Loaders - Weekly Inspection	Repaired grease lines on steering Cleaned are full of dirt to u/s cover Repaired seized fuse box assessor	11/25/2017
Loaders - Weekly Inspection	Weekly inspection and repairs	11/18/2017
Replace Transmission hose	Checked for oil leak and found tran hose from filter to trans leaking. Hard one cover up from leak. Remove failed hose and fitted new one - test	11/15/2017
Inspect intermittent rotator fault	Unable to locate fault at time of inspection. will monitor to locate fault.	11/11/2017
Loader 250 Hour Service	250 hour service	11/09/2017
replace starter motor	Attend call out - starter U/S - won't jump start. R&R new starter - test -OK	11/09/2017
repair rear cab lights, inspect front lights flashing on and off, inspect rotator movrment	Replace globes on rear of cab Inspect front lights Check bushes and pins in front	11/09/2017
inspect grease fault	Inspected, measured and started efficient ordering process. Fitted grease lines that were ordered and tested	11/15/2017
Repair auto grease unit	Investigate fault bleed system, locate ruptured grease line and attempt to fit joiner until new hose can arrive	10/28/2017
Loaders - Weekly Inspection	Weekly inspection	10/31/2017

Investigate and Repair Rotator fault	Replaced rotator hyd motor - shaft seized on gear. front seal leaking	10/22/2017
Loader 250 Hour Service	Completed as part WO-GFE-004-357	10/15/2017
Loaders - Weekly Inspection	Weekly Inspection	10/15/2017
Loader 500 Hour Service	Carry out 500 Hour Service as per SHEMS-14-FM-MW085 checklist	10/15/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	10/07/2017
Replace AM/FM radio aerial	Replaced inop aerial	09/30/2017
Fill grease pod	Fill grease pod	09/21/2017
Loaders - Weekly Inspection	Completed as per WO-GFE-004-228	10/29/2017
Loaders - Weekly Inspection	Carry out weekly inspection	09/23/2017
Loader 250 Hour Service	Carry out service	09/30/2017
Investigate and Repair Rotator Bearings	As per WO-GFE-004-075	09/11/2017
Carry out repairs to rotator as required.	Remove rotator from machine Disassemble rotator and found worn bearing on reduction gear. Parts were sent to Kalgoorlie for repairs. Fitted and tested when reutnred	09/11/2017
investigate excessive play in rotator	Call out investigate excess play in rotator. Parked up machine. Rotator to be stripped down. Suspect bearing failure	09/09/2017
Grease up	Escort to and from site and carry out grease up	09/09/2017
Loaders - Weekly Inspection	Weekly	09/15/2017
Loaders - Weekly Inspection	Completed as per WO-GFE-004-005 Complited as per WO-GFE-004-055	09/10/2017
Loader 500 Hour Service		09/10/2017
Loader 1000 Hour Service	Carry out as per paper work	09/10/2017
hyd oil leak	Investigated hyd oil leak and found hyd hose leak due to O Ring failed. Replaced O ring and tested	09/02/2017
Loaders - Weekly Inspection	Weekly service	09/03/2017
Loaders - Weekly Inspection	Carried out inspection as per sheet	08/30/2017
Westrac to inspect T/Convertor leak	Westrac completed inspection of loader leaks	08/31/2017
Investigate Rotator fault	Investigate Rotator fault and replace pump	08/24/2017

B/Down - Investigate Rotator INOP	travel to site, investigate flush mounting and bolts OK Start up and test operation Ok have noticed electrical fault which requires further inspection	08/24/2017
Investigate Rotator fault and replace pump if required	Investigate major oil leak from rotator pump. replaced roator pump and topped up hydraulic oil	08/22/2017
Loaders - Weekly Inspection	Carried out as per paper work	08/19/2017
Loader 250 Hour Service	Carry out as per paperwork	08/19/2017
Blown EGR hose	Replace EGR base as required	08/23/2017
Loader 250 Hour Service	Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist	08/09/2017
Repair Tyne and fit 800mm billet	Repair Tyne and fit 800mm billet Regal Engineering	08/28/2017
Replace RH Tyne	Swap RH tyre to LHS and fit new tyre to RHS.	08/04/2017
Repair oil leak from Trans output seal	Westrac on site to carry out repairs as required for leaks to Trans Output seal and Trans filter housing, starter motor seals.	10/24/2017
Replace fast fill with blanking plate	Fit cover over diesel fast fill	08/14/2017
Loaders - Weekly Inspection	Carry out weekly inspection Greased rotator	08/09/2017
Loader 500 Hour Service	Carry out 500 hour service	07/29/2017
Loaders - Weekly Inspection		07/24/2017
6 Monthly Service Fire Equipment	Level 2 test carried out by Australian Fire Suppression	07/13/2017
Replace starter motor	w/o raised to purchase starter motor later changed under duplicate w/o	07/15/2017
Loaders - Weekly Inspection	CARRY OUT SERVICE AS PER WO-GFE-003-617	07/14/2017
Loader 250 Hour Service	CARRY OUT SERVICE AS PER PAPERWORK	07/14/2017
Loaders - Weekly Inspection	carried out weekly service	07/11/2017
Loader 2000 Hour Service	Carry out service as per paperwork	06/23/2017
Carry out Top Set	Valve set completed by Westrac	07/06/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	06/30/2017
Repair Tynes welds	Repair Tynes welds Regal Engineering	06/20/2017
Loaders - Weekly Inspection	Completed as per paperwork	06/23/2017
Loaders - Weekly Inspection	Weekly inspection	06/18/2017

Loader 1000 Hour Service	Carry out service as per paper work	06/23/2017
Repair Rotator Tyne	Repair Rotator Tyne Regals Engineering	06/20/2017
Replace Torque Convertor Temp Sensor	<p>CANNOT CANCEL DUE TO UNPROCESSED INVOICES.</p> <p>THESE ARE OLD WO'S WITH NO CONFIRMATION WORK HAS BEEN DONE, BUT IT CAN BE ASSUMED DUE TO THE TIMEFRAME BETWEEN CREATED DATE AND NOW.</p> <p>COMPLETE AS PER SHAUN GRAHAM AND NEIL BALDWINS REQUEST</p>	03/05/2020
Loaders - Weekly Inspection	Weekly Inspection	06/09/2017
Investigate and repair Auto Grease fault.	<p>INVESTIGATE FAULT WITH AUTO GREASER.</p> <p>CARRY OUT TEMPORARY REPAIRS, REQUIRES SOME NEW GREASE LINES.</p>	05/27/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	05/27/2017
Loader 250 Hour Service	<p>Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist</p> <p>REMOVE AND CLEAR TRANSMISSION SCREEN FILTER</p>	05/28/2017
Remove / Replace and Overhaul Rotator pump motor	<p>Inspected oil leak, found rotator pump failed</p> <p>Removed &amp; replaced</p> <p>STRIP &amp; ASSESS ROTATOR MOTOR AS REQUIRED</p>	05/25/2017
Replace Artic hose	Replaced artic hose	05/12/2017
Replace w/screen wipers	Remove & replace both wiper arms / blades	05/14/2017
Loaders - Weekly Inspection	Completed as per WO-GFE-003-196	05/12/2017
Loaders - Weekly Inspection	CARRIED OUT WEEKLY SERVICE AS PER PAPER WORK	05/06/2017
Loader 500 Hour Service	Carry out service as per paper work	05/12/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	05/01/2017
Investigate and repair Rotator INOP	Remove cover and inspect, tighten loose hose and fittings, Replace broken bolts as required, Test as required, Panel beat FRT cover and refit	04/19/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	04/15/2017
	Complete as part of WO-GFE-002-958	

Loader 250 Hour Service	Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist	04/15/2017
Remove and replace Rotator motor	Investigate oil leak coming from Rotator, found rotator pump had blown a seal, changed out pump.	04/08/2017
Replace batteries	Replace batteries	04/10/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	04/01/2017
Repair / overhaul rotator pump	Repair / overhaul rotator pump HOS EXPRESS	03/28/2017
Replace leaking rotator Hyd Q/D fitting	Replace male and female couplings	03/24/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	03/23/2017
Loaders - Weekly Inspection	Complete as part of WO-GFE-002-691	03/13/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	03/05/2017
Loader 1000 Hour Service	Carry out 1000 Hour Service as per SHEMS-14-FM-MW085 checklist	03/13/2017
C/Out Leaking Rotator pump and repair.	C/Out Leaking Rotator pump and repair	02/20/2017
Investigate fault with UHF radio and stereo	Locate blown fuse, note fuse box shows signs of getting hot will require further inspection by Auto electrician, Double R Auto Electrician inspected and repair damaged wiring	02/24/2017
Replace secondary f/filter bowl and return filter back to OEM spec	Replace secondary f/filter bowl and return filter back to OEM spec	02/18/2017
Investigate and repair electrical fault for 2 way, reverse cam, stereo	Found solder join had come loose where the fuse holder for radio, 2 way etc. picks up power supply, Replaced blown fuse, Repair fuse holder.	02/13/2017
C/Out leaking Rotator Pump	Remove and replace leaking rotator pump Replaced allen key bolt as required	02/10/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	02/18/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183 Completed as part of WO-GFE-002=495	02/12/2017
Loader 250 Hour Service	Carry out 250 Hour Service as per service sheets attached.	02/12/2017

Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183 Checked over radio and 2-way fault and found there is voltage drop. Needs further investigating.	01/27/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	01/19/2017
Loader 500 Hour Service	Carry out 500 Hour Service as per SHEMS-14-FM-MW085 checklist	01/19/2017
Replace fuel line	Replace fuel line	03/13/2017
Modify Fork Tyne as per Regals plan	Modify Fork Tyne as per Regals plan	01/06/2017
Replace Transmission hose	Replace transmission hose and filter, replace trans oil	03/23/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	01/10/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183 As part of WO-GFE-002-153	01/01/2017
Loader 250 Hour Service	Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist	01/01/2017
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	12/17/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	12/23/2016
Extend steps another rung as per BHP recommendation.	Extend steps another rung as per BHP recommendation.	12/23/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	12/09/2016
Loader 2000 Hour Service	Carry out 2000 Hour Service as per SHEMS-14-FM-MW085 checklist	12/13/2016
Modify spare kibble fork from Narngulu to suit kibble rotator.	JLW Engineering. 1. Modify kibble fork as per drawings. Price - \$1,760.00 incl GST.	12/07/2017
Replace fuel cap	Replace fuel cap	12/19/2016
Repair rotator cover	Repair rotator cover	12/02/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	12/01/2016

Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183 Wash down machine Change steering pump filter Inspect rotator pump	11/19/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	11/29/2016
Investigate and repair fault with rotator and pump	Found rotator pump mounting bolts failed and damaged Hyd hoses. Removed pump and broken bolts. Fitted new pump and mounting bolts, Torqued to spec. Fitted new hoses, topped up Hyd oil and tested ok.	11/04/2016
Repair Tynes	Remove and replace tyne with spare send to Kal for Repair / Replacement Removed and Replaced tynes, Torque mounting bolts	11/20/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	11/11/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183 as part of 500 hr service WO-GFE-001-714	11/05/2016
Loader 500 Hour Service	Carry out 500 Hour Service as per SHEMS-14-FM-MW085 checklist	11/05/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	10/23/2016
Lock Loader into 2nd Gear (Westrac)	Lock Loader into 2nd Gear (Westrac)	10/22/2016
Repair Rotator tines	Regal engineering Repaired tynes as per Engineers report, Remove and refit tynes	10/14/2016
Repair cracked tynes	Temporary repair carried out will need a boilermaker to carry out full repair.	10/12/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	10/14/2016
Loader 250 Hour Service	Carry out 250 Hour Service as per SHEMS-14-FM-MW085 checklist	10/07/2016
Remove and Replace Hydraulic motor	Remove and Replace Hydraulic motor	10/05/2016
Kal Tire to replace 4 x Tyres	Kal Tire to replace 4 x Tyres	09/28/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	09/23/2016

Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183	09/30/2016
carry out welding repairs to tines	carry out welding repairs to tines carried by Double R	09/20/2016
Investigate and Repair fault with Rotator	Investigate and Repair fault with Rotator	06/21/2016
Intermittent Starting fault	Intermittent Starting fault	09/19/2016
Check battery light intermittent fault	Checked charging fault, Found rectifier wire very loose, Tightened terminal, Tested OK	09/17/2016
Repair Cracked Tines	Repair Cracked Tines, Double R boilermaker to carry out repairs.	09/17/2016
Loaders - Weekly Inspection	Carry out Weekly inspection as per SHEMS-14-FM-MW183 Temp repair to crack tines	09/16/2016
Replace Steering pump	Remove all hoses as required, drain hydraulic oil, remove steering pump. Fit new steering pump and O-rings as required. Refit all hoses as required, Fill Hydraulic oil and filter. Test Pressures of pump all ok.	11/27/2016
1. Oil leak at kibble rotator hydraulic motor.	Hosepress. 1. Overhaul hydraulic motor. Price - \$881.54 + GST.	09/01/2016
Loader 1000 Hour Service	Carry out 1000 Hour Service as per SHEMS-14-FM-MW085 checklist	09/09/2016
Fill auto greaser and inspect Artic pins	Fill auto greaser and inspect Artic pins	09/01/2016
RHS rotator Q/Hitch nipple blocked	RHS rotator Q/Hitch nipple unblocked	
RH Step light INOP	RH Step light replace fuse	08/30/2016
POS 4 F/D top up	POS 4 F/D top up	
Inspect grease system fault	Remove grease lines and make sure grease is coming out ok, remove, clean, and refit breather / bleeder. fit manual grease nipple and grease	08/27/2016
Carry out 250 HR Service and Inspection	Carry out 250 HR Service and Inspection as per SHEMS-14-FM-MW085. Completed by Double R Leinster	08/26/2016
Fire suppression system	Protector fire Services supplied and fitted fire suppression system.	03/21/2016
Wire up fire suppression system	R&Ms wired up fire suppression system	03/29/2016
Remove and Replace Water Pump	Remove and Replace water Pump. work completed by Double R Leinster	08/26/2016

Carry out Weekly Service and Inspection	Carry out Weekly Service and Inspection as per SHEMS-14-FM-MW-183	08/21/2016
Welding repairs to Rotator	Welding repairs to Rotator carried out by Double R	08/16/2016
Investigate noisy steer pins Investigate noisy Hydraulic pump Top up Hydraulic oil	After coming back from repair there was noise from centre Pins and Steer pins, Used grease system on loader to grease pins, Still no grease. removed fittings and fitted grease nipples manual pump grease into pins and tested. Fitted fittings back into grease system allow pump to run and monitor. Investigate noisy Hydraulic pump Top up Hydraulic oil  Double R 2.5 HRS	08/18/2016
Lower Artic Pin Failure	Transport to Regal Engineering in Kal for repairs Replaced both Artic pins and bushes	08/10/2016
Carry out Weekly service and Inspection	Carry out Weekly Service and Inspection as per SHEMS-14-FM-MW183  Sent off site for Artic Pins C/O	08/19/2016
Overhaul Leaking Hydraulic Motor	Overhaul Leaking Hydraulic Motor	08/10/2016
Breakdown Fuel Leak	Travel to Site investigate fuel leak and repair, Found bolt had come out of muffler bracket and was sitting on fuel line. Bolt rubbed through fuel line. removed fuel line, bronzed up and fitted, Tested all ok	08/06/2016
Replace dip stick	Replace dip stick	08/09/2016
Carry out Weekly service and Inspection as per SHEMS-14-FM-MW183	Carry out Weekly service and Inspection as per SHEMS-14-FM-MW183  Replace Mirrors Repair Quick hitch grease nipples for pins	08/05/2016
Leaking hydraulic motor	Remove and Replace hydraulic motor.	08/02/2016
Repair broken Rotator tines	Double R Boilermaker's to carry out welding repairs to tines	07/31/2016
Weekly Service and inspection	Double R to carry out Weekly Service and inspection	07/26/2016
Travel to Leinster fuel , bulk, Check over	Travel to Leinster fuel , bulk Grease, Check over	07/22/2016
Carry out Weekly Service	Carry out Weekly Service as per SHEMS-14-FM-MW183  Work carried out by Double R Leinster.	07/19/2016
Replace fuel cap	Replace damaged fuel cap fitted by operator.	07/21/2016

inspect and repair loose bolts in rotator backing plate	Double R Leinster to investigate and repair loose bolts on rotator backing plate.	07/03/2016
Replace centre FRT W/Screen	Remove and replace FRT centre w/screen as request by Supervisor Work carried out by Leinster Smash	07/08/2016
Loader 500 Hour Service	Carry out 500 Hour Service as per SHEMS-14-FM-MW085 checklist Work carried out by Double R Leinster	07/08/2016
Weekly loader inspection as per SHEMS-14-FM-MW183	Weekly loader inspection as per SHEMS-14-FM-MW183 work completed by Double R contarcting	07/28/2016
Replace front windscreen motor	Replace front windscreen motor Double R time on job 7.5hrs	06/21/2016
westrac to inspect artic pin movement	westrac to inspect artic pin movement	06/14/2016
Call Out. Damaged e-vac cover	Traveled to site, checked over loader and found cover had been left unlocked causing it to open and damage. Removed cover and fitted temp cover until we get a new one.	06/11/2016
1. Leaking kibble rotator hydraulic motor.	1. Overhaul hydraulic motor. Price - \$942.27 incl GST.	06/03/2016
1. service kit items.	Complete as per PO dates - no paperwork	06/17/2016
Loader 250 Hour Service	svc carried out by Double R Leinster	06/13/2016
1. Spare rotator hydraulic motors.	1. 2 x roller stator motor - kibble rotator 14 tooth shaft. Price - \$2,984.52 incl GST.	05/30/2016
rotator hydraulic pump leaking	remove and replace rotator hydraulic pump.	05/30/2016
HYD oil leak	Traveled to breakdown, Checked hyd oil leak and found hyd fitting on hyd motor for the attatchment was leaking. Ordered correct fittings and fittted	05/27/2016
Check over hyd motor bolts on attatchment	Check over hyd motor bolts on attatchment	05/27/2016
replace mirrors as requested by supervisor	replace mirrors and brackets	08/05/2016
Westrac to carry out Hydraulic pressure checks Aircond repairs.	1.Westrac to carry out Hydraulic pressure checks 2. Remove & install A/C fan motor. Price - \$1,104.88 incl GST	05/22/2016
Cab air conditioning blower motor faulty.	Westrac C/O blower motor	05/23/2016
Checked over befor going into service	Checked over befor going into service	05/01/2016

Fit rotator drive motor	Geraldton Workshop removed belly plates. Fit rotator drive motor & fitted rotator box to loader.	04/21/2016
Float loader from Geraldton to Mt Keith	Float loader from Geraldton to Mt Keith	04/25/2016
Supply wheel chocks + bracket.	1. 2 x SISWCM chocks. 2. 1 x SISWCB bracket. Price - \$1,712.62 incl GST.	04/18/2016
Supply & Install fleet numbers and high vis tape	Geraldton Sign Makers supplied and installed fleet numbers and High vis tape.	04/04/2016
1. Manufacture hydraulic motor , drive adaptor for rotator.	1. Manufacture & supply , hydraulic motor , splined drive adaptor. Price - \$1,425.00 + GST.	04/07/2016
1. Install hydraulic componentry for kibble bucket rotator.	HoseXpress installed hydraulics for Kibble bucket rotator	04/26/2016
Clean Loader	Pressure cleaned loader	04/20/2016
1. engine adjustments. 2. re locate one E stop. 3. Change oil boom cylinder pins.	11/4/16 Pemco started on removing panels from engine bay, snapped 3 x bolts in frame work. Removed exhaust system, removed intake system and air filter housing, removed ECU, remove fuel filter head and mounting bracket. Remove rocker covers, set timing up on flywheel. Carry out valve set and MEUI adjustments, clean rocker covers and install new gaskets, refit to engine.  Refit exhaust system, air cleaner housing intake system, ECU. Drill out and tap broken bolts in frame work. Fit 90% of engine panelling, fit fuel filter head and mounting plate. Removed tools from machine and start. move machine out of workshop. 11/4/16: repaired threads on top engine cover, fit exhaust tip and engine side panels. Removed old E stop, drill holes and fit new E-stop away from AFFF system. Run new wires and insulate and test - all good.  Drained and refill oil in pivot points on boom, check levels.	04/11/2016
Carry out arrival inspection.	Arrival Inspection carried out by Geraldton Workshop.	03/15/2016
SLIGHT WEEP ON TILT CYLINDER		03/09/2016
~Mob: Loader CAT - 2000 Hour Service		03/04/2016
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		02/05/2016

*^ Mobile - Front End Loader, Cat, 988H 250 Hour Service		01/12/2016
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		01/12/2016
03656 Beau Falvo - repair & replace u/s door strut & old wiper blades		01/11/2016
03389 Beau Falvo - Worn Cutting Edge	Replaced cutting edge and bolts	12/05/2015
03387 Beau Falvo - Cutting Edge Low	Fitted 4 x new bolts	12/03/2015
03470 Stu McCaig - Cutting Edge Worn	Inspect 988, look for new kux out into out load and re-check bucket	12/02/2015
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		12/24/2015
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		11/27/2015
03365 Beau Falvo - Replace R/H Beacon		12/01/2015
03363 Beau Falvo - Poor Lighting		11/23/2015
03364 Beau Falvo - Replace Broken Mud Flaps		11/13/2015
REPLACE FUSE HATCH LID R/H SIDE OF CAB		12/05/2015
250 SERVICE AND LIGHT REPAIRS		11/12/2015
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		11/08/2015
01461 Dave Stinson - carry out inspection, fill grease pod, top up oil, check over ahead of FEL04 full life		09/29/2015
01020 Beau Falvo - Worn Cutting Edge & Grease Issue		08/22/2015
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		09/14/2015
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		08/15/2015
* Mobile - 3-Weekly Front End Loader, Cat, 988H Inspection		07/25/2015
LOADER NOT STARTING		07/16/2015
AC Repairs		04/22/2015
Fit sun visor		04/15/2015
Mobile - 988H Inspection - Monthly		04/24/2015

Mobile - 988H Inspection - Monthly		03/17/2015
Fill grease		02/16/2015
Running Hot		02/06/2015
Mobile - 988H Inspection - Monthly		02/17/2015
Fill grease, repair seat not adjusting up/down.		01/23/2015
Replace UHF with Motorola		01/08/2015
Repair mudflaps and rear steps.		02/06/2015
Repair hydraulic leak.		12/10/2014
Mobile - 988H Inspection - Bi-Weekly		12/09/2014
Mobile - 988H Inspection - Bi-Weekly		11/16/2014
BD 3424 (Morgan Brown) - grease pot was filled with incorrect grease	removed component & filled with correct grease	10/21/2014
Mobile - 988H Inspection - Bi-Weekly		11/03/2014



















































































