

Description	Work Done	Completed
Inspection - Front End Loader	OFF SITE	10/26/2024
Inspection - Front End Loader	completed	09/24/2024
Inspection - Front End Loader	completed	09/17/2024
filter order	ordered	09/02/2024
Inspection - Front End Loader	COMPLETED	09/10/2024
Inspection - Front End Loader	completed	09/03/2024
fuel filter	Fuel filter	08/26/2024
1 x 503-8698 (Sender AS-LE)	order damaged one on FEL24	08/21/2024
Inspection - Front End Loader	COMPLETED	08/27/2024
Westrac FEL0095 06/08/24 Engine Oil Cooler Integral Sealing Pipe Primary Fuel Filter Housing Gaskets Seals	Completed	08/06/2024
WESTRAC REPAIR- COOLANT IN DIESEL	completed	08/07/2024
INSTALL HYDRAULIC OIL SIGHT GLASS	WESTRAC BRINGS	08/02/2024
Inspection - Front End Loader	completed daily	08/13/2024
A Service - Front End Loader	completed	08/07/2024
Defects	completed	08/27/2024
Inspection - Front End Loader	COMPLETED DAILY	07/31/2024
Inspection - Front End Loader	complete	07/23/2024
REPLACE HYD HOSES IN ARTIC AREA	REPLACED HYDRAULIC HOSES IN ARTIC AREA & FIX STRIPPED THREADS	04/25/2024
Westrac FEL0095 06/07/24 Recliner Kit	Completed	07/08/2024
Inspection - Front End Loader	completed daily	07/17/2024

westrac stock order	ordered	07/01/2024
replace coolant hose	done	06/27/2024
Smoke Bomb Cab Test	completed	08/07/2024
Inspection - Front End Loader	completed daily	07/17/2024
C Service - Front End Loader	Service completed	07/21/2024
eFIRE&SAFETY FEL95 & Grader & Excavator Cat 349k Suppression System - Level 5 Recharge / Service	Eton from eFire & Equipment to complete.	06/25/2024
lift cylinder hoses	completed	08/07/2024
kaltire - wheel assembly	KAL TIRE FIT MAJOR REPAIR TYRE TO SUPPLIED WHEEL	06/09/2024
Inspection - Front End Loader	COMPLETED DAILY	07/02/2024
Inspection - Front End Loader	complete	06/27/2024
A Service - Front End Loader	COMPLETED	06/27/2024
Inspection - Front End Loader	completed	06/26/2024
Replace Window Wipers	Parts ordered on the 12/06/24	06/17/2024
westrac order	ordered	06/10/2024
Inspection - Front End Loader	COMPLETED DAILY	06/11/2024
Inspection - Front End Loader	COMPLETED DAILY	06/11/2024
Inspection - Front End Loader	COMPLETED DAILY	06/11/2024
B Service - Front End Loader	completed	06/12/2024
Inspection - Front End Loader	completed daily	05/21/2024
Inspection - Front End Loader	completed daily	05/21/2024
A Service - Front End Loader	CSA CONTRACT	05/24/2024
Smoke Bomb Cab Test	COMPLETED	06/06/2024
Inspection - Front End Loader	completed daily	05/15/2024
Service kits	Completed	05/11/2024
Inspection - Front End Loader	completed daily	05/14/2024
D Service - Front End Loader	Completed	05/08/2024
Inspection - Front End Loader	completed daily	05/14/2024
G.E.T stock	ordered / completed	04/30/2024

1x 403-0370 Dmmuset 1x 1W-5455 Clamp-V Band 4x 346-0335 Clamp band	ORDER COMPLETED	04/30/2024
Inspection - Front End Loader	completed daily	04/30/2024
WINDSCREEN LEAKING FROM TOP	Completed	05/13/2024
Inspection - Front End Loader	completed	04/15/2024
parts ordering	ordered parts	04/06/2024
PEWAG - ORDER - JOINING LINK SETS	ORDER COMPLETED	04/30/2024
Exhaust clamps	parts ordered	04/03/2024
Fire suppression	completed fire suppression - Eton from eFire & safety	04/03/2024
Smoke Bomb Cab Test	completed by Maca	04/02/2024
Inspection - Front End Loader	completed daily	04/04/2024
Inspection - Front End Loader	completed daily	04/04/2024
REPAIR FUNCTIONALITY OF ARMREST	completed by Maca	04/02/2024
Inspection - Front End Loader	completed	03/25/2024
Inspection - Front End Loader	completed	03/19/2024
Inspection - Front End Loader	completed	03/19/2024
G.E.T WORN / MISISNG	completed	03/13/2024
Inspection - Front End Loader	completed daily	03/10/2024
Implement Pump - Westrac	completed	06/19/2024
Inspection - Front End Loader	completed	02/26/2024
gasket,latch,pawl	Completed	02/17/2024
Dogbone bush	Parts Ordered	02/20/2024
FRONT TYRE CHAINS	Parts Ordered	02/20/2024
Smoke Bomb Cab Test	Completed	02/28/2024
Inspection - Front End Loader	completed daily	02/09/2024
Inspection - Front End Loader	completed daily	02/09/2024
Inspection - Front End Loader	completed daily	02/09/2024
C Service - Front End Loader	complete	04/01/2024
Inspection - Front End Loader	Complete	01/22/2024
Teeth and Gum replacement	Teeth and gums replaced	03/02/2024
Inspection - Front End Loader	completed	01/14/2024
Inspection - Front End Loader	AS PER WO-YAK-022-092	01/14/2024

A Service - Front End Loader	Carried out A-service as per service sheet.	01/14/2024
BLOWN HYDRAULIC HOSE	BLOWN HOSE REPLACED	12/28/2023
Smoke Bomb Cab Test	Complete	01/10/2024
Inspection - Front End Loader	COMPLETED DAILY	12/29/2023
B Service - Front End Loader	COMPLETED BY DOUBLE R WHEN ON SITE.	12/29/2023
Inspection - Front End Loader	COMPLETED AND WO'S CREATED FOR REPAIRS	12/24/2023
DEFECTS	completed	02/13/2024
Inspection - Front End Loader	COMPLETED DAILY	12/17/2023
Inspection - Front End Loader	COMPLETED DAILY	12/17/2023
MUDFLAP MISSING DOOR SEAL	Complete	01/10/2024
Smoke Bomb Cab Test	COMPLETE WITH NEW WO-YAK-021-916	12/28/2023
D Service - Front End Loader	COMPLETED BY ZACH	11/11/2023
mid-life and repairs completed 22-12-2022	mid-life and repairs completed 22-12-2022  COMPLETED AT AES  18241HRS	12/22/2022
Smoke Bomb Cab Test	As per work order	12/06/2023
Inspection - Front End Loader	As per work order	12/06/2023
Inspection - Front End Loader	Complete	12/06/2023
B Service - Front End Loader	Done	12/06/2023
A Service - Front End Loader	COMPLETE WITH B SERVICE WO-YAK-021-904	12/28/2023
A Service - Front End Loader	As per work order	12/06/2023
Inspection - Front End Loader	All work done in accordance to work plan.	11/24/2023
Windscreen Leak	sealed replaced L/H upper boom hose	11/12/2023
Inspection - Front End Loader	work done on WO-YAK-021-497	11/24/2023
Inspection - Front End Loader	COMPLETE	11/07/2023
REPLACE REVERSE CAMERA	Fitted	10/28/2023
Inspection - Front End Loader	COMPLETE WITH NEW WO	10/24/2023
Inspection - Front End Loader	COMPLETE WITH NEW WO	10/24/2023

Inspection - Front End Loader	COMPLETE WITH NEW WO	10/10/2023
Inspection - Front End Loader	COMPLETE WITH NEW WO	10/10/2023
Defects as per Work Plan	As per work order	09/17/2023
SERVICE A/C UNIT	As per work order	09/17/2023
Inspection - Front End Loader	complete with new WO	10/03/2023
Inspection - Front End Loader	As per work order	09/16/2023
Inspection - Front End Loader	As per work order	09/17/2023
A Service - Front End Loader	As per work order	09/17/2023
C Service - Front End Loader	As per work order	09/14/2023
Inspection - Front End Loader	completed by jonny and rye	08/27/2023
A Service - Front End Loader	COMPLETE WITH B SERVICE	08/23/2023
Inspection - Front End Loader	COMPLETED WITH NEW WO	08/24/2023
B Service - Front End Loader	Perform service as per the assigned survey.	08/27/2023
Welding / REPAIRS with next service	Replaced RH Steps	08/27/2023
	Changed hydraulic oil + filters	
Inspection - Front End Loader	COMPLETE	08/03/2023
A Service - Front End Loader	COMPLETE WITH B SERVICE	08/23/2023
REPAIRS	completed	08/26/2023
Inspection - Front End Loader	as per WO-YAK-020-251	07/27/2023
Inspection - Front End Loader	AS PER WO-YAK-020-154	07/23/2023
Caterpillar 988H Front End Loader (A service)	AS PER WO-YAK-020-023	07/02/2023
Repairs	complete	07/05/2023
Inspection - Front End Loader	complete	07/05/2023
Inspection - Front End Loader	AS PER WO-YAK-020-031	07/04/2023
Caterpillar 988H Front End Loader (D service)	complete	07/05/2023
DEFECTS	complete	07/05/2023
Inspection - Front End Loader	AS PER WO-YAK-020-011	07/02/2023
Belly Plate	complete	07/05/2023
REPAIRS / DEFECTS	complete	07/05/2023
RH safety gate taped off Rear tyres worn	Replace emergency ladder and steps - DONE Remove tape from safety gate - DONE Inspect rear tyres - Ok for use	06/11/2023

STEERING FAULTS	FULL OUT SPOOL ON STEERING WHEEL CONTROL VALVE AND REPLACED	05/19/2023
STEERING FAULT STUCK AT FULL LOCK	Removed steering valve spool and inspected Found worn/scuffed and getting stuck in housing Pinched spool from loader 67 and fitted to 95 Tested ok	05/20/2023
Steer Cylinder	Replace steer cylinder Took steer cylinder off FEL00117	05/05/2023
Lost Steering	Removed and cleaned out valve	05/08/2023
REPAIRS / DEFECTS	new work order created	06/14/2023
Rim Crack Testing	inspected	12/25/2022
OIL LEAK	Completed	12/22/2022
Rear Diff pinion seal leaking	replaced	01/30/2023
Front end loader-generic (B service)	Not required - C Service at AES	10/21/2022
Caterpillar 988H Front End Loader (A service)	Completed	10/11/2022
Caterpillar 988H Front End Loader (A service)	not required	08/23/2022
Caterpillar 988H Front End Loader (A service)	Not required	08/06/2022
Caterpillar 988H Front End Loader (A service)	Not Required	08/03/2022
Caterpillar 988H Front End Loader (A service)	Not Required	08/03/2022
Caterpillar 988H Front End Loader (C service)	as per westrac CSA	07/21/2022
Caterpillar 988H Front End Loader (A service)	as per westrac CSA	07/21/2022
Front end loader-generic (B service)	westrac	07/09/2022
Caterpillar 988H Front End Loader (A service)	westrac	07/09/2022
Front end loader-generic (B service)	westrac	07/09/2022
Broken grease line	Replaced broken grease line and test	06/15/2022
Reverse camera not working	Marked closed as backlog cleanup	10/27/2022
Front end loader-generic (E service)	Service asset as per attached service sheet	05/31/2022
Broken grease line	Replaced grease line on dog-bone	05/18/2022
Caterpillar 988H Front End Loader (C service)	as per work plan	04/04/2022
Trans Leak - Drove to Yaka to inspect, drove back to W/S to collect tools and tighten loose fittings.	Trans Leak - Drove to Yaka to inspect, drove back to W/S to collect tools and tighten loose fittings.	05/02/2022
Orange beacon light not working, transmission oil leak	Replaced transmission hose Replaced beacon bulb	05/10/2022

Beacon broken, windscreen wiper replacing, windscreen leaking into cab when wet, fire suppression unit needs fixing, transmission leaking oil	3rd party serviced fire suppression system, replaced beacon bulb , fit new windscreen wipers and siliconed window	05/02/2022
defects	repair fire suppression system	04/22/2022
Replace grease line on dog bone	Replace damaged grease line on dog bone	04/04/2022
Tension tyre chain	as per work plan	04/04/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	03/23/2022
defect	replace 'O' rings in lift cylinder Replace L/H rear steps	02/27/2022
Front end loader-generic (B service)	Service asset as per attached service sheet	02/24/2022
defect	repair oil leak from lift cylinder hose	02/18/2022
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet	02/20/2022
blown grease hose	blown grease hose remove and replace	02/09/2022
LEAKING LIFT CYLINDER HOSE O-RING	REPLACED O-RING	02/06/2022
carry out tasks	completed	02/24/2022
oil leak	replaced leaking hydraulic hose under cab	01/26/2022
coolant leak	secured loose hose clamps	01/23/2022
o ring leaking	o ring leaking	01/18/2022
hydraulic oil leak	hydraulic leak repaired	01/18/2022
aircon hose replaced and a/c system re gased	aircon hose replaced and a/c system re gased	01/16/2022
remove and replace relief valve	remove and replace relief valve	01/17/2022
Caterpillar 988H Front End Loader (A service)	carried out by westrac	12/05/2021
Caterpillar 988H Front End Loader (A service)	Service asset as per attached service sheet Vehicle is in Perth for mid life rebuild	11/15/2021
Caterpillar 988H Front End Loader (D service)	As per service sheet	09/22/2021
Caterpillar 988H Front End Loader (A service)	As per service sheet	09/22/2021
WR 0768 - AC FAULT	REPLACED AC BELT AND TESTED - OK	08/09/2021
0202 - Blown hydraulic hose	Remove and replace high pressure hydraulic hose  18,027 hours	07/29/2021

0813 - Blown hose	Travelled to Yala Removed blown hose  NO HOURS GIVEN 28/7 - 18,020 hours 30/7 - 18,029 hours	07/29/2021
1297 - SEAT	REMOVE AND REPLACE LOADER SEAT  17997 HR	07/25/2021
3406 - RHS Tyre Chains, RHS Mirror, Windscreen, Door Seals	Completed	08/02/2021
3405 - Heater not working, RHS Mirror needs replacing, Replace door seals, Seat springs need changing	Completed	08/02/2021
0170 - Exhaust leak	Travelled to break down Repaired broken exhaust clamp Ran up and recovered  NO HOURS GIVEN	06/30/2021
0158 - Drivers heater fault	carried out	07/31/2021
03024 - REPLACE DPF, INSPECT GBT (?)	Completed	05/28/2021
02704 - FIX DOOR LATCHES, MOUNT MINE RADIO	FIX DOOR LATCHES, MOUNT MINE RADIO 17310 HR	05/30/2021
Front end loader-generic (D service)	carried out	07/31/2021
02704 - Fit new straps, fix door latches, mount mine radio	Fit new straps, fix door latches, mount mine radio 17,310 km	05/30/2021
03024 - Replace DPF and inspect GET	Replace DPF and inspect GET 17,294 hours	05/28/2021
Front end loader-generic (B service)	Service asset as per attached service sheet	06/06/2021
02986 - REPLACE STEERING CYLINDER, LEAKING FROM CRACK IN WELD	REPLACE STEERING CYLINDER, LEAKING FROM CRACK IN WELD  17260 HR	05/13/2021

03085 - COMPLAINT NO OIL PRESSURE - ALARM COMING OFF AND ON	CHECK CODES - LOW PRESSURE FAULT, CHECK ECU OIL PRESSURE LOW. CONNECT MANUAL GAUGES - ALL OK. SUSPECT SWITCH U/S. WENT TO OHP NO PART AVAILABLE  17641 HR	05/11/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	06/06/2021
02940 - REPLACED LH STEERING CYLINDER	REPLACED LH STEERING CYLINDER  17001 HR	05/03/2021
Front end loader-generic (B service)	Service asset as per attached service sheet	06/06/2021
00838 - ENGINE FILTER HOSE	16909 HR	06/02/2021
02973 - ASSEMBLE STEP AND FIT AT YAKA LHS	ASSEMBLE STEP AND FIT AT YAKA LHS  16576 HR	04/22/2021
02922 - SEAT FAULT.	INSPECTED - SUSPECTED FAULTY SHOCK SHOCKS TO BE ORDERED	04/27/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	05/10/2021
03062 - REPLACE HOSE, MAKE HOSE AND REFILL TANK. TEST - ALL OK. GREASE BUCKET PIN	167474 KM	04/16/2021
02550 - Inspect and grease bucket as requested	Inspect and grease bucket as requested  15,432 hours	03/20/2021
00428 - Grease bucket pins, fix grease line	Grease bucket pins, fix grease line  16,475 hours	04/03/2021
00822 - Fit grease line olive fitter, fit new trans fitter	Fit grease line olive fitter, fit new trans fitter  16,416 hours	03/30/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	04/18/2021
Front end loader-generic (C service)	Service asset as per attached service sheet	04/18/2021
Front end loader-generic (B service)	Service asset as per attached service sheet	03/16/2021

00353: 1. AUTO GREASER NOT WORKING 2. BROKEN GREASE LINE	1. TEST POWER AT PLU, CLEAN PLUG, TEST OK 2. REMOVE BROKEN GREASE LINE, GET NEW HOSE MADE AT HEAVYSHED, FIT NEW LINE  15670 HR	02/04/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	03/02/2021
Front end loader-generic (B service)	Service asset as per attached service sheet	02/15/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	02/05/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	02/05/2021
22747 - Exhaust leak	Replace EGR hose and boost hose  14,231 hrs	12/01/2020
22662 - Grease lines, check over	Fix grease lines  14,024 hours	10/16/2020
22899 - Boost hose split	Fit new boost hose	10/16/2020
Front end loader-generic (B service)	Service asset as per attached service sheet	01/19/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	01/19/2021
Front end loader-generic (C service)	Service asset as per attached service sheet	01/19/2021
Front end loader-generic (D service)	Service asset as per attached service sheet	01/19/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	01/03/2021
Front end loader-generic (A service)	Service asset as per attached service sheet	01/03/2021
Rim Crack Testing	pos 1and 2 rims replaced by Kal tire	12/09/2020
Front end loader-generic (B service)	Service asset as per attached service sheet	12/08/2020
22665 - Fire suppression	Fix low pressure switch  14,024hr	10/19/2020
Front end loader-generic (A service)	Service asset as per attached service sheet	11/23/2020
Front end loader-generic (A service)	Service asset as per attached service sheet	11/01/2020
Front end loader-generic (C service)	Service asset as per attached service sheet	10/23/2020
Front end loader-generic (A service)	Carry out service & repairs  13,966 hour	10/15/2020
Front end loader-generic (A service)	Service asset as per attached service sheet	11/01/2020

Front end loader-generic (B service)	Service asset as per attached service sheet carried out by westrac	09/29/2020
22942 - Air con malfunction	Carry out repairs Air compressor, drier, expansion valve replacement  13,283Hr	09/07/2020
Front end loader-generic (A service)	Carry out service  13463 Km	09/21/2020
Front end loader-generic (D service)	carry out service as per service sheet	09/03/2020
23017 - Loader de-rated adblue, emissions fault	Diagnose emissions issue causing derate Found water in Adblue tank nox sensors faulty Order 2 sensor from Westrac Awaiting arrival to be fitted	08/21/2020
23037 - No A/C	Breakdown at Yakabindie, A/C not working Blow out cab filter, check for A/C frelink up Turn temp up a few degrees and check operation	08/24/2020
Front end loader-generic (C service)	Service asset as per attached service sheet	08/19/2020
Front end loader-generic (B service)	Service asset as per attached service sheet	08/19/2020
REMOVE BUCKET AND PREP FOR TRANSPORT TO RELOCATE MACHINE	BULL CRANK PIN SR122A - HAND OVER 25/6/2020 JOB CANCELLED - MEANTIME TO BE PROCEED	07/24/2020
REPAIR COOLANT LEAK	Ordered radiator cap and filled coolant Machine not tested for coolant loss due to being located to another site	06/24/2020
10634 - FAN VIBRATION/ ENGINE VIBRATION	RUN UP AND EST FAN AT HIGH SPEED AND FOUND NO FAULT POSSIBLE FAULT IN HI/SPEED SHAFT	06/10/2020
FILL GREASE POT AND INSPECT AT 11906 HRS	FILL GREASE POT AND INSPECT, MOVE REVERSER SCREEN TO LOWER POSITION	06/11/2020
10624 - Fill grease pot and inspect	Fill grease system and inspect for ship loading (iron ore)	06/02/2020
CHECK AUTO GREASER & COOLANT	6/6/20 - Made up temp grease line, main line leaking 6/6/20 - Coolant low, replace radiator pressure cap and fan, fan out of balance	06/05/2020

BRAKE ADJUSTMENT, CHECK LEFT PEDAL BRAKING	RIM PULL PARAMETER WERE SET 1 - 35% SET 2 - 36% SET 3 - 80% SRT 1 - 35% SRT 2 - 54% SET 3 - 80%	06/06/2020
REPLACE LEAKING BRAKE PUMP HOSE	Replaced brak epump hose	06/03/2020
FILL GREASE SYSTEMS & INSPECT FOR SHIP LOADING	Fill grease pot and inspect	06/02/2020
10534 - Fill grease pot and inspect	Inspection and order parts	04/28/2020
10612 - Broken grease lines	fit GREASE NIPPLE AND GREASE	05/17/2020
10613 - Adblue fault	Adblue pump making 2kpa only Westrac was called out	05/17/2020
10616 - Inspection and fill grease pot	Check all oils, fill grease por ad general checkover of unit	05/19/2020
Front end loader-generic (B service)	CARRY OUR SERVICE AS PER APPRECIATED SERVICE SHEET	05/21/2020
1986 - windscreen not sealed at bottom joint	Repaired, filled up with silicone	04/30/2020
10537 - Leaking hyd hoses	Replace main hyd control supply hose and sterrol valve hose	05/01/2020
Front end loader-generic (A service)	Complete	04/07/2020
2846 - Check machine + fill grease pot	Check machine + fill grease pot	04/01/2020
2828 - Grease and inspect	Grease and inspect	03/28/2020
1978 - Multiple repairs	All repairs carried out	02/05/2020
FIT UP REVISOIN MIRRORS	Fit out mirrors to 988k	02/24/2020
auto greaser fault/oil leaks	Repaired grease line to front buckle dog bone pin. Check and repaired grease system control module. Adjusted to max grease Inspect grease pot at 8kg	02/17/2020