

Number	Type	Date Open	Date Closed	Kilometres	Fault	Repairer / Notes
R-9180	Fault	04/01/2026			12301	UHF ISSUE.
R-8856	Reverse Be	08/29/2025			11122, 11394, 11447	REPLACED WIPER BLADES. REPLACED FRONT BRAKR PADS. REPLACED GASKET ON TURBO DRAIN.
S-7528	A - 10k	12/17/2025	12/17/2025	280,000	10,000	ACTUALLY DONE AT 280 341 KM.
R-7967	Fuel cap	09/23/2024	03/31/2025	270,000	9166	Internal Workshop - Night Shift REPLACED FUEL CAP. SERVICE COMPLETED BY TOM.
S-6875	A - 10k	03/24/2025	03/31/2025	270,000	10,059	ACTUALLY DONE AT 270507 KM.
R-7867	Intercooler	09/09/2024	08/26/2024	259,624		Internal Workshop - Night Shift REPLACED LHS INTERCOOLER LINE. FIT NEW LHS WINDOW REG.
R-7555	Headlights	06/17/2024	08/20/2024	259,941	8406	A Grade Auto Repair REPLACED HEADLIGHT BULB. Internal Workshop - Night Shift SERVICE ACTUALLY DONE AT 259941KM. REPLACED INTERCOOLER. REPLACED LHS INTERCOOLER LINE,
S-6467	A - 10k	08/19/2024	08/20/2024	259,941	8,685	REPLACED LHS WINDOW REG. Tyre rotation not done this service as they are not due.
S-6101	A - 10k	03/04/2024	03/05/2024	251,256	10,479	Service completed buy Jay.
R-7042	Door trim, f	01/10/2024	01/10/2024	247,696		Internal Workshop - Night Shift Fitted new wipers and steering wheel. Polished headlights. Fitted new toolbox to tray. Fitting new
R-5454	Tyre	11/08/2022	09/01/2023	0	5589	Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.
R-5211	Coolant	09/23/2022	09/01/2023	0	5367	Other. Check for any coolant or oil leaks - (Visual). Coolant leaking somewhere, no visual leakâ€™s Based on audit conducted by Jay
R-5333	Wipers	10/17/2022	07/17/2023	240,777	5480	Replaced wiper blades.
S-5649	A - 15k	07/13/2023	07/17/2023	240,777	15,777	
R-6442	Belt tensor	07/12/2023	07/12/2023	240,759		Internal Workshop - Night Shift Belt noise belt running offline. Inspect belt found belt tensioner faulty. Remove belt tensioner from
R-5033	UHF	08/19/2022	06/14/2023	0	5200	UHF Hand piece not working properly Replaced by Ritchie.
R-6236	Belt	05/26/2023	05/16/2023	239,336		Internal Workshop - Field Service
R-5924	Turbo	12/09/2022	12/09/2022	230,721		Q Ford Turbo replaced due to actuator being faulty.
S-4958	A - 15k	09/30/2022	10/17/2022	225,000	15,000	
R-3926	Fire exting	02/17/2022	07/21/2022	0	4250	Other. Fire Extinguisher. No extinguisher. Extinguisher not required on ute.

R-4303	Car Jack	05/17/2022	05/18/2022	212,561	4568	Other. Jack. No car jack. Jay purchased jack for ute.
R-3412	Flashing lig	06/15/2021	03/31/2022	210,000	2964	Replaced bulb. Replaced transmission supplied by Ford. Replaced front brake pads. Replaced flow metre.
S-4515	A - 15k	04/01/2022	03/31/2022	210,000	6,000	Replaced LHS indicator line.
R-4022	Windscreer	03/13/2022	03/20/2022	210,631	4329	Jay inspected and crack is not in view of driver. No replacement required yet.
S-4059	B - 15k	11/18/2021	11/18/2021	204,000	4,103	Internal Workshop Jay.
S-3518	B - 100k	03/31/2021	02/10/2021	199,897	14,333	Internal Workshop Service done by Jay Internal Workshop Service done by Steve C
S-3282	B - 100k	12/22/2020	12/22/2020	185,564	15,705	Needs 4 x new tyres
S-3109	B - 100k	04/09/2020	04/09/2020	169,859	14,093	Internal workshop B service done, general check over for NSW trip
S-3108	B - 100k	11/08/2019	11/08/2019	155,766	16,288	Internal workshop B service done, topped up fluid levels, replaced pull start housing on air compressor on B tray of ute DEFECT: rear
R-2293	Battery	06/17/2019	06/17/2019	142,978		Internal workshop Fitted new battery
R-2294	Tyres	05/14/2019	05/14/2019	142,978		Internal workshop Repaired & fitted RH steer tyre
R-2295	Tyre repairs	05/13/2019	05/13/2019	142,978		Internal workshop Fitted RHS steer - needs puncture repair Internal workshop B service done, wheel alignment & balance & rotation done, windscreen was replaced by O'Brian glass, NOTE: air
S-3107	B - 100k	05/09/2019	05/09/2019	139,478	16,335	filter was not put in properly last service - has dust in intake do SOS in 2000km & change oil
S-3106	B - 100k	11/13/2018	11/13/2018	123,143	16,950	Internal workshop Replaced a/con filter, load tested battery - all good, windscreen needs to be replaced, inspected brakes - ok
S-3105	C	05/24/2018	05/24/2018	106,193	106,193	Internal workshop Replaced wiper blades, Serviced air compressor motor and pump
S-3104	B - 100k	11/30/2017	11/30/2017	90,939	14,987	Internal workshop Inspected the brakes and they still seem ok
R-2296	Wheel aligr	09/08/2017	09/08/2017	82,237		Internal workshop Balance and Wheel alignment - Millards, Fitted a tool box, replaced the fuel line and pump for the diesel tank
S-3103	B - 100k	07/04/2017	07/04/2017	75,952	13,185	Internal workshop Checked breaks - Front @ 50% and Rear @ 70%
S-3102	B - 100k	01/24/2017	01/24/2017	62,767	15,420	Internal workshop B service done
S-3101	B - 100k	07/13/2016	07/13/2016	47,347	17,755	Internal workshop Checked output shaft movement, seems ok
S-3100	B - 100k	10/13/2015	10/13/2015	29,592	14,685	Internal workshop Monitor Movement in gearbox output shaft, Replaced ABS fuse
S-3099	B - 100k	01/27/2015	01/27/2015	14,907	14,907	Internal workshop B service done