

Number	Type	Date Open	Date Closed	Kilometres	Fault	Repairer / Notes
S-7102	A - 10k	07/08/2025	07/08/2025	320,000	10,000	Internal Workshop - Night Shift ACTUALLY DONE AT 321341 KM SERVICE COMPLETED BY TOM.
S-6906	A - 10k	04/09/2025	04/08/2025	310,000	10,000	ACTUALLY DONE AT 313076 KM.
T-184	Tyre	02/13/2025	02/13/2025	307487		Tyreplus Replaced all 4 tyres. Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H.
S-6462	A - 10k	08/13/2024	09/03/2024	300,000	8,737	ACTUALLY SERVICED AT 302132KM. Internal Workshop - Night Shift Removed battery, fuel filter, intake manifold to get to EGR to remove for new EGR. Fit EGR Cooler & Valve Fit intake manifold etc Fit bonnet Fill with fresh coolantTest drive Clean front of car of grease Clear engine code. Needs new sump plug o'ring next service - JC
R-7482	EGR Cooler	04/11/2024	04/11/2024	296,417		Replaced steering wheel Replaced plastic trim on D/S Seat Fitted GPS system Replaced all 3 unis on tail shaft Replaced LHS guard Fitted new grill Replaced EGR valve F cleaned intake Replaced RHS engine mount Polished both headlights Replaced all 4 tyres supplied and fitted by Goodyear. Fitted new toolbox tray Fitted 200L diesel tank to tray Replaced LHS front parker
S-5997	A - 15k	01/10/2024	01/10/2024	291,263	11,481	Cleaned cab out
R-5069	Wipers	08/29/2022	01/10/2024	291,253	5260	Fit new wipers and arms.
R-5453	Flashing lig	11/15/2022	09/01/2023	0	5628	Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.
R-5111	Headlights	09/05/2022	09/01/2023	0	5290, 5301	Not Working. Lights. RHS Headlight (low beam) blown Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.
R-4919	Lights	08/09/2022	09/01/2023	0	5153	Not Working. Lights. RHS Stop light blown Based on audit conducted by Jay on 1/9/23 this repair has been completed and light replaced in the last 12 months.
S-5513	A - 15k	05/22/2023	05/22/2023	279,782	14,867	
R-6327	GPS	04/12/2023	04/12/2023	27,494		A Grade Auto Repair Fitted by A Grade.
S-4762	A - 15k	08/08/2022	08/08/2022	264,915	24,579	Internal Workshop Brad Turner Closed Job Card Other. General Defects: Please upload pics. Needs wheel alignment, on visual inspection there is very noticeable positive camber and pulls hard to the left. Engine has miss at idle, blows smoke on start up. Loud injector rattle under load. Drivers door doesn't close properly due to previous damage. Wheel alignment being
R-4696	Wheel aligr	07/11/2022	07/13/2022	262,836	4978	completed 13/07/22 at Keperra tyre shop. Jay - other items do not require action.

R-4456	Brakes	05/27/2022	05/27/2022	261,023		Remove front brakes and rotors, replacing with new. Remove rear brakes, replacing drums and shoes with new. Adjust brakes. Replaced RH rear wheel stud with new. Adjust hand brake. Found front brakes and rotors need replacing.
R-4457	Brakes	05/26/2022	05/26/2022	261,012		Internal Workshop Fitted new air con pump. New belt. New radiator and shroud.
R-3604	Air Conditio	11/01/2021	11/01/2021	251,318		Internal Workshop Repaired LHR tyre - job done by Garth
R-2998	Tyres	06/28/2021	06/28/2021	246,859		Internal Workshop Fit new intercooler Found broken front gill - fit screws & speed nuts Job done by Phil D & Scott P
R-2785	Intercooler	05/05/2021	05/05/2021	242,745		Internal Workshop Service done by Max,
S-3461	B - 100k	04/16/2021	04/16/2021	240,336	9,330	Replace transmission oil
R-2231	Fuel cap	12/14/2020	04/08/2021	238,986		Internal workshop Replaced fuel cap supplied by Ford Job done by Jay
S-3520	B - 100k	01/18/2021	01/18/2021	231,006	15,013	Internal Workshop Service done by Jay
R-2281	Diff oil	08/07/2020	08/07/2020	225,983		Internal workshop Topped up rear diff with Castrol 80/90 Internal workshop Replace centre uni joint - travel home to gt puller tool for rear diff yoke / flange - replace pinion seal rear diff flange / yoke - refit tailshaft - test drive - no vibration - suggest top up diff oil - lost about 100ml
R-2282	Uni joints	08/06/2020	08/06/2020	225,983		Service done
S-70	B - 100k	04/14/2020	04/14/2020	215,993	5,593	Internal workshop Picked up new injectors, cleaned up rocker cover, replaced #4 injector seal due to damage, record injector's positions & fit with clamps, hand tightened hold down clamps, fit and tightened fuel lines, fit injector harness, fit rubber cover
R-2283	Injectors	02/04/2020	02/04/2020	211,163		Internal workshop B service done, replaced all 4 tyres with good 2nd hand ones DEFECTS: flashing light not very bright
S-3097	B - 100k	01/15/2020	01/15/2020	210,400	9,468	Internal workshop B service done, Needs UHF remote, flashing light does work but not very clear, front brake pads just under 50%, needs new tyres both front & rear - Brad organised with Jay to book in for tyres 5/9/19
S-3096	B - 100k	09/05/2019	09/05/2019	200,932	15,874	Diesel Australia Had 4 injectors checked by Diesel Australia - 2 failed, replaced 3 with 2nd hand ones and the 4th one with new injector (in cylinder 4), all injectors coded by Diesel Australia
R-2284	Injectors	05/31/2019	05/31/2019	190,909		Internal workshop B service done
S-3095	B - 100k	03/08/2019	03/08/2019	185,058	21,903	Internal workshop Topped up coolant, replaced wiper blades
S-3094	B - 100k	07/12/2018	07/12/2018	163,155	8,010	Internal workshop 4 New tyres and wheel alignment
R-2285	Tyres	07/02/2018	07/02/2018	169,150		Internal workshop Air con low pressure line from tx to condensor replaced , full regas, replaced coolant with Penrite 8 year
R-2286		04/18/2018	04/18/2018	160,768		Internal workshop Tyres are getting low again, replaced front rotors and pads
S-3093	B - 100k	03/06/2018	03/06/2018	155,145	15,886	Internal workshop Millards Carried out a full wheel alignment on the vehicle
S-3092	B - 100k	10/18/2017	10/18/2017	139,259	15,387	Internal workshop Repaired in line fuse for the diesel pump, feull wheel alignment at millards
S-3091	B - 100k	06/15/2017	06/15/2017	123,872	17,262	Internal workshop Rewired LHS rear brake light
S-3090	C	01/25/2017	01/25/2017	106,610	106,610	Internal workshop Replaced tyres, wheel nuts and wheels off Unit 440 which had only done 3000ks, replaced both wiper blades
R-2287	Tyres	10/25/2016	10/25/2016	93,805		Internal workshop B service done
S-3089	B - 100k	09/21/2016	09/21/2016	90,127	15,900	Internal workshop Replaced front brake pads and rotors
R-2288	Brake pads	08/26/2016	08/26/2016	88,000		Internal workshop B service done
S-3088	B - 100k	04/27/2016	04/27/2016	74,227	16,159	Internal workshop Rotated tyres
R-2289	Tyres	02/11/2016	02/11/2016	66,300		Internal workshop Pushed dint out of LHS door, replaced all tyres with coopers again, painted rusty battery clamp, panel beated the engine bash plate straight again
S-3087	B - 100k	11/27/2015	11/27/2015	58,068	58,068	Internal workshop Topped Up Brake Fluid, Passenger door has been damaged, tyres all all nearly worn out again!?!
R-2290	Check over	07/28/2015	07/28/2015	43,249		Internal workshop Rotated tyres
R-2291	Tyres	03/18/2015	03/18/2015	28,230		Internal workshop Fitted new tyres as the old ones were compleatly worn out. Very Prematurly!
R-2292	Tyres	11/04/2014	11/04/2014	13,716		