

Number	Type	Date Open	Date Closed	Kilometres Closed	Fault	Repairer / Notes	Cost / Invoice
R-8622	Windscreen Replacement	06/09/2025			10531, 10908	Fixer Windscreens Star cracked in windscreen	\$0.00
R-8342	Brake lights	02/19/2025			10907, 11412, 9870	Internal Workshop - Night Shift Rear LH brake light out	\$0.00
R-8999	Brake booster	11/25/2025	11/25/2025	204,422		Internal Workshop - Field Service Replaced brake booster, supplied by Q-Ford springwood Internal Workshop - Night Shift REPLACED FRONT BRAKE PADS.	\$0.00
S-7048	B - 100k	06/19/2025	06/18/2025	200,000	93,028	ACTUALLY COMPLETED AT 201346 KM.	\$0.00
S-6925	A - 10k	04/29/2025	04/24/2025	190,000	10,000	ACTUALLY SERVICED AT 193951KM.	\$0.00
S-6924	A - 10k	04/29/2025	04/24/2025	190,000	10,000	Internal Workshop - Night Shift ACTUALLY SERVICED AT 193951KM.	\$0.00
T-185	Tyre	02/18/2025	02/18/2025		185,515	Tyreplus All 4 tyres replaced. Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H. ACTUALLY DONE AT 181223KM	\$0.00
S-6761	A - 10k	01/23/2025	01/23/2025	180,000	10,000	Internal Workshop - Night Shift SERVICE COMPLETED BY AZAAK H. ACTUALLY DONE AT171415KM.	\$0.00
S-6637	A - 10k	11/04/2024	11/04/2024	170,000	10,000	Internal Workshop - Night Shift SERVICE COMPLETED BY JARROD H. FRONT TIMING CASE COVER GOT REPLACED AND RE-SEALED BY Q FORD SPRINGWOOD UNDAE WARRANTY DUE TO IT LEAKING.	\$0.00
S-6483	A - 10k	08/28/2024	09/09/2024	160,000	10,000	Internal Workshop - Night Shift SERVICE COMPLETED BY JAROD H. ACTUALLY DONE AT 152942KM	\$0.00
S-6411	A - 10k	07/16/2024	07/16/2024	150,000	10,000	TIMING COVER LEAKING. Service completed by Tyson. Service completed at 145000 on the 27/05/2024.	\$0.00
S-6264	A - 10k	05/27/2024	05/27/2024	140,000	4,899	Service back dated to 140000 to make services realign Tyre rotation not done this service as they are not due.	\$0.00
S-6099	A - 10k	03/04/2024	03/05/2024	135,101	14,980	Service completed buy Jay.	\$0.00
S-5947	A - 15k	11/10/2023	11/10/2023	120,121	13,149	service completed by Jay	\$0.00
R-6520	Guard	07/31/2023	09/08/2023		0	6728 Internal Workshop - Night Shift Rear drivers side mudguard loose Tightened as per Jay Audit 8/9/23	\$0.00
R-6519	Brake lights	07/31/2023	09/08/2023		0	6727 Internal Workshop - Night Shift Repaired wiring as per Jay Audit 8/9/23	\$0.00
R-6480	Wiper blades	07/25/2023	08/01/2023		106,972	6706 Internal Workshop - Night Shift Wiper blades replaced.	\$0.00
R-6479	Tyres	07/25/2023	08/01/2023			6705 Good Year Beenleigh New tyres and rotation at Goodyear Beenleigh. Internal Workshop - Night Shift Replaced both brake light globes Rear drive shocks starting to leak Clean and adjusted rear brakes Remoe trans pan and filter - replace Top up and check trans oil Secure loose mud guard	\$0.00
S-5696	B - 105k	07/26/2023	08/01/2023	106,972	106,972	Tyres need replacing soon	\$0.00
R-6239	UHF	05/16/2023	05/17/2023		97,525	6408 A Grade Auto Repair A grade auto found the cord between the unit and hand piece faulty. They removed cord	\$0.00
R-5858	First Aid Kit	02/13/2023	03/27/2023		90,136	6030 Check first aid kit. Don't have one Matilda ordered one 28/02/23 and gave to Michael.	\$0.00
R-5274	Lights	10/04/2022	03/27/2023		90,136	5425 Internal Workshop - Field Service Not Working. Check all lights, reflectors & lenses. Rear brake light out.	\$0.00
R-5112	Wipers	09/05/2022	03/27/2023		90,136	5295 Internal Workshop - Night Shift Other. Wipers. Needs new ones. Thomas - replaced wipers.	\$0.00
R-5045	Tyre	08/23/2022	03/27/2023		90,136	5228 Other. Tyre Condition (Visual). Tyre rotation. Jay - tyres all even.	\$0.00
S-5475	A - 15k	03/27/2023	03/27/2023	90,136	15,215	Internal Workshop - Night Shift Completed by Tyson.	\$0.00
S-5241	A - 15k	12/20/2022	12/20/2022	74,921	14,295	Internal Workshop - Field Service Completed by Thomas.	\$0.00
S-5015	A - 15k	09/26/2022	09/26/2022	60,626	15,626	COMPLETED BY THOMAS	\$0.00
S-4838	A - 15k	06/14/2022	06/14/2022	45,000	15,000		\$0.00
S-4273	A - 15k	02/08/2022	02/08/2022	30,000	15,000		\$0.00
S-4043	A - 15000	09/01/2021	09/01/2021	15,000	15,000	Internal Workshop	\$0.00