

Number	Type	Date Open	Date Closed	Kilometres	Fault	Repairer / Notes
S-7729	A - 10k	04/02/2026	04/07/2026	315,000	10,000	Internal Workshop - Night Shift ACTUALLY DONE AT 317070 KM.
S-7295	A - 10k	09/15/2025	09/15/2025	305,000	10,000	Internal Workshop - Night Shift ACTUALLY DONE AT 305771 KM System was playing up.
S-6879	B - 100k	03/28/2025	03/28/2025	295,000	0	So we had to add this service in to clear the service history.
R-8193	Brakes	11/29/2024	03/19/2025	295,000	9559	Internal Workshop - Night Shift REPLACED FRONT BRAKE PADS AND ROTARS.
R-7157	Engine mou	02/01/2024	03/19/2025	295,000		Internal Workshop - Night Shift REPLACED RHS ENGINE MOUNT. SERVICE COMPLETED BY TOM.
S-6864	B - 100k	03/19/2025	03/19/2025	295,000	101,395	STILGOT TO COMPLETE THE 100K SERVICE.
S-6269	A - 10k	05/30/2024	06/26/2024	280,000	7,867	SERVICE COMPLETED BY TYSON E.
R-7158	Transmissi	02/01/2024	03/04/2024	275,558		Internal Workshop - Night Shift Replaced trans cooler with 2nd had one. RHS engine mount needs replacing - JC
S-5998	A - 15k	01/10/2024	01/16/2024	272,133	14,907	Trans cooler starting to leak - JC
R-5446	UHF	11/10/2022	09/01/2023		5602	Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.
R-4944	Battery	08/11/2022	06/14/2023		5159	Not Working. Battery not keeping charge. Been replaced, unknown date.
R-4757	Transfer ca	07/16/2022	06/14/2023		5017, 5020	Transfer case leaking Replaced output seal of transfer case. Done by Steve. Internal Workshop Completed by Ritchie.
S-5485	A - 15k	04/05/2023	04/05/2023	257,226	17,226	Has broken engine mount (R-6174).
R-4536	Fire extingui	06/20/2022	07/07/2022		4795	Other. Fire Extinguisher. Not installed Jay purchased a new one for this unit.
R-4539	Engine	06/20/2022	06/20/2022	242,400	4794	Other. General Defects: Please upload pics. Engine ticks loud on first start up in cold weather. No action
S-4614	A - 15k	06/08/2022	06/08/2022	240,000	15,625	Completed by Steven Lewis.
R-3694	Tyre	12/12/2021	05/09/2022	237,530	3998, 4133	Replaced tyres week 09/05/2022 by Good Year Beenleigh.
R-3898	UHF	02/14/2022	03/14/2022	251,488	4208	UHF hand piece replaced, parts from Maxi Parts. Jay.
R-3899	Windscreer	02/14/2022	02/21/2022	228,582	4209	Jay inspected and crack is not in view of driver. No replacement required yet.
R-3902	Wipers	02/14/2022	02/14/2022		0 4211, 4328	Replaced by Steve Cremin on site.

R-3901	Fire extingui	02/14/2022	02/14/2022	250,124	4210	Extinguisher is in cab under seat, not fitter to ute.
R-3417	Gearbox	06/25/2021	01/26/2022	224,375	3041, 3303	Replaced trans.
R-2610	Electrical	03/16/2021	01/26/2022	224,375	2087, 2828	Internal Workshop Replaced.
S-4262	A - 15k	01/26/2022	01/26/2022	224,375	30,770	
R-3746	Fuel cap	01/09/2022	01/04/2022	221,943	4049	Replaced fuel cap.
R-3490	Wheel aligr	10/20/2021	11/21/2021	217,126	3828	Tyre Power Tyre shop in Beaudesert done wheel alignment. Internal Workshop Service done by Max, Replaced transmission oil & filter,
S-3460	B - 100k	04/16/2021	04/16/2021	193,605	11,173	Need to book vehicle in at Ford - trans still shifting hard
R-2414	Gearbox	01/28/2021	01/28/2021	186,088		Internal Workshop Replace gearbox
S-3241	B - 100k	01/04/2021	01/04/2021	182,432	8,532	Internal Workshop Service done by Steve Cremin
S-3236	B - 100k	10/02/2020	10/02/2020	173,900	15,000	Internal Workshop Service done by Steve Cremin
R-221	Seatbelt	08/05/2020	08/07/2020	0		Clip was handed over to Michael Shield to replace
S-285	B - 100k	06/24/2020	06/24/2020	158,900		Service done Internal workshop REPLACED MOTOR - replaced: new battery, new belt, both headlight bulbs, new EGR cooler,
S-3131	C	11/29/2019	11/29/2019	143,000	143,000	windscreen wipers, new tyres, also replaced engine oil, oil filter, fuel filter, air filter & a/con filter
S-3130	B - 100k	09/19/2018	09/19/2018	129,420	16,226	Internal workshop Replaced front brake pads, rubber exhaust mount missing (halfway down under tray body)
S-3129	B - 100k	03/21/2018	03/21/2018	113,194	15,070	Internal workshop Put rear number plate back on
S-3128	B - 100k	10/05/2017	10/05/2017	98,124	15,139	Internal workshop B service done
R-2302	Battery	05/18/2017	05/18/2017	85,263		Internal workshop Replaced the battery
S-3127	B - 100k	04/20/2017	04/20/2017	82,985	17,754	Internal workshop B service done
R-2303	Wheel aligr	01/06/2017	01/06/2017	73,888		Internal workshop Front end alignment and wheel balance, replaced diesel transfer pump on the 600 ltr tank
S-3126	B - 100k	09/27/2016	09/27/2016	65,231	12,332	Internal workshop Replaced the fuce for the 12v plug
S-3125	B - 100k	05/16/2016	05/16/2016	52,899	21,633	Internal workshop Topped up Brake fluid, cleaned air con filter.
S-3124	B - 100k	08/18/2015	08/18/2015	31,266	15,492	Internal workshop Puncture repair to front right hand tyre
S-3123	B - 100k	03/30/2015	03/30/2015	15,774	15,774	Internal workshop Rear Diff Oil Low