DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
27/10/2018	209	XN75AH	23742	35404	Elect\SC	NO TRAILER LIGHTS	REPLACED BLOWN FUSE AND ELECTRICAL LEAD
31/10/2018	209	XN75AH	23742	40000	VehService\BS	B SERVICE	K & J COMPLETED B SERVICE AS PER AGREEMENT
31/10/2010	203	7(117 37 (11	237 13	10000	Venservice (BS	SOFTWARE CAMPAIGN 181612 -	K & J TRUCKS - CARRIED OUT SOFTWARE UPDATE
21/11/2018	209	XN75AH	24016	61861	DrCabElect	RADIO	CAMPAIGN AS REQUIRED
29/11/2018	209	XN75AH	24121	56905	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER ATTACHED CHECKLIST
							SCANIA - PROMOTIONAL MAINTENANCE - B SERVICE, AND
30/01/2019	209	XN75AH	24956	89641	VehService\BS	B SERVICE	CHANGE WIPER BLADES
25/02/2019	209	XN75AH	25495	110143	DriCabRep\WSCR	Windscreen Replacement	Windscreen Replacement
28/02/2019	209	XN75AH	25224	110662	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER CHECKLIST
							COMPLETED ANNUAL COMPLIANCE CHECK AS PER
2/03/2019	209	XN75AH	25426	114223	COMP\AI	Annual Inspection	CHECKLIST
						BUNK COOLER KEEPS TURNING	
30/03/2019	209	XN75AH	25680	131753	DrCabElect	OFF	SENT TO BRISKAIR UNDER WARRANTY.
							SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
							MAINTENANCE SCHEDULE.
							REMOVED AND REPLACED NOX SENSOR. CARRIED OUT
							DEVALIDATION TEST. REPLACED MISSING RETARDER BOLT
							POWER STEERING LINE LEAKING: TIGHTENED FITTING AND
							CLEANED PIPE.
							CHECK AND REPORT HIGH EMISSIONS LIGHT ON DASH,
							REDUCED ENGINE OUTPUT: Checked fault codes, found
							active fault for exhaust temp sensor T113. Carried out
							software updates. Carried out calibration after updates and
							cleared all fault codes. Road test vehicle.
30/03/2019	209	XN75AH	25679	131753	VehService\BS	B SERVICE	

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
						BUNK COOLER NOT WORKING	
13/04/2019	209	XN75AH	25882	143375	DrCabElect	AGAIN	REPAIRED UNDER WARRANTY BY BRISK AIR
							_
							RAY HALL TYRES- FITTED 8 X NEW FALKEN 295/80R22.5
19/04/2019	209	XN75AH	26709	146748	TYRES\DRIVE	FIT NEW TYRES	152/148M BI851A TYRE TO POS 5, 6, 7, 8, 9, 10, 11, 12
							RAY HALL TYRES - FITTED 2 X NEW CONTINENTAL
23/04/2019	209	XN75AH	26537	148501	TYRES\STEER	FIT NEW TYRES	385/65R22.5 160K HSR2 20P TYRE POS 1 & 2
29/04/2019	209	XN75AH	26032	152192	VehService\AS	A SERVICE	A Service completed as per checklist, all ok.
						ELECTRICAL PLUG NEEDS TO BE	
1/05/2019	209	XN75AH	26096	154418	Elect	REPLACED.	REPLACED TRAILER PLUG
5/05/2019	209	XN75AH	26250	156918	DriCabRep\WBW	Wiper Blades	Changed wiper blades
							SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
5/06/2019	209	XN75AH	26950	173682	VehService\BS	B SERVICE	MAINTENANCE SCHEDULE.
					Breakdown\Breakdow		
12/06/2019	209	XN75AH	26951	177754	n	Breakdown	Scania attended breakdown and replaced faulty APS unit
2/07/2019	209	XN75AH	27121	193856	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER CHECKLIST
12/07/2019	209	XN75AH	27451	200540	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES ROTATED TYRES POS 1, 2
							RAY HALL TYRES ROTATED TYRES POS 5, 6, 7, 8, 9, 10, 11 &
12/07/2019	209	XN75AH	27452	200540	TYRES\ROTATE	ROTATE TYRES	12
							B SERVICE COMPLETED BY K & J SCANIA FLEX SERVICE - AS
8/08/2019	209	XN75AH	27600	211460	VehService\BS	B SERVICE	PER CHECKLIST
8/08/2019	209	XN75AH	27652	211460	Elect\P/BRAKE AL	PARK BRAKE ALARM	PARK BRAKE ALARM INSTALLED BY K & J
23/10/2019	209	XN75AH	28382	264370	DriCabRep\Damage	SUNVISOR BROKEN	Replaced broken sunvisor
							SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
23/10/2019	209	XN75AH	28381	264370	VehService\BS	B SERVICE	MAINTEANCE SCHEDULE
23/11/2019	209	XN75AH	28766	285061	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER CHECKLIST
5/12/2019	209	XN75AH	29035	294254	Elect\EP	Suzi Socket	Replaced Suzi lead socket.
					•		SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
16/01/2020	209	XN75AH	29932	314498	VehService\BS	B SERVICE	MAINTENANCE SCHEDULE

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
29/01/2020	209	XN75AH	29813	325554	DriCabRep	Batteries	Replaced Cab Cooler Batteries
4/02/2020	209	XN75AH	30061	329310	TYRES\PUNT	Puncture	RAY HALL TYRES - REPAIRED PUNCTURE TO POS 12
							RAY HALL TYRES - FITTED 2 X NEW FALKEN 385/65R22.5
29/02/2020	209	XN75AH	30425	345437	TYRES\STEER	FIT NEW TYRES	160K RI151 TO POS 1 & 2
29/02/2020	209	XN75AH	30428	345437	TYRES\DRIVE	FIT NEW TYRES	RAY HALL TYRES - FITTED 8 X NEW FALKEN 295/80R22.5 152/148M BI851A TYRE TO POS 5, 6, 7, 8, 9, 10, 11, 12
3/03/2020	209	XN75AH	30289	350909	COMP\AI	Annual Inspection	COMPLETED ANNUAL COMPLIANCE CHECK. ALL OK
6/03/2020	209	XN75AH	30204	350909	VehService\AS	A SERVICE	'A' SERVICE COMPLETED
							K & J - HARDWIRE 12V TWIN AUX PLUG, FIT NEAR UHF HANDPIECE. HARD WIRE 12v TWIN AUX PLUG. FIT NEAR UHF RADIO. HARD WIRE SUPPLY WIRE RELAY SWITCH AND SUPPLY RELAY SWITCH FUSES. RUN WIRES. SECURE AUXILARY PLUGS NEAR UHF RADIO. FIT AND TEST. R1 REPAIR/REFIT SPRING AT L/H END OF SLEEPER SPRING AT L/H/S OF SLEEPER CAME OUT OF PLACE. REFITTED AND TIGHTENED SCREWS. REPAIR/REFIT SPRING AT L/H END OF SLEEPER R1 CHECK/REPAIR DOWNHILL SPEED CONTROL DOWN HILL SPEED CONTROL AND ADAPTIVE CRUISE CONTROL INOPERABLE DUE TO IMPACT DAMAGE TO DISTANCE SENSOR. REPLACED DISTANCE SENSOR,
30/03/2020	209	XN75AH	30613	366105	VehService\BS	FLEX SERVICE	CALIBRATED AND ROAD TESTED.
23/04/2020	209	XN75AH	30909	377185	Elect\BATT	BATTERIES	REPLACED DEAD BATTERIES
1/05/2020	209	XN75AH	31359	380936	TYRES\ROTATE	ROTATE TYRES	RAY HALL TYRES ROTATED TYRES POS 1, 2. POS 5, 6, 7, 8, 9, 10, 11, 12
7/05/2020	209	XN75AH	31087	387359	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER CHECKLIST. REPLACED HUB CAP

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
2/06/2020	209	XN75AH	31417	400833	Elect\EP	TRAILER ELECT PLUG	REPLACED ELECTRICAL PLUG ON TRAILER
							SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
							MAINTENANCE SCHEDULE.
							WINDSCREEN WIPER WASHER PIPE SPLIT - REPLACED
							DOOR HINGE BOLT LOOSE -TIGHTENED
23/06/2020	209	XN75AH	31638	415923	VehService\BS	B SERVICE	THROUGH SHAFT SEAL LEAKING - REPLACED SEAL
28/06/2020	209	XN75AH	31703	416683	Engine	ENGINE LIGHT ON	CLEARED INACTIVE CODES ALL OK
20/07/2020	209	XN75AH	32212	440373	TYRES\PUNT	PUNCTURE REPAIR	RAY HALL TYRES REPAIRED A PUNCTURE TO POS 20
							RAY HALL TYRES ROTATED TYRES POS 5, 6, 7, 8, 9, 10, 11 &
20/07/2020	209	XN75AH	32213	440373	TYRES\ROTATE	ROTATE TYRES	12
							COMPLETED 'A' SERVICE, ALL OK.
21/07/2020	209	XN75AH	31889	440375	VehService\AS	A SERVICE	REPLACED WIPER BLADES
19/08/2020	209	XN75AH	32186	459229	WINDSCREEN	CRACK IN WINDSCREEN	REPLACED WINDSCREEN, ALL OK
							SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
1/09/2020	209	XN75AH	32288	467618	VehService\BS	B SERVICE	MAINTENANCE SCHEDULE
7/09/2020	209	XN75AH	32724	470113	TYRES\STRIP/FIT	TYRES	RAY HALL TYRES STRIPPED & FLIPPED POS 1, 2
4/10/2020	209	XN75AH	32836	491021	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER ATTACHED CHECKLIST
							RAY HALL TYRES - FITTED 2 X NEW KUMHO 385/65R22.5 20L
24/11/2020	209	XN75AH	33431	519329	TYRES\TP01	FIT NEW TYRES	LS03 (160k) TO POS 1 & 2
							SCANIA - COMPLETED B SERVICE UNDER FLEXIBLE
2/12/2020	209	XN75AH	33646	518796	VehService\BS	B SERVICE	MAINTENANCE SCHEDULE
7/12/2020	209	XN75AH	33914	535745	Elect\BATT	FLAT BATTERIES	TESTED BATTERIES - REPLACED
4/01/2021	209	XN75AH	33906	549873	Chassis\AL	AIR DRIER PIPE	REPLACED AIR COMP TO AIR DRIER SUPPLY PIPE
11/01/2021	209	XN75AH	33725	545982	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE, ALL OK
						FAULTY ELECTRIAL TRAILER	
						PLUG, BLINKERS ONLY	
4/02/2021	209	XN75AH	34279	568693	Elect	WORKING SOMETIMES	REPLACED TRAILER ELCECTRIC PLUG
						WIPER BLADES NEED	
24/02/2021	209	XN75AH	34580	588460	DrCabElect	REPLACING	REPLACED WIPER BLADES

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
24/02/2021	209	XN75AH	34578	588460	VehService\AS	A SERVICE	A SERVICE COMPLETED AS PER CHECKLIST
1/03/2021	209	XN75AH	34615	568000	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK
11/03/2021	209	XN75AH	34957	596403	TYRES\STRIP/FIT	STRIP & FIT	RAY HALL TYRES STRIP AND FLIP POS 1, 2, ROTATE
11/03/2021	209	XN75AH	34958	596403	TYRES\DRIVE	FIT NEW TYRES	RAY HALL TYRES - FITTED 8 X NEW FALKEN 295/80R22.5 152/148M BI851A TYRE TO POS 5, 6, 7, 8, 9, 10, 11, 12
12/03/2021	209	XN75AH	34733	596404	COMP\AI	Annual Inspection	ANNUAL COMPLIANCE CHECK COMPLETED
22/04/2021 23/04/2021	209 209	XN75AH XN75AH	35552 35291	620031 619456	TYRES\ROTATE VehService\AS	TYRE ROTATION A SERVICE	RAY HALL TYRES ROTATED TYRES POS 5, 6, 7, 8, 9, 10, 11, 12 A SERVICE COMPLETED AS PER CHECKLIST
23/04/2021	209	XIV/SAH	35291	019450	venservice (AS	A SERVICE	RAY HALL TYRES - FITTED 2X NEW FALKEN 385/65R22.5
24/05/2021	209	XN75AH	35834	636484	TYRES\STEER	FIT NEW TYRES	160K RI151 TO POS 1 & 2
21/05/2021	209	VNIZEALI	35829	638693	Breakdown\Breakdow	BREAKDOWN	ADTRANS ATTENDED BREAKDOWN: OIL LEAK FROM POWER STEERING AREA. INSPECTED AND FOUND POWER STEERING LEAK FROM MAIN LINE FROM POWER STEERING PUMP. REMOVED HOSE ASSEMBLY AND HAD HOSE ASSEMBLY MADE UP. FITTED NEW POWER STEERING PIPE ASSEMBLY. BLED SYSTEM AND RECHECKED FOR LEAKS. ALL OK.
31/05/2021	209	XN75AH	35829	638693	n	BREAKDOWN	
16/06/2021	209	XN75AH	35788	640394	VehService\BS	B SERVICE	CARRIED OUT 'B' SERVICE FIX CAB TILT LEAK
2/07/2021	209	XN75AH	36361	660492	VehService\AS	A SERVICE	CARRIED OUT 'A' SERVICE
						EXHAUST LEAK	SCANIA AS PER INVOICE CHECK AND REPORT EXHAUST LEAK CAUSE: EXHAUST FLEX PIPE DEFORMED REMEDY: DIAGNOSED AND FOUND EXHAUST FLEX PIPE ON THE LEFT HAND SIDE OF ENGINE TO BE DEFORMED AND LEAKING. REMOVED AND REPLACED PIPE WITH GASKETS AS
14/07/2021	209	XN75AH	36771	606941	Breakdown	SENT TO SCANIA	REQUIRED - ALL OK

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
31/07/2021	209	XN75AH	36818	679520	TYRES\ROTATE	ROTATE TYRES	HALLS TYRES - ROTATE POS 1 & 2
2/08/2021	209	XN75AH	36728	679529	VehService\BS	B SERVICE	CARRIED OUT 'B' SERVICE
							TRUCK EEZ - AS PER INVOICE
							CALL OUT AIR LEAK/HEATER NOT WORKING
							CHECK AND REPAIR AIR LEAK FROM LEFT HAND FRONT OF
							ENGINE BAY. SUPPLY & FIT METRIC JOINER TO AIR LINE
							WRAP IN RUBBER AND CABLE TIE HEATER AND AIR LEAK
18/08/2021	209	XN75AH	37401	689938	Breakdown	BREAKDOWN - AIR LEAK	NOW OK
3/09/2021	209	XN75AH	37112	701431	VehService\AS	A SERVICE	CARRIED OUT 'A' SERVICE
							HALLS TYRES - ROTATE POS 1 & 2 - FLIP ON RIM
9/09/2021	209	XN75AH	37174	703992	TYRES\ROTATE	ROTATE TYRES	ROTATE POS 5, 6, 7, 8, 9, 10, 11, 12
							COMPLETED 'B' SERVICE
22/10/2021	209	XN75AH	37708	718823	VehService\BS	B SERVICE	REPLACED MISSING HUBCAPS
11/11/2021	209	XN75AH	38117	725696	Elect\EP	ELECTRICAL PLUG	REPLACED FAULTY ELECTRICAL PLUG - ALL OK
							REMOVED POWER STEERING PUMP
4/12/2021	209	XN75AH	38247	736076	Steering\PS	POWER STEERING PUMP	REPLACED WITH NEW PUMP AND REFILL WITH FLUID
							REMOVE EXHAUST FLEX, CLEAN UP AND WELD CRACKS
4/12/2021	209	XN75AH	38248	736076	EXH	EXHAUST FLEX CRACKED	REFIT FLEX
11/12/2021	209	XN75AH	38294	738735	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK
11/12/2021	209	AN73AII	30234	730733	venservice (A3	A SERVICE	HALLS TYRE SERVICE - AS PER INVOICE 209588
12/01/2022	209	XN75AH	38953	747878	TYRES\ROTATE	ROTATE TYRES	ROTATE TYRES POS 1 & 2
12/01/2022	203	ANTOAN	30333	747070	TINESTROTATE	ROTATE TIMES	COMPLETED 'B' SERVICE - ALL OK
18/02/2022	209	XN75AH	39041	759664	VehService\BS	B SERVICE	NEEDS RIGHT HAND SIDE WHITE PARTY HAT LIGHT
10/02/2022	203	7.117 37 111	33041	73300-7	venservice (DS	D SERVICE	REPLACED CRACKED WINDSCREEN
19/02/2022	209	XN75AH	39200	759583	WINDSCREEN\WSCR	WINDSCREEN	NORTHEAST AUTOGLASS - INVOICE 12463
,,			2020		1111123011211 (173011		
19/02/2022	209	XN75AH	39045	759664	COMP\AI	Annual Inspection **PASS**	COMPLETED ANNUAL COMPLIANCE - ALL OK

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							SCANIA - WARRANTY - PLUGGED IN ACTIVE CODE FOR FUEL
							PRESSURE CHECKED FOR LEAKS, CLEANED OUT FUEL FILTER
							HOUSING. FOUND PIPE BREATHING IN AIR BECAUSE IT WAS
						BREAKDOWN - TURNING OVER	SPLIT. REPLACED THE WHOLE LINE FROM FUEL FILTER
8/03/2022	209	XN75AH	41526	768163	Breakdown	NOT FIRING	HOUSING TO TANK. BLEED SYSTEM - ALL OK
							CONNECTED LAPTOP AND FOUND A FAULTY EXHAUST
						TRUCK IN LIMP MODE	TEMPERATURE SENSOR
						INCREASED EXHAUST	REMOVED & REPLACED THEN CLEARED CODE
17/03/2022	209	XN75AH	39714	775984	Engine	EMISSIONS SYMBOL ON DASH	TEST DROVE - ALL OK
							SCANIA - AS PER INVOICE 41236864
							Carry out devalidation on vehicle
							Vehicle passed and no fault codes
							Check emission control, 1 off, in exhaust 179.40 1
							system. Incl. use Scania Diagnos.
22/03/2022	209	XN75AH	39329	774110	EXH	ADBLUE DEVALIDATION	211002, DC16, Air compressor silencer, remove plate
						DASH DISPLAY SAYS AIR FILTER	
2/04/2022	209	XN75AH	39715	777824	Engine	BLOCKED	REPLACED A WET AIR FILTER - ALL OK
							SCANIA - AS PER INVOICE 32235043
							CAUSE: ENGINE MALFUNCTION TURNING OVER NOT FIRING
							REMEDY: CONNECTED COMPUTER AND FOUND ACTIVE
							FAULT CODE FOR LOW FUEL PRESSURE.
							CHECKED FOR LEAKS - NO LEAKS, CHECKED FUEL FILTER
							HOUSING - FULL OF DIRT CLENED OUT AND
							BLED SYSTEM. FULL OF AIR INSPECTED FUEL LINE FROM
						BREAKDOWN	FILTER TO TANK AND FOUND LINE WAS SPLIT.
					Breakdown\Breakdow	ENGINE MALFUNCTION	REPLACED THE WHOLE FUEL LINE, BLED THE SYSTEM.
4/04/2022	209	XN75AH	39322	768163	n	TURNING OVER NOT FIRING	CHECKED OVER AND ALL OK

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							HALLS TYRE SERVICE - AS PER INVOICE 211724
							FIT 4 X NEW FALKEN 295/80R22.5 152/148M BI851A TO
11/04/2022	209	XN75AH	39541	778794	TYRES\DRIVE	FIT NEW TYRES	POS 9, 10, 11, 12.
12/04/2022	209	XN75AH	39351	780158	VehService\AS	A SERVICE	CARRIED OUT 'A' SERVICE
							CASINO TRUCK REPAIRS - AS PER INVOICE 1367
							TERMINAL WAS BROKEN ON BATTERY.
							DIDN'T HAVE THE CORRECT TERMINAL MADE A
							TEMPORARY FIX. REPLACED BATTERY LEAD ONCE BACK AT
26/04/2022	209	XN75AH	39683	782254	Breakdown\BATT	BREAKDOWN - BATTERY	WORKSHOP
						STARTER MOTOR	REMOVED AND REPLACED STARTER MOTOR.
26/04/2022	209	XN75AH	39837	782367	Elect\BATT	BATTERIES	REPLACED POSITIVE BATTERY LEAD AND BATTERIES
							REMOVED AND REPLACED FRONT DIFF, DIFF SEAL AND AXLE
							GASKETS.
26/05/2022	209	XN75AH	39954	788970	DrivLine\FwdDiff	BLOWN DIFF	REFILLED WITH OIL AND TEST DROVE - ALL OK
28/05/2022	209	XN75AH	39955	789481	DrivLine\DiffOil	DIFF OIL CHANGE	REPLACED DIFF OIL AND FILTERS
28/05/2022	209	XN75AH	39956	789481	DrivLine\TransOil	TRANMISSION OIL CHANGE	REPLACED TRANSMISSION OIL AND FILTER
							MOORES HEAVY TYRE SERVICE - AS PER INVOICE 0232
29/06/2022	209	XN75AH	41033	798364	TYRES\ROTATE	ROTATE TYRES	ROTATE POS 9, 10, 11, 12
1/07/2022	209	XN75AH	40189	800420	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE - ALL OK
							REMOVE BROKEN MIRROR ASSEMBLY AND FIT NEW
							ASSEMBLY
6/07/2022	209	XN75AH	40353	801665	DriCabRep	MIRROR	WIRE UP LIGHT ON MIRROR COVER
							COMPLETED 'B' SERVICE - ALL OK
30/08/2022	209	XN75AH	41200	819052	VehService\BS	B SERVICE	NEEDS SPINNER FILTER
							REPLACED SPINNER FILTER THAT WASN'T REPLACED AT
3/09/2022	209	XN75AH	41366	820574	Engine	SPINNER FILTER	SERVICE

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							SCANIA - AS PER INVOICE 41238070
							CHECK AND REPORT BAND THEN NEUTRALISED & CANNOT
							SELECT THE GEARS - VEHICLE HAS LOST ALL DRIVE. FAILED
							CLUTCH
							REMOVE GEARBOX FOUND RELEASE BEARING HAD FAILED.
							ONCE CLUTCH WAS REMOVED FOUND FLYWHEEL HAD
							LARGE GROOVES. HAD TO SEND FLYWHEEL OUT TO BE
							REPAIRED.
							REFIT FLYWHEEL WITH NEW REAR MAIN SEAL. REFITTED
							GEARBOX. HAD TO REPLACE GEARBOX COOLANT MOUNTS.
							REFILL WITH COOLANT. ROAD TEST. ALL OK
							ADJUST TAPPETS - ADJUST ENGINE VALVES AND TAPPETS.
							CHECK AND REPORT ON COOLANT LEAK
							TOP RETARDER HOSE SPLIT UNDER HOSE CLAMP
							DRAINED COOLANT TO REMOVE AND REPLACE DAMAGED
							HOSE. FILLED WITH COOLANT AND PRESSURE TESTED.
14/09/2022	209	XN75AH	41524	824054	Breakdown	BREAKDOWN - CLUTCH	OKAY. WASHED DOWN TRUCK.
							MOORES HEAVY TYRE SERVICE - AS PER INVOICE 0464
24/09/2022	209	XN75AH	41776	825293	TYRES\STEER	FIT NEW TYRES	FIT 2 X NEW SAILUN 385/65R22.5 164K SFR1 TO POS 1 & 2
22/10/2022	209	XN75AH	41902	833294	Elect	TAIL LIGHT LENS BROKEN	REPLACED BUSTED TAIL LIGHT LENS LEFT HAND SIDE
24/10/2022	209	XN75AH	41896	833822	Chassis	SUZI LEAD CLIP	REPLACE BROKEN SUZI LEAD CLIP
							COMPLETED 'A' SERVICE - ALL OK
10/11/2022	209	XN75AH	42068	835835	VehService\AS	A SERVICE	CLEANED DIFF BREATHERS
25/11/2022	209	XN75AH	42275	845155	Chassis\AL	AIRLEAK	REPLACED SUZI AIR FITTING
							MOORES HEAVY TYRE SERVICE - AS PER INVOICE 0719
13/12/2022	209	XN75AH	42664	847408	TYRES\ROTATE	ROTATE TYRES	ROTATE TYRES POS 9, 10, 11, 12 TO POS 5, 6, 7, 8

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							MOORES HEAVY TYRE SERVICE - AS PER INVOICE 0719
							FIT 4 X NEW HAULMAX 295/80R22.5 ATT312 DRV TO POS 9,
13/12/2022	209	XN75AH	42665	847408	TYRES\DRIVE	FIT NEW TYRES	10, 11, 12.
6/01/2023	209	XN75AH	42710	856429	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE
						Annual Inspection	COMPLETED ANNUAL COMPLIANCE INSPECTION - ALL OK.
14/02/2023	209	XN75AH	43047	867352	COMP\AI	*PASS*	REPLACED MISSING BOLT FROM ADBLUE TANK
16/02/2023	209	XN75AH	43061	868905	Elect	SUZI ELECTRICAL LEAD	CHECKED AND REPAIRED SUZI ELECTRICAL LEAD
24/02/2023	209	XN75AH	43134	870621	Engine	BELT HOUSING COVER	REPLACED BELL HOUSING INSPECTION COVER
							MOORES HEAVY TYRE SERVICE - AS PER INV 0949
27/02/2023	209	XN75AH	44050	871089	TYRES\ROTATE	ROTATE TYRES	ROTATE TYRES POS 1 & 2
							REMOVED AND REPLACED ALL BELTS, PULLEYS AND
28/02/2023	209	XN75AH	43199	871398	Engine\BLTS	BELTS, PULLEYS, TENSIONERS	TENSIONERS
28/02/2023	209	XN75AH	43200	871398	Engine\WP	WATER PUMP	REMOVED AND REPLACED WATERPUMP
							COMPLETED 'A' SERVICE - ALL OK
						Service As Per Attached	NEEDS NEW FLEX TO MUFFLER
3/03/2023	209	XN75AH	43152	873880	VehService\AS	Checklist	CAB AIRBAGS CRACKED
10/03/2023	209	XN75AH	43516	880648	DriCabRep\AB	AIR BAG	REMOVED AND REPLACED FRONT CAB AIR BAGS
							REMOVED AND REPLACED EXHAUST PIPE FROM TURBO
10/03/2023	209	XN75AH	43517	880648	Engine\EXH	EXHAUST PIPE	BACK

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							SCANIA - AS PER INVOICE 42216559
							Carried out following repairs. Remove and fit 1 propeller
							shaft. Troubleshoot gearchange faults
							CARRY OUT OPTICRUISE REBUILD
							Checked operation. Checked fault codes. Checked
							opticruise. Excessive corrosion and water ingress. Stripped
							and cleaned. Assessed damage. Reassembled with new seals
							and orings. Filled with new oil. Cleaned. Checked operation.
							Cleared fault codes. Checked for leaks.
							Renew valve housing, on gearbox with Opticruise.
							Control cylinder retarder renewal
							Remove and fit longitudinal stroke cylinder, on gearbox with
							Opticruise. Recondition longitudinal stroke cylinder, on the
							gearbox. Renew lateral stroke cylinder, on gearbox.
							Recondition lateral stroke cylinder, on gearbox with
							Opticruise.
12/04/2023	209	XN75AH	43838	882669	Breakdown	BREAKDOWN	Test drive vehicle.
							REMOVED AND REPLACED LEFT HAND REAR TAIL LIGHT
28/04/2023	209	XN75AH	43890	888075	Elect\Lights	TAIL LIGHTS	ASSEMBLY
3/05/2023	209	XN75AH	43924	889493	DrivLine\DiffOil	DIFF OIL CHANGE	REPLACED DIFF OILS
3/05/2023	209	XN75AH	43852	889493	VehService\CS	C SERVICE	COMPLETED 'C' SERVICE
3/05/2023	209	XN75AH	43925	889493	DrivLine\TransOil	TRANSMISSION OIL CHANGE	REPLACED TRANSMISSION OIL
4/05/2023	209	XN75AH	44383	889493	EXH\E	NOX SENSOR	REMOVED AND REPLACED A FAULTY NOX SENSOR
19/05/2023	209	XN75AH	44147	895128	Chassis\SC	SUZI LEADS	REPLACED BROKEN SUZI LEADS WITH NEW ONES
10/06/2023	209	XN75AH	44693	902069	DriCabRep	CAB SUSPENSION	REPLACED REAR CAB SUSPENSION BUSHES - ALL OK
14/06/2023	209	XN75AH	44718	903596	DriCabRep\Radio	RADIO	REMOVED AND REPLACED FAILED RADIO UNIT - ALL OK
17/06/2023	209	XN75AH	44675	904465	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
24/07/2023	209	XN75AH	45002	915693	DriCabRep\WBW	DriCabRep\WBW	REPLACED 2 X WIPER BLADES
							COMPLETED 'B' SERVICE - ALL OK
							- TIGHTENED ALL WALKWAY, TANK STRAP AND FOOT PLATE
3/08/2023	209	XN75AH	45206	919860	VehService\BS	B SERVICE	CLAMPS ON REAR
							MHTS - AS PER INV 1462
							SUPPLY & FIT 2 X NEW SAILUN 385/65R22.5 160K S825 TO
6/08/2023	209	XN75AH	45863	920431	TYRES\STEER	TYRES\STEER	POS 1 & 2
							MHTS - AS PER INV 1462
6/08/2023	209	XN75AH	45864	920431	TYRES\ROTATE	TYRES\ROTATE	ROTATE TYRES POS 9, 10, 11, 12 TO POS 5, 6, 7, 8
							MHTS - AS PER INV 1462
							SUPPLY & FIT 2 X NEW HAULMAX 295/80R22.5 ATT312 TO
6/08/2023	209	XN75AH	45865	920431	TYRES\DRIVE	TYRES\DRIVE	POS 9, 10, 11, 12
							REPLACED LEFT HAND REAR MARKER PLATE BRACKET AND
30/08/2023	209	XN75AH	45312	928185	Chassis	Chassis	BOTH REAR REFLECTORS.
							REMOVED AND REPLACED EXHAUST TEMP SENSOR. TEST
30/08/2023	209	XN75AH	45311	928185	Engine\FCODE	Engine\Fcode	DROVE - ALL OK
							PREDEBON - AS PER INV 75365
							Locate fault with gearbox grinding from 7th to 6th gears,
							planetary low range gear synchro fault.
							Drain cooling system, retarder & gearbox.
							Remove & refit drive shaft, retarder & planetary assembly.
							Inspect low range gear & synchro fault.
							Supply & fit new planetary assembly.
							Refill cooling system, retarder & gearbox.
1/09/2023	209	XN75AH	46035	928532	GEARBOX\GB	GEARBOX\GB	Test drive vehicle
							COMPLETED 'A' SERVICE - ALL OK
23/09/2023	209	XN75AH	45468	933941	VehService\AS	A Service	- TIGHTENED WALKWAY CLAMPS
11/10/2023	209	XN75AH	45573	939489	Chassis	Chassis	REPLACED WORN ADBLUE TANK MOUNT BOLTS
11/10/2023	209	XN75AH	45574	939489	Elect\Lights	Elect\Lights	REPLACED 3 X CAB MARKER LIGHTS

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
18/10/2023	209	XN75AH	45673	942175	Engine\OL	Engine\OL	REPLACED DIPSTICK
9/11/2023	209	XN75AH	45910	949811	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE - ALL OK
							REMOVED WHEEL, CALIPER BOOSTER AND HUB. REPLACED
							ROTOR, BOOSTER AND CALIPER. RETENSIONED BEARING.
							REPLACED PADS AND HARDWARE. ALSO REPLACED PADS
24/11/2023	209	XN75AH	46059	953569	Brakes\BO	Brakes\BO	ON OTHER AXLE DUE TO 10% DIFFERENCE.
4/01/2024	209	XN75AH	46341	963614	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK
							COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED -
						Annual Inspection	ALL OK
12/02/2024	209	XN75AH	46636	975098	COMP\AI	*PASSED*	- REPLACED WORN HORSE SHOE
12/02/2024	209	XN75AH	46638	975098	Valve Set\VALVE SET	Valve Set\VALVE SET	COMPLETED VALVE ADJUSTMENT
24/02/2024	209	XN75AH	46713	979472	VehService\BS	B SERVICE	COMPLETED 'B' SERVICE - ALL OK
							COMPLETED 'A' SERVICE - ALL OK
4/04/2024	209	XN75AH	47144	994404	VehService\AS	A SERVICE	FIT 3 X ENGINE MOUNT BOLTS
							REMOVED ADBLUE TANK. WELDED BOLT MOUNT AND
							GROUND OUT TO SIZE. REFIT TANK WITH NEW BOLTS - ALL
16/04/2024	209	XN75AH	47319	996736	ADBLUE\ADB	ADBLUE\ADB	OK
							MHTS - AS PER INV 2222.
							SUPPLY & FIT 4 X NEW HAULMAX 295/80R22.5 ATT312 TO
19/04/2024	209	XN75AH	47351	997984	TYRES\DRIVE	TYRES\DRIVE	POS 9, 10, 11, 12.
							MHTS - AS PER INV 2222.
19/04/2024	209	XN75AH	47350	997984	TYRES\ROTATE	TYRES\ROTATE	ROTATE POS 9, 10, 11, 12 TO POS 5, 6, 7, 8.
							MHTS - AS PER INV 2259.
27/04/2024	209	XN75AH	47424	1000025	TYRES\ROTATE	TYRES\ROTATE	ROTATE TYRES POS 1 & 2.
							REPLACED RIGHT HAND SIDE WIPER BLADE DUE TO
9/05/2024	209	XN75AH	47500	1003430	DriCabRep\WBW	DriCabRep\WBW	DAMAGE
30/05/2024	209	XN75AH	47664	1009020	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
/							
31/05/2024	209	XN75AH	47680	1009595	DriCabRep\AC	AIR CON VENT	REMOVED AND REPLACED AC VENT THAT WAS DAMAGED
16/07/2024	209	XN75AH	47946	1024680	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK.
						REVERSE ALARM NOT	TESTED REVERSE ALARM. FOUND IT HAD POWER BUT NOT
13/08/2024	209	XN75AH	48242	1032465	Elect\REV	WORKING	WORKING. REPLACED WITH NEW ONE. TESTED - ALL OK
							MHTS - AS PER INV 2615.
26/08/2024	209	XN75AH	48429	1036768	TYRES\ROTATE	TYRES\ROTATE	ROTATE TYRES POS 9, 10, 11, 12 TO POS 5, 6, 7, 8.
							MHTS - AS PER INV 2615
							SUPPLY & FIT 4 X NEW HAULMAX 295/80R22.5 ATT312 DRV
26/08/2024	209	XN75AH	48431	1036768	TYRES\DRIVE	TYRES\DRIVE	TO POS 9, 10, 11, 12.
							MHTS - AS PER INV 2615.
							SUPPLY & FIT 2 X NEW SAILUN 385/65R22.5 160K S825 TO
26/08/2024	209	XN75AH	48430	1036768	TYRES\STEER	TYRES\STEER	POS 1 & 2.
5/09/2024	209	XN75AH	48386	1040184	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK.
							REMOVED AND REPLACED REVERSE SQUARKER DUE TO
26/09/2024	209	XN75AH	48550	1046204	Elect\REV	Elect\REV	DAMAGE. RELOCATED TO A BETTER SPOT. TESTED - ALL OK
							FOUND BATTERIES STRUGGLING TO START SO TESTED AND
							CAME BACK NO GOOD. REPLACED 2 X BATTERIES, CHECKED
14/10/2024	209	XN75AH	48708	1051358	Elect\BATT	Elect\BATT	CHARGE RATE - ALL OK
24/10/2024	209	XN75AH	48753	1053418	ADBLUE\ADB	ADBLUE\ADB	REPLACED ADBLUE MOUNT BOLTS
							COMPLETED 'A' SERVICE - ALL OK.
							REPAIRED REVERSE SQUARKER, REPLACED MISSING
29/10/2024	209	XN75AH	48749	1054783	VehService\AS	A SERVICE	HUBCAP.
					·		REMOVED AND REPLACED AIR CON CONTROL PANEL AND
13/11/2024	209	XN75AH	48814	1059953	DriCabRep\AC	DriCabRep\AC	CALIBRATED IT.

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							HAD FAULT CODES. FOUND FAULTY INJECTOR. REMOVED
							OLD INJECTOR AND REPLACED WITH NEW ONE. FOUND
							TURBO WAS FAULTY, REMOVED TURBO AND REPLACED -
13/11/2024	209	XN75AH	48694	1051907	Engine\INJ	Engine\INJ	ALL OK
							FOUND LEAKING REAR CAB AIRBAG. REMOVED AND
15/11/2024	209	XN75AH	48994	1060963	DriCabRep\AB	DriCabRep\AB	REPLACED. CHECKED FOR AIR LEAKS - ALL OK
							PREDEBON - AS PER INV 78414.
							RENEW WHEEL BEARINGS, TENSION WHEEL NUTS, CHECK
22/11/2024	209	XN75AH	49167	1062999	WBearings\Steer W/B	WBearings\Steer	FRONT WHEELS TOE IN ADJUSTMENT.
							PREDEBON - AS PER INV 78414.
22/11/2024	209	XN75AH	49170	1062999	DrivLine\KPR	DrivLine\KPR	FIT NEW KING PIN KITS
							PREDEBON - AS PER INV 78414.
							RENEW BRAKE CALIPERS, ROTORS, BRAKE PADS ON STEER.
							BRAKE CALIPERS ON DRIVE.
22/11/2024	209	XN75AH	49169	1062999	Brakes\-	Brakes\-	ADJUST BRAKES.
							PREDEBON - AS PER INV 78414.
							RENEW WHEEL BEARING UNITS. ASSEMBLE. TENSION
22/11/2024	209	XN75AH	49168	1062999	WBearings\Drive WB	WBearings\Drive	WHEEL NUTS.
28/11/2024	209	XN75AH	49005	1063112	DriCabRep\DL	DriCabRep\DL	REMOVED AND REPLACED FAULTY DRIVERS DOOR HANDLE
21/12/2024	209	XN75AH	49164	1070302	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK
12/02/2025	209	XN75AH	49534	1083836	DrivLine\TransOil	Transmission Oil Change	REMOVED AND REPLACED GEARBOX OIL AND FILTER
						Comp\AI	COMPLETED ANNUAL COMPLIANCE INSPECTION - PASSED -
12/02/2025	209	XN75AH	49522	1083836	COMP\AI	*PASSED*	ALL OK.
12/02/2025	209	XN75AH	49535	1083836	DrivLine\DiffOil	Diff Oil Change	REMOVED AND REPLACED DIFF OILS AND FILTER
12/02/2025	209	XN75AH	49521	1083836	VehService\AS	A SERVICE	COMPLETED 'A' SERVICE - ALL OK.
13/03/2025	209	XN75AH	49847	1092275	Elect\EP	Elect\EP	REMOVED AND REPLACED DAMAGED ELECTRICAL PLUG

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
							DRAINED ENGINE OIL. REMOVED TEMP/LEVEL SENSOR
							FROM SUMP. REPLACED WITH NEW ONE. REFILLED ENGINE
13/03/2025	209	XN75AH	49832	1092272	Engine\FCODE	Engine\FCODE	OIL
13/03/2025	209	XN75AH	49833	1092272	Engine\AIRCLNR	Engine\AIRCLNR	REMOVED AND REPLACED AIR FILTER
							MHTS - AS PER INV 3241.
							SUPPLY & FIT 4 X NEW SAILUN 295/80R22.5 152M S737 TO
26/03/2025	209	XN75AH	50031	1096193	TYRES\DRIVE	TYRES\DRIVE	POS 5, 6, 7, 8.
							COMPLETED B SERVICE - ALL OK.
							NEEDS ENGINE MOUNTS, RETARDER COOLANT PIPE MOUNT
							X 1, STRIP ABOVE WINDSCREEN MISSING, DOOR TRIM
							MISSING, NEEDS DRIVERS SEAT COVER. FOUND BLOWN
2/04/2025	209	XN75AH	49905	1099269	VehService\BS	B SERVICE	FUSE FOR ROOF LIGHTS.
30/04/2025	209	XN75AH	50168	1107327	Engine\M	Engine\M	REPLACED FRONT ENGINE MOUNTS
30/04/2025	209	XN75AH	50169	1107327	GEARBOX\GB	GEARBOX\GB	REPLACED COOLANT PIPE BUSH
30/04/2025	209	XN75AH	50170	1107327	DriCabRep	DriCabRep	REPLACED MISSING WINDOW TRIM ON DRIVERS SIDE
							MBAH BLAST & PAINT - AS PER INV 1944.
							PREP, PRIME AND PAINT SUN VISOR.
5/05/2025	209	XN75AH	50226	1108694	DriCabRep	DriCabRep SUNVISOR	SHOOBRIDGE - FITTED PAINTED VISOR ABOVE WINDSCREEN
							COMPLETED 'A' SERVICE - ALL OK.
17/05/2025	209	XN75AH	50260	1113320	VehService\AS	A SERVICE	WINDSCREEN CRACKED. ALL DRIVE AIRBAGS CRACKED.
							RAISED GEARBOX AND REMOVED MOUNTING BOLTS.
							REMOVED CROSS MEMBER AND MOUNTS. REPLACED
20/05/2025	209	XN75AH	50304	1113933	Engine	Engine	MOUNTS AND REASSEMBLED - ALL OK
							NORTHEAST AUTOGLASS - AS PER INV 21082.
3/06/2025	209	XN75AH	50458	1117458	DriCabRep\WSCR	DriCabRep\WSCR	REPLACED WINDSCREEN
11/06/2025	209	XN75AH	50517	1120251	DriCabRep\Seat	DriCabRep\Seat	INSTALLED SEAT COVER ON DRIVERS SIDE SEAT
8/07/2025	209	XN75AH	50718	1123870	Chassis\AB	Chassis\AB	REPLACED REAR DRIVE AIR BAGS

DATE	UNIT	REGO	JOB NO.	ODOMETER	CODE\SUBCODE	DESCRIPTION	COMPLETION DETAILS
11/07/2025	209	XN75AH	50737	1124134	Chassis\AB	Chassis\AB	REPLACED FRONT DRIVE AIRBAGS
						DASH LIGHT DIMMER NOT	
11/07/2025	209	XN75AH	50736	1124134	DrCabElect\E	WORKING	REMOVED AND REPLACED A FAULTY SWITCH
14/07/2025	209	XN75AH	50750	1124395	DrivLine\OL	DrivLine\OL	REPLACED DIFF BREATHER AND SLEEVE
30/07/2025	209	XN75AH	50852	1128893	VehService\BS	B SERVICE	COMPLETED B SERVICE - ALL OK