

906-1

SO # 266964

### SERVICE ORDER CUSTOMER COPY



Printed 06/30/2026 8:02:32 AM

User MWC Page 1

<b>Customer No</b> MORRE2  <b>Home Cell Email</b>  Term See Details	<b>Advisor</b> ROBIN <b>Shop</b> S1 <b>Priority</b>	<b>Promised</b> 04/21/2022 4:30 PM <b>Opened</b> 04/21/2022 9:23 AM <b>Cashiered</b> 09/07/2022 9:23 AM	<b>Tag#</b> <b>Location</b> <b>PO #</b>
	<b>License</b> 804 MNY <b>Year</b> 2016 <b>Vehicle ID No</b> 1C6RR7PM6GS129056 <b>Engine</b> 3.0L ECODIESEL V6	<b>Odom In</b> 210444 <b>Make</b> RAM <b>Selling Dealer</b>	<b>Odom Out</b> 210454 <b>Model</b> 1500 <b>Extended Warranty</b>

Request	Description	Job	CSR	Status
0	OIL IN COOLANT CUSTOMER LOST OIL PRESSURE, HE SHUT ENGINE DOWN IMMEDIATLY,CUSTOMER THINKS THERE WAS NO ENGINE DAMAGE DONE . THINKS OIL COOLER LEAKED	1	9319	Original

  

Labour	Description	Type	Amount
0	DIAGNOSE	CLR	146.99
Technician	2479 - BRANDEN		
Cause	Towed vehicle in, Checked oil level. OK. Connected scan tool, No DTCs related to engine. Oil change done 3700km ago. Lifted and removed lower oil pan. Found bearing material in pan.		
<b>Labour Total</b>			146.99
<b>Request Sub-total</b>			146.99

Request	Description	Job	CSR	Status
0	REPLACE ENGINE	2	3227	Approved

  

Labour	Description	Type	Amount
0	REPLACE ENGINE	CLR	2,351.84

  

Part	Description	Shp	Bin	Type	Retail	Price	Amount
5158048AH	ENGINE	1	OAR S	CPRO	15,218.49	14,920.00	14,920.00
CORE CHARGE	CORE CHARGE 5158048AH	1		CPRO	1,000.00	1,000.00	1,000.00
68334956AA	TUBE KIT	1	D23	CPRO	597.24	558.00	558.00
68442532AA	CAP	1	A08B	CPRO	36.24	36.24	36.24
68175338AC	ANTIFREEZ	2	A19	CPRO	53.24	53.24	106.48
ENVIRO5	Enviro fee \$1.00	2		CPRO	1.00	1.00	2.00
C-5158048AH	CORE - ENGINE	-1		CPRO	1,000.00	1,000.00	(1,000.00)
Technician	1556 - KEVIN						
Cause	engine failed internally						
<b>Parts Total</b>							15,622.72
<b>Labour Total</b>							2,351.84
<b>Request Sub-total</b>							17,974.56

I authorize you to do the repair work set out in this work order. I acknowledge that you have a lien on the vehicle until the full amount owing for materials supplied and services rendered pursuant to this work order has been paid. The lien shall be enforceable at all times until payment in full has been made, whether the vehicle is in my possession or in your possession. If I am given possession of the vehicle before the full amount outstanding is paid, I agree to surrender the vehicle to you on demand. I agree that you are not responsible for loss or damage of any kind to the vehicle or to any contents of the vehicle. I also agree that you are not responsible for any loss I may suffer because of delays caused by unavailability of parts, or delays in parts shipments. You and your employees are authorized to operate this vehicle for the purpose of testing and/or inspection.

"WE AND OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FFUN NORTH BATTLEFORD WILL USE THE INFORMATION PROVIDED BY YOU TO (I) PERFORM SERVICES AS MAY BE DIRECTLY REQUESTED BY YOU; (II) PROVIDE MORE INFORMATION REGARDING THE PRODUCTS AND SERVICES OF US, OUR AFFILIATES INCLUDING SCOTT CAMPBELL DODGE LTD. AND BUSINESS PARTNERS, (III) GENERATE STATISTICAL AND AGGREGATED DATA THAT DOES NOT IDENTIFY YOU PERSONALLY, AND (IV) DISCLOSE YOUR INFORMATION TO OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FIAT CHRYSLER FOR THE PURPOSE OF PROVIDING SERVICE TO YOU AND TO PROVIDE YOU MORE INFORMATION REGARDING THEIR PRODUCTS AND SERVICES, BY PROVIDING YOUR INFORMATION TO US. YOU CONSENT TO THESE USES. YOU MAY NOTIFY US IN WRITING IF IN THE FUTURE YOU DO NOT CONSENT TO ANY OF THESE USES OF THE INFORMATION YOU PROVIDE.

Payment for services are due upon completion and notification of services rendered. Storage fees in the amount of \$50.00 per week will begin 7 days after notification has been given upon completion or customer requested termination of services.

If in the process of your vehicle service the wheels were removed, you are required to return within 100kms for a free retorque. Customer initials \_\_\_\_\_

DATE \_\_\_\_\_

CUSTOMER SIGNATURE \_\_\_\_\_

**SO # 266964**

**SERVICE ORDER  
 CUSTOMER COPY**



Printed 06/30/2026 8:02:32 AM

User MWC Page 2

<b>Customer No</b> MORRE2		<b>Advisor</b> ROBIN	<b>Promised</b> 04/21/2022 4:30 PM	<b>Tag#</b>
<b>Home</b> _____		<b>Shop</b> S1	<b>Opened</b> 04/21/2022 9:23 AM	<b>Location</b>
<b>Cell</b> _____		<b>Priority</b>	<b>Cashiered</b> 09/07/2022 9:23 AM	<b>PO #</b>
<b>Email</b> _____		<b>License</b> 804 MNY	<b>Odom In</b> 210444	<b>Odom Out</b> 210454
<b>Term See Details</b>		<b>Year Make</b> 2016 RAM	<b>Model</b> 1500	<b>In Service Date</b>
		<b>Vehicle ID No</b> 1C6RR7PM6GS129056	<b>Selling Dealer</b>	<b>Model Number</b> DS6R98
		<b>Engine</b> 3.0L ECODIESEL V6	<b>Extended Warranty</b>	<b>Colour</b>
			<b>Fleet #</b>	<b>Delivery Date</b>

Correction under vehicle is packed with mud, P1 cleaned mud from under vehicle

removed cab, replaced engine, topped up coolant, rad cap broken off, replaced rad cap, evacuate and recharge ac system, road test, all ok now

Request	Description	Job	CSR	Status
0	DIAGNOSE ABS LIGHT	3	3227	Approved
Labour	Description		Type	Amount
0	DIAGNOSE ABS LIGHT		CLR	159.99
Technician	1556 - KEVIN		Labour Total	159.99
Cause	pulled out wheel speed sensor pin		Request Sub-total	159.99
Correction	scanned vehicle found codes ABS C0034-1D Right Front Wheel Speed Sensor-Circuit Current Out of Range Active DTCM U0415 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module "A" Active ORC U1110-00 Lost Vehicle Speed Message- Active ITBM U0415-00 Invalid Data Received from Anti-Lock Brake System (ABS) Control Module "A"- Active test wiring to right fornt wheel speed sensor, found pulled out wheel speed sensor pin, reinstalled and check tension, reconnected codeds stored now, abs and track lights out now			

I authorize you to do the repair work set out in this work order. I acknowledge that you have a lien on the vehicle until the full amount owing for materials supplied and services rendered pursuant to this work order has been paid. The lien shall be enforceable at all times until payment in full has been made, whether the vehicle is in my possession or in your possession. If I am given possession of the vehicle before the full amount outstanding is paid, I agree to surrender the vehicle to you on demand. I agree that you are not responsible for loss or damage of any kind to the vehicle or to any contents of the vehicle. I also agree that you are not responsible for any loss I may suffer because of delays caused by unavailability of parts, or delays in parts shipments. You and your employees are authorized to operate this vehicle for the purpose of testing and/or inspection.

"WE AND OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FFUN NORTH BATTLEFORD WILL USE THE INFORMATION PROVIDED BY YOU TO (I) PERFORM SERVICES AS MAY BE DIRECTLY REQUESTED BY YOU; (II) PROVIDE MORE INFORMATION REGARDING THE PRODUCTS AND SERVICES OF US, OUR AFFILIATES INCLUDING SCOTT CAMPBELL DODGE LTD. AND BUSINESS PARTNERS, (III) GENERATE STATISTICAL AND AGGREGATED DATA THAT DOES NOT IDENTIFY YOU PERSONALLY, AND (IV) DISCLOSE YOUR INFORMATION TO OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FIAT CHRYSLER FOR THE PURPOSE OF PROVIDING SERVICE TO YOU AND TO PROVIDE YOU MORE INFORMATION REGARDING THEIR PRODUCTS AND SERVICES, BY PROVIDING YOUR INFORMATION TO US. YOU CONSENT TO THESE USES. YOU MAY NOTIFY US IN WRITING IF IN THE FUTURE YOU DO NOT CONSENT TO ANY OF THESE USES OF THE INFORMATION YOU PROVIDE.

Payment for services are due upon completion and notification of services rendered. Storage fees in the amount of \$50.00 per week will begin 7 days after notification has been given upon completion of customer requested termination of services.

If in the process of your vehicle service the wheels were removed, you are required to return within 100kms for a free retorque. Customer initials \_\_\_\_\_

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_



FFUN NORTH BATTLEFORD

DODGE RAM

Jeep CHRYSLER

3042 99 St North Battleford, SK S9A 3W8  
Phone: 306 445 6640 | Toll Free: 888 804.0030

Fax: 306 445.8828

FFUN.DODGE.NORTH.BATTLEFORD.COM

SO # 266964

### SERVICE ORDER CUSTOMER COPY



Printed 06/30/2026 8:02:33 AM

User MWC Page 3

Customer No	MORRE2
Home	
Cell	
Email	
Term See Details	

Advisor	ROBIN	Promised	04/21/2022 4:30 PM	Tag#
Shop	S1	Opened	04/21/2022 9:23 AM	Location
Priority		Cashiered	09/07/2022 9:23 AM	PO #

License	Odom In	Odom Out	In Service Date	Stock No
804 MNY	210444	210454		
Year	Make	Model	Model Number	Colour
2016	RAM	1500	DS6R98	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1C6RR7PM6GS129056				
Engine	3.0L ECODIESEL V6	Fleet #		

You will be receiving a survey from STELLANTIS Canada based on your RECENT SERVICE. If you are not COMPLETELY SATISFIED, please contact Melissa or Neil with any concerns. We appreciate you taking the time to fill out the survey & your continued business.

INITIALS x \_\_\_\_\_

Labour	2,658.82
Parts	15,622.72
Supplies	75.00
<b>Sub-Total</b>	<b>18,356.54</b>
GST	917.83
PST	1,101.39
<b>Total Invoice</b>	<b>20,375.76</b>
After Hrs/Mth End	10,000.00
CHEQUES	10,375.76

I authorize you to do the repair work set out in this work order. I acknowledge that you have a lien on the vehicle until the full amount owing for materials supplied and services rendered pursuant to this work order has been paid. The lien shall be enforceable at all times until payment in full has been made, whether the vehicle is in my possession or in your possession. If I am given possession of the vehicle before the full amount outstanding is paid, I agree to surrender the vehicle to you on demand. I agree that you are not responsible for loss or damage of any kind to the vehicle or to any contents of the vehicle. I also agree that you are not responsible for any loss I may suffer because of delays caused by unavailability of parts, or delays in parts shipments. You and your employees are authorized to operate this vehicle for the purpose of testing and/or inspection.

WE AND OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FFUN NORTH BATTLEFORD WILL USE THE INFORMATION PROVIDED BY YOU TO (I) PERFORM SERVICES AS MAY BE DIRECTLY REQUESTED BY YOU; (II) PROVIDE MORE INFORMATION REGARDING THE PRODUCTS AND SERVICES OF US, OUR AFFILIATES INCLUDING SCOTT CAMPBELL DODGE LTD. AND BUSINESS PARTNERS, (III) GENERATE STATISTICAL AND AGGREGATED DATA THAT DOES NOT IDENTIFY YOU PERSONALLY, AND (IV) DISCLOSE YOUR INFORMATION TO OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FIAT CHRYSLER FOR THE PURPOSE OF PROVIDING SERVICE TO YOU AND TO PROVIDE YOU MORE INFORMATION REGARDING THEIR PRODUCTS AND SERVICES, BY PROVIDING YOUR INFORMATION TO US, YOU CONSENT TO THESE USES. YOU MAY NOTIFY US IN WRITING IF IN THE FUTURE YOU DO NOT CONSENT TO ANY OF THESE USES OF THE INFORMATION YOU PROVIDE.

Payment for services are due upon completion and notification of services rendered. Storage fees in the amount of \$50.00 per week will begin 7 days after notification has been given upon completion or customer requested termination of services.

If in the process of your vehicle service the wheels were removed, you are required to return within 100kms for a free retorque. Customer initials \_\_\_\_\_

DATE \_\_\_\_\_

CUSTOMER SIGNATURE \_\_\_\_\_



FFUN NORTH BATTLEFORD

DODGE RAM

Jeep CHRYSLER

3042 99 St. North Battleford S4S 6S6  
Phone: 306.445.6610 | Toll Free: 1.888.804.0030  
Fax: 306.445.8622  
FFUNDODGENORTHATTLEFORD.COM

SO # 275412

SERVICE ORDER  
CUSTOMER COPY



Printed 06/30/2026 8:03:53 AM

User MWC Page 1

Customer No MORRE2

Home Cell Email

Term CHEQUES

Advisor	Jaimie Adams	Promised	06/14/2023 4:30 PM	Tag#
Shop	S1	Opened	06/13/2023 11:16 AM	Location
Priority		Cashiered	06/28/2023 4:31 PM	PO #

License	Odom In	Odom Out	In Service Date	Stock No
804 MNY	245117	245119		
Year Make	Model	Model Number	Colour	
2016 RAM	1500	DS6R98		
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1C6RR7PM6GS129056				
Engine	3.0L ECODIESEL V6	Fleet #		

Request	Description	Job	CSR	Status
0	Customer was coming back from Saskatoon, crossed the Borden bridges when a 'Service electronic throttle control' warning message came on. Vehicle experienced a power loss as he climbed the hill, customer pulled over at the peak of the hill and shut vehicle off. Have not been able to start again since (cranks but won't start) - Inspect & report	1	JLA	Original

Labour	Description	Type	Amount
0	customer was coming back from Saskatoon, crossed the Borden bridges when a 'Service electronic throttle control' warning message came on. Vehicle experienced a power loss as he climbed the hill, customer pulled over at the peak of the hill and shut vehicle off. Have not been able to start again since (cranks but won't start) - Inspect & report	CLR	0.00

Part	Description	Shp	Bin	Type	Retail	Price	Amount
55366298AA	O RING	1	B29B	CPRO	70.24	70.24	70.24
NAT IN PROCESS - 2 WEEKS							
68161407AE	PUMP	1	E08	CPRO	825.49	825.49	825.49
NAT IN PROCESS - 2 WEEKS							
CORE CHARGE	CORE CHARGE 68161407AE	1		CPRO	50.00	50.00	50.00
Technician	5233 - CHRIS			Parts Total			945.73
Cause	In tank fuel pump failed.			Labour Total			319.98
				Request Sub-total			1,265.71

I authorize you to do the repair work set out in this work order. I acknowledge that you have a lien on the vehicle until the full amount owing for materials supplied and services rendered pursuant to this work order has been paid. The lien shall be enforceable at all times until payment in full has been made, whether the vehicle is in my possession or in your possession. If I am given possession of the vehicle before the full amount outstanding is paid, I agree to surrender the vehicle to you on demand. I agree that you are not responsible for loss or damage of any kind to the vehicle or to any contents of the vehicle. I also agree that you are not responsible for any loss I may suffer because of delays caused by unavailability of parts, or delays in parts shipments. You and your employees are authorized to operate this vehicle for the purpose of testing and/or inspection.

"WE AND OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FFUN NORTH BATTLEFORD WILL USE THE INFORMATION PROVIDED BY YOU TO (I) PERFORM SERVICES AS MAY BE DIRECTLY REQUESTED BY YOU; (II) PROVIDE MORE INFORMATION REGARDING THE PRODUCTS AND SERVICES OF US, OUR AFFILIATES INCLUDING SCOTT CAMPBELL DODGE LTD. AND BUSINESS PARTNERS, (III) GENERATE STATISTICAL AND AGGREGATED DATA THAT DOES NOT IDENTIFY YOU PERSONALLY, AND (IV) DISCLOSE YOUR INFORMATION TO OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FIAT CHRYSLER FOR THE PURPOSE OF PROVIDING SERVICE TO YOU AND TO PROVIDE YOU MORE INFORMATION REGARDING THEIR PRODUCTS AND SERVICES, BY PROVIDING YOUR INFORMATION TO US. YOU CONSENT TO THESE USES. YOU MAY NOTIFY US IN WRITING IF IN THE FUTURE YOU DO NOT CONSENT TO ANY OF THESE USES OF THE INFORMATION YOU PROVIDE.

Payment for services are due upon completion and notification of services rendered. Storage fees in the amount of \$50.00 per week will begin 7 days after notification has been given upon completion of customer requested termination of services.

If in the process of your vehicle service the wheels were removed, you are required to return within 100kms for a free retorque. Customer Initials \_\_\_\_\_

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_

**SO # 275412**

**SERVICE ORDER  
 CUSTOMER COPY**



Printed 06/30/2026 8:03:54 AM

User MWC Page 2

<b>Customer No</b> MORRE2	<b>Advisor</b> Jaimie Adams	<b>Promised</b> 06/14/2023 4:30 PM	<b>Tag#</b>
	<b>Shop</b> S1	<b>Opened</b> 06/13/2023 11:16 AM	<b>Location</b>
	<b>Priority</b>	<b>Cashiered</b> 06/28/2023 4:31 PM	<b>PO #</b>

  

<b>Home</b>	<b>License</b> 804 MNY	<b>Odom In</b> 245117	<b>Odom Out</b> 245119	<b>In Service Date</b>	<b>Stock No</b>
<b>Cell</b>	<b>Year</b> 2016	<b>Make</b> RAM	<b>Model</b> 1500	<b>Model Number</b> DS6R98	<b>Colour</b>
<b>Email</b>	<b>Vehicle ID No</b> 1C6RR7PM6GS129056	<b>Selling Dealer</b>	<b>Extended Warranty</b>	<b>Delivery Date</b>	
<b>Term CHEQUES</b>	<b>Engine</b> 3.0L ECODIESEL V6	<b>Fleet #</b>			

**Correction** PCM P016F-00 Closed Loop Fuel Pressure Control at Limit - Pressure Too Low- Stored  
 PCM P016D-00 Excessive Time to Enter Closed Loop Fuel Pressure Control- Pending  
 PCM P0087-00 Fuel Rail Pressure Too Low - Bank 1- Stored  
 Disconnect fuel line to check fuel supply engine, no fuel supply.  
 Hook up auxiliary fuel pump directly to supply to engine. Engine starts and runs.  
 Vehicle fuel pump is not running. Need to check pump for power. Lower fuel tank enough to access fuel pump connector to disconnect. Hook up test light to fuel pump ckt and turn on key, has good power and ground. Needs a new fuel pump.  
 Replace fuel pump, reinstall fuel tank. Starts and runs. Clear all codes and road test, ok.

Request	Description	Job	CSR	Status
0	Key fob has intermittently been inoperable/not responding to truck for command start - Inspect & report	2	JLA	Approved

  

Labour	Description	Type	Amount
0	Key fob has intermittently been inoperable/not responding to truck for command start - Inspect & report	CLR	0.00

  

Part	Description	Shp	Bin	Type	Retail	Price	Amount
5066241AB	BATTERY	1	B04C	CPRO	11.74	11.74	11.74
<b>Technician</b> 5233 - CHRIS							
<b>Cause</b> Key fob has intermittent signal.							
<b>Correction</b> Check key fob battery, has 3.02 volts a bit weak. Replace battery and try it, if it continues to work intermittently it will require replacement.							
<b>Parts Total</b>							11.74
<b>Request Sub-total</b>							11.74

Request	Description	Job	CSR	Status
0	under drivers seat (attached to frame) - loose wiring harness, ziptied up currently - Advise if able to resecure	3	JLA	Approved

  

Labour	Description	Type	Amount
0	under drivers seat (attached to frame) - loose wiring harness, ziptied up currently - Advise if able to resecure	CLR	0.00

I authorize you to do the repair work set out in this work order. I acknowledge that you have a lien on the vehicle until the full amount owing for materials supplied and services rendered pursuant to this work order has been paid. The lien shall be enforceable at all times until payment in full has been made, whether the vehicle is in my possession or in your possession. If I am given possession of the vehicle before the full amount outstanding is paid, I agree to surrender the vehicle to you on demand. I agree that you are not responsible for loss or damage of any kind to the vehicle or to any contents of the vehicle. I also agree that you are not responsible for any loss I may suffer because of delays caused by unavailability of parts, or delays in parts shipments. You and your employees are authorized to operate this vehicle for the purpose of testing and/or inspection.

"WE AND OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FFUN NORTH BATTLEFORD WILL USE THE INFORMATION PROVIDED BY YOU TO (I) PERFORM SERVICES AS MAY BE DIRECTLY REQUESTED BY YOU; (II) PROVIDE MORE INFORMATION REGARDING THE PRODUCTS AND SERVICES OF US, OUR AFFILIATES INCLUDING SCOTT CAMPBELL DODGE LTD. AND BUSINESS PARTNERS. (III) GENERATE STATISTICAL AND AGGREGATED DATA THAT DOES NOT IDENTIFY YOU PERSONALLY, AND (IV) DISCLOSE YOUR INFORMATION TO OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FIAT CHRYSLER FOR THE PURPOSE OF PROVIDING SERVICE TO YOU AND TO PROVIDE YOU MORE INFORMATION REGARDING THEIR PRODUCTS AND SERVICES, BY PROVIDING YOUR INFORMATION TO US. YOU CONSENT TO THESE USES. YOU MAY NOTIFY US IN WRITING IF IN THE FUTURE YOU DO NOT CONSENT TO ANY OF THESE USES OF THE INFORMATION YOU PROVIDE.

Payment for services are due upon completion and notification of services rendered. Storage fees in the amount of \$50.00 per week will begin 7 days after notification has been given upon completion or customer requested termination of services.

If in the process of your vehicle service the wheels were removed, you are required to return within 100kms for a free retorque. Customer initials \_\_\_\_\_

DATE \_\_\_\_\_

CUSTOMER'S SIGNATURE \_\_\_\_\_

**SO # 275412**

**SERVICE ORDER  
 CUSTOMER COPY**



Printed 06/30/2026 8:03:54 AM

User MWC Page 3

Customer No MORRE2

Home

Cell

Email

Term CHEQUES

Advisor	Jaimie Adams	Promised	06/14/2023 4:30 PM	Tag#
Shop	S1	Opened	06/13/2023 11:16 AM	Location
Priority		Cashiered	06/28/2023 4:31 PM	PO #

License	Odom In	Odom Out	In Service Date	Stock No
804 MNY	245117	245119		
Year	Make	Model	Model Number	Colour
2016	RAM	1500	DS6R98	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1C6RR7PM6GS129056				
Engine	3.0L ECODIESEL V6	Fleet #		

Technician 5233 - CHRIS  
 Cause No problem found.  
 Correction Wiring all looks like its supposed to be. The air suspension control module is disconnected from a air delete so normal. Wiring has to be a bit loose in order for the seat to move fore and aft.

You will be receiving a survey from STELLANTIS Canada based on your RECENT SERVICE. If you are not COMPLETELY SATISFIED, please contact Melissa or Neil with any concerns. We appreciate you taking the time to fill out the survey & your continued business.  
 INITIALS x \_\_\_\_\_

Labour	319.98
Parts	957.47
Supplies	35.20
<b>Sub-Total</b>	<b>1,312.65</b>
GST	65.63
PST	78.76
<b>Total Invoice</b>	<b>1,457.04</b>
CHEQUES	1,457.04

I authorize you to do the repair work set out in this work order. I acknowledge that you have a lien on the vehicle until the full amount owing for materials supplied and services rendered pursuant to this work order has been paid. The lien shall be enforceable at all times until payment in full has been made, whether the vehicle is in my possession or in your possession. If I am given possession of the vehicle before the full amount outstanding is paid, I agree to surrender the vehicle to you on demand. I agree that you are not responsible for loss or damage of any kind to the vehicle or to any contents of the vehicle. I also agree that you are not responsible for any loss I may suffer because of delays caused by unavailability of parts, or delays in parts shipments. You and your employees are authorized to operate this vehicle for the purpose of testing and/or inspection.

"WE AND OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FFUN NORTH BATTLEFORD WILL USE THE INFORMATION PROVIDED BY YOU TO (I) PERFORM SERVICES AS MAY BE DIRECTLY REQUESTED BY YOU; (II) PROVIDE MORE INFORMATION REGARDING THE PRODUCTS AND SERVICES OF US, OUR AFFILIATES INCLUDING SCOTT CAMPBELL DODGE LTD. AND BUSINESS PARTNERS, (III) GENERATE STATISTICAL AND AGGREGATED DATA THAT DOES NOT IDENTIFY YOU PERSONALLY, AND (IV) DISCLOSE YOUR INFORMATION TO OUR SERVICE PROVIDERS AND AFFILIATES INCLUDING FIAT CHRYSLER FOR THE PURPOSE OF PROVIDING SERVICE TO YOU AND TO PROVIDE YOU MORE INFORMATION REGARDING THEIR PRODUCTS AND SERVICES, BY PROVIDING YOUR INFORMATION TO US. YOU CONSENT TO THESE USES YOU MAY NOTIFY US IN WRITING IF IN THE FUTURE YOU DO NOT CONSENT TO ANY OF THESE USES OF THE INFORMATION YOU PROVIDE.

Payment for services are due upon completion and notification of services rendered. Storage fees in the amount of \$50.00 per week will begin 7 days after notification has been given upon completion or customer requested termination of services.

If in the process of your vehicle service the wheels were removed, you are required to return within 100kms for a free retorque. Customer initials \_\_\_\_\_

DATE \_\_\_\_\_ CUSTOMER SIGNATURE \_\_\_\_\_