

10001 139 Avenue • Grande Prairie, AB • T8X 0V3 Tel: (780) 532-9555 • 1-800-422-6094 service@windsorford.com • www.windsorford.com

SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M. Saturday - 8:00 A.M. - 5:00 P.M.

GENUINE PEOPLE TREATING YOU LIKE A PERSON

OUR REPUTATION IS YOUR EXPERIENCE

SO # 602838

Status

Printed 10/02/2025 8:36:45 AM

SERVICE ORDER CUSTOMER COPY

Page

Customer No 10053
Attn: SHANE KNOBLOCH
Adrenaline Auto Sales Ltd.
730048 Hwy 2

County Of Grande Prairie No. 1, AB T8X 0T7

Home Bus (780) 512-5311

Cell (780) 512-5311 Today
Email shane.adrenaline@gmail.com

Type W Term DEBIT

Advisor	Shay G	Location	Promised	05/06/2025 6:00 PM
Shop	WF	PO#	Opened	05/06/2025 3:36 PM
Tag#	3096		Cashiered	06/26/2025 11:44 AM

User

592

License Odom In **Odom Out** In Service Date Stock No NONE 68371 68375 Year Make Model **Model Number** Colour 2021 **FORD** SUPER DUTY F-550 DRW F5H 1 OXFORD Vehicle ID No **Selling Dealer Extended Warranty Delivery Date** 1FDUF5HNXMDA07481

Engine 7.3L 2V DEVCT NA PFI V8 GAS

160CHECK AND ADVISE ON ENGINE NOISE- RUNS ROUGH1SHAY GOriginalLabourDescriptionTypeAmount12650DEEC System Diagnosis - (Quick Test)W12650D45Engine Module - Diagnostic Pin Point TestW12650DX1EEC System Diagnosis - (Quick Test)W12650D47Relative Compression/Power Balance - TestW6007EEngine Exchange - DiagnosisW6007E1Inspect and Determine Engine Condition - Check 7.3L DEVCTW6007AEngine Assembly - Remove and Install 7.3L DEVCTW6007A1Cylinder Assembly Short Block - Replace 7.3L DEVCTWMTBOLTMT FOR BROKEN BOLTSWADAdditional DiagnosticsW
12650DEEC System Diagnosis - (Quick Test)W12650D45Engine Module - Diagnostic Pin Point TestW12650DX1EEC System Diagnosis - (Quick Test)W12650D47Relative Compression/Power Balance - TestW6007EEngine Exchange - DiagnosisW6007E1Inspect and Determine Engine Condition - Check 7.3L DEVCTW6007AEngine Assembly - Remove and Install 7.3L DEVCTW6007A1Cylinder Assembly Short Block - Replace 7.3L DEVCTWMTBOLTMT FOR BROKEN BOLTSWADAdditional DiagnosticsW
12650D45 Engine Module - Diagnostic Pin Point Test W 12650DX1 EEC System Diagnosis - (Quick Test) W 12650D47 Relative Compression/Power Balance - Test W 6007E Engine Exchange - Diagnosis W 6007E1 Inspect and Determine Engine Condition - Check 7.3L DEVCT W 6007A Engine Assembly - Remove and Install 7.3L DEVCT W 6007A1 Cylinder Assembly Short Block - Replace 7.3L DEVCT W MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
12650DX1 EEC System Diagnosis - (Quick Test) W 12650D47 Relative Compression/Power Balance - Test W 6007E Engine Exchange - Diagnosis W 6007E1 Inspect and Determine Engine Condition - Check 7.3L DEVCT W 6007A Engine Assembly - Remove and Install 7.3L DEVCT W 6007A1 Cylinder Assembly Short Block - Replace 7.3L DEVCT W MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
12650D47Relative Compression/Power Balance - TestW6007EEngine Exchange - DiagnosisW6007E1Inspect and Determine Engine Condition - Check 7.3L DEVCTW6007AEngine Assembly - Remove and Install 7.3L DEVCTW6007A1Cylinder Assembly Short Block - Replace 7.3L DEVCTWMTBOLTMT FOR BROKEN BOLTSWADAdditional DiagnosticsW
6007E Engine Exchange - Diagnosis W 6007E1 Inspect and Determine Engine Condition - Check 7.3L DEVCT W 6007A Engine Assembly - Remove and Install 7.3L DEVCT W 6007A1 Cylinder Assembly Short Block - Replace 7.3L DEVCT W MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
6007E1 Inspect and Determine Engine Condition - Check 7.3L DEVCT W 6007A Engine Assembly - Remove and Install 7.3L DEVCT W 6007A1 Cylinder Assembly Short Block - Replace 7.3L DEVCT W MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
6007A Engine Assembly - Remove and Install 7.3L DEVCT W 6007A1 Cylinder Assembly Short Block - Replace 7.3L DEVCT W MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
6007A1 Cylinder Assembly Short Block - Replace 7.3L DEVCT W MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
MTBOLT MT FOR BROKEN BOLTS W AD Additional Diagnostics W
AD Additional Diagnostics W
Part Description Shp Bin Type Retail Price Amount
LC3Z 6009 A CYLINDER ASY - SHORT 1 SPORD WR84
short block
LC3Z 6754 A TUBE - OIL LEVEL IND 1 F2 WR84
LC3Z 6500 C TAPPET - VALVE 16 F3 WR84
AL3Z 6379 BA BOLT - HEX.HEAD 8 F1D WR84
W715106 S439 BOLT 2 M4 WR84
W706447 S437 BOLT 3 M3 WR84
W711336 S441 NUT 6 M4 WR84
W715618 S437 NUT 4 M4 WR84
W709771 S440 NUT - ADJUSTING SCRE 2 M4 WR84
W520514 S440 NUT - HEX. 4 M3 WR84
edm
LC3Z 6020 A GASKET 2 F1D WR84
CORE CHARGE CORE CHARGE LC3Z 6009 A 1 WR84
YF 37200 KIT - AIR CONDITIONI 1 D1D WR84
YF 37616 KIT 1 D1D WR84
LC3Z 6A340 A BOLT 1 F1D WR84

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

PRIVACY STATEMENT: Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility



10001 139 Avenue • Grande Prairie, AB • T8X 0V3 Tel: (780) 532-9555 • 1-800-422-6094 service@windsorford.com • www.windsorford.com

SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M. Saturday - 8:00 A.M. - 5:00 P.M.

GENUINE PEOPLE TREATING YOU LIKE A PERSON

OUR REPUTATION IS YOUR EXPERIENCE

SO # 602838

Status

Printed 10/02/2025 8:36:45 AM

SERVICE ORDER **CUSTOMER COPY**

Page

Customer No 10053 Attn: SHANE KNOBLOCH Adrenaline Auto Sales Ltd. 730048 Hwy 2 County Of Grande Prairie No. 1, AB T8X 0T7

Home Bus (780) 512-5311 Cell (780) 512-5311 Today

Email shane.adrenaline@gmail.com

1348 -

Type W Term DEBIT

Advisor	Shay G	Location	Promised	05/06/2025 6:00 PM
Shop	WF	PO #	Opened	05/06/2025 3:36 PM
Tag#	3096		Cashiered	06/26/2025 11:44 AM

User

592

License Odom In **Odom Out** In Service Date Stock No NONE 68371 68375 Year Make Model **Model Number** Colour 2021 **FORD** SUPER DUTY F-550 DRW F5H 1 OXFORD Vehicle ID No **Selling Dealer Extended Warranty Delivery Date** 1FDUF5HNXMDA07481

Engine 7.3L 2V DEVCT NA PFI V8 GAS

LC3Z 6065 A	BOLT - HEX.HEAD	20	F3	WR84
W712861 S439	BOLT	8	M4	WR84
W716090 S437	BOLT	4	M4	WR84
LC3Z 8C387 A	GASKET	1	G1D	WR84
edm				
LC3Z 6051 G	GASKET - CYLINDER HE	1	F3	WR84
LC3Z 6051 H	GASKET - CYLINDER HE	1	F3	WR84
LC2Z 9448 A	GASKET	2	G2	WR84
LC3Z 6584 A	GASKET	2	F3	WR84
edm				
W714870 S430	NUT	16	M4	WR84
CM 4717	KIT - "O" RING	2	B1D	WR84
RG 571	SEAL - THERMOSTAT	1	C1D	WR84
LC3Z 9K492 A	STUD	16	G1D	WR84
XL 5 A	GREASE - CHASSIS LUB	1	J2	WR84
CVC 13 G	ANTI-FREEZE	3	WH1	WR84
YN 12 D	OIL - COMPRESSOR - A	1	J2	WR84
CXO 5W30 BSP	MOTORCRAFT SAE 5W-30	7.81	SHOP	WR84
ENOIL	TXLEV ENVIRO FEE OIL	20.81	SPORD	WR84
LC3Z 8507 A	GASKET - WATER PUMP	1	G1D	WR84
F2AZ 6397 A	SLEEVE - GUIDE	2	F1D	WR84
W709001 S300	PIN - LOCATING	4	M4	WR84
CVC 13 G	ANTI-FREEZE	1	WH1	WR84
RTS 1068	SEAL	1	C1D	WR84
Technician 6 -				

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

PRIVACY STATEMENT: Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility

Customer Signature:



10001 139 Avenue • Grande Prairie, AB • T8X 0V3 Tel: (780) 532-9555 • 1-800-422-6094 service@windsorford.com • www.windsorford.com

SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M. Saturday - 8:00 A.M. - 5:00 P.M.

GENUINE PEOPLE TREATING YOU LIKE A PERSON

OUR REPUTATION IS YOUR EXPERIENCE

SO # 602838

Status

Printed 10/02/2025 8:36:45 AM

County Of Grande Prairie No. 1, AB T8X 0T7

(780) 512-5311 Today

shane.adrenaline@gmail.com

Term DEBIT

Type W

Bus

SERVICE ORDER CUSTOMER COPY

Page

Customer No
Attn: SHANE KNOBLOCH
Adrenaline Auto Sales Ltd.
730048 Hwy 2

Advisor Shay G
Shop WF
PO #
Tag# 3096

 Promised
 05/06/2025 6:00 PM

 Opened
 05/06/2025 3:36 PM

 Cashiered
 06/26/2025 11:44 AM

592

LicenseOdom InOdom OutIn Service DateStock NoNONE6837168375

YearMakeModelModel NumberColour2021FORDSUPER DUTY F-550 DRW F5H1 OXFORDVehicle ID NoSelling DealerExtended WarrantyDelivery Date

User

1FDUF5HNXMDA07481

Engine 7.3L 2V DEVCT NA PFI V8 GAS

Cause

Home

Email

Cell

runs rough, check engine light on. scanned for codes p0300, p0301, p0308 stored. performed relative compression test, #8 down 6%. perform manual compression test and confirmed low compression. tear down needed to inspect for repair. check stock on short block/lifters edm stk

Removed enigne assembly from the vehicle and set on engine stand. Completely disassembled the enigne and found cylinder #1 lifter is stuck in the bore and cannot be removed. Used a borescope and verified sever damage to the underside of the lifter as well as the camshaft assembly. Will need to replace the short block assembly.

Correction

During removal 3 out of 4 exhaust manifold studs broke. Performed broken bolt extraction on all 3 bolts .Transferred all components onto the new short block. Performed cylinder head cleaning and inspection and verified no concerns, Installed the cylinder heads with new gaskets and bolts. Reassembled the engine and reinstalled into the vehicle. Topped off all fluid levels and filled engine oil. Ran engine and performed crankshaft relearn procedure. inspect for leaks and verified none found.

(Could not road test as the vehicle has no box/taillamps)

(780) 512-5311

Request Description Job **CSR Status** QUOET TO REPLACE LEAKING BRAKE MASTER CYLINDER SHAY G Original Description **Amount** Labour Type QUOET TO REPLACE LEAKING BRAKE MASTER CYLINDER 160 CD 468.00 Part Description Shp Bin Type Retail **Price Amount BRMC 284** CYLINDER ASY - MASTE CR20T 463.95 372.04 372.04 edm PM 20 FLUID - BRAKE 3 J2 CR20T 16.53 14.05 42.15 LC3Z 7E395 F **CABLE ASY - SELECTOR** F1 CR20T 236.25 189.45 189.45 1348 -Parts Total Technician 603.64 Cause Customer requested replacment Labour Total 468.00 Replaced brake master cylinder as per customers request. Request Sub-total 1,071.64 Correction **CSR** Request Description Job **Status** 99P Windsor Ford Vehicle Report Card 3 SHAY G Original Labour Description **Amount** Type

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

PRIVACY STATEMENT: Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.



10001 139 Avenue ● Grande Prairie, AB ● T8X 0V3 Tel: (780) 532-9555 ● 1-800-422-6094 service@windsorford.com ● www.windsorford.com

SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M. Saturday - 8:00 A.M. - 5:00 P.M.

GENUINE PEOPLE TREATING YOU LIKE A PERSON

OUR REPUTATION IS YOUR EXPERIENCE

SO # 602838

Status

Printed 10/02/2025 8:36:45 AM

SERVICE ORDER CUSTOMER COPY

User

592

	10/02/2025 8:36:45 AM		SICIVIL				User	592		Page 4
Customer N Attn: SHANE Adrenaline Au 730048 Hwy 2	KNOBLOCH uto Sales Ltd.	Advisor Shop Tag#	Shay G WF 3096	Loca PO #			Promised Opened Cashiered		05/06/2025 (05/06/2025 (06/26/2025	3:36 PM
,	ande Prairie No. 1, AB T8X 0T7	License NONE	Odo 6837		Odom (Out	In Service Da	ite	Stock No	
,	Bus (780) 512-5311 B0) 512-5311 Today ane.adrenaline@gmail.com Type W Term DEBIT	Year M 2021 Fo Vehicle ID	ake DRD No NXMDA07481	Model SUPER Selling	DUTY F- Dealer		Model Number F5H ended Warrant		Colour 1 OXFO Delivery I	
99PA	WINDSOR FORD SAFETY & RELIA	BILITY INSP	ECTION \$49.	95 VALUE	-NO CHA	ARGE			С	0.00
Technician	1348 -									
Request 888 Labour 888	Description CUSTOMER INFORMATION/CONT SHANE CUSTOMER'S PREFERRED METH TEXT CALL EMAIL_ ENGINE HOURS Would you like your used parts retur Description CUSTOMER INFORMATION/CONT SHANE CUSTOMER'S PREFERRED METH TEXT CALL EMAIL_ ENGINE HOURS Would you like your used parts retur	ned Yes / No ACT#	TACT: (not applicable) TACT:					Job 4	CSR SHAY G Type CQL	Status Origina Amoun 0.00
Technician	999 -							lab	CSB	Ctatus
Request 190 Labour	Description CHECK AND ADVISE ON AUTO 4X Description Electronic Shift - Four Wheel Drive -	Diagnosis						Job 5	CSR SHAY G Type W	Status Approved Amoun
7453D 7453D45 4462ACT	4X4 Systems - Diagnostic Pin Point Halfshaft or Axle Shaft Assembly - F		e and Install c	r Replace	Dual Wh	eels R∩1	ГН		W	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

PRIVACY STATEMENT: Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.



10001 139 Avenue ● Grande Prairie, AB ● T8X 0V3 Tel: (780) 532-9555 ● 1-800-422-6094 service@windsorford.com ● www.windsorford.com

SERVICE HOURS - Mon - Fri 7:30 A.M. - 6:00 P.M. Saturday - 8:00 A.M. - 5:00 P.M.

GENUINE PEOPLE TREATING YOU LIKE A PERSON

OUR REPUTATION IS YOUR EXPERIENCE

SO # 602838

Attn: SHANE KNOBLOCH

Adrenaline Auto Sales Ltd.

Status

Customer No

730048 Hwy 2

Printed 10/02/2025 8:36:45 AM

County Of Grande Prairie No. 1, AB T8X 0T7

(780) 512-5311 Today

shane.adrenaline@gmail.com

Term DEBIT

Type W

Bus

SERVICE ORDER CUSTOMER COPY

Page

 Advisor
 Shay G
 Location
 Promised
 05/06/2025 6:00 PM

 Shop
 WF
 PO #
 Opened
 05/06/2025 3:36 PM

 Tag#
 3096
 Cashiered
 06/26/2025 11:44 AM

User

592

License Odom In Odom Out In Service Date Stock No

NONE 68371 68375

YearMakeModelModel NumberColour2021FORDSUPER DUTY F-550 DRW F5H1 OXFORDVehicle ID NoSelling DealerExtended WarrantyDelivery Date

1FDUF5HNXMDA07481

Engine 7.3L 2V DEVCT NA PFI V8 GAS

Cause

Home

Email

Cell

Tested and verified the 4wd auto mode dose not operate as it should. Found if the hublocks are manually locked then 4wd will work indicating the front axle will not engage. Connected FDRS and performed TCCM self test and found no DTCs are present. Checked Oassis and found no TSB, SSM or GSBs apply for this concern. Followed symptom based diagnostic pinpoint test F in section 308-07A of the WSM. Found during Pinpoint test that both front outer axle/knuckle seals are leaking and require replacement. inspected lines and found no

contamination

Correction Removed both the front axle shafts Reinstalled both front axle shafts with new seals. Road test and verified 4wd Auto now operates as it should. Re inspect for

10053

(780) 512-5311

leaks and verified no leaks are present.

 Labour
 468.00

 Parts
 603.64

 Supplies
 58.50

 Env Fee
 5.00

 Sub-Total
 1,135.14

 GST
 56.76

 Total Invoice
 1,191.90

DEBIT 1,191.90

Additional Work Authorization

 Date / Time
 Contact
 Phone Number
 Comments
 Amount

 05/08/2025 10:33:58 AM
 Adrenaline Auto Sales (780) 512-5311
 \$940.69

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes or authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

PRIVACY STATEMENT: Personal information is collected in accordance with applicable privacy legislation and is governed by the Dealer's Privacy Policy. Your privacy is important to us. Ask us if you would like information about our Privacy Policy. We provide this personal information to Ford Motor Company of Canada Limited (together with third parties acting on its behalf "Ford") to enable Ford to administer your transaction, to provide you with services, to improve automotive related products and services by conducting customer surveys, and to provide you with marketing material which may be of interest to you. To obtain the Ford Privacy Policy or if you do not want to receive marketing or survey materials from Ford please call 1-800-565-FORD (3673).

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS

DISCLAIMER: Wheel lug nuts must be retorqued 100km after any wheel has been removed. This is the CUSTOMERS responsibility.