

TAX INVOICE



Mercedes-Benz Trucks
Professional Diagnosis & Repairs

18B Leader Street
Truganina Victoria 3029
ABN: 58938655011
Tel: 0456076528
Email: accounts@msstar.com.au

Tax Invoice Number: 3834

Date: 21/03/2025

Due Date: 21/03/2025

Payment Term: COD

BILL TO:

ICE Road Transport Solution Pty Ltd

Tel: 0434043411

Email: sonny@iceroad.com.au

FOR:

26 Transmission Diagnosis, 000 Defects report found during the work on the vehicle, 26 Remove install transmission, 54 Batteries/cables MP4/5, 26 Transmission oil change MP4, 49 Exhaust system repairs

Odometer: 945,849 Kms

Engine Hours: 14,682 Hrs

Make	Model/Year	Body Type	Reg No.	Fleet No.	VIN
Mercedes Benz	2658/2019		XB40TI		WDB96342420338599

Description	Qty.	Unit Price	Disc.	Amount
000 Preventive Maintenance Recommendation on Vehicles Over 1 Million Kilometers				
Propeller-shaft and jack-shaft repairs/replacement				
Front axle wheel bearings replacement				
0 WORKSHOP CONSUMABLES				
WORKSHOP CONSUMABLES	1.0	\$30.00		\$30.00
26 Transmission Diagnosis				
26 Remove install transmission				
26 Transmission oil change MP4				
Every 160000Km/2000Hrs or two years				
MB Xentry Diagnosis	1.0	\$240.00		\$240.00
Labour	18.0	\$140.00		\$2,520.00
Seal Transmission Input Shaft Actros	1.0	\$37.85		\$37.85
Oil Pipe Input Shaft	1.0	\$31.59		\$31.59
Titan Gear MP80	15.0	\$12.20		\$183.00
Transmission G330-12 715381 Genuine	1.0	\$29,200.00	10.0%	\$26,280.00
Prop Shaft Bolt Genuine	1.0	\$19.00		\$19.00
Seal Ring Oil Pipe G330 MP4/5	1.0	\$24.25		\$24.25
A0199970547 - SEALING RING Input-shaft PM4	1.0	\$25.42		\$25.42
O-ring air supply G330	1.0	\$19.00		\$19.00
Transmission oil lines O-rings kit	2.0	\$37.50		\$75.00
Nut Prop Shaft Genuine	1.0	\$15.50		\$15.50

54 Batteries/cables MP4/5			
Battery N200 S4 LH Positive BOSCH	2.0	\$469.00	\$938.00
Battery Cover SMC MP4	1.0	\$224.00	\$224.00
49 Exhaust system repairs			
Labour	1.0	\$140.00	\$140.00
Gasket Exhaust Flex Pipe 471/3	1.0	\$49.50	\$49.50
Flex Pipe Bottom Clamp 471/3 MP4	1.0	\$389.00	\$389.00

26 TRANSMISSION DIAGNOSIS

- ✘ Carry out road test confirm customer complaint
Transmission very noisy and crunching into gears
- ✘ Carry out quick test check faults related to the complaint
RPM sensor fault in TCM
- ✘ Check oil level and condition
Drained transmission oil found full of metal
Major bearings/gears failure.

000 DEFECTS REPORT FOUND DURING THE WORK ON THE VEHICLE

- !!! Defects found/repared during the work on the vehicle
Warning on dash not related to the repairs

26 REMOVE INSTALL TRANSMISSION

- ✓ Removed transmission, inspected for leaks, input shaft play,
Disassembles transmission.
Found bearings worn out failed
Main shaft top bearing catastrophic failure.
All gears and shafts are damaged
Drive shaft damaged, countershaft damaged
Range gears damaged

Repair cost of this transmission is too high.
As discussed with customer installed new transmission
- ✓ Remove batterie and battery box/walk plates
Remove walk plates and cab frame/seizes frame
Removed transmission, inspected for leaks, input shaft play,
Carried out teaching and read test all OK

54 BATTERIES/CABLES MP4/5

- ✓ Check over batteries/terminal/cables
Replaced both batteries
Positive battery cable terminal in poor condition may need new cable in the future

E.S

26 TRANSMISSION OIL CHANGE MP4

- ✓ Carry out transmission
Oil Service
ES

49 EXHAUST SYSTEM REPAIRS

- ✓ Carry out exhaust system check
Replaced cracked exhaust clap kit and seal on the flax pipe

ES

Subtotal	\$31,241.11
GST	\$3,124.11
Total	\$34,365.22
Paid	\$0.00
Balance Due	\$34,365.22

-Please make Payment via EFT using the following details:

-Westpac

-MS Star Service Pty Ltd

-BSB: 033-161

-ACC: 313-009

-Please reference your Invoice Number

-For all card payments 0.75% Surcharges may apply

-Please send payment confirmation before collecting the vehicle.