



## Vehicle History Summary

Fleet #	16204
Registration	
Make	DAF
Model	CF7585
VIN / Chassis #	XL RTE75PCEG025776
Build Date	10/14

Date	Reading / Units	Type / Repairer Notes	Repairer
02/10/2025	847,727 kms	<b>DEFECT, NHVR ROADWORTHY</b> R-32127 NHVR annual inspection - FAILED AHV1591256 Check and tested ADR 35 operation all ok Replace tail light lense Replace brake light globe Clear defect CA2885735	HNL Fleet Sydney workshop, NHVR
26/09/2025	847,698 kms	<b>Batteries</b> R-32038 Removed batteries from charge and re - installed to vehicle as requested.	KJS Fleet
26/09/2025	847,711 kms	<b>FLAT BATTERIES</b> R-32036 Drive to Wetherill Park,jumpstarted truck as requested.Consider changing batteries.	KJS Fleet
25/09/2025		<b>CHARGE BATTERIES</b> R-32023 Carried out removing batteries and placing on charge.Recommend cleaning battery terminals and repairing charge equaliser wiring when refitting batteries to vehicle.	KJS Fleet
08/09/2025	847,696 kms	<b>PREPARE FOR SALE</b> R-31678 Remove all HNL artwork Replace black drive guards Replace marker plates Swap rear plastic mirror covers	KJS Fleet
08/09/2025	847,696 kms	<b>B - 30000</b> S-14181 Carried out vehicle B service and inspection as per HNL checklist Replace engine oil & fuel filters Replace engine air filter Grease chassis Carry out all general service checks and adjustments	KJS Fleet
08/09/2025	847,696 kms	<b>JUMP START</b> R-31702 Jump start truck as requested.	KJS Fleet
02/07/2025	847,695 kms	<b>No Start</b> R-31758 Jump start truck as requested.	KJS Fleet
30/10/2024	847,694 kms	<b>DEFECT, NHVR ROADWORTHY</b> R-27979 NHVR annual inspection - Defect Replace driver side seat belt Check over defect items - All ok	KJS Fleet, NHVR
28/10/2024	847,667 kms	<b>Pre Rego Check over</b> R-27978 Basic check over before inspection booking Replace number plate light Noted - Requires driver side seat belt	KJS Fleet
25/10/2024	847,637 kms	<b>JUMP START</b> R-27957 Jump started engine & check charge rate - All ok	KJS Fleet
12/09/2024	847,635 kms	<b>JUMP START</b> R-27481 Drove to weighbridge and jump started as requested.	KJS Fleet
02/09/2024		<b>ELECTRICAL</b> R-27341 SERVICE CALL TO DEPOT. CHECK FOR CAUSE OF REAR LIGHTS NOT OPERATING CORRECTLY WHEN A TRAILER CONNECTED. CHECK CHASSIS AND OTHER EARTHS. CHECK REAR LIGHT. FOUND FAULTY EARTH. OPEN REAR LIGHT ASSEMBLY. FOUND REAR LIGHT TO BE FAULTY AND REMOVE. PICK UP PART AND RETURN. SUPPLY AND FIT NEW	Crowhurst Auto Electrical Pty Ltd
27/08/2024	847,540 kms	<b>Breakdown - Truck</b> R-27230 Drove to breakdown,jump started truck as required and returned to workshop.	KJS Fleet

Date	Reading / Units	Type / Repairer Notes	Repairer
15/08/2024	846,095 kms	<b>Anderson Lead R-27112</b> Replace missing anderson lead - Charge to MTE	KJS Fleet
08/08/2024	845,759 kms	<b>Anderson Lead Fault R-26983</b> Supply and fit new Anderson lead as requested,tested all okay.	KJS Fleet
05/08/2024	845,721 kms	<b>Bumper Bar Damage R-26932</b> Removed bumper and headlight surrounds and front grill.Removed all mounting brackets,number plate mounts and fog light mounts,install new bumper.Reinstall grill and headlight surround,inspected and found O/S tail light loom has short,will require new loom and plug	KJS Fleet
02/08/2024	845,721 kms	<b>Accident Damage R-26815</b> REPAIRED AS PART OF R#26932 FRONT BAR AND LIGHTS DAMAGED REPLACED BAR / FOG LAMPS AND SURROUND	HNL Sydney Workshop
23/07/2024	844,327 kms	<b>Electical 7 Pin plug R-26785</b> Driver reported 7 pin plug,replaced and test all okay.Found no tailights.Replaced all Globes on N/S bar indicator.Replaced 2 marker and indicator globe on O/S tail light will need to be replaced and repositioned as wiring harness is worn causing lights to flicker.	KJS Fleet
09/07/2024	84,917 kms	<b>Anderson Lead Charge Fault R-26698</b> Anderson lead not charging.Repair wiring to circuit breaker and test charge rate-14.8v	KJS Fleet
12/06/2024	839,949 kms	<b>Turntable Assembly R-26182</b> Inspected turntable and components,visually looked okay,re adjusted jaws and tested on several trailers,seem ok need to monitor operation.	KJS Fleet
11/06/2024	839,949 kms	<b>mirrors R-26165</b> Re install spotter mirror and backing order upper mirror glass and pick up parts. Install upper mirror glass and back cover.	KJS Fleet
07/06/2024	839,948 kms	<b>Mirror Assembly R-26154</b> REPLACE MIRROR GLASS - DVR 01585	HNL Sydney Workshop
07/06/2024	839,948 kms	<b>REAR BAR DAMAGE R-26295</b> REAR BAR DAMAGED BY 16205	Workhorse Collision Repair
03/06/2024	839,422 kms	<b>A - 10000 S-11480</b> A Service Carried out A service as requested, repaired stone guard mount and inspected damage N/S spot lights air box has hole in it at rear.	HNL Fleet Sydney
29/05/2024	838,768 kms	<b>Turntable Assembly R-26014</b> Inspected and found not locking in to trailer.Tested on HNL trailer was ok,tested several times in workshop was ok.Turntable has recently been kitted.	KJS Fleet
13/05/2024	837,622 kms	<b>A - 10000 S-11310</b> Carried out A Service as per HNL Check List. Rebuild Turn Table.	KJS Fleet
10/05/2024	837,622 kms	<b>Turntable - Damaged Jaws R-25812</b> Inspected turntable with tester,jaws failed. Adjusted jaws,jaws are at maximum adjustment,failed after adjustment,Turntable needs jaw rebuild.	KJS Fleet
08/05/2024	837,612 kms	<b>REAR BARS R-25783</b> Removed damaged rear bar,installed bar from 16205,wire up lights and swap number plates.	KJS Fleet
26/04/2024	836,921 kms	<b>BRAKE LIGHT ISSUE R-25636</b> Replaced globe and inspected Brake lights. During inspection lights turned off automatically.Worked at normal operation when pedal is pressed in unable to fault. Recommend monitoring possible brake switch wearing.	KJS Fleet
18/04/2024	836,510 kms	<b>FLAT TYRE R-25552</b> Removed damaged tyre and fit new tyre to vehicle.Old tyre was put in trailer and dropped off at workshop.	KJS Fleet
15/04/2024	831,172 kms	<b>Puncture Repair T-3889</b>	BRIDGESTONE

Date	Reading / Units	Type / Repairer Notes	Repairer
		Repair tyre - Position 8	
14/04/2024	836,369 kms	<b>B - 30000</b> S-11135	KJS Fleet
		Carried out vehicle B service and inspection as per HNL checklist All ok Replace engine oil & fuel filters Grease turntable	
02/04/2024	833,129 kms	<b>no start fault</b> R-25350	KJS Fleet
02/04/2024	833,129 kms	<b>Electrical - Starter Motor Replacement</b> R-25326	HNL Sydney Workshop
		STARTER MOTOR REPLACED Drove to dock found truck has started and been taken to the workshop and inspected and found starter motor causing issues. Organized parts from gilbert and roach as per mick bell request. Pick up parts, removed starter motor and install new and test all ok.	
08/01/2024	829,624 kms	<b>Check Vehicle Lights</b> R-24454	KJS Fleet
		Replace right rear tail lamp globe Check all lights and wiring to lamp assembly - All ok	
04/01/2024	829,235 kms	<b>Anderson Lead</b> R-24431	KJS Fleet
		Replace missing anderson lead	
27/11/2023		<b>Rego Inspection</b> R-24079	KJS Fleet
		Registration Inspection Transfer rego from Queensland to NSW All ok NSW - New rego XO65XL	
22/11/2023		<b>2024 REGO PAPERS</b> R-24053	HNL WORKSHOP
		2024 REGO PAPERS	
20/10/2023	820,642 kms	<b>Engine Light</b> R-23545	Gilbert and Roach
		Engine light / Exhaust warning Suspension fault - Replace hand controller inside cabin Invoice attached.	
19/09/2023	818,119 kms	<b>Anderson Lead</b> R-23348	KJS Fleet
		Check and repair damaged anderson lead Replace 175amp fitting to end of lead All ok	
07/07/2023	811,736 kms	<b>Alternator Warning Light</b> R-22588	HNL Fleet Sydney
		Check alternator warning light on dash Raise cabin and found alternator wiring harness at back of alternator loose Re connected and check over for faults All ok - Road tested	
03/07/2023	679,472 kms	<b>No Start</b> R-22515	HNL Fleet Sydney
		Travelled to Engadine, found negative terminal corroded, went to battery world Kirrawee they didnt have the Battery, had old batter at the workshop. Fitted Battery	
14/06/2023	810,860 kms	<b>no start fault</b> R-22317	HNL Sydney Workshop
		Check engine no start flat battery Jump started vehicle and run engine Check charge rate All ok	
07/06/2023	810,793 kms	<b>DRIVE TYRES</b> T-3230	Bridgestone Australia Ltd
		DRIVE TYRES POS 5/6 FITTED 11R22.5 FIRESTONE FD664	
31/05/2023	810,250 kms	<b>DRIVE TYRES</b> T-3214	Bridgestone Australia Ltd
		DRIVE TYRES POS 7/8 FITTED 11R22.5 FIRESTONE FD664	
19/05/2023	809,285 kms	<b>Brake Test</b> R-22065	Gilbert & Roach Huntingwood
		Brake Test - Passed attached	
17/05/2023	195,775 kms	<b>Brake Fault, Check Vehicle Lights</b> R-22052	HNL Sydney Workshop
		Check vehicle lights - Check & report on all vehicle lights All ok - No fault found Check vehicle brakes - No fault found - DVR 02239 Replaced blown fuse for A/c blower fan	
15/05/2023	808,963 kms	<b>Anderson Lead Fault</b> R-22034	HNL Sydney Workshop
		replace missing anderson lead jump start truck	
06/04/2023	808,817 kms	<b>alternator fault</b> R-21683	Crowhurst Auto Electrical Pty Ltd, KJS Fleet
		Remove & replace alternator. All ok Sublet Crowhurst, repair wiring fault Road tested all ok	
04/04/2023	808,815 kms	<b>Transmission Fault</b> R-21655	Gilbert & Roach Huntingwood, HNL Fleet Sydney

Date	Reading / Units	Type / Repairer Notes	Repairer
		Sublet transmission fault Gilbert & Roach Huntingwood Check over vehicle & tested transmission & clutch Advised no fault found on inspection but suspected clutch slave / mini pack fault Return to Metcash workshop for repair. Remove & replace clutch mini pack / slave booster Road tested OK	
29/03/2023		<b>Breakdown - Tow</b> R-21597 16204 broke down at Milperra , wouldn't select gear. Needed to be towed. towed to G&R	HNL Fleet Sydney
21/03/2023	808,691 kms	<b>no start fault</b> R-21502 Check vehicle no start Check & found isolator switch off Turn on isolator switch & tested start All ok	HNL Sydney Workshop
01/03/2023		<b>Breakdown - Truck</b> R-21318 ATTEND BREAKDOWN AT NEWCASTLE EAST - TG BATTERY ISSUE FOUND CHARGE EQUALISER NOT WIRED CORRECTLY RE-WIRE / RUN AND TEST OK	HNL WORKSHOP
22/02/2023		<b>Anderson Lead Charge Fault</b> R-21185 anderson lead fault repaired	HNL Fleet Sydney
25/01/2023	806,112 kms	<b>No Start</b> R-20918 Check & report engine no start Check & load tested batteries Remove & replace faulty batteries Check alternator charge rate - All ok 28v	HNL Fleet Sydney
18/01/2023	803,200 kms	<b>Registration Inspection</b> R-20816 Registration inspection - Transfer to NSW. Remove & replace axle 2 left & right disc rotors / brake pads / wear sensors Replaced hub nut (Gilbert & Roach torqued to spec) Replaced exhaust brake solenoid & tested Replace number plate lamp Wash down engine area Complete registration inspection All ok	Gilbert & Roach Huntingwood
03/01/2023	802,903 kms	<b>B - 30000</b> S-8355 Carried out vehicle B service & inspection as per HNL checklist Replaced left spotter mirror assembly	HNL Fleet Sydney, KJS Fleet
16/12/2022	799,036 kms	<b>Anderson Lead</b> R-20586 Replace missing anderson lead All ok	HNL Sydney Workshop
12/12/2022	797,584 kms	<b>Electrical - Headlight Globe</b> R-20527 Replace headlight globe left side CCheck all lights	HNL Sydney Workshop
24/11/2022		<b>Registration</b> O-2409	
21/11/2022	792,007 kms	<b>BRAKE PADS, brake wear sensor</b> R-20325 Brake Warning on dash Remove & replace front & rear brake pads Replace brake wear indicator wiring front & rear Road test	KJS Fleet
11/10/2022	781,303 kms	<b>Windscreen Wiper Blades</b> R-19924 REPLACE WIPER BLADES	HNL Sydney Workshop
14/09/2022	774,220 kms	<b>B - 30000</b> S-7763 CARRY OUT 'B' SERVICE 30,000KLM DAF	HNL Fleet Sydney
10/09/2022	762,000 kms	<b>Puncture Repair</b> T-2741 PUNCTURE REPAIR POS 2	Bridgestone Australia Ltd
20/07/2022	758,161 kms	<b>Battery Box Cover</b> R-19249 REPLACE BATTERY CLIPS	HNL Sydney Workshop
19/07/2022		<b>Windscreen Wiper Fault</b> R-19234 wiper wiring fault	MJR Auto Electrical
15/07/2022	757,096 kms	<b>Breakdown - Truck</b> R-19196 ATTEND BREAKDOWN AT MT WHITE WEIGH BRIDGE NO POWER TO TRUCK FOUND MAIN FUSE HAD BLOWN - PICK UP PARTS FIT NEW FUSE RUN AND TEST OK	HNL Sydney Workshop
11/07/2022	755,734 kms	<b>battery replacement</b> R-19145 REPLACED BATTERY REPLACED BATTERY COVER LOCK AND CLIPS	HNL Sydney Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
19/05/2022		<b>B - 30000</b> S-7268 CARRY OUT B SERVICE . CARRY OUT BRAKE RELINE 1ST AND 2ND AXLE .	HNL Sydney Workshop
17/05/2022	740,829 kms	<b>RUNOUT TYRE</b> T-2533 FIT RUNOUT TYRE POS 8	Bridgestone Australia Ltd
22/03/2022	727,347 kms	<b>Anderson Lead, Anderson Plug</b> R-18182 FITTED NEW ANDERSON PLUG AND LEAD .	HNL Sydney Workshop
17/03/2022	726,757 kms	<b>STEER TYRE</b> T-2413 STEER TYRE FITTED POS 2 FITTED 295/80R22.5 BRIDGESTONE R154	Bridgestone Australia Ltd
02/03/2022	723,945 kms	<b>Cab Doors</b> R-18029 REMOVE AND REPLACE DOOR LATCHED AND DOOR HANDLE AND CHECK OPERATION ALL OK .	HNL Sydney Workshop
10/02/2022	726,534 kms	<b>STEER TYRE</b> T-2344 FLAT STEER TYRE AT VALENTINE	Bridgestone Australia Ltd
04/02/2022	715,707 kms	<b>Anderson Lead Charge Fault</b> R-17853 CHECK CHARGING ISSUE - REPLACED CIRCUIT BREAKER	HNL WORKSHOP
16/12/2021	705,018 kms	<b>Electrical - Fuses, long tail suzi coil</b> R-17471 INSPECTED AND FOUND ELEC SUZI LREAD FAILED , REMOVE AND REPLACED SUZI LEAD AND CHECK OPERATION ALL OK .	HNL Sydney Workshop
30/11/2021		<b>Registration</b> O-1954	
25/11/2021	698,931 kms	<b>Rego Inspection</b> R-17253 PINK SLIP INSPECTION FOR QUEENSLAND REGO	HNL Sydney Workshop
13/11/2021	694,660 kms	<b>B - 30000</b> S-6492 b service.- DVR 05537 REPLACED REAR BRAKE PADS . REPLACED ALL 4 REAR AIR BAGS . REPLACED BELTS AND TENSIONERS .	HNL Sydney Workshop
08/10/2021	679,900 kms	<b>Electrical - Faulty Lights</b> R-16735 traveled to saber indicators on trailer not working reset circuit breaker checked operation all ok	HNL Sydney Workshop
31/08/2021	667,874 kms	<b>Door Locks, Turntable Inspection</b> R-16314 CHECKED OPERATION OF TURNTABLE LOCK WITH TESTING TOOL A NUMBER OF TIMES AND CANT FAULT TURNTABLE LOCK . ADJUSTED DOOR STRIKER AND CHECKED OPERATION ALL OK .	HNL Sydney Workshop
17/08/2021	666,638 kms	<b>Electrical - Fuses</b> R-16063 TRAVEL TO SABRE INSPECTED TRUCK AND FOUND R/H BLINKER INOP . CHECKED AND FOUND 10 AMP FUSE BLOWN , REPLACED FUSE AND CHECK OPERATION ALL OK BLINKERS WORKING.	HNL Fleet Sydney
12/05/2021	669,909 kms	<b>EXHAUST NOX SENSOR AFTER TREATMENT</b> R-15086 FOUND FAULT CODE FOR NOX SENSOR , CHECKED WIRING OK , REMOVE AND REPLACED NOX SENSOR	Gilbert & Roach Huntingwood
24/03/2021	642,606 kms	<b>DRIVE TYRES</b> T-1475 Replace x 4 drive tyres Position 5-6-7-8	Bridgestone Australia Ltd
23/03/2021	642,606 kms	<b>Brake Reline</b> R-14167 Service Repairs Continue - Raise axles front & rear Remove & replace steer axle brake disc rotors Including removal of hub assembly, adjust bearing & replace with new locking hub nuts Replace steer axle brake pads Replace steer axle brake wear indicator sensors Adjusted brakes Tension wheel nuts Remove & replace drive axle brake pads left & right Remove & replace drive axle brake wear indicator sensors Adjusted brake Tension wheel nuts All ok	HNL Fleet Sydney
23/03/2021	642,606 kms	<b>B - 30000</b> S-5539 Carried out vehicle B service & inspection, per HNL checklist Replace engine oil & filters Replace engine fuel filters Replace engine air filter Replace air dryer filter Check adjustment & grease turntable Carry out all general service checks Replace male & female air fittings at suzi coils	HNL Fleet Sydney
13/01/2021	634,064 kms	<b>Repairs, Turntable - Grease Plate &amp; Jaws</b> R-13248	HNL Fleet Sydney

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check & top up engine oil level as required Check coolant level Check operation of all lights Clean & grease turntable plate Check all brake pad wear & report Check vehicle exterior for damage Start engine & check for dash warnings Visual inspection of under body Check correct charge voltage at anderson plug All ok Replace number plate globe	
12/12/2020	629,457 kms	<b>Engine - Check Codes</b> R-12930	HNL Fleet Sydney
		Rectify engine no start Load tested batteries, all ok Test & locate faulty starter motor Travel to Gilbert & Roach Huntingwood & collect parts Remove & replaced starter motor Tested operation, start & run engine. All ok	
09/12/2020	629,155 kms	<b>Turntable - Damaged Jaws</b> R-12884	HNL Fleet Sydney
		Rectify jaw turntable wont release Check & found turntable jaw at end of adjustment Remove turntable plate from chassis foot mount Remove & replaced Jost jaw kit Remove & replaced Jost locking bar Remove & replaced left & right mounting feet bushes & all mounting plate bolts / nuts, tension at Jost spec Adjust jaw Tested operation with test pin Grease top plate All ok	
27/11/2020	627,336 kms	<b>Cooling System - Leaks</b> R-12740	HNL Fleet Sydney
		Rectify coolant leak Check system & found coolant header tank leaking Drain system Remove & replaced coolant header tank Refill system with coolant, bleed & run engine Road test & check Replace radiator cap All ok	
27/11/2020		<b>Registration</b> O-1433	
27/11/2020		<b>CTP</b> O-1434	
25/11/2020	626,994 kms	<b>Service, Turntable - Grease Plate &amp; Jaws</b> R-12691	HNL Fleet Sydney
		Carried out vehicle A - Service checks as per HNL checklist Top up engine oil level as required Replaced worn radiator cap Replaced left front outer fog lamp assembly Replaced checker plate mounted fire extinguisher Replaced male air fitting at suzi line to trailer Replaced missing left headlight rear cover Carry out general check over for rego renewal All ok Brake Test - PASSED attached	
23/11/2020	587,734 kms	<b>Brake Test</b> R-13090	Gilbert & Roach Huntingwood
		Brake Test	
05/11/2020	622,358 kms	<b>Engine - Cooling System</b> R-12389	HNL Fleet Sydney
		Driver complaint of low coolant warning on dash Check & confirm fault Top up coolant header tank Check engine bay area for leaks, could not fault Raise cabin & check for any signs of water leaks. All ok Could not fault at time of inspection Grease turntable	
02/11/2020	622,122 kms	<b>New Tyres</b> T-1111	ADZ Tyre & Battery
		Super Premium Steer (B/Stone)- 295/80r 22.5 pos 1,2 as per Attachment	
01/09/2020	606,356 kms	<b>Pressure Check</b> T-1062	ADZ Tyre & Battery
		Pressure Check as per Attachment	
21/08/2020	603,853 kms	<b>C - 90000</b> S-4575	HNL Fleet Sydney
		Carry out B service & inspection Replaced engine oil & filters Replaced engine fuel filters Replaced engine air filter Replaced cabin fresh air filter Replaced air drier filter assembly Grease chassis & turntable Adjusted turntable jaw Drain & replaced coolant Carry out all general service checks Remove & replaced left rear tail light globes, all.	
19/08/2020	603,015 kms	<b>Service - Vehicle "C" Service</b> R-11060	Gilbert & Roach Huntingwood
		Replace transmission oils (Synthetic) Replace diff oils (Synthetic) 300k Service Interval	
18/08/2020	602,797 kms	<b>Cooling System Warning</b> R-11099	HNL Fleet Sydney
		Driver complaint of coolant warning Check & top up 1L coolant Raise cabin & visually check over for leaks None found Warning only came up when engine cold Could not fault at time of inspection	
11/08/2020		<b>Electrical - Headlight Globe</b> R-10987	HNL Fleet Sydney
		Left headlight not working Remove & replaced left side headlight globe Tested operation of all lights All ok	
21/07/2020	546,768 kms	<b>Electrical - Fault</b> R-10678	HNL Sydney Workshop
		Rectify rear light damaged Confirm fault, remove damaged light assembly Straighten rear bar to best of ability Replace right rear tail lamp complete unit Tested operation of all lights All ok	
28/05/2020		<b>Registration</b> O-1081	
28/05/2020		<b>CTP</b> O-1082	

Date	Reading / Units	Type / Repairer Notes	Repairer
25/05/2020		<b>Pressure Check</b> T-514 Pressures Only (x10) as per Attachment	ADZ Tyre & Battery
21/04/2020		<b>Pressure Check</b> T-319 Pressure Check as per Attachment	ADZ Tyre & Battery
28/02/2020	566,343 kms	<b>B - 30000</b> S-3766 Carry out B service Replace all engine oil & fuel filters Replace cabin fresh air filter Replace left rear tail light lense Replace left rear indicator globe Replace front left & right indicator globes Grease turntable Carry out all general service checks & adjustments	HNL Sydney Workshop
13/02/2020		<b>Brake Fault</b> R-8134 Replace front & rear brake pads Replace brake wear sensors	TRS
12/02/2020	562,746 kms	<b>Brake Disc Pads</b> R-8214 Checked all brakes Replaced steer and drive axle brake pads Replaced all wear sensors Adjust brakes and tension wheel nuts	TRS
04/02/2020	561,111 kms	<b>Electrical - Headlight Assembly</b> R-7855 removed and replaced blown headlight	HNL Sydney Workshop
09/01/2020		<b>Accident Damage</b> R-7350 Replace left mirror complete Detail clean cabin	HNL Sydney Workshop
24/12/2019	553,612 kms	<b>Registration Inspection</b> R-7138 Carry out pink slip / safety inspection Brake Test report checked all lights checked all tires checked and reported brakes: steer: 8mm 80% drive: 9mm 90% cleaned, checked and greased turn table checked seat belt checked demister fan checked horn checked wheel bearings	HNL Sydney Workshop
12/12/2019	551,468 kms	<b>Engine Light</b> R-6846 picked up truck from Gilbert and Roach brought truck back to Sydney yard	HNL Sydney Workshop
08/12/2019	551,433 kms	<b>Engine Fuel Hoses</b> R-6718 Inspected fuel leak found fuel leaking from fuel filter/ hand primer housing Removed and replaced housing Checked for leaks none found all ok	HNL Sydney Workshop
08/11/2019	544,976 kms	<b>Cab Window Faulty</b> R-6217 removed and replaced RHS window reg tested all ok	HNL Sydney Workshop
24/10/2019	541,353 kms	<b>Anderson Lead Charge Fault</b> R-5878 inspected why the Anderson lead wasn't charging trailer 1609 checked if batteries were charging found the circuit braker removed and replaced circuit braker on truck retested charging system tailgate batteries are now charging	HNL Sydney Workshop
13/09/2019	533,455 kms	<b>Electrical - Headlight Globe</b> R-5187 REMOVED AND REPLACED RHS BLOWN HEADLIGHT GLOBE TESTED ALL OK	HNL Sydney Workshop
30/08/2019	530,282 kms	<b>B - 30000</b> S-2787 REMOVED AND REPLACED ENGINE OIL AND FILTERS REMOVED AND REPLACED FUEL FILTERS REMOVED AND REPLACED AIR FILTER REMOVED AND REPLACED AIR DRYER FILTER REMOVED AND REPLACED WIPER BLADES CLEANED AND REGRESSED TURNTABLE CLEANED CAB FITTED FLOOR MATS CHECKED ALL TIRES CHECKED ALL LIGHTS CHECKED AND REPORTED BRAKES: STEER: 8MM 80% DRIVE: 8MM 80%	HNL Sydney Workshop
03/08/2019	525,063 kms	<b>Engine Light</b> R-4611 Replace engine fan hub Replace engine drive belt & tensioner	HNL Sydney Workshop
12/07/2019	522,349 kms	<b>Breakdown - After Hours</b> R-4494 Engine No Start Travel to 7/11 Lithgow. Rectify no start Inspect & found burnt anderson lead plug, suspected short on anderson lead bracket. Replaced damaged lead Replace damaged circuit breaker Replace damaged batteries Start engine & test run. All ok. Install fire extinguisher to rear deck plate All ok.	HNL Sydney Workshop
31/05/2019		<b>Registration</b> O-620	

Date	Reading / Units	Type / Repairer Notes	Repairer
11/04/2019	511,306 kms	C - 90000 S-2489	IDR
		'C' SERVICE COMPLETED IN QUEENSLAND BEFORE COMING TO THORNTON	

Signed: \_\_\_\_\_  
Name: \_\_\_\_\_  
Date: \_\_\_\_\_