

ADAPT-A-LIFT GROUP PTY LTD

Service History Listing Active Units

For Equipment Code From: H18559 To: H18559
For Date Posted From: All To: All
Don't Show Cost

For Customer Code From: All To: All
For Branch Code From: All To: All

Date: 7/08/2026
Time: 10:12:58AM

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H18559		Description: YALE GLP25MX					
Make: YALE		Model: GLP25MX		Serial No.: D871R12467V			
1831217	Prep for auction	NWILLIAMS	3/06/2026	Internal	378.0	\$0.00	Carry out equipment condition assessment
1752309	advertise online - used	JDITCHBURN	26/09/2025	Internal	376.0	\$0.00	Carry out equipment condition assessment
Steam clean equipment as necessary.							
carried out photo of unit, unit barred & had to use workshop fork to move unit out of the way to get my unit out, cleaned unit.							
1750102	Prep for transport	NMORAN	18/09/2025	Internal	376.0	\$0.00	Replace Battery,
Replace LPG Hose as required,							
Replace LPG Hose Coupling as required,							
Carry out Inspection and Diagnosis of Electrical System							
Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,							
Check/Inspect/Diagnose Hydraulic Oil Leak and test operation,							
Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,							
Prep unit for transport							
found split gas hose, replaced hose							
found gas coupling damaged, replace coupling							
found damaged wiring behind seat, repair							
found damaged starter wiring , repair							
unit would now start, upon starting found excessdivd							
hydraulic oil leak, no steering and no hydraulic functions,							
repair hydraulic leak, after repairing main leak found 4							
other leaks requiring repair, repaired , steering and							
hydraulics all good.							
replace battery all good to go							

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H18559		Description: YALE GLP25MX					
Make: YALE		Model: GLP25MX		Serial No.: D871R12467V			
1583122	general repair for dash	DDEJESUS	28/11/2023	Internal	50.0	\$0.00	Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Steam clean equipment as necessary. Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Remove ancillary items and Dashboard, inspect and report, Repair Dashboard as necessary, Replace Dashboard, Remove ancillary items and Mirror and Replace, Refit Mirror and ancillary items, Replace Revolving/Flashing/Strobe light, Replace Light/s Replace Steering Wheel, Replace Battery, Repair Light/s Replace Seat, Repair Seat Switch Wiring,
1574954	Green Tag Inspection	DDEJESUS	25/10/2023	Internal	50.0	\$0.00	Repair Load Guard as necessary, Steam clean equipment as necessary. Carry out equipment condition assessment
1568316	RENTAL RETURN - CHECK FOR DAMAGES	201WORKSHOP	24/10/2023	Internal	50.0	\$0.00	
1570425	DE HIRE - Seat,Dash, RHS Mirror, Beacon Light, Both Rear Lights, Keys	201WSHOP-ALLOCATOIN	6/10/2023	External	50.0	\$69.20	Carry out equipment condition assessment 1. seat burnt 2. dash burnt 3.right mirrior missing 4. beacon ligjt burnt 5. both rear light burnt 6. keys missing
1564576	Scheduled Service - TC IC 2000HR SM - 2000hrs .2000 Hour Service	DDEJESUS	28/09/2023	Internal	50.0	\$0.00	2000hr Service

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H18559		Description: YALE GLP25MX					
Make: YALE		Model: GLP25MX		Serial No.: D871R12467V			
1577692	Scheduled Service Job. 1000 Hour Service	DDEJESUS	25/02/2023	Internal	50.0	\$0.00	1000hr Service
1496716	SERVICE NOT DONE Scheduled Service - NKA 1000HR SM .1000 Hour Service	201SUBC	25/11/2022	Internal	50.0	\$0.00	Labour Carry out equipment condition assessment Found the machine burned
1446245	Full inspection - mechanical, electrical, body & cosmetic. ETkt 117885	201WSHOP-ALLOCATOIN	21/04/2022	Internal	50.0	\$0.00	
1438239	Can they fix the seatbelt on the unit.	NCLARKE	14/03/2022	External	50.0	\$452.00	Repair Seat as necessary, Remove ancillary items and Mirror and Replace, Refit Mirror and ancillary items, replaced seat belt and mirror please charge cust damage Travel to site,
1422739	Swap over Rotator from H11211 to H18559. SF EMAIL via Stas.	JPrinitis	22/12/2021	Internal	5.0	\$0.00	Carry out equipment condition assessment travel to site and check both units, found unit H18559 is not fitted with the 4th valve. Note spoke with Ken and advised i could fit the rotator but it would not work until 4th valve or divertor valve is fitted to unit. was told divertor valve is a safety issue and unit must be fitted with a 4th valve.
1417529	New Sale - Addition to STR	TREDSHAW	6/12/2021	Cap Prep	4.0	\$0.00	- New unit PDI, clean, test, ensure full function - Touch up paint if required - Fit factory supplied lexan roof - Calibrate built in weight gauge - LPG cert / plate Carry out New Equipment Predelivery to correct specification. Prepare For Hire - Workshop Steam clean equipment as necessary. Gas Inspection Grease All Points on Unit, Install Hard Labels,
Equipment Total:						\$521.20	
Customer Total:						\$521.20	