

DOBBS PETERBILT





3707 Airport Way S. Seattle, Washington 98134

TF: (800) 255-7383

Invoice: 021R2325

Date / Hour: 12/15/2022 12:33:03PM

Repair Order: 2325 Customer: 801156 Branch: Seat

Total Invoice: \$19,225.74 ***Open Account - Charge***

Page 1 of 4

Bill To: **Grady Excavating**

46832 SE Middle Fork RD. North Bend, WA 98045

Ship To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045

Email: ap@gradyexcavating.com

Shop:425-423-7932

Customer P/O: G58 Open Date: 10/04/2022 Completion Date: 12/14/2022

Add User: matthew.austin Salesperson: ataylor

Unit Number: G58 Model Year: 2016 Make/Model: Peterbilt 367

VIN: 1NPTX4EX7GD319249 Type: Truck Meter: 509401 Miles In-Service Date: 05/11/2015 ECM Reading: 18412

Task: 521 **Engine Assembly - Miscellaneous Repair** Department: Service

Complaint: Customer States: Quote for engine overhaul

Cause: Cylinder block counterbore fretting on cylinde 5 and 6

Correction: Pressure washed engine, pulled into shop. Connected to Insite and printed faults, features, and parameters. Started EDS#

DSCBM7706 for internal coolant loss. Has several inactive faults for both coolant and aftertreatment, all within the last 3 hours. Followed EDS trouble shooting tree. Removed EGR outlet piping, turbo, plumbing, EGR mass measurement assembly, and aftertreatment fuel injector. Inspected air compressor for leaks, no issues found. Removed hood, cooling system, exhaust system, intake system, front gear housing cover, damper, idler gear, camshaft gear, fuel rail, lines, pass through tubes, valve cover, rocker assemblies, camshaft, injectors, and head. Cleaned block, and measured liner height. Found liner protrusion on cylinders #5 and #6 are out of spec. Took TruVideo for documentation. Recommend counter bore machine with new cylinder liners. Removed oil pump, block stiffener, and piston cooling nozzles. Removed piston rod assemblies and liners. Disassembled piston rod assemblies and cleaned rods. Replaced injector o-rings and seals. Laid out new seals, o-rings, gaskets, and components to prep for assembly. Installed liners. Installed piston rod assemblies and cooling nozzles. Installed head with new head bolts and gasket. Torqued to spec. Installed fuel return line on back of head. Installed camshaft, camshaft retainer plate, injectors, pass through tubes, crossovers, and rocker assemblies. Torqued all to spec. Assembled engine. Installed radiator assembly, charged A/C, and filled with coolant. Pulled out of shop, ran up to temp with cap off, then topped off coolant. Installed hood. Performed break-in road test. No issues found during drive. During inspection found lower radiator hose is leaking. Drained coolant. Removed and replaced lower coolant piping. Vacuum filled cooling system. Found no more leaks.

Supp. Part	t	Description / Ref Number	U/M	Quantity	Price	Extended Price
EXM10	105816EXX	OIL-DELVAC 1300 SUP 15W-4	GA	11.0	\$19.18	\$210.98
PTBPR	105FBC	LUBRIPLATE	EA	3.0	\$9.02	\$27.06
CUM10	3164067CUM	SEALANT	EA	1.0	\$20.10	\$20.10
CUM10	3678506CUM	SCREWHEX FLANGE HEAD CAP	EA	22.0	\$19.40	\$426.80
CUM10	3678610CUM	PLUG	EA	2.0	\$13.76	\$27.52
CUM10	3678804CUM	SCREWHEX FLANGE HEAD CAP	EA	4.0	\$12.65	\$50.60
CUM10	3684359CUM	GASKET-EXH OUT CONNECTION	EA	1.0	\$11.25	\$11.25
CUM15	3824421	CLEANERSOLVENT (JUG)	EA	1.0	\$34.17	\$34.17
CUM10	4377682CUM	SCREW-HEX FLANGE HEAD CAP	EA	2.0	\$13.71	\$27.42
CUM10	4963857CUM	GASKET-INJECTOR	EA	1.0	\$14.58	\$14.58
CUM10	4966441CUM	GASKET-EXH OUT CONNECTION	EA	1.0	\$15.71	\$15.71
CUM10	4984152CUM	SEAL-O RING	EA	1.0	\$2.60	\$2.60
CUM10	5264570CUM	GASKET-DRAIN OIL	EA	1.0	\$2.96	\$2.96
CUM10	5292265CUM	ISOLATOR-THERMAL	EA	1.0	\$3.93	\$3.93
CUM10	5298564CUM	SHIM	EA	6.0	\$47.58	\$285.48
CUM10	5693737CUM	KIT, CLASSIC OVERHAUL	EA	1.0	\$6,493.16	\$6,493.16
Tac Scr15	619-C02T	3M SCOTCH-BRITE	EA	1.0	\$1.63	\$1.63
Tac Scr15	679-003	3/8 PLUG	EA	1.0	\$1.15	\$1.15
Phillips15	8-43117DSP	CABLE TIE-11"BLK NYL 50#	EA	25.0	\$0.05	\$1.25

^{**} See Last Page for Invoice Total **



DOBBS PETERBILT





3707 Airport Way S. Seattle, Washington 98134

TF: (800) 255-7383

Invoice: 021R2325

Date / Hour: 12/15/2022 12:33:03PM

Repair Order: 2325 Customer: 801156 Branch: Seat

Total Invoice: \$19,225.74

Open Account - Charge

Page 2 of 4

Bill To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045 Ship To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045

Email: ap@gradyexcavating.com

Shop: 425-423-7932

Customer P/O: G58			Open Date: 10/04/2022		Completion Date: 12/14/2022		
Add User: matthew.austin		Sales	Salesperson: ata				
Phillips15	8-44147DSP	CABLE TIE-14"BLK NYL 120#	EA	25.0	\$0.12	\$3.00	
Levins15	AMRPZAA734	ZEP N/C BRAKE CLNR 12/14OZ	EA	8.0	\$4.56	\$36.48	
TRPCT	EC3501	COOLANT-TRP ELC 50/50 JUG	JG	14.0	\$11.06	\$154.84	
TRPCT	EC3501	COOLANT-TRP ELC 50/50 JUG	JG	1.0	\$11.06	\$11.06	
PACPR	F66-2300-100	PIPE-LOWER WATER	EA	1.0	\$407.64	\$407.64	
PACPR	K37-1029	FILTER-ELEMENT FUEL 10	EA	2.0	\$49.73	\$99.46	
Weitron15	R134A-LBS	FREON R134A LBS	EA	3.0	\$13.68	\$41.04	
Levins15	SCOT75130	SCOTT SHOP TOWELS ON A ROLL, Blue (30/55) (751	I3EA	1.0	\$3.14	\$3.14	
PTBPR	ST6002	TANK-ASSY SURGE OE N5346001	EA	1.0	\$199.78	\$199.78	
TRP	VH11600	KIT- O-RING- HVAC SERVICE	EA	1.0	\$3.76	\$3.76	
TRP	VH11600	KIT- O-RING- HVAC SERVICE	EA	1.0	\$3.76	\$3.76	

Detail Tax Info:

Sales Tax

\$1,787.43 Total: \$1,787.43 Total Parts: \$8,622.31
Total Labor: \$7,616.00
Total Environmental Fee: \$200.00
Total Shop Supplies: \$1,000.00

Invoice Subtotal: \$17,438.31
Total Tax: \$1,787.43

Total Invoice: \$19,225.74

 Payment Method
 Terms
 Due Date

 Open Account - Charge
 Net 30 Days
 1/14/2023

Remit To:

Dobbs Peterbilt - Seattle, WA

P.O. Box 35144 #1022

Seattle, WA 98124-5144



DOBBS PETERBILT





3707 Airport Way S. Seattle, Washington 98134

TF: (800) 255-7383

Invoice: **021R2325**

Date / Hour: 12/15/2022 12:33:03PM

Repair Order: 2325 Customer: 801156 Branch: Seat

Total Invoice: \$19,225.74

Open Account - Charge

Page 3 of 4

Bill To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045 Ship To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045

Email: ap@gradyexcavating.com

Shop: 425-423-7932

Customer P/O: G58 Open Date: 10/04/2022 Completion Date: 12/14/2022

Add User: matthew.austin Salesperson: ataylor

LIMITED WARRANTY

THIS LIMITED WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS AND YOU MAY ALSO HAVE OTHER RIGHTS, WHICH VARY FROM STATE TO STATE. WHO IS COVERED: The Dealership issuing this invoice (the "Dealership) offers this limited warranty to only you, the customer listed on this repair order/invoice. It does not extend to any subsequent owner. It cannot be transferred to any other person.

WHAT IS COVERED: The Dealership warrants the workmanship of our labor performed in conjunction with repairs for 90 days (the "Warranty Period"). Said Warranty Period commence on the date ("Invoice Date") that the repairs are completed. The following items will void this Limited Warranty; if the failure was caused by misuse, abuse, lack of or improper maintenance, accident, alterations, overheating, and/or lack of lubrication or coolant. For any failure caused by the Dealership's workmanship (labor) covered by this Limited Warranty, the Dealership will either repair or replace such failure, at its option, in the Dealership facility. YOUR RESPONSIBILES: All items must be returned to our shop with transportation charges prepaid for our inspection and determination within 60 days from the date of the sales invoice covering said items. The customer is required to return the vehicle to the Dealership or authorized repair facility at the customer's expense, You must retain copies of your Repair Orders/Invoices, and, upon request, be able to present them to us when requesting coverage under this Limited Warranty. Upon return of the vehicle to you, you must pay for any parts, labor, products, expenses, freight and taxes that the Dealership is not obligated to provide or pay for under this Limited Warranty.

WHAT IS NOT COVERED: Repairs which are still covered by a manufacturer's warranty or recall or other third party warranty/service contract. The Dealership's Limited Warranty shall be secondary to any such warranty or service contract that provides coverage for repair claims covered hereunder. Damage caused by you for failure to use manufacturer approved fluids, or the lack thereof, including but not limited to oil, antifreeze, and DEF. Any failure or damage resulting from your failure to perform maintenance in accordance with the manufacturer's recommendations; your failure to maintain appropriate fluid levels (e.g. oil, water, DEF, transmission fluid); your continued operation of the vehicle after warning light notification; modification or operation of the vehicle in a manner that is not in conformance with the manufacturer's specifications or intended use; an accident or collision; your use of improper or contaminated fluids including fuel, and/or misuse, abuse, tampering, negligence, theft, vandalism, or acts of nature or God. Parts installed and/ or repairs performed on vehicles used primarily for off road competition or engaging in a contest of speed or endurance of any type.

INSPECTION RIGHTS: The Dealership reserves the right to inspect the vehicle and any parts removed from or installed in the vehicle both prior to and after a repair is performed pursuant to a claim made under this Limited Warranty

EXCLUSIVE REMEDY: The performance of labor to effect repairs is the exclusive remedy available under this written Limited Warranty . THE PERFORMANCE OF LABOR TO EFFECT REPAIRS IS YOUR SOLE AND EXCLUSIVE REMEDY AND OUR ENTIRE LIABILITY FOR ANY BREACH OF THIS LIMITED WARRANTY. OUR LIABILITY SHALL UNDER NO CIRCUMSTANCES EXCEED THE ACTUAL AMOUNT PAID BY YOU FOR THE LABOR WE SUPPLIED, NOR SHALL WE UNDER ANY CIRCUMSTANCES BE LIABLE FOR ANY CONSEQUENTIAL, INCIDENTAL, SPECIAL OR PUNITIVE DAMAGES OR LOSSES, WHETHER DIRECT OR INDIRECT.

SOME STATES DO NOT ALLOW THE EXCLUSION OR LIMITATION OF INCIDENTAL OR CONSEQUENTIAL DAMAGES, SO THE ABOVE LIMITATION OR EXCLUSION MAY NOT APPLY TO YOU.

IMPLIED WARRRANTY DISCLAIMER: The only warranty on parts and products sold in conjunction with repairs performed by the manufacturer or supplier of said parts or products. Except for the limited warranty on the workmanship of our labor, the Dealership expressly disclaims all implied warranties including any implied warranties of the merchantability and fitness for a particular purpose for any period beyond the Warranty Period. WE LIMIT THE DURATION AND REMEDIES OF ALL IMPLIED WARRANTIES, INCLUDING WITHOUT LIMITATION THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE TO THE DURATION OF WARRANTY PERIOD.

SOME STATES DO NOT ALLOW LIMITATIONS ON HOW LONG AN IMPLIED WARRANTY LASTS, SO THE ABOVE LIMITATION MAY NOT APPLY TO YOU. NO ASSUMPTION OF LIABILITY: The Dealership does not authorize any other person to assume for it any liability in connection with the sales of any parts or products of this repair.

THE FOLLOWING APPLIES TO ALL OF OUR CUSTOMERS

STORAGE CHARGES: I understand and agree that a daily storage charge may be assessed if I fail to pick up the vehicle after being notified that the repairs have been completed. Storage charges will accrue at the rate of \$45.00 per day beginning 15 days after the repair has been completed. Storage fees will also accrue at the same charge if I fail to authorize repairs to be performed within three days after the data of communication from the Dealership.

DISASSEMBLY/REASSEMBLY CHARGES: If you authorize disassembly of the vehicle or a vehicle component to provide an estimate or commencement of repairs and do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work and you agree to pay the same. Such charges will be directly related to the actual amount of labor and parts involved in the inspection, repair or service. I have been advised that disassembly of the vehicle may prevent restoration of the vehicle to its prior condition.

DELAYS AND LEGAL LIABILITY: I understand and agree that the Dealership is not responsible for any delays caused by unavailability of parts or shipping by the supplier or transporter or any losses or downtime relating to such delays, nor is it responsible for loss or damage to the vehicle or articles left in the vehicle in the event of fire, theft, or any other cause beyond its control. The Dealership will not be responsible for personal property. You and your representative agree to hold the Dealership harmless and not liable for any missing or damaged property.

WARNING: Products being sold to you can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other









3707 Airport Way S. Seattle, Washington 98134 TF: (800) 255-7383 Date / Hour: 12/15/2022 12:33:03PM

Invoice: 021R2325

Repair Order: 2325 Customer: 801156 Branch: Seat

Total Invoice: \$19,225.74

Open Account - Charge

Page 4 of 4

Bill To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045 Ship To: Grady Excavating

46832 SE Middle Fork RD. North Bend, WA 98045

Email: ap@gradyexcavating.com

Shop: 425-423-7932

_ Date: ___

Customer P/O: G58	Open Date: 10/04/2022	Completion Date: 12/14/2022			
Add User: matthew.austin	Salesperson: ataylor				
eproductive harm. For more information go to www.P65Warnings.ca.gov.					