

**DOBBS PETERBILT**

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383



Invoice: **021R3087**
Date / Hour: 3/31/2023 6:08:51PM
Repair Order: 3087
Customer: 801156
Branch: Seat
Total Invoice: \$61,412.19
Open Account - Charge

Page 1 of 5

Bill To: Grady Excavating Inc - NORTH BEND - SHIP TO
PO Box 467
Mukilteo, WA 98275

Ship To: Grady Excavating Inc - NORTH
BEND - SHIP TO
46832 SE Middle Fork Rd
North Bend, WA 98045
Office Phone: 425-423-7932
Email: ap@gradyexcavating.com

Work: 425-423-7932

Shop: 425-423-7932

Customer P/O: G67

Open Date: 03/23/2023

Completion Date: 03/31/2023

Add User: matthew.austin

Salesperson: ataylor

Unit Number: G-67**Model Year: 2016****Make/Model: Peterbilt 367****Type: Truck****VIN: 1NPTX4EX7GD319252****Meter: 1 Miles****In-Service Date: 07/15/2015**

Unit Components:

ManufacturerModelPart NumberSerial Number

79814000

Task: 1 521 Engine Assembly - Miscellaneous Repair Department: Service

Complaint: Customer Requests Engine Swing**Cause:** Recon Engine Swing

Rear motor mounts

Front Motor mounts

Oil

Coolant

Serpentine Belts

DPF/DOC Clean

Air Filters

Fuel Filters

Correction: Pushed vehicle into shop and unloaded pallet of parts.

Removed side step and aftertreatment system. All clamps on aftertreatment are rusted and have damaged or broken threads.

Recommend replacing all damaged aftertreatment clamps. All bolts for belly pan under aftertreatment severely corroded, bolts either broke or were already missing. Will need to install new nut certs or bolts and washers. Front DPF differential pressure sensor tube is seized and should be replaced.

Removed hood, radiator assembly, radiator braces, oem engine harness, charge and start harness, power steering pump, fuel lines, heater hoses and engine. Set engine on stands. Swapped block heater, stand off brackets, coolant fittings, fan hub, fan, mega bracket, alternator, AC compressor, front engine bracket, rear engine support brackets, ECM and flywheel from old engine to new engine. Installed new belts on engine. Supported cab. Replaced rear motor mounts. Had to remove front engine mount cross member and press motor mount bolts out. Installed front motor mount cross member with new motor mounts and bolts. Installed new engine in frame. Clutch is in new like condition. Reinstalled clutch, transmission, shift tower, transmission harness, air lines, shift linkage, drivelines, and hydraulic pump. Routed oem engine harness, charge and start harness and air lines. Installed power steering pump radiator assembly, condenser, fuel cooler, radiator shrouds, braces, coolant reservoir and hood. Found windshield washer reservoir was broken. Installed new washer reservoir. Hooked up coolant and ac lines. Installed charge air and fresh air plumbing. Filled with new washer fluid, engine oil, coolant and ATF in power steering reservoir. Replaced frame mounted fuel filter. Primed fuel system. Connected to ECM, cleared inactive faults, reset aftertreatment maintenance, reset fuel injectors, and added note about recon replacement mileage and hours in customer info tab. Started engine and ran. Found there is a loud belt screech. Removed belts and checked pulleys. Found accessory idler could be heard when rotating by hand. Replaced idler and ran engine. Screech was less but still present. Sprayed bearing on accessory tensioner with lube and screech went away temporarily. Replaced accessory tensioner. Topped off all fluids and performed road test. No issues noted on drive. Checked for leaks after drive. None found.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
PTBPR	05-16401	MOUNT-ENGINE FRONT	EA	2.0	\$23.28	\$46.56
CUM10	DR7080RXCUM-C	ENGINE-ISX 15 13 B 600@1900 XPI-Core	EA	-1.0	\$9,018.75	\$(9,018.75)
Original Invoice: 021R3087						
CUM10	2866337CUM	GASKET-CIRCULAR 5"	EA	2.0	\$12.83	\$25.66
CUM10	2871453CUM	GASKET-DPF ASSY	EA	2.0	\$33.08	\$66.16
CUM10	2871863CUM	CLAMP-V BAND	EA	2.0	\$83.46	\$166.92

** See Last Page for Invoice Total **

**DOBBS PETERBILT**

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383



Invoice: **021R3087**
Date / Hour: 3/31/2023 6:08:51PM
Repair Order: 3087
Customer: 801156
Branch: Seat
Total Invoice: \$61,412.19
Open Account - Charge

Page 2 of 5

Bill To: Grady Excavating Inc - NORTH BEND - SHIP TO
PO Box 467
Mukilteo, WA 98275

Ship To: Grady Excavating Inc - NORTH BEND - SHIP
TO
46832 SE Middle Fork Rd
North Bend, WA 98045
Office Phone: 425-423-7932
Email: ap@gradyexcavating.com

Work: 425-423-7932

Shop: 425-423-7932

Customer P/O: G67

Open Date: 03/23/2023

Completion Date: 03/31/2023

Add User: matthew.austin

Salesperson: ataylor

CUM10	3689465CUM	PULLEY-IDLER	EA	1.0	\$110.94	\$110.94
CUM10	3690067CUM	TENSIONER-BELT	EA	1.0	\$285.91	\$285.91
FUL10	4305294	GASKET-SHIFT LEVER HOUSIN	EA	1.0	\$12.37	\$12.37
CUM10	4988280CUM	GASKET-PUMP HYDRAULIC	EA	1.0	\$3.62	\$3.62
CUM10	5289964CUM	TUBE-FORMED MULTIPLE	EA	1.0	\$129.35	\$129.35
CUM10	5294271CUM	CLAMP-BAND	EA	1.0	\$67.71	\$67.71
PTBPR	90-0013	CLAMP-V BAND 5"	EA	2.0	\$11.50	\$23.00
PACPR	A22-1016-001	PLATE-MOUNTING FRONT ENGI	EA	1.0	\$13.25	\$13.25
PACPR	A22-1016-002	PLATE-MOUNTING FRONT ENGI	EA	1.0	\$13.02	\$13.02
MISC	CLEAN	DPF/DOC CLEAN	EA	1.0	\$264.55	\$264.55
DYC10	D84-1000-6061620	BELT-POLY 6 RIBS X 1620 E	EA	1.0	\$52.75	\$52.75
TRP	D84-1000-6122180	BELT-POLY 12 RIBS X 2180	EA	1.0	\$100.99	\$100.99
CUM10	DR7080RXCUM	ENGINE-ISX 15 13 B 600@1900 XPI	EA	1.0	\$46,843.25	\$46,843.25
CUM10	DR7080RXCUM-C	ENGINE-ISX 15 13 B 600@1900 XPI-Core	EA	1.0	\$9,018.75	\$9,018.75
TRPCT	EC3501	COOLANT-TRP ELC 50/50 JUG	JG	15.0	\$11.06	\$165.90
PTBVN	F16-6009031B413SB0	CLAMP-HOSE T BOLT	EA	1.0	\$13.38	\$13.38
PTBVN	HE8716	HOSE-HUMP DBL 4"X6" SILTU	EA	1.0	\$33.26	\$33.26
MMF10	HWC04428	BOLT-HEX M20-2.50X120 CL1	EA	2.0	\$17.17	\$34.34
MMF10	HWC05722	WASHER-ROUND M20X37X4 HDN	EA	4.0	\$2.29	\$9.16
PTBPR	K169-163-20CA	NUT-HEX SL NYL M20-2.50X22.15T CAD	EA	2.0	\$16.40	\$32.80
PACPR	K37-1029	FILTER-ELEMENT FUEL 10	EA	1.0	\$50.47	\$50.47
PACPR	M84-6044-005	STRAP ASSY-DIESEL PARTICU	EA	1.0	\$49.12	\$49.12
PACPR	M84-6044-007	STRAP ASSY-SELECTIVE CATA	EA	1.0	\$50.66	\$50.66
PTBVN	N5355001	BOTTLE - WASHER ASSY	EA	1.0	\$244.85	\$244.85
DON10	P625128	AIR FILTER RADIALSEAL	EA	2.0	\$86.27	\$172.54
TRPWS	TWS0013	FLUID-WINDSHIELD WASH -20	EA	1.0	\$3.09	\$3.09
PACPR	U30027	MOUNT-ENGINE REAR	EA	2.0	\$498.38	\$996.76
PTBVN	W34-1095-070	BOLT-FLANGE M16X2X70 10.9	EA	8.0	\$3.39	\$27.12

Detail Tax Info:

Sales Tax

\$5,709.53

Total: \$5,709.53

Total Parts: \$50,109.46
Total Core Charge: \$9,018.75
Total Core Ret: \$(9,018.75)
Total Labor: \$5,393.20
Total Environmental Fee: \$200.00

** See Last Page for Invoice Total **



DOBBS PETERBILT

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383



Invoice: **021R3087**
Date / Hour: 3/31/2023 6:08:51PM
Repair Order: 3087
Customer: 801156
Branch: Seat
Total Invoice: \$61,412.19
Open Account - Charge
Page 3 of 5

Bill To: Grady Excavating Inc - NORTH BEND - SHIP TO
PO Box 467
Mukilteo, WA 98275

Ship To: Grady Excavating Inc - NORTH BEND - SHIP
TO
46832 SE Middle Fork Rd
North Bend, WA 98045
Office Phone: 425-423-7932
Email: ap@gradyexcavating.com

Work: 425-423-7932

Shop: 425-423-7932

Customer P/O: G67

Open Date: 03/23/2023

Completion Date: 03/31/2023

Add User: matthew.austin

Salesperson: ataylor

Invoice Subtotal:	\$55,702.66
Total Tax:	\$5,709.53
Total Invoice:	\$61,412.19

Payment Method

Terms

Due Date

Open Account - Charge

Net 30 Days

4/30/2023

Remit To:

Dobbs Peterbilt - Seattle, WA
P.O. Box 35144 #1022
Seattle, WA 98124-5144

**DOBBS PETERBILT**

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383



Invoice: **021R3087**
Date / Hour: 3/31/2023 6:08:51PM
Repair Order: 3087
Customer: 801156
Branch: Seat
Total Invoice: \$61,412.19
Open Account - Charge

Page 4 of 5

Bill To: Grady Excavating Inc - NORTH BEND - SHIP TO
PO Box 467
Mukilteo, WA 98275

Ship To: Grady Excavating Inc - NORTH BEND - SHIP TO
46832 SE Middle Fork Rd
North Bend, WA 98045
Office Phone: 425-423-7932
Email: ap@gradyexcavating.com

Work: 425-423-7932

Shop: 425-423-7932

Customer P/O: G67

Open Date: 03/23/2023

Completion Date: 03/31/2023

Add User: matthew.austin

Salesperson: ataylor

LIMITED WARRANTY

THIS LIMITED WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS AND YOU MAY ALSO HAVE OTHER RIGHTS, WHICH VARY FROM STATE TO STATE.

WHO IS COVERED: The Dealership issuing this invoice (the "Dealership") offers this limited warranty to only you, the customer listed on this repair order/invoice. It does not extend to any subsequent owner. It cannot be transferred to any other person.

WHAT IS COVERED: The Dealership warrants the workmanship of our labor performed in conjunction with repairs for 90 days (the "Warranty Period"). Said Warranty Period commence on the date ("Invoice Date") that the repairs are completed. The following items will void this Limited Warranty; if the failure was caused by misuse, abuse, lack of or improper maintenance, accident, alterations, overheating, and/or lack of lubrication or coolant. For any failure caused by the Dealership's workmanship (labor) covered by this Limited Warranty, the Dealership will either repair or replace such failure, at its option, in the Dealership facility.

YOUR RESPONSIBILITIES: All items must be returned to our shop with transportation charges prepaid for our inspection and determination within 60 days from the date of the sales invoice covering said items. The customer is required to return the vehicle to the Dealership or authorized repair facility at the customer's expense. You must retain copies of your Repair Orders/Invoices, and, upon request, be able to present them to us when requesting coverage under this Limited Warranty. Upon return of the vehicle to you, you must pay for any parts, labor, products, expenses, freight and taxes that the Dealership is not obligated to provide or pay for under this Limited Warranty.

WHAT IS NOT COVERED: Repairs which are still covered by a manufacturer's warranty or recall or other third party warranty/service contract. The Dealership's Limited Warranty shall be secondary to any such warranty or service contract that provides coverage for repair claims covered hereunder. Damage caused by you for failure to use manufacturer approved fluids, or the lack thereof, including but not limited to oil, antifreeze, and DEF. Any failure or damage resulting from your failure to perform maintenance in accordance with the manufacturer's recommendations; your failure to maintain appropriate fluid levels (e.g. oil, water, DEF, transmission fluid); your continued operation of the vehicle after warning light notification; modification or operation of the vehicle in a manner that is not in conformance with the manufacturer's specifications or intended use; an accident or collision; your use of improper or contaminated fluids including fuel, and/or misuse, abuse, tampering, negligence, theft, vandalism, or acts of nature or God. Parts installed and/or repairs performed on vehicles used primarily for off road competition or engaging in a contest of speed or endurance of any type.

INSPECTION RIGHTS: The Dealership reserves the right to inspect the vehicle and any parts removed from or installed in the vehicle both prior to and after a repair is performed pursuant to a claim made under this Limited Warranty

EXCLUSIVE REMEDY: The performance of labor to effect repairs is the exclusive remedy available under this written Limited Warranty. THE PERFORMANCE OF LABOR TO EFFECT REPAIRS IS YOUR SOLE AND EXCLUSIVE REMEDY AND OUR ENTIRE LIABILITY FOR ANY BREACH OF THIS LIMITED WARRANTY. OUR LIABILITY SHALL UNDER NO CIRCUMSTANCES EXCEED THE ACTUAL AMOUNT PAID BY YOU FOR THE LABOR WE SUPPLIED, NOR SHALL WE UNDER ANY CIRCUMSTANCES BE LIABLE FOR ANY CONSEQUENTIAL, INCIDENTAL, SPECIAL OR PUNITIVE DAMAGES OR LOSSES, WHETHER DIRECT OR INDIRECT.

SOME STATES DO NOT ALLOW THE EXCLUSION OR LIMITATION OF INCIDENTAL OR CONSEQUENTIAL DAMAGES, SO THE ABOVE LIMITATION OR EXCLUSION MAY NOT APPLY TO YOU.

IMPLIED WARRANTY DISCLAIMER: The only warranty on parts and products sold in conjunction with repairs performed by the manufacturer or supplier of said parts or products. Except for the limited warranty on the workmanship of our labor, the Dealership expressly disclaims all implied warranties including any implied warranties of the merchantability and fitness for a particular purpose for any period beyond the Warranty Period. WE LIMIT THE DURATION AND REMEDIES OF ALL IMPLIED WARRANTIES, INCLUDING WITHOUT LIMITATION THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE TO THE DURATION OF WARRANTY PERIOD.

SOME STATES DO NOT ALLOW LIMITATIONS ON HOW LONG AN IMPLIED WARRANTY LASTS, SO THE ABOVE LIMITATION MAY NOT APPLY TO YOU.

NO ASSUMPTION OF LIABILITY: The Dealership does not authorize any other person to assume for it any liability in connection with the sales of any parts or products of this repair.

THE FOLLOWING APPLIES TO ALL OF OUR CUSTOMERS

STORAGE CHARGES: I understand and agree that a daily storage charge may be assessed if I fail to pick up the vehicle after being notified that the repairs have been completed. Storage charges will accrue at the rate of \$45.00 per day beginning 15 days after the repair has been completed. Storage fees will also accrue at the same charge if I fail to authorize repairs to be performed within three days after the date of communication from the Dealership.

DISASSEMBLY/REASSEMBLY CHARGES: If you authorize disassembly of the vehicle or a vehicle component to provide an estimate or commencement of repairs and do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work and you agree to pay the same. Such charges will be directly related to the actual amount of labor and parts involved in the inspection, repair or service. I have been advised that disassembly of the vehicle may prevent restoration of the vehicle to its prior condition.

DELAYS AND LEGAL LIABILITY: I understand and agree that the Dealership is not responsible for any delays caused by unavailability of parts or shipping by the supplier or transporter or any losses or downtime relating to such delays, nor is it responsible for loss or damage to the vehicle or articles left in the vehicle in the event of fire, theft, or any other cause beyond its control. The Dealership will not be responsible for personal property. You and your representative agree to hold



DOBBS PETERBILT

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383



Invoice: **021R3087**
Date / Hour: 3/31/2023 6:08:51PM
Repair Order: 3087
Customer: 801156
Branch: Seat
Total Invoice: \$61,412.19
Open Account - Charge

Page 5 of 5

Bill To: Grady Excavating Inc - NORTH BEND - SHIP TO
PO Box 467
Mukilteo, WA 98275

Ship To: Grady Excavating Inc - NORTH BEND - SHIP
TO
46832 SE Middle Fork Rd
North Bend, WA 98045
Office Phone: 425-423-7932
Email: ap@gradyexcavating.com

Work: 425-423-7932

Shop: 425-423-7932

Customer P/O: G67

Open Date: 03/23/2023

Completion Date: 03/31/2023

Add User: matthew.austin

Salesperson: ataylor

the Dealership harmless and not liable for any missing or damaged property.

WARNING: Products being sold to you can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.

Customer Signature: _____ Date: _____