



# Vehicle History Detail



Fleet #	GR25
Registration	1494C0
Make	Caterpillar
Model	140M
VIN / Chassis #	CAT0140MTB9D03723

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		<b>body repairs</b> R-2715 Cleaned all rust up n repainted	Internal Workshop		\$405.00
24/02/2025	13,254 hrs	<b>Glass</b> R-2162 2X DOOR GLASS FITTED GLASS			\$3,628.39
24/02/2025	13,255 hrs	<b>CALLOUT</b> R-2164 Inspect grader for fault witch had been occurring over the past 12months intermittently. Machine would start and run but engine would nearly stall over 6 seconds constantly no matter the throttle position ect. Connected scan tool to inspect various faults and parameters. Reoccurring fault for the engine ecu; 268-2 Programmed parameter faults. Found certain engine sensors going abnormal every time engine nearly stalls and as the engine stalls an alert for engine over speed would flash up then go away. Check power supply for all ecus from alternator to breaker box and all connections in and out of the breaker box, slight corrosion. Inspect harness to ecu all ok visually. Remove connectors off engine ecu to find corrosion on certain pins. Clean as required and retest machine. Engine issue rectified running normal test drove around yard multiple times start and stop multiple times all ok. Recalibrate engine number into ecu and FTS value witch automatically cleared the 268 fault code. Replace in cab park brake switch with new one supplied.	Clark Equipment		\$1,271.05
06/12/2024		<b>Cutting Edges</b> R-2060	Internal Workshop		\$1,463.44
06/12/2024		<b>Cutting Edges</b> R-2062	Internal Workshop		\$790.91
06/12/2024		<b>Bucket Teeth</b> R-2055	Internal Workshop		\$319.00
26/11/2024		<b>Cutting Edges</b> R-2015			\$3,127.30
12/11/2024	12,784 hrs	<b>C - 1000hrs</b> S-874 CARRIED OUT SERVICE	Central Gulf Diesel		\$2,876.50
10/11/2024		<b>tyres</b> R-1978	Internal Workshop		\$1,514.80
23/10/2024		<b>UHF Radio</b> R-1941	Internal Workshop		\$651.20
22/10/2024		<b>Electrical</b> R-1643 supplied beacons			\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
22/10/2024		<b>Doors</b> R-1910	Internal Workshop		\$2,878.39
22/10/2024		<b>Cutting Edges</b> R-1903	Internal Workshop		\$1,715.18
22/10/2024		<b>Electrical</b> R-1896	Internal Workshop		\$1,699.85
22/10/2024		<b>REGO</b> R-1643 new plates ordered			\$0.00
22/10/2024		<b>Electrical</b> R-1643 REPLACED ARM REST ADJUSTERS ON SEAT REPLACED RIPPER SWITCH ASSY AND TEST OK. SUPPLIED SCARAFIER TIPS	Internal Workshop		\$5,862.86
20/10/2024		<b>Bridgestone</b> T-237	Bridgestone Australia LTD		\$3,852.16
05/09/2024		<b>Parts Only</b> R-1762 SUPPLIED SCARAFIER TIPS	Internal Workshop		\$1,171.72
19/08/2024	15,003 hrs	<b>New</b> T-224 replaced 4x drive tyres new replaced steer tyres s/hand repaired 1x spare	Central Gulf Diesel		\$3,093.20
19/08/2024	15,003 hrs	<b>New</b> T-226 REPLACED 2X STEER TYRES			\$2,973.61
30/07/2024		<b>Air Conditioner</b> R-1678 REPAIRED WIRE TO A/C COMPRESSOR CLEANED CONDENSOR AND ADJUSTED REFRIGERANT LEVEL TEST OPERATION OK.	Central Gulf Diesel		\$1,860.10
23/07/2024	12,360 hrs	<b>Electrical</b> R-1478 DIAGNOSE ERRATIC SHIFTING FROM DRIVE. CHECKED OEPRATION AND DIAGNOSE INTERMITTENT SHIFTING DUE TO FAULTY SHIFT SWITCH. REMOVED AND FABRICATED HYDRAULIC HOSE AND REPLACE.CHECK HYDRAULIC OIL AND TEST OK REPLACED DIRECTION SWITCH AND TEST OK. SUPPLIED AND FITTED SCARAFIER TIPS AND SHANKS	Internal Workshop		\$2,937.14
05/07/2024		<b>Blades, tyres</b> R-1606			\$7,668.36
06/06/2024	12,090 hrs	<b>Steering</b> R-1492 SUBLET CRACK REPAIR TO STEER AXLE. CARRIED OUT TEMPORARY REPAIR TO AXLE AND REFIT COMPONENTS.	XIT ENGINEERING		\$6,520.00
22/05/2024		<b>Battery</b> R-1337 Isolator hard to turn on. Isolator needs to be replaced. ORDER NEW ISOLATOR. isolator has been repaired and tested ok.	Internal Workshop		\$321.65
22/05/2024	12,067 hrs	<b>Engine</b> R-1351 Inspected issue and found that the exhaust has a hole in it and needs replacement so i have fitted gr 38's exhaust onto grader 25 so grader 25 can still be operated until new exhaust and clamps arrive. Waiting for new parts to arrive to complete the job. new components fitted	Internal Workshop		\$1,341.37

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
09/05/2024	12,067 hrs	<b>C - 1000hrs</b> S-378 Carried out B service replaced engine oil and filters. Replaced fuel filters. Replaced air filter inner and outer. Checked lights and electrical. Checked hydraulic systems. Checked brakes and suspension. Checked wheels and tyres. Checked safety systems. removed and replaced engine wiring harness and mounting cables as required. Test operation ok. Removed and replaced exhaust components as required. adjusted blade and replaced blade slides.	Internal Workshop		\$1,097.88
08/05/2024		<b>Doors</b> R-1443 replaced broken door glass and seal. Replaced latches. Cleaned glass from cab. adjusted door and test operation ok.	Internal Workshop		\$448.78
26/04/2024	12,058 hrs	<b>Injector</b> R-1432 DIAGNOSED ENGINE MISSFIRE.REMOVED AND REPLACED INJECTOR AND SEALS. CONNECT SCAN TOOL AND CLEAR CODES.TEST RUN AND INSPECT OK.	Internal Workshop		\$4,383.73
26/04/2024		<b>Cutting Edges</b> R-1435 REMOVED AND REPLACED CUTTING BLADES AND AJUSTED AS REQUIRED. REMOVED AND REPLACED RIPPER SHANKS AND TEETH.	Internal Workshop		\$22,812.20
16/04/2024	11,952 hrs	<b>seat</b> R-1327 Inspected problem and found that the seat gas strut had failed and seat has gone further past its operating range and broken a wire that goes to seat up switch. Repaired wiring and fixed fault with seat not going up and down Gass strut will need to be replaced. Will replace strut when parts come to avoid damaging the seat. Seat strut is ordered and will need replacing and wire has been fixed on inspection. Seat strut has been fitted and tested.	Internal Workshop		\$543.67
27/01/2023	10,846 hrs	<b>A - 250hrs</b> S-432			\$937.83
06/11/2022	10,292 hrs	<b>Blades, Brakes , Gauges, Windscreen</b> R-649 all items repaired except the fuel gauge not working - this needs to be investigated further	Fabbro Diesel Services		\$0.00
12/10/2022		<b>Air , Blades, Lights</b> R-497 1- part currently unavailable 2-coolant supplied 3- replaced 4- monitor further	Fabbro Diesel Services		\$104.50
06/09/2022	10,322 hrs	<b>A - 250hrs</b> S-227 diagnosed electrical fault rewired main harness plug into cab note needs new plug and harness	BDS Mechanical		\$1,672.00
28/07/2022	8,658 hrs	<b>Blades</b> R-496 GR25, 8658hrs, 23/07/22 (Completed Works) - Replace top LHS blade slides - Fit new blade slide adjuster locknut repair completed as per email with S-166	Fabbro Diesel Services		\$0.00
28/07/2022	8,658 hrs	<b>A - 250hrs</b> S-166 GR25, 8658hrs, 23/07/22 -250hr service completed - 2x 328-3655 filter changed in addition to service - All air filters changed (cab/engine) R-497 completed	Fabbro Diesel Services		\$836.00
24/07/2022	10,104 hrs	<b>Electrical, Joystick</b> R-466 - Fit bulb to rotating beacon - Knock wheel lean pivot pin back in and retighten remove and replace LH joystick steering calibrate, run machine on job and get feedback from operator, fault no longer present replace bulb, bulbs keep blowing, need to replace with magnetic led beacon	Fabbro Diesel Services		\$261.25

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
28/06/2022		<b>Parts Only</b> R-306 Fitter: Robbie Brammer Site: Silkwood Dates: 20/06/2022 - 26/06/2022 Labour - Date: 20/06/2022 Hours: 10.5 Labour - Date: 21/06/2022 Hours: 9.5 Labour - Date: 22/06/2022 Hours: 12.5 Labour - Date: 23/06/2022 Hours: 13.5 Labour - Date: 24/06/2022 Hours: 11.5 Labour - Date: 25/06/2022 Hours: 12.0 Labour - Date: 26/06/2022 Hours: 9	Fabbro Diesel Services		\$1,254.00
23/06/2022		<b>Parts Only</b> R-260 June parts	Hastings Deering CAT		\$422.07
13/06/2022		<b>UHF Radio</b> R-48 replace UHF replace stepping hoses replaced cutting edges and ripper boots	BDS Mechanical Townsville		\$470.25
24/05/2022	10,000 hrs	<b>Bushes, Engine</b> R-245 prior to travel remove 2x injectors from GR38 as no injectors left in country to purchase arrive at Ethridge job site and begin troubleshooting misfire connect laptop and check faults, found 3 x inactive faults for low current to injectors 2,5,6, suspected harness issue remove rocker cover and inspect harness, found rubbing on #4 valve spring and shorting out, due to unsecured harness harness will require securing correctly at a later date when parts arrive as anchor points broken re-assemble and run, all ok no misfire or faults replace articulation cylinder bushes and pins due to excessive play. use manufactured bronze bushes instead of fiber composite bush. extra work leaking hose at front hydraulic valve replace o'ring, tested and no leak	Fabbro Diesel Services		\$0.00
20/05/2022		<b>Registration</b> O-75 New plates I494C0	TMR		\$32.17
17/05/2022		<b>Parts Only</b> R-215 Labour Hire Fitter: Robbie Brammer Site: Silkwood Dates: 09/05/22 - 15/05/22 Labour - Date: 09/05/22 Hours: 11.5 Labour - Date: 10/05/22 Hours: 7.5 Labour - Date: 11/05/22 Hours: 11.5 Labour - Date: 12/05/22 Hours: 12 Labour - Date: 13/05/22 Hours: 12.5 Labour - Date: 14/05/22 Hours: 9.5 Labour - Date: 15/05/22 Hours: 6.5	Fabbro Diesel Services		\$5,904.25
17/05/2022		<b>Parts Only</b> R-326 Fitter: Robbie Brammer Site: Silkwood Dates: 09/05/22 - 15/05/22 Labour - Date: 09/05/22 Hours: 11.5 Labour - Date: 10/05/22 Hours: 7.5 Labour - Date: 11/05/22 Hours: 11.5 Labour - Date: 12/05/22 Hours: 12 Labour - Date: 13/05/22 Hours: 12.5 Labour - Date: 14/05/22 Hours: 9.5 Labour - Date: 15/05/22 Hours: 6.5	Fabbro Diesel Services		\$5,904.25
10/05/2022		<b>Parts Only</b> R-209 Labour Hire Fitter: Robbie Brammer Site: Silkwood Dates: 02/05/22 - 06/05/22 Labour - Date: 03/05/22 Hours: 8.5 Labour - Date: 04/05/22 Hours: 11.5 Labour - Date: 05/05/22 Hours: 11.5 Labour - Date: 06/05/22 Hours: 11.5	Fabbro Diesel Services		\$4,493.50
06/05/2022	9,877 hrs	<b>D - 2000hrs</b> S-33	Fabbros Diesel Services		\$0.00
30/04/2022		<b>Parts Only</b> R-345 parts invoices	Hastings Deering CAT		\$5,603.00
28/04/2022		<b>Parts Only</b> R-231 Labour Hire Fitter: Robbie Brammer Site: Townsville Dates: 19/04/22 - 24/04/22 Labour - Date: 19/04/22 Hours: 11.5 Labour - Date: 20/04/22 Hours: 11.5 Labour - Date: 21/04/22 Hours: 11.5 Labour - Date: 22/04/22 Hours: 11.5 Labour - Date: 23/04/22 Hours: 11.5 Labour - Date: 24/04/22 Hours: 3	Fabbro Diesel Services		\$7,680.75

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
20/04/2022		<b>Parts Only R-208</b> Labour Hire Fitter: Robbie Brammer Site: Townsville Dates: 11/04/22 - 15/04/22 Labour - Date: 11/04/22 Hours: 10.5 Labour - Date: 12/04/22 Hours: 9 Labour - Date: 13/04/22 Hours: 10.5 Labour - Date: 14/04/22 Hours: 10.5 Labour - Date: 15/04/22 Hours: 3	Fabbro Diesel Services		\$4,545.75
20/04/2022		<b>Parts Only R-324</b> Fitter: Robbie Brammer Site: Townsville Dates: 11/04/22 - 15/04/22 Labour - Date: 11/04/22 Hours: 10.5 Labour - Date: 12/04/22 Hours: 9 Labour - Date: 13/04/22 Hours: 10.5 Labour - Date: 14/04/22 Hours: 10.5 Labour - Date: 15/04/22 Hours: 3	Fabbro Diesel Services		\$4,545.75
11/04/2022		<b>Parts Only R-323</b> Site: Townsville Dates: 04/04/22 - 10/04/22 Labour - Date: 04/04/22 Hours: 11.5 Labour - Date: 05/04/22 Hours: 11.5 Labour - Date: 06/04/22 Hours: 11.5 Labour - Date: 07/04/22 Hours: 11.5 Labour - Date: 08/04/22 Hours: 11.5 Labour - Date: 09/04/22 Hours: 11.5 Labour - Date: 10/04/22 Hours: 11.5	Fabbro Diesel Services		\$7,210.50
11/04/2022		<b>Parts Only R-207</b> Labour Hire Fitter: Robbie Brammer Site: Townsville Dates: 04/04/22 - 10/04/22 Labour - Date: 05/04/22 Hours: 11.5 Labour - Date: 06/04/22 Hours: 11.5 Labour - Date: 07/04/22 Hours: 11.5 Labour - Date: 08/04/22 Hours: 11.5 Labour - Date: 09/04/22 Hours: 11.5 Labour - Date: 10/04/22 Hours: 11.5	Fabbro Diesel Services		\$7,210.50
06/04/2022		<b>Parts Only R-205</b> Labour Hire Fitter: Robbie Brammer Site: Silkwood Dates: 28/3/22 - 3/4/22 Labour - Date: 02/4/22 Hours: 9.5 Labour - Date: 03/4/22 Hours: 9.5	Fabbro Diesel Services		\$1,985.50
04/04/2022		<b>Brakes , Cab, Chassis, Circle drive motor, Electrical, G.E.T, Glass, hydraulic hoses , Hydraulics, Steering R-27</b>			\$1,095.88
03/04/2022		<b>Parts Only R-321</b> Fitter: Robbie Brammer Site: Silkwood Dates: 28/3/22 - 3/4/22 Labour - Date: 28/3/22 Hours: 10.5 Labour - Date: 29/3/22 Hours: 9.5 Labour - Date: 30/3/22 Hours: 9.5 Labour - Date: 31/3/22 Hours: 9.5 Labour - Date: 01/4/22 Hours: 9.5 Labour - Date: 02/4/22 Hours: 9.5 Labour - Date: 03/4/22 Hours: 9.5	Fabbro Diesel Services		\$1,985.50
17/03/2022		<b>Registration O-46</b> Due date 17.03.2022 Paid GCA CCP 17.03.2022	TMR	2FE26B	\$244.67
25/01/2022		<b>Licence Fee O-97</b> ET licence fee	Hastings Deering CAT	2014411605	\$299.19
12/09/2021	9,694 hrs	<b>B - 500hrs S-75</b> LH mirror missing, RH door glass cracked all over, UHF transmits but doesn't receive, wiper blades u/s all, LH auto manual switch active fault, LH top door wiper arm u/s, front indicators missing, front lights missing, all 4 blade lights not working, cab lights to LHS both not working, joystick handrest needs padding, switch missing from RH wipers rear, RH blade lift has movement, blade slide form worm both sides top and bottom, side shift cycl has moderate movement, cutting eges missing bolts, moleboard worn on bottom corners both sides, A fram bolt needs adjusting has play, circle drive motor leaking, blade lift studs have movement, front end, pins have excessive play, steer cyl mount pins have play, front axle pivot has excessive play, tie rod bent, RH steer cyl stud loose, tranny oil low, scarifier teeth worn - big ones, outside fire extinguisher missing, straighten cab protection rail, tandem swivel leaking L&R, hose damaged barrel end, hyd oil low, circle drive oil needs top up	Fabbros Diesel Services		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
------	---------	-----------------------	----------	---------	------

59 Records

Total: \$153,928.50