

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Apr 29, 2024	Apr 29, 2024		Apr 30, 2024 4:40 AM	Apr 30, 2024 4:40 AM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
2	✓ Boards broke, repalce	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	2x10x10 Kropp Shop 2.0 \$0.00 \$0.00			
3	✓ ABS codes	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	K181625 - 6' 90 ABS WSS Kropp Shop 2.0 \$0.00 \$0.00			
4	✓ Tie up brake lines rubbing on crossmember	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	P clip Kropp Shop 1.0 \$0.00 \$0.00			
5	✓ Middle LH hub stud NFG	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	Wheel stud Kropp Shop 1.0 \$0.00 \$0.00			
	Wheel nut Kropp Shop 1.0 \$0.00 \$0.00			
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Jul 22, 2024	Jul 22, 2024		Jul 22, 2024 5:17 AM	Jul 22, 2024 5:17 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Air leak on exhaust of abs valve	\$0.00	\$0.00	\$0.00
---	------------------------------------	--------	--------	--------

Notes

Rear RH brake pot bypassing

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Checked oil level in lubricator and filled with wd40	\$0.00	\$0.00	\$0.00
---	--	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Oct 25, 2024	Oct 25, 2024		Oct 25, 2024 9:51 AM	Apr 11, 2025 6:00 AM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ #3 RH inside tire NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ #3 RH s cam bushing wore	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	CC RH S cam	Kropp Shop		1.0	\$0.00	\$0.00
	6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
	cc s cam bushing	Kropp Shop		1.0	\$0.00	\$0.00
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ #3 shoes RH nfg	\$0.00	\$0.00	\$0.00		
5	✓ #1 both sides cam rotation 120	\$0.00	\$0.00	\$0.00		
	Notes					
	LH missing roller in shoe					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Brake Drum	Kropp Shop		2.0	\$0.00	\$0.00
	Q plus hardware kit	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ LH front top board needs replaced	\$0.00	\$0.00	\$0.00		
7	✓ fill lubricator	\$0.00	\$0.00	\$0.00		

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

8	✓ cut down front tridem mudflaps	\$0.00	\$0.00	\$0.00
9	✓ cracks on front of trailer to weld	\$0.00	\$0.00	\$0.00
10	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2025	Jul 23, 2025		Jul 24, 2025 5:51 AM	Jul 24, 2025 5:51 AM

Line	Task	Parts	Labor	Total
1	✓ Rear rh supply line leaking	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial Tag Closed Meters

2C9CSS3W5HM183259

Type	Created	Scheduled	Due	Started	Closed
	Jul 29, 2025	Jul 29, 2025		Jul 30, 2025 8:17 AM	Jul 30, 2025 8:17 AM

Line	Task	Parts	Labor	Total
1	✓ LH front inside tire nfg	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	245 Trailer - Trailer Tire Kropp Shop 1.0 \$0.00 \$0.00			
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Aug 5, 2025	Aug 5, 2025		Aug 5, 2025 6:43 PM	Aug 5, 2025 6:43 PM

Line	Task	Parts	Labor	Total		
1	✓ Front axle RH brake pot changed	\$157.00	\$0.00	\$157.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$157.00	\$157.00
2	✓ Rear axle LH brake pot changed	\$157.00	\$0.00	\$157.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$157.00	\$157.00
3	✓ change hopper board	\$0.00	\$0.00	\$0.00		
		Part Cost				\$314.00
		Labor				\$0.00
		Subtotal				\$314.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$314.00

Notes

Notes	User	Time
Diagnosed and repairs completed by Dave H and Steve A	Trent Court	Aug 5, 2025 4:58 AM

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Scheduled	Due	Started	Closed
	Oct 2, 2025		Oct 2, 2025 1:37 PM	Oct 2, 2025 1:37 PM

Line	Task	Parts	Labor	Total
1	✓ Clam slow to close	\$0.00	\$0.00	\$0.00

Notes

Add WD-40 to lubricator and rebuild air valve

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Oct 13, 2025	Oct 13, 2025		Oct 13, 2025 10:12 AM	Oct 13, 2025 10:12 AM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ LH middle outside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ check hub levels	\$0.00	\$0.00	\$0.00		
4	✓ check brake stroke	\$0.00	\$0.00	\$0.00		
5	✓ check air leaks	\$0.00	\$0.00	\$0.00		
6	✓ fill lubricator	\$0.00	\$0.00	\$0.00		
7	✓ check lights	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	May 1, 2026	May 1, 2026		May 5, 2026 3:57 PM	May 7, 2026 9:56 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ Front axle brakes	\$0.00	\$0.00	\$0.00
4	✓ Missing adjuster bar on back right slack	\$0.00	\$0.00	\$0.00
5	✓ Back axle scam bushings	\$0.00	\$0.00	\$0.00
6	✓ Middle axle s cam bushings	\$0.00	\$0.00	\$0.00
7	✓ Front right scam bushing	\$0.00	\$0.00	\$0.00
8	✓ Clam jaw needs wleded	\$0.00	\$0.00	\$0.00
9	✓ Slack adjuster bar bushings x5	\$0.00	\$0.00	\$0.00
10	✓ Tighten rods on air cylinder	\$0.00	\$0.00	\$0.00
11	✓ Back axle right hand shock	\$0.00	\$0.00	\$0.00
12	✓ Back axle left hand shock	\$0.00	\$0.00	\$0.00
13	✓ Low hubs	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

CD59 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9CSS3W5HM183259		

Type	Created	Scheduled	Due	Started	Closed
	Aug 2, 2026	Aug 2, 2026		Aug 2, 2026 8:16 AM	Aug 2, 2026 8:17 AM

Line	Task	Parts	Labor	Total
1	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Change L/H center axle brake shoes and drum			
2	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Change L/H wheel speed sensor			
3	✓ Change wheel	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	L/H middle inside			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00