

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Mar 9, 2024	Mar 9, 2024		Mar 9, 2024 7:27 PM	Mar 9, 2024 7:27 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

#7 LH inside wore out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	May 1, 2024	May 1, 2024		May 1, 2024 7:38 AM	May 2, 2024 3:48 PM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
2	✓ Install lift axle	\$0.00	\$0.00	\$0.00
3	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

RH front inside

RH rear inside

LH rear inside

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		3.0	\$0.00	\$0.00

4	✓ Flat tire	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

RH lift axle outside

LH rear outside

5	✓ Front bunk marker lights not working	\$0.00	\$0.00	\$0.00
6	✓ LH middle marker not working	\$0.00	\$0.00	\$0.00
7	✓ LH rear taillight bar marker grommet tire lights falling out	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2" grommet	Kropp Shop		1.0	\$0.00	\$0.00

8	✓ Licence plate light out of holder	\$0.00	\$0.00	\$0.00
9	✓ Air lines between rear axles hanging	\$0.00	\$0.00	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
HAB 8 96 FS - Rubber air brake service 96" long	Kropp Shop		2.0	\$0.00	\$0.00

10 ✓ LH middle brakes waking out of drum \$0.00 \$0.00 \$0.00

Notes

may need s cam bushings- inspect

Shim S Cam, re bush and replace rollers

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00

11 ✓ LH rear axle brakes need changed \$0.00 \$0.00 \$0.00

Notes

Shoes good needs hardware kit

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

12 ✓ RH rear tri functional replace \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-24691 - TRI-FUNCIONAL QUIK-ALIGN	Kropp Shop		1.0	\$0.00	\$0.00

13 ✓ LH front teflon washers falling out \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00

14 ✓ Change red gladhqdnd \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
red glad hand	Kropp Shop		1.0	\$0.00	\$0.00

15 ✓ junction box rear LH frame falling off \$0.00 \$0.00 \$0.00

16 ✓ Limit chains broke/ missing pins \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
------	-----------	------------	-----	-----------	------

Kropp Contracting
Shop

Work Order 1091
Trent Court

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

3/8" chain	Kropp Shop	1.0	\$0.00	\$0.00
3/8 bitch link	Kropp Shop	4.0	\$0.00	\$0.00
3/8 Clevis pin	Kropp Shop	2.0	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
Service	May 13, 2024	May 13, 2024		May 13, 2024 6:21 AM	May 13, 2024 6:21 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Change #7 LHS inside			
2	✓ Mudflap	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Change and reinstall mudflap hanger in front of lift axle			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Jul 12, 2024		Jul 12, 2024 7:26 AM	Jul 12, 2024 7:26 AM

Line	Task			Parts	Labor	Total
1	✓ Lift axle airbag blown			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8006 air bag	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jul 16, 2024	Jul 16, 2024		Jul 16, 2024 5:02 AM	Jul 16, 2024 5:02 AM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
Notes				
LH signal out				
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Kropp Contracting
Shop

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

Work Order 1191
Trent Court

CLOSED

KROPP CONTRACTING LTD. PRE-TRIP INSPECTION REPORT
Box 227 Shaw Lake, Alberta T8B 2A6
Phone (780) 894-6200

Unit # Truck 801 Location of Inspection July 13/24
Operator/Inspector Steven Pinner Time of Inspection 13:00
Owner/Phone Steven Pinner Date Time 18/12 @ 11:50

PERSONAL COMPLETE INSPECTION AND NOTE ANY DEFECTIVE ITEMS BELOW

TRUCK ☐ The following defects were found during the inspection:

TRAILER ☐ The following defects were found during the inspection:

SAFETY TRIP INSPECTION ☒ SAFETY TRIP INSPECTION OF VEHICLES IS SATISFACTORY
I have inspected the vehicle and found it to be in good condition and ready for use. I have also inspected the vehicle and found it to be in good condition and ready for use.

Inspector's Signature Steven Pinner Date July 13/24
Supervisor/Inspector's Signature _____ Date _____

☐ ABOUT CORRECTIVE REMEDIES

Left back camera angled out on scale

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jul 17, 2024	Jul 17, 2024		Jul 17, 2024 6:05 AM	Jul 17, 2024 6:05 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00
	Notes middle LH axle inside and outside NFG			
2	✓ air lines rubbing middle axle	\$0.00	\$0.00	\$0.00
	Notes tie up air lines			
3	✓ lift axle air lines rubbing	\$0.00	\$0.00	\$0.00
	Notes tie up air libnes			
4	✓ middle axle air tank loose	\$0.00	\$0.00	\$0.00
	Notes tighten bolts			
5	✓ brake pot stroke	\$0.00	\$0.00	\$0.00
	Notes Scale said stroke was out as REG stroke but LONG stroke pots are installed adjusted to 1.5"			
6	✓ wrappers no good	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)

Kropp Contracting
Shop

Work Order 1195

Cam Nadeau

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

CLOSED

Total Cost

\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Sep 16, 2024		Sep 16, 2024 10:44 AM	Sep 16, 2024 10:44 AM

Line	Task	Parts	Labor	Total
1	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	Middle LH ,rh shocks nfg			
2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	Rh rear saddle cracked middle LH cracked			
3	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	Rh rear trifunctional no good			
4	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	Front rh inside flat, front LH inside wore out			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Oct 8, 2024		Oct 8, 2024 7:12 AM	Oct 8, 2024 7:12 AM

Line	Task	Parts	Labor	Total		
1	✓ Middle LH inside tire no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Oct 12, 2024		Oct 12, 2024 10:31 AM	Oct 12, 2024 10:31 AM

Line	Task	Parts	Labor	Total		
1	✓ Lift axle tires both insides wore out	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Oct 18, 2024	Oct 18, 2024		Oct 20, 2024 11:08 AM	Oct 20, 2024 11:08 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	Notes			
	6 blink code			
2	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	RH front S cam tube spinning			
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	Back RH axle cracked, Lift axle LH beam cracked			
4	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	Loose shocks both sides middle axle			
5	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	Lift axle LH tires NFG, RH front outside NFG, LH front inside flat			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		4.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)

Kropp Contracting
Shop

Work Order 1339

Nate Vandenberghe

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

CLOSED

Total Cost

\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Nov 1, 2024		Nov 1, 2024 10:24 PM	Nov 1, 2024 10:24 PM

Line	Task	Parts	Labor	Total
1	✓ Broken stakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#3 rh stake			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Rh rear marker light out			
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Lift axle cracks #8 rh loose u bolt and cracked			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 16, 2024 9:37 AM	Nov 16, 2024 9:37 AM

Line	Task	Parts	Labor	Total		
1	✓ RH lift inside tire no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Front axle LH inside no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ bunk 5 stake pocket crack	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Dec 14, 2024		Dec 14, 2024 5:15 PM	Dec 14, 2024 5:15 PM

Line	Task	Parts	Labor	Total
1	✓ Suspension	\$0.00	\$0.00	\$0.00

Notes

middle lh shock nfg

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jan 17, 2025	Jan 17, 2025		Jan 18, 2025 9:40 PM	Jan 18, 2025 9:40 PM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	light on					
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh rear brake shoes nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Bunk bolts	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#5 LH, #4RH, #2RH loose					
4	✓ Hub Levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	top up					
5	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh front out side nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ weld crossmember cracks	\$0.00	\$0.00	\$0.00		
7	✓ RH middle beam u bolts loose	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

Work Order 1584
Nate Vandenberghe, Everett Twin

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

8	✓ RH beam saddle cracks	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 1, 2025 11:04 AM	Feb 1, 2025 11:04 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	RH WSS wire cut			
2	✓ Bunk bolts	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#2,3,5 loose bolts			
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	license plate light out			
4	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	RH rear crack			
5	✓ Suspension	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	rh middle shock mount bolt loose			
6	✓ Tires	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	RFO nfg LRO nfg			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 1629

Everett Twin

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Feb 12, 2025		Feb 12, 2025 8:43 PM	Feb 12, 2025 8:43 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	no stop light			
2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	back rh saddle			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Feb 27, 2025	Feb 27, 2025		Feb 28, 2025 3:25 PM	Feb 28, 2025 3:25 PM

Line	Task	Parts	Labor	Total
1	✓ #6 LH S-cam tube broken	\$0.00	\$0.00	\$0.00
2	✓ Dust cover	\$0.00	\$0.00	\$0.00

Notes

#5 RH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Replace shock		\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Feb 28, 2025	Feb 28, 2025		Feb 28, 2025 3:29 PM	Feb 28, 2025 3:29 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Adjust #8 RH			
2	✓ Bunk bolts	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#5 LH			
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00
4	✓ Suspension	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#8 RH inner U-bolt loose			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 6:54 PM	Mar 6, 2025 6:54 PM

Line	Task	Parts	Labor	Total		
1	✓ Front RH brake shoe roller MIA	\$0.00	\$0.00	\$0.00		
2	✓ Front RH Shoes NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ RH front S cam tube loose (needs tack welded)	\$0.00	\$0.00	\$0.00		

Notes

inner bushing wore, tube not round- replaced

	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ RH front Scam bushing walking cam out of place			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	cc s cam bushing	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ re shim RH slack adjuster			\$0.00	\$0.00	\$0.00
6	✓ RH front Wheel seal leaking			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
	75 W 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Mar 7, 2025		Mar 7, 2025 10:32 AM	Mar 7, 2025 10:32 AM

Line	Task	Parts	Labor	Total		
1	✓ Middle LH outside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Mar 10, 2025	Mar 10, 2025		Mar 10, 2025 11:33 AM	Mar 10, 2025 11:33 AM

Line	Task	Parts	Labor	Total		
1	✓ RFO, RMO wheels bent	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Apr 23, 2025	Apr 23, 2025		Apr 25, 2025 10:34 AM	Apr 29, 2025 6:45 PM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
3	✓ Install lift axle	\$0.00	\$0.00	\$0.00		
4	✓ LH front axle slack adjuster nfg	\$0.00	\$0.00	\$0.00		
5	✓ LH middle saddle crack	\$0.00	\$0.00	\$0.00		
6	✓ Lift axle cracks LH side	\$0.00	\$0.00	\$0.00		
7	✓ LH middle shock loose	\$0.00	\$0.00	\$0.00		
8	✓ LH s cam tube not on center of spider	\$0.00	\$0.00	\$0.00		
9	✓ RH rear inside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
10	✓ RH rear wheel seal	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ LH rear scam hard to turn	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ rear junction box hanging	\$0.00	\$0.00	\$0.00		
13	✓ LH mid clevis pin wore and loose	\$0.00	\$0.00	\$0.00		
14	✓ rh front inside tire nfg	\$0.00	\$0.00	\$0.00		

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

15	✓ middle axle both sides brake job			\$0.00	\$0.00	\$0.00
16	✓ lh rear axle brake job			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
17	✓ lh rear wheel bearings no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	10082225 - Con met trailer hub	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost						\$0.00
Labor						\$0.00
Subtotal						\$0.00
Tax 1 (0.0%)						\$0.00
Tax 2 (0.0%)						\$0.00
Credit						(\$0.00)
Total Cost						\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jul 18, 2025	Jul 18, 2025		Jul 18, 2025 10:05 AM	Jul 18, 2025 10:06 AM

Line	Task	Parts	Labor	Total
1	✓ Scam tube loose <u>Notes</u> RF&LM	\$0.00	\$0.00	\$0.00
2	✓ Hub levels <u>Notes</u> RR,RF, RHS lift axle	\$0.00	\$0.00	\$0.00
3	✓ Loose shock <u>Notes</u> RF lower shock bolt loose	\$0.00	\$0.00	\$0.00
4	✓ Replace tire <u>Notes</u> LFI nfg	\$0.00	\$0.00	\$0.00
5	✓ Dust cover <u>Notes</u> RF	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)

Kropp Contracting
Shop

Work Order 1983

Everett Twin

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

CLOSED

Total Cost

\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2025	Jul 23, 2025		Jul 24, 2025 5:25 AM	Jul 24, 2025 5:25 AM

Line	Task	Parts	Labor	Total		
1	✓ Front LH. Brake pot nfg cracked and leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jul 25, 2025	Jul 25, 2025		Jul 25, 2025 3:35 PM	Jul 25, 2025 3:35 PM

Line	Task	Parts	Labor	Total		
1	✓ Lift axle shocks nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	66502 - Lift axle shock	Kropp Shop		2.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
Tire	Sep 8, 2025		Sep 8, 2025 5:22 AM	Sep 8, 2025 5:22 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

2 used tires. Lift axle R/H

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Sep 8, 2025	Sep 8, 2025		Sep 8, 2025 2:49 PM	Sep 8, 2025 2:56 PM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00

Notes

LMO

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lift axle valve leaking	\$0.00	\$0.00	\$0.00
---	---------------------------	--------	--------	--------

Notes

Add lubrication to valve and actuator valve to move lube around.
Found valve no longer leaking

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Sep 25, 2025	Sep 25, 2025		Sep 25, 2025 2:39 PM	Sep 30, 2025 2:43 PM

Line	Task	Parts	Labor	Total
1	✓ Tire nfg	\$0.00	\$0.00	\$0.00

Notes

Lift axle LHS inner

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Nov 14, 2025		Nov 14, 2025 5:06 PM	Nov 14, 2025 5:06 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	scam tubes loose			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	hubs low			
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	lh rear signal out, rh front marker dim, rh rear outside marker out			
4	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Nov 27, 2025	Nov 27, 2025		Nov 27, 2025 4:46 PM	Nov 27, 2025 4:46 PM

Line	Task	Parts	Labor	Total
1	✓ Left midway marker replaced and pigtail	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Nov 30, 2025	Nov 30, 2025		Nov 30, 2025 12:04 PM	Nov 30, 2025 12:04 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00

Notes

rh rear wheel seal leaking

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Dec 9, 2025	Dec 9, 2025		Dec 9, 2025 9:57 PM	Dec 9, 2025 9:57 PM

Line	Task	Parts	Labor	Total
1	✓ New hub install on back right axel	\$486.00	\$0.00	\$486.00

Notes

Wheels run loose, broken tabs on hub

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Wheel nut	Kropp Shop		10.0	\$0.00	\$0.00
10082225 - Con met trailer hub	Kropp Shop		1.0	\$486.00	\$486.00
Part Cost					\$486.00
Labor					\$0.00
Subtotal					\$486.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$486.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2025	Dec 13, 2025		Dec 14, 2025 11:08 AM	Dec 14, 2025 11:08 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	tightened clevis nut on middle right hand axle			
2	✓ Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	adjust Lh rear brake			
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	#6LH #7RH			
4	✓ other	\$0.00	\$0.00	\$0.00

Notes

changed molly on trailer

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
1" molly	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jan 8, 2026	Jan 8, 2026		Jan 8, 2026 4:05 PM	Jan 8, 2026 4:05 PM

Line	Task			Parts	Labor	Total
1	✓ LH rear inside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ LH rear brake pot nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jan 14, 2026	Jan 14, 2026		Jan 14, 2026 5:39 PM	Jan 14, 2026 5:39 PM

Line	Task	Parts	Labor	Total
1	✓ Front LH rim bent	\$0.00	\$0.00	\$0.00
2	✓ License plate hanging	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2026	Feb 1, 2026		Feb 1, 2026 8:27 PM	Feb 1, 2026 8:27 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00

Notes

abs wire tie up

2	✓ Broken stakes	\$1,100.00	\$0.00	\$1,100.00
---	-----------------	------------	--------	------------

Notes

#6 RH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00

3	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

bunk lights out, license plate light out, tail light out

Part Cost	\$1,100.00
Labor	\$0.00
Subtotal	\$1,100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$1,100.00

T895 - 2019 Cross Country Cross Country Mfg.

Parent: N129 - 2026 KENWORTH T880

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Feb 10, 2026	Feb 10, 2026		Feb 10, 2026 9:14 PM	Feb 10, 2026 9:14 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
2	✓ Reflectors	\$0.00	\$0.00	\$0.00
Notes				
Rear right hand bunk light out				
3	✓ Air leak on middle axle tank	\$0.00	\$0.00	\$0.00
4	✓ Back left air bag line leaking	\$0.00	\$0.00	\$0.00
5	✓ #5 right hand scam broke	\$0.00	\$0.00	\$0.00
6	✓ Back axle brake out of adjustment	\$0.00	\$0.00	\$0.00
7	✓ Right rear bunk light out	\$0.00	\$0.00	\$0.00
8	✓ #5 LH bunk bolt #2 LH and rh bunk bolt	\$0.00	\$0.00	\$0.00
9	✓ Front left limit chain	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Scheduled	Due	Started	Closed
	Feb 10, 2026		Feb 10, 2026 9:13 PM	Feb 10, 2026 9:13 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00

Notes

Broken s cam #5lh Air leak behind middle axle air tank

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2026	Feb 25, 2026		Feb 25, 2026 5:25 PM	Feb 25, 2026 5:25 PM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	back rh slack pin mia					
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front lh brakes wore					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Bunk bolts	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#6 stake rh bolt mia					
4	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	FLI, RMI RMO nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		3.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T895 - 2019 Cross Country Cross Country Mfg.

CLOSED

Parent: N129 - 2026 KENWORTH T880

Serial	Tag	Closed Meters
2C9GSX3Z0KM183895	5PN360	

Type	Created	Scheduled	Due	Started	Closed
	Jun 15, 2026	Jun 15, 2026		Jun 16, 2026 9:54 AM	Jun 19, 2026 7:27 PM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ Wire up lift axle	\$0.00	\$0.00	\$0.00
4	✓ Rh front inside flat	\$0.00	\$0.00	\$0.00
5	✓ Front rh brake won't release	\$0.00	\$0.00	\$0.00
6	✓ middle rh brake not hooked up to slack adjuster	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00