

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Mar 28, 2024	Mar 28, 2024		Mar 28, 2024 7:04 AM	Mar 28, 2024 7:05 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ winch handle	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

#5,#6 handles broke off

2	✓ air leak	\$0.00	\$0.00	\$0.00
---	------------	--------	--------	--------

Notes

front axle between air bags

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3/8 Union	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ check tires	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

4	✓ check hub levels	\$0.00	\$0.00	\$0.00
---	--------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Apr 17, 2024	Apr 17, 2024		Apr 18, 2024 7:54 PM	Apr 22, 2024 1:10 PM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ #4 stake cracked RH	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ licence plate light out	\$0.00	\$0.00	\$0.00		
4	✓ LH tail light gromet tore	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Oval gromet	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ straighten out plate along LH frame rail	\$0.00	\$0.00	\$0.00		
6	✓ replace suspension pressure guage	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4" pressure guage	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle, back axle both sides					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		4.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		4.0	\$0.00	\$0.00
8	✓ saddle crack	\$0.00	\$0.00	\$0.00		

Notes

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Back axle both sides, tighten u bolts that are loose

9	✓ abs codes	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

LH wheel speed sensor code

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$0.00	\$0.00

10	✓ mud flap	\$0.00	\$0.00	\$0.00
----	------------	--------	--------	--------

Notes

Front of tri axle bracket loose

11	✓ install lift axle	\$0.00	\$0.00	\$0.00
----	---------------------	--------	--------	--------

12	✓ lift axle mud flap install	\$0.00	\$0.00	\$0.00
----	------------------------------	--------	--------	--------

13	✓ wheel seal	\$0.00	\$0.00	\$0.00
----	--------------	--------	--------	--------

Notes

lift axle RH

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
80w 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00
hub cap	Kropp Shop		1.0	\$0.00	\$0.00

14	✓ scam bushings	\$0.00	\$0.00	\$0.00
----	-----------------	--------	--------	--------

Notes

lift axle both sides

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
9" LH s cam	Kropp Shop		1.0	\$0.00	\$0.00
9" RH s cam	Kropp Shop		1.0	\$0.00	\$0.00
2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
6" slack adjuster CC	Kropp Shop		2.0	\$0.00	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

15	✓ lift axle dust cover RH			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Dust cover bolt on	Kropp Shop		1.0	\$0.00	\$0.00
16	✓ Middle axle RH scam bushings wore			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	CC RH S cam	Kropp Shop		1.0	\$0.00	\$0.00
	X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
	80 w 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	May 31, 2024	May 31, 2024		May 31, 2024 6:06 AM	May 31, 2024 6:06 AM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

#2 RH outside flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jun 27, 2024	Jun 27, 2024		Jun 29, 2024 8:58 AM	Jun 29, 2024 8:58 AM

Line	Task	Parts	Labor	Total
1	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	Front RH saddle			
	Front axle cracks			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	LH, RH cracks welded, crossmember between hangers cracked			
	Lift axle suspension hanger crack			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jul 15, 2024	Jul 15, 2024		Jul 18, 2024 11:00 AM	Jul 18, 2024 11:00 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

Front axle LH outside

Rear axle RH inside

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2024	Jul 23, 2024		Jul 31, 2024 6:53 PM	Jul 31, 2024 6:53 PM

Line	Task	Parts	Labor	Total
1	✓ Trailer hub	\$0.00	\$0.00	\$0.00

Notes

Front LH hub sheared studs off drum and wheels MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Con met trailer hub	Kropp Shop		1.0	\$0.00	\$0.00
80 w 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00
hub cap	Kropp Shop		1.0	\$0.00	\$0.00
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
Lug nuts	Kropp Shop		10.0	\$0.00	\$0.00
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Sep 17, 2024	Sep 17, 2024		Sep 17, 2024 3:43 AM	Sep 17, 2024 3:43 AM

Line	Task	Parts	Labor	Total		
1	✓ #2 RH stake broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cross country stake	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Oct 10, 2024	Oct 10, 2024		Oct 10, 2024 4:28 PM	Oct 10, 2024 4:28 PM

Line	Task	Parts	Labor	Total
1	✓ RH lift axle Clevis pin on slack gone	\$0.00	\$0.00	\$0.00
2	✓ LH front axle brake job	\$0.00	\$0.00	\$0.00

Notes

S cam and tube relapsed as well as new shoes shimmed slack adjuster

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
Cc LH S cam	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Oct 18, 2024	Oct 18, 2024		Oct 18, 2024 6:46 AM	Oct 18, 2024 6:46 AM

Line	Task	Parts	Labor	Total
1	✓ other	\$100.00	\$0.00	\$100.00

Notes

ABS wheel speed sensor tore RH middle axle, LH lift Tie rod end NFG

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
R230072 - Tie rod end	Kropp Shop		1.0	\$0.00	\$0.00
K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00
Part Cost					\$100.00
Labor					\$0.00
Subtotal					\$100.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$100.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Oct 25, 2024		Oct 25, 2024 6:36 PM	Oct 25, 2024 6:36 PM

Line	Task	Parts	Labor	Total		
1	✓ Middle RH inside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Nov 2, 2024		Nov 2, 2024 5:54 PM	Nov 2, 2024 5:54 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	Notes			
	6 blink code			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	LH marker light out			
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	Front RH cracked lift cracked			
4	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	Front RH nfg, middle RH nfg			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 17, 2024 10:50 AM	Nov 17, 2024 10:50 AM

Line	Task	Parts	Labor	Total
1	✓ Front left hand axle shock	\$0.00	\$0.00	\$0.00
2	✓ Limit chain clevis pin	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Nov 26, 2024	Nov 26, 2024		Nov 26, 2024 5:27 PM	Nov 26, 2024 5:27 PM

Line	Task	Parts	Labor	Total
1	✓ Trailer scales not working bags have no air	\$0.00	\$0.00	\$0.00

Notes

Found multiple air leaks to supply on leveling valve and replaced,
ride hight was way off and adjusted

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Dec 15, 2024	Dec 15, 2024		Dec 15, 2024 8:33 PM	Dec 15, 2024 8:33 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	middle LH marker out bunk front markers out			
2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	RH front saddle cracked			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jan 5, 2025	Jan 5, 2025		Jan 5, 2025 4:06 AM	Jan 5, 2025 4:06 AM

Line	Task			Parts	Labor	Total
1	✓ Front RH air bag blown			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jan 19, 2025	Jan 19, 2025		Jan 19, 2025 9:24 PM	Jan 19, 2025 9:24 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> tie up hoses hanging all over	\$0.00	\$0.00	\$0.00
2	✓ Brakes <u>Notes</u> front rh tube bent	\$0.00	\$0.00	\$0.00
3	✓ Hub Levels <u>Notes</u> front axle low hubs	\$0.00	\$0.00	\$0.00
4	✓ Lights - All <u>Notes</u> RH mid ship marker out	\$0.00	\$0.00	\$0.00
5	✓ Saddle cracks <u>Notes</u> front RH crack u bolts loose	\$0.00	\$0.00	\$0.00
6	✓ Suspension <u>Notes</u> lh front air bag bolt MIA	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 1596

Trent Court

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jan 28, 2025	Jan 28, 2025		Jan 29, 2025 5:39 PM	Jan 29, 2025 5:39 PM

Line	Task	Parts	Labor	Total
1	✓ Axle saddle cracks middle LH ,rear LH	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Feb 2, 2025	Feb 2, 2025		Feb 2, 2025 6:53 PM	Feb 2, 2025 6:53 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	6 blink code			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	RH front shock bolt loose			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2025	Feb 25, 2025		Feb 25, 2025 1:51 PM	Feb 25, 2025 1:51 PM

Line	Task			Parts	Labor	Total
1	✓ Front LH air bag blown			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 5, 2025 8:15 PM	Mar 5, 2025 8:15 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> light on	\$0.00	\$0.00	\$0.00
2	✓ Hub Levels <u>Notes</u> top up hubs	\$0.00	\$0.00	\$0.00
3	✓ Saddle cracks <u>Notes</u> Front RH and LH cracked	\$0.00	\$0.00	\$0.00
4	✓ Suspension <u>Notes</u> Front LH inside u bolt loose	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 6:07 PM	Mar 6, 2025 6:07 PM

Line	Task	Parts	Labor	Total		
1	✓ Front LH inside tire NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2025	Mar 11, 2025		Mar 16, 2025 10:12 AM	Mar 16, 2025 10:12 AM

Line	Task			Parts	Labor	Total
1	✓ RH front beam broke			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RH beam	Kropp Shop		1.0	\$0.00	\$0.00
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
	S-21140 - U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ RH front air bag no good			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2025	Mar 17, 2025		Mar 17, 2025 6:36 PM	Mar 17, 2025 6:36 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Front LH air bag	\$150.00	\$0.00	\$150.00
---	--------------------	----------	--------	----------

Notes

ran with no air and broke base

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00

2	✓ rear rh air bag	\$150.00	\$0.00	\$150.00
---	-------------------	----------	--------	----------

Notes

blown and replaced

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00

Part Cost	\$300.00
Labor	\$0.00
Subtotal	\$300.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$300.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Mar 19, 2025		Mar 19, 2025 1:51 PM	Mar 19, 2025 1:51 PM

Line	Task			Parts	Labor	Total
1	✓ LH rear beam cracked-replace			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
	S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
	S-21140 - U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00
	LH beam	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Mar 21, 2025	Mar 21, 2025		Mar 21, 2025 1:58 PM	Mar 21, 2025 1:58 PM

Line	Task			Parts	Labor	Total
1	✓ LH front air bag			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	May 28, 2025	May 28, 2025		May 28, 2025 4:37 PM	May 28, 2025 5:15 PM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ brake pot	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Loose S cam tube	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Weld LM and LF s cam tube on trailer					
4	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RF trailer brakes sticking, brakes came in smoking, grease self adjuster and retest brake operation. Readjusted brakes					
5	✓ saddle crack	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LR trailer saddle crack, buff and weld					
6	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jun 6, 2025	Jun 6, 2025		Jun 6, 2025 3:07 PM	Jun 6, 2025 3:15 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Loose S cam tube	\$0.00	\$0.00	\$0.00
---	--------------------	--------	--------	--------

Notes

LR scam tube loose, weld

2	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

LH lift axle brakes found roller in dust shield inspection cover.
Remove wheels and drum and inspect parts for replacement

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Marker lights inop	\$0.00	\$0.00	\$0.00
---	----------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00
6050 - Oval Red light	Kropp Shop		1.0	\$0.00	\$0.00

4	✓ saddle crack	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

Lift axle LHS, gouge, preheat and weld

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jun 10, 2025	Jun 10, 2025		Jun 10, 2025 11:57 AM	Jun 10, 2025 11:57 AM

Line	Task	Parts	Labor	Total
1	✓ Hub level	\$0.00	\$0.00	\$0.00
2	✓ lift axle cracks	\$0.00	\$0.00	\$0.00

Notes

Saddle crack done

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jun 17, 2025	Jun 17, 2025		Jun 17, 2025 7:32 PM	Jun 17, 2025 7:32 PM

Line	Task			Parts	Labor	Total
1	✓ Trailer Brakes			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jul 7, 2025	Jul 7, 2025		Jul 7, 2025 7:44 AM	Jul 7, 2025 7:44 AM

Line	Task			Parts	Labor	Total
1	✓ Lift axle inside rh nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Front axle LH outside nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Jul 25, 2025		Jul 25, 2025 1:25 PM	Jul 25, 2025 1:25 PM

Line	Task			Parts	Labor	Total
1	✓ Front middle and rear inside tires nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		3.0	\$0.00	\$0.00
2	✓ Front LH inside tire nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Aug 29, 2025		Aug 29, 2025 3:35 PM	Aug 29, 2025 3:35 PM

Line	Task	Parts	Labor	Total
1	✓ Adjuster shims MIA	\$0.00	\$0.00	\$0.00
	Notes			
	LM adjuster shims & circlip MIA, shim and install circlip			
2	✓ Replace tire	\$0.00	\$0.00	\$0.00
	Notes			
	LH inner lift axle tire NFG			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Oct 16, 2025		Oct 16, 2025 4:31 AM	Oct 16, 2025 4:31 AM

Line	Task			Parts	Labor	Total
1	✓ #6 LH stake broke off			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Oct 23, 2025	Oct 23, 2025		Oct 24, 2025 3:26 PM	Oct 24, 2025 3:26 PM

Line	Task	Parts	Labor	Total
1	✓ Replace 7 wire plugs	\$0.00	\$0.00	\$0.00
2	✓ Replace ripped off dolly leg	\$0.00	\$0.00	\$0.00
3	✓ Put aluminum cover on trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Oct 30, 2025	Oct 30, 2025		Oct 30, 2025 3:49 PM	Nov 3, 2025 7:12 PM

Line	Task	Parts	Labor	Total
1	✓ Replace shock	\$0.00	\$0.00	\$0.00
	Notes			
	S-20002 shock			
2	✓ Shim brake adjuster	\$0.00	\$0.00	\$0.00
	Notes			
	LM adjuster loose, add shim(s)			
3	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
4	✓ Air leak	\$0.00	\$0.00	\$0.00
	Notes			
	Air leak off of brake service valve on lift axle. Remove, clean and reinstall fittings with sealant. Test for leaks, no leaks			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Nov 14, 2025	Nov 14, 2025		Nov 14, 2025 2:05 PM	Nov 14, 2025 2:05 PM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	rear axle low			
2	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	middle rh inside nfg front rh outside nfg			
3	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	install lift axle mudflap			
4	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 8:25 AM	Dec 14, 2025 11:07 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> , middle lh adj and weld scam	\$0.00	\$0.00	\$0.00
2	✓ Brakes <u>Notes</u> Needed new drum and Clovis pin and scam tube welded back LH brake all destroyed	\$0.00	\$0.00	\$0.00
3	✓ other <u>Notes</u> front mudflap bracket loose	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Dec 23, 2025		Dec 23, 2025 2:33 AM	Dec 23, 2025 2:33 AM

Line	Task	Parts	Labor	Total
1	✓ LH front brake pot bracket weld back knt	\$0.00	\$0.00	\$0.00

Notes

Welded back on

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jan 16, 2026	Jan 16, 2026		Jan 19, 2026 2:37 PM	Feb 11, 2026 8:14 PM

Line	Task	Parts	Labor	Total		
1	✓ Broken brake pot front right	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Missing brake spring on middle left	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus hardware kit	Kropp Shop		1.0	\$0.00	\$0.00
	X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
	cc s cam bushing	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Saddle crack middle left	\$0.00	\$0.00	\$0.00		
4	✓ Missing cotter pin middle left	\$0.00	\$0.00	\$0.00		
	Notes					
	Middle left slack missing cotter pin					
5	✓ Missing dust cover middle right	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Missing license plate	\$0.00	\$0.00	\$0.00		
7	✓ Abs wire not plugged in	\$0.00	\$0.00	\$0.00		
8	✓ Replace horsecock	\$0.00	\$0.00	\$0.00		
9	✓ Rebuild back left brake and scam	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

	X039 - CC S cam tube	Kropp Shop	1.0	\$0.00	\$0.00
	6" slack adjuster CC	Kropp Shop	1.0	\$0.00	\$0.00
	cc s cam bushing	Kropp Shop	1.0	\$0.00	\$0.00
10	✓ Bunk bolts loose		\$0.00	\$0.00	\$0.00
11	✓ Flat tire middle right inside		\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ Limit chains front axle		\$0.00	\$0.00	\$0.00
13	✓ Tie up air lines		\$0.00	\$0.00	\$0.00
14	✓ Back right airbag missing top nut		\$0.00	\$0.00	\$0.00
15	✓ Scam tubes need welded on middle axle both side		\$0.00	\$0.00	\$0.00
16	✓ Middle left axle slack adjuster questionable		\$0.00	\$0.00	\$0.00
17	✓ Front right inside tire has a buldge		\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
18	✓ Abs wire rubbed through on middle RH side		\$0.00	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Feb 24, 2026		Feb 24, 2026 7:51 PM	Feb 24, 2026 7:51 PM

Line	Task			Parts	Labor	Total
1	✓ #2 1h STAKE BROKE			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Feb 26, 2026	Feb 26, 2026		Feb 26, 2026 4:38 AM	Feb 26, 2026 4:38 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00

Notes

Back left and both middle axles scam tubes need welded scam

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Scheduled	Due	Started	Closed
	Mar 11, 2026		Mar 11, 2026 6:35 PM	Mar 11, 2026 6:35 PM

Line	Task			Parts	Labor	Total
1	✓ RHRO flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z5KM183889	5PN359	

Type	Created	Scheduled	Due	Started	Closed
	Jun 2, 2026	Jun 2, 2026		Jun 2, 2026 4:49 PM	Jun 19, 2026 7:27 PM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ ABS codes	\$200.00	\$0.00	\$200.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K181625 - 6' 90 ABS WSS	Kropp Shop		2.0	\$100.00	\$200.00
4	✓ Lh rear brake pot	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Lh middle brake pot	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ lift axle cracks	\$0.00	\$0.00	\$0.00		
7	✓ Lift axle steer shock	\$0.00	\$0.00	\$0.00		
8	✓ Lift axle left side wheel bearing needs adjusted	\$0.00	\$0.00	\$0.00		
9	✓ Dolly leg support needs straightened	\$0.00	\$0.00	\$0.00		
10	✓ Lift axle bolts loose	\$0.00	\$0.00	\$0.00		
11	✓ Left hand inside lift axle tire separating	\$0.00	\$0.00	\$0.00		
12	✓ Bunk 4 loose	\$0.00	\$0.00	\$0.00		
13	✓ Cracked cross member behind bunk 4	\$0.00	\$0.00	\$0.00		

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

14	✓ Brakes on front left			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ Brakes on front right			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
16	✓ Loose bunk bolts on #3			\$0.00	\$0.00	\$0.00
17	✓ Middle axel right hand brake missing s cam roller			\$0.00	\$0.00	\$0.00

Notes

More diagnostic required bushing no good?

18	✓ Scam needs welded middle right axel			\$0.00	\$0.00	\$0.00
19	✓ Winch #6			\$0.00	\$0.00	\$0.00
20	✓ Wire up lift axel			\$0.00	\$0.00	\$0.00
21	✓ Trailer light signal			\$0.00	\$0.00	\$0.00
22	✓ No signal in tail bar left			\$0.00	\$0.00	\$0.00
23	✓ Center light in bumper			\$0.00	\$0.00	\$0.00
24	✓ Molly			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	1" molly	Kropp Shop		1.0	\$0.00	\$0.00
25	✓ No license plate light			\$0.00	\$0.00	\$0.00
26	✓ Lift axel dust cover			\$0.00	\$0.00	\$0.00
27	✓ Left hand front bunk light			\$0.00	\$0.00	\$0.00
28	✓ Loose air bag bolt middle right			\$0.00	\$0.00	\$0.00
29	✓ Front Axel trifunctionals			\$0.00	\$0.00	\$0.00

T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-24691 - TRI-FUNCIONAL QUIK-ALIGN	Kropp Shop		2.0	\$0.00	\$0.00
30	✓ Red glad hand			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	red glad hand	Kropp Shop		1.0	\$0.00	\$0.00
31	✓ lift axle control box rotted off			\$0.00	\$0.00	\$0.00
	Notes					
	replaced with new box					
32	✓ spaceship valve leaking			\$0.00	\$0.00	\$0.00
	Notes					
	lube and free up piston					

Part Cost	\$200.00
Labor	\$0.00
Subtotal	\$200.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$200.00