

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2024	Mar 11, 2024		Mar 11, 2024 2:59 PM	Mar 11, 2024 2:59 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brake pot	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

Middle LH MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
hab 6 28 fs - Rubber air brake supply	Kropp Shop		1.0	\$0.00	\$0.00
hab 6 28 fs - Rubber air brake supply	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Brake pot bracket broke off axle	\$0.00	\$0.00	\$0.00
---	------------------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
brake pot bracket	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 16, 2024	Mar 16, 2024		Mar 16, 2024 1:16 PM	Mar 16, 2024 1:16 PM

Line	Task	Parts	Labor	Total
1	✓ brake pot bracket broke off	\$0.00	\$0.00	\$0.00

Notes

weld bracket back on #6 LH

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Mar 20, 2024		Mar 20, 2024 2:46 PM	Mar 20, 2024 2:46 PM

Line	Task	Parts	Labor	Total
1	✓ Weld brake pot bracket	\$0.00	\$0.00	\$0.00

Notes

Middle LH bracket broke off

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jun 5, 2024	Jun 5, 2024		Jul 9, 2024 6:55 AM	Jul 9, 2024 6:55 AM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Sep 17, 2024	Sep 17, 2024		Sep 17, 2024 5:48 AM	Sep 17, 2024 5:48 AM

Line	Task	Parts	Labor	Total		
1	✓ Lift axle airbag blown	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8006 air bag	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Oct 10, 2024	Oct 10, 2024		Oct 10, 2024 7:45 AM	Oct 12, 2024 10:37 AM

Line	Task	Parts	Labor	Total		
1	✓ Lift axle RH tires no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ #2 bunk bolt outside MIA	\$0.00	\$0.00	\$0.00		
3	✓ Rubbing airlines on all axles	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Tie up lines and add rubber hoses around lines to stop chafing					
4	✓ lift brakes no movement	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Service valve needed air supply checked operation and verified stroke					
5	✓ frobt axle brake stroke out	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Clevis pin missing added and checked stroke					
6	✓ front axle RH clevis pin MIA	\$0.00	\$0.00	\$0.00		
7	✓ Loose brake pot middle RH	\$0.00	\$0.00	\$0.00		
8	✓ lift Axle crack RH side	\$0.00	\$0.00	\$0.00		
9	✓ Middle LH saddle crack	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

Work Order 1320

Trent Court

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Oct 18, 2024	Oct 18, 2024		Oct 25, 2024 9:16 AM	Oct 25, 2024 9:16 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

wrapper winch bent

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Oct 25, 2024		Oct 25, 2024 6:34 PM	Oct 25, 2024 6:34 PM

Line	Task			Parts	Labor	Total
1	✓ Back LH REAR axle inside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Nov 2, 2024	Nov 2, 2024		Nov 2, 2024 2:25 PM	Nov 2, 2024 2:25 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Suspension	\$150.00	\$0.00	\$150.00
---	--------------	----------	--------	----------

Notes

Back RH airbag nfg

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00

2	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

Front RH both tires nfg back LH outside nfg

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$150.00
Labor	\$0.00
Subtotal	\$150.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$150.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Nov 14, 2024		Nov 14, 2024 12:04 PM	Nov 14, 2024 12:04 PM

Line	Task	Parts	Labor	Total
1	✓ RH front brake pot bracket broke off	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 17, 2024 10:50 AM	Nov 17, 2024 10:50 AM

Line	Task			Parts	Labor	Total
1	✓ Loose brake pot			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Nov 29, 2024	Nov 29, 2024		Nov 29, 2024 11:14 AM	Nov 29, 2024 11:14 AM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
Notes				
RHS lift axle #8 rhs				
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Dec 15, 2024		Dec 15, 2024 6:55 PM	Dec 15, 2024 6:55 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00

Notes

front bunk lights out, Rear LH outside marker on light bar out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3050 - 2" red marker light	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

rear RH dust cover MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jan 2, 2025	Jan 2, 2025		Jan 2, 2025 11:38 AM	Jan 2, 2025 11:38 AM

Line	Task	Parts	Labor	Total		
1	✓ #6LH wheel studs broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
	10082225 - Con met trailer hub	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Jan 14, 2025		Jan 14, 2025 4:58 PM	Jan 14, 2025 4:58 PM

Line	Task	Parts	Labor	Total
1	✓ Front RH brake pot bracket broke off weld back on	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jan 19, 2025	Jan 19, 2025		Jan 19, 2025 6:41 PM	Jan 19, 2025 6:41 PM

Line	Task	Parts	Labor	Total
1	✓ Saddle cracks	\$0.00	\$0.00	\$0.00

Notes

back rh saddle

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Feb 2, 2025	Feb 2, 2025		Feb 2, 2025 10:15 AM	Feb 2, 2025 10:15 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brakes	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

LH rear shoes

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

lh signal not working, marker on center out, license plate light out,
rh marker out, middle marker out, rh tails out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3050 - 2" red marker light	Kropp Shop		2.0	\$0.00	\$0.00
6050 - Oval Red light	Kropp Shop		2.0	\$0.00	\$0.00
3 wire pigtail	Kropp Shop		2.0	\$0.00	\$0.00
2 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

front lh inside nfg

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 1638

Trent Court

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Feb 14, 2025		Feb 14, 2025 9:33 AM	Feb 14, 2025 9:33 AM

Line	Task	Parts	Labor	Total
1	✓ Suspension	\$0.00	\$0.00	\$0.00

Notes

rear rh air bag bolt rear rh inside u bolt loose

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 5, 2025 8:16 PM	Mar 5, 2025 8:16 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> light on	\$0.00	\$0.00	\$0.00
2	✓ Brake Connections <u>Notes</u> Front RH brake pot hanging	\$0.00	\$0.00	\$0.00
3	✓ Saddle cracks <u>Notes</u> rear rh saddle crack	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 6:07 PM	Mar 6, 2025 6:07 PM

Line	Task			Parts	Labor	Total
1	✓ Front LH inside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 18, 2025	Mar 18, 2025		Mar 18, 2025 10:41 AM	Mar 18, 2025 10:41 AM

Line	Task			Parts	Labor	Total
1	✓ Front LH inside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ LH middle outside tire no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	May 31, 2025		May 31, 2025 4:17 PM	May 31, 2025 4:17 PM

Line	Task			Parts	Labor	Total
1	✓ LH lift bag blown			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8006 air bag	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
Tire	Jun 5, 2025	Jun 5, 2025		Jun 5, 2025 6:14 AM	Jun 5, 2025 6:14 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Replace tire	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

#6RHS inside

#8 RHS inside

2 used tires

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Jun 23, 2025		Jun 23, 2025 7:00 PM	Jun 23, 2025 7:00 PM

Line	Task	Parts	Labor	Total		
1	✓ Leveling valve no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Rapid response levelling valve	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Lights INOP	\$0.00	\$0.00	\$0.00		

Notes

License plate light out. Splice broken wire

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jun 25, 2025	Jun 25, 2025		Jun 25, 2025 2:06 PM	Jun 25, 2025 2:06 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
3	✓ Weld cracks	\$0.00	\$0.00	\$0.00

Notes

#6RHS, # 7 both sides, #8RHS

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Jun 25, 2025		Jun 25, 2025 6:01 PM	Jun 25, 2025 6:01 PM

Line	Task	Parts	Labor	Total
1	✓ saddle crack	\$0.00	\$0.00	\$0.00
	Notes			
	LM, rr, RF, LF			
2	✓ Loose brake pot	\$0.00	\$0.00	\$0.00
	Notes			
	Both rear axle pots loose, tightened up			
		Part Cost	\$0.00	
		Labor	\$0.00	
		Subtotal	\$0.00	
		Tax 1 (0.0%)	\$0.00	
		Tax 2 (0.0%)	\$0.00	
		Credit	(\$0.00)	
		Total Cost	\$0.00	

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jul 11, 2025	Jul 11, 2025		Jul 11, 2025 4:09 AM	Jul 11, 2025 4:09 AM

Line	Task	Parts	Labor	Total
1	✓ LH front brake falling apart	\$0.00	\$0.00	\$0.00

Notes

S cam snap ring broke.... Scam walked into drum... shoes were damaged, drum was gouged

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ LH front outside tire nfg	\$0.00	\$0.00	\$0.00
---	-----------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jul 25, 2025	Jul 25, 2025		Jul 25, 2025 3:34 PM	Jul 25, 2025 3:34 PM

Line	Task			Parts	Labor	Total
1	✓ Front LH tires nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Lift axle rh outside nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Jul 28, 2025		Jul 28, 2025 5:02 PM	Jul 28, 2025 5:02 PM

Line	Task	Parts	Labor	Total
1	✓ lift axle cracks	\$0.00	\$0.00	\$0.00
2	✓ saddle crack	\$0.00	\$0.00	\$0.00
Notes				
RR cracked				
3	✓ Rear bumper cracked	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Aug 11, 2025		Aug 11, 2025 7:00 AM	Aug 11, 2025 7:00 AM

Line	Task			Parts	Labor	Total
1	✓ Rear rh inside tire blowout			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Aug 14, 2025		Aug 14, 2025 5:14 AM	Aug 14, 2025 5:14 AM

Line	Task	Parts	Labor	Total
1	✓ Air scale issue	\$0.00	\$0.00	\$0.00

Notes

No flow in suspension line

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Aug 26, 2025	Aug 26, 2025		Aug 26, 2025 2:11 PM	Aug 26, 2025 2:11 PM

Line	Task			Parts	Labor	Total
1	✓ Lights inop			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Aug 29, 2025		Aug 29, 2025 2:08 PM	Aug 29, 2025 2:08 PM

Line	Task	Parts	Labor	Total		
1	✓ Rh inside lift axle flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Sep 10, 2025	Sep 10, 2025		Sep 10, 2025 5:10 PM	Sep 10, 2025 5:11 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Dust cover MIA	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

LF dust cover MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Bunk crack	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

#6 LHS cracked

3	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

Grease and adjust brakes

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Oct 3, 2025	Oct 3, 2025		Oct 3, 2025 2:53 PM	Oct 3, 2025 2:53 PM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

#6 LHI, #6 outer and inner RHS

2	✓ Replace #6 LH stake	\$1,100.00	\$0.00	\$1,100.00
---	-----------------------	------------	--------	------------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00

Part Cost	\$1,100.00
Labor	\$0.00
Subtotal	\$1,100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$1,100.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Oct 6, 2025	Oct 6, 2025		Oct 8, 2025 10:30 PM	Oct 8, 2025 10:30 PM

Line	Task			Parts	Labor	Total
1	✓ Middle LH ABS speed sensor tore off			\$100.00	\$0.00	\$100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00
				Part Cost		\$100.00
				Labor		\$0.00
				Subtotal		\$100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$100.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Oct 16, 2025	Oct 16, 2025		Oct 22, 2025 4:43 PM	Oct 22, 2025 4:43 PM

Line	Task	Parts	Labor	Total		
1	✓ Remove and replace rear axle suspension hangers	\$0.00	\$0.00	\$0.00		
2	✓ Rear axle tri functional bushings no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-24691 - TRI-FUNCIONAL QUIK-ALIGN	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ Front rh dust cover mia	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ King pin wore out	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	KP100 - 2" king pin 3/8 plate	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Oct 28, 2025	Oct 28, 2025		Oct 28, 2025 3:40 PM	Oct 29, 2025 5:14 PM

Line	Task	Parts	Labor	Total
1	✓ Bend dolly leg	\$0.00	\$0.00	\$0.00
	Notes			
	RHS bent, bend back			
2	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
3	✓ Bunk bolts loose	\$0.00	\$0.00	\$0.00

Notes

#5 LHS

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Nov 3, 2025	Nov 3, 2025		Nov 3, 2025 11:40 AM	Nov 3, 2025 7:10 PM

Line	Task	Parts	Labor	Total
1	✓ Replace shock	\$0.00	\$0.00	\$0.00
	Notes			
	S-20002 trailer shock			
2	✓ Loose brake pot	\$0.00	\$0.00	\$0.00
	Notes			
	RR brake pot broken off, weld bracket back on			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 9:40 AM	Dec 14, 2025 9:40 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	lh front brake backed off S cam needs welding RH rear needs adjustment			
2	✓ Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	dust covers middle RHS, snap ring middle LH slack			
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	license plate light bracket nfg			
4	✓ Suspension	\$0.00	\$0.00	\$0.00
	Notes			
	limit chains, tighten leveling valve			
5	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jan 15, 2026	Jan 15, 2026		Jan 17, 2026 6:47 AM	Jan 17, 2026 6:47 AM

Line	Task	Parts	Labor	Total		
1	✓ Back right slack adjuster	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Adjust back right and front left	\$0.00	\$0.00	\$0.00		
3	✓ Tie up air line between 6 and 7th axle	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Scheduled	Due	Started	Closed
	Feb 1, 2026		Feb 1, 2026 6:19 PM	Feb 1, 2026 6:19 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

LHRI flat

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Feb 11, 2026	Feb 11, 2026		Feb 11, 2026 6:36 PM	Feb 11, 2026 6:36 PM

Line	Task	Parts	Labor	Total
1	✓ Right tail light out	\$0.00	\$0.00	\$0.00
2	✓ Right rear beam and saddle broke	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Feb 24, 2026	Feb 24, 2026		Feb 24, 2026 10:27 AM	Feb 24, 2026 10:27 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> rh rear brake pot bracket broke	\$0.00	\$0.00	\$0.00
2	✓ Brakes <u>Notes</u> front lh scam tube needs tack	\$0.00	\$0.00	\$0.00
3	✓ Lights - All <u>Notes</u> rear 3 markers out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 2, 2026	Mar 2, 2026		Mar 2, 2026 5:24 PM	Mar 2, 2026 5:24 PM

Line	Task	Parts	Labor	Total		
1	✓ Back rh brake pot bracket weld	\$0.00	\$0.00	\$0.00		
2	✓ Front rh tri functional bolt loose	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-24679 - Quick align pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
	Eccentric washer	Kropp Shop		1.0	\$0.00	\$0.00
	Concentric washer	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Mar 20, 2026	Mar 20, 2026		Mar 25, 2026 7:39 AM	Mar 25, 2026 7:39 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	Front axle s cams need welded			
2	✓ Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	Front axle brakes out of adjustment			
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	4 hub cap breathers were plugged			
4	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	Licsense plate light			
5	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	Broken frame in front of first axle left side			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T809 - 2017 Cross Country Cross Country Mfg.

Serial	Tag	Current Meters
2C9GSX3Z2HM183809	6HW872	

Type	Created	Scheduled	Due	Started	Closed
	Jul 15, 2026	Jul 15, 2026		Jul 15, 2026 2:49 PM	

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ Wheel seal back right axle	\$0.00	\$0.00	\$0.00
4	✓ Broken saddle back right axle	\$0.00	\$0.00	\$0.00
5	✓ Broken bunk #2	\$0.00	\$0.00	\$0.00
6	✓ New suspension line	\$0.00	\$0.00	\$0.00
7	✓ Marker out on right hand tail lights	\$0.00	\$0.00	\$0.00
8	✓ Marker on right side of bumper out	\$0.00	\$0.00	\$0.00
9	✓ Marker on front left bunk out	\$0.00	\$0.00	\$0.00
10	✓ Centre lights out in tail bar	\$0.00	\$0.00	\$0.00
11	✓ Lift axle cracks	\$0.00	\$0.00	\$0.00
12	✓ Lift axle u bolt cracked	\$0.00	\$0.00	\$0.00
13	✓ Lift axle bolts loose	\$0.00	\$0.00	\$0.00
14	✓ High vis tape	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00