

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Mar 12, 2024	Mar 12, 2024		Mar 12, 2024 5:08 PM	Mar 12, 2024 5:08 PM

Line	Task	Parts	Labor	Total
1	✓ other	\$0.00	\$0.00	\$0.00

Notes

air leak on supply line to tank

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3/8 Plastic Airline	Kropp Shop		1.0	\$0.00	\$0.00
3/8 Union	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ scale box	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

Kinked airline @ front LH airbag re tie up

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	May 14, 2024	May 14, 2024		May 14, 2024 5:21 AM	May 16, 2024 5:37 AM

Line	Task	Parts	Labor	Total
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00
2	✓ Install lift axle	\$0.00	\$0.00	\$0.00
3	✓ Move airlines on middle axle	\$0.00	\$0.00	\$0.00
4	✓ Replace shock	\$0.00	\$0.00	\$0.00

Notes

RH front axle shock NFG

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00

5	✓ Air bag bolt broke off	\$150.00	\$0.00	\$150.00
---	--------------------------	----------	--------	----------

Notes

RH middle air bag bolt broke off

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00

6	✓ Brake pot bracket	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

LH rear bracket cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
05-162 - Brake pot bracket	Kropp Shop		1.0	\$0.00	\$0.00

7	✓ Replace tire	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

RH front inside

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
8 ✓ Replace trifunctional bushings			\$0.00	\$0.00	\$0.00

Notes

RH rear axle bushing NFG

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
S-24691 - TRI-FUNCTIONAL QUIK-ALIGN	Kropp Shop		1.0	\$0.00	\$0.00
9 ✓ Trailer Brakes			\$0.00	\$0.00	\$0.00

Notes

Lift axle both sides

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00
Brake Drum	Kropp Shop		2.0	\$0.00	\$0.00
10 ✓ Lift axle steer shock			\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
66502 - Lift axle shock	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$150.00
Labor	\$0.00
Subtotal	\$150.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$150.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2024	Oct 20, 2024		Oct 20, 2024 5:57 PM	Oct 20, 2024 5:57 PM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle air lines rubbing					
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	back rh brake pot nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lift axle cracked					
4	✓ Suspension	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle rh air bag bolts loose/mia					
		Part Cost		\$0.00		
		Labor		\$0.00		
		Subtotal		\$0.00		
		Tax 1 (0.0%)		\$0.00		
		Tax 2 (0.0%)		\$0.00		
		Credit		(\$0.00)		
		Total Cost		\$0.00		

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Nov 30, 2024		Nov 30, 2024 6:57 PM	Nov 30, 2024 6:57 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00

Notes

Air leak on pedal

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Jan 7, 2025		Jan 7, 2025 5:39 PM	Jan 7, 2025 5:39 PM

Line	Task	Parts	Labor	Total
1	✓ Back marker lights unplugged	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Jan 11, 2025		Jan 11, 2025 4:27 AM	Jan 11, 2025 4:27 AM

Line	Task			Parts	Labor	Total
1	✓ #1 stake broke			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Jan 19, 2025	Jan 19, 2025		Jan 19, 2025 9:24 PM	Jan 19, 2025 9:24 PM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	RH brake pot loose			
2	✓ Bunk cracks	\$0.00	\$0.00	\$0.00
	Notes			
	#6,2,4 bunk crack			
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	Notes			
	rear axle low			
4	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	marker light light bar out LH,RH			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 1, 2025 11:13 AM	Feb 1, 2025 11:13 AM

Line	Task	Parts	Labor	Total												
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Middle RH brake pot loose															
2	✓ Brakes	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Front RH shoes wore out,															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Q plus shoe kit</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00											
3	✓ Bunk cracks	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	#2 crack															
4	✓ other	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Rear rh air line supply nfg tie up chafing lines															
5	✓ Suspension	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	rear rh air bag bolt															

Kropp Contracting
Shop

Work Order 1631

Nate Vandenberghe

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Feb 15, 2025	Feb 15, 2025		Feb 15, 2025 5:55 PM	Feb 15, 2025 5:55 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> loose brake pot rh middle	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> no marker lights	\$0.00	\$0.00	\$0.00
3	✓ Saddle cracks <u>Notes</u> front lh saddle	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 10:54 AM	Mar 3, 2025 10:54 AM

Line	Task	Parts	Labor	Total
1	✓ Brakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	middle LH brake backed off			
2	✓ Suspension	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	middle rh air bag bolts loose/mia			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Mar 13, 2025		Mar 13, 2025 7:09 AM	Mar 13, 2025 7:09 AM

Line	Task			Parts	Labor	Total
1	✓ RH rear axle air bag			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Mar 19, 2025		Mar 19, 2025 2:37 PM	Mar 19, 2025 2:37 PM

Line	Task	Parts	Labor	Total		
1	✓ RH middle inside tire flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Mar 21, 2025		Mar 21, 2025 2:17 PM	Mar 21, 2025 2:17 PM

Line	Task	Parts	Labor	Total
1	✓ front RH inside flat	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 2, 2025	May 2, 2025		May 2, 2025 4:36 AM	May 2, 2025 4:41 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
3	✓ Welding	\$0.00	\$0.00	\$0.00
Notes				
-R/H Lift axle beam cracked				
- R/H and L/H upper air bag mounts				
- weld saddle cracks				
4	✓ Flat tire	\$0.00	\$0.00	\$0.00
Notes				
#6RHS outside flat				
#8LHS inside flat				
5	✓ Change Moly	\$0.00	\$0.00	\$0.00
6	✓ Lights	\$0.00	\$0.00	\$0.00
Notes				
Repair wiring				
7	✓ Grease	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

Work Order 1841

Cam Nadeau

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
Welding	May 4, 2025	May 4, 2025		May 4, 2025 1:47 PM	May 4, 2025 1:47 PM

Line	Task	Parts	Labor	Total
1	✓ Weld frame	\$0.00	\$0.00	\$0.00
2	✓ Weld #6 LHS brake pot bracket	\$0.00	\$0.00	\$0.00
3	✓ Replace Molly	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
electrical	May 13, 2025	May 13, 2025		May 13, 2025 7:08 AM	May 13, 2025 7:08 AM

Line	Task	Parts	Labor	Total
1	✓ Trailer lights	\$0.00	\$0.00	\$0.00

Notes

Front R/H marker light wiring shorted to ground

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
Tire	May 21, 2025	May 21, 2025		May 21, 2025 6:40 AM	May 21, 2025 6:40 AM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00
	Notes			
	#8 LHS inside			
2	✓ air bag	\$0.00	\$0.00	\$0.00
	Notes			
	LH lift axle lift bag			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Jun 6, 2025	Jun 6, 2025		Jun 6, 2025 4:48 PM	Jul 16, 2025 8:09 AM

Line	Task	Parts	Labor	Total
1	✓ Loose Scam	\$0.00	\$0.00	\$0.00
	Notes RHS lift axle adjuster/Scam loose. Remove adjuster and wheels and drum to inspect. repaired by shimming adjuster			
2	✓ saddle crack	\$0.00	\$0.00	\$0.00
	Notes LF, RF, RM, LR, and RR			
3	✓ ABS codes	\$0.00	\$0.00	\$0.00
	Notes Found LHS WSS wire broken near brake pot air lines			
4	✓ Air bag bolt broke off	\$0.00	\$0.00	\$0.00
	Notes RM air bag bolt broke and air bag base shifted			
5	✓ Brake pot bracket	\$0.00	\$0.00	\$0.00
	Notes replace RM pot bracket			
6	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
	Notes Middle axle			

Kropp Contracting
Shop

Work Order 1904

Everett Twin

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Jul 3, 2025	Jul 2, 2025		Jul 3, 2025 7:07 PM	Jul 3, 2025 7:07 PM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

LRI NFG

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Jul 18, 2025	Jul 18, 2025		Jul 18, 2025 9:20 AM	Jul 18, 2025 9:20 AM

Line	Task	Parts	Labor	Total		
1	✓ Rh rear axle outside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Aug 14, 2025		Aug 14, 2025 6:37 AM	Aug 14, 2025 6:37 AM

Line	Task	Parts	Labor	Total		
1	✓ RH middle brake pot bracket broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	05-162 - Brake pot bracket	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ RH middle brake pot stud broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Oct 28, 2025	Oct 28, 2025		Oct 28, 2025 7:00 AM	Oct 28, 2025 7:21 PM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ Trailer Brakes	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Air bag bolt broke off	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Spin base of airbag					
4	✓ ABS wire broken	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LHM ABS wire broken, tap both sensors into tone ring					
5	✓ Loose bunk bolts	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#5 LH loose					
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Nov 12, 2025	Nov 12, 2025		Nov 15, 2025 4:39 AM	Nov 15, 2025 4:39 AM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle rh brake pot bracket cracked					
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front rh scam tube tacked, set brake middle LH scam tube tack					
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle and rear rh low, front and rear lh low					
4	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh lift inside nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	tie up front bunk wires, tie up rear junction box					
6	✓ Lift axle steer shocks no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	66502 - Lift axle shock	Kropp Shop		2.0	\$0.00	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

7	✓ Rh tie rod end no good			\$0.00	\$0.00	\$0.00
Part		Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
R230068 - Tie rod end		Kropp Shop		1.0	\$0.00	\$0.00
8	✓ air tank loose			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Nov 29, 2025	Nov 29, 2025		Nov 30, 2025 5:46 AM	Nov 30, 2025 5:46 AM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	rear rh low			
2	✓ other	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	control box air leaks, lift axle crack			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Dec 8, 2025	Dec 8, 2025		Dec 9, 2025 9:59 PM	Dec 9, 2025 9:59 PM

Line	Task	Parts	Labor	Total
1	✓ #6 rh stake broke	\$0.00	\$0.00	\$0.00
2	✓ Trailer scales dropping off weight when loading	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2026	Jan 31, 2026		Jan 31, 2026 8:27 AM	Jan 31, 2026 10:08 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

adjuster pin boot tore, not holding adjustment replaced with new

middle LH slack adj diagnose

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Brakes	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

adj all brakes

3	✓ Bunk bolts	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

#2 lh bunk loose

4	✓ Hub Levels	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

rh rear low

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Feb 12, 2026	Feb 12, 2026		Feb 12, 2026 8:04 PM	Feb 12, 2026 8:04 PM

Line	Task			Parts	Labor	Total
1	✓ Stake on back left			\$1,100.00	\$0.00	\$1,100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cc stake	Kropp Shop		1.0	\$1,100.00	\$1,100.00
				Part Cost		\$1,100.00
				Labor		\$0.00
				Subtotal		\$1,100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$1,100.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Feb 26, 2026	Feb 26, 2026		Feb 26, 2026 8:08 PM	Feb 26, 2026 8:08 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	Front LH slack cotter pin MIA			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	rh signal out			
3	✓ other	\$0.00	\$0.00	\$0.00
	Notes			
	air leak rear of trailer			
4	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	LHRI nfg RHRI flat			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Created	Scheduled	Due	Started	Closed
	Mar 23, 2026	Mar 23, 2026		Mar 23, 2026 12:37 PM	Mar 23, 2026 12:37 PM

Line	Task	Parts	Labor	Total		
1	✓ LH middle outside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T807 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
2C9GSX3Z9HM183807	6KX722	

Type	Scheduled	Due	Started	Closed
	Jul 20, 2026		Jul 20, 2026 4:36 PM	Jul 20, 2026 4:36 PM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00