

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Mar 20, 2024	Mar 20, 2024		Mar 23, 2024 3:37 PM	Mar 23, 2024 3:37 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

Rear LH inside separated

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Mar 23, 2024		Mar 23, 2024 2:38 PM	Mar 23, 2024 2:38 PM

Line	Task	Parts	Labor	Total
1	✓ Brake pot leaking	\$0.00	\$0.00	\$0.00

Notes

Back axle LH leaking

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Mar 25, 2024	Mar 25, 2024		Mar 25, 2024 4:48 PM	Mar 25, 2024 4:48 PM

Line	Task	Parts	Labor	Total
1	✓ saddle crack	\$0.00	\$0.00	\$0.00

Notes

Back RH saddle cracked, broken beyond repair

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
#2 saddle	Kropp Shop		1.0	\$0.00	\$0.00
U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00
Pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Nov 2, 2024		Nov 2, 2024 7:05 PM	Nov 2, 2024 7:05 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> Middle LH adjuster pin loose	\$0.00	\$0.00	\$0.00
2	✓ other <u>Notes</u> Front and middle dust covers	\$0.00	\$0.00	\$0.00
3	✓ Tires <u>Notes</u> Front LH outside tire	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Nov 16, 2024		Nov 16, 2024 6:33 AM	Nov 16, 2024 6:33 AM

Line	Task	Parts	Labor	Total
1	✓ lift axle cracks	\$0.00	\$0.00	\$0.00
2	✓ Loose air bag bolts front axle both sides	\$0.00	\$0.00	\$0.00
3	✓ Middle LH clevis pin missing	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Dec 15, 2024		Dec 15, 2024 6:59 PM	Dec 15, 2024 6:59 PM

Line	Task	Parts	Labor	Total
1	✓ Suspension	\$150.00	\$0.00	\$150.00

Notes

rh front air bag

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag		Kropp Shop	1.0	\$150.00	\$150.00
Part Cost					\$150.00
Labor					\$0.00
Subtotal					\$150.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$150.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 7:21 AM	Jan 19, 2025 7:21 AM

Line	Task	Parts	Labor	Total
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	LM,LR,RF low			
2	✓ Tires	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	RH middle tires nfg			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Jan 20, 2025	Jan 20, 2025		Jan 20, 2025 7:46 PM	Jan 20, 2025 7:46 PM

Line	Task			Parts	Labor	Total
1	✓ Rh front airbag blown			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Jan 28, 2025	Jan 28, 2025		Jan 29, 2025 5:39 PM	Jan 29, 2025 5:39 PM

Line	Task			Parts	Labor	Total
1	✓ RH rear axle airbag blown			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 2, 2025	Feb 2, 2025		Feb 2, 2025 7:19 PM	Feb 2, 2025 7:19 PM

Line	Task	Parts	Labor	Total		
1	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RH middle pot clevis loose					
2	✓ Saddle cracks	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RR,RF cracked					
3	✓ Suspension	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LM shock bolt loose					
4	✓ RH middle slack adjuster no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6" slack adjuster CC	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 11, 2025	Feb 11, 2025		Feb 11, 2025 9:01 AM	Feb 13, 2025 10:16 AM

Line	Task	Parts	Labor	Total		
1	✓ Front LH inside flat tire	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ No stop lights on trailer	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	7 wire female plug	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Middle RH brake pot bracket broke off	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	welded and brake pot rod was bent- replaced					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ middle LH brake no contact	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Removed dust cover to get access to view, got driver to operate brakes and contact was made					
5	✓ Middle LH, Rear RH,LH contaminated	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	removed all dust covers to view... found there was no contamination visible at all, was ice/brake dust coming from view hole					

Notes	User	Time
Level 1 Scale repairs	Trent Court	Feb 11, 2025 8:58 AM

Alberta

CVSA
COMMERCIAL VEHICLE INSPECTION REPORT

AR269-001

Page 1 of 6

Alberta

CVSA
COMMERCIAL VEHICLE INSPECTION REPORT

CVSE
INFO

INSPECTION LEVEL: 1

Vehicle(s) inspected this day of February 2020 at 16:04 hours at/for Street Lusk YR

City/Prov

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

CVSE

INFO

INSPECTION RESULT: **OUT OF SERVICE**
 VEHICLE(S) OUT OF SERVICE UNTIL OUT OF SERVICE DEFECTS BELOW ARE CORRECTED
 FAILURE TO REPORT INDICATED REPAIRS BY BUSINESS MAY RESULT IN PROSECUTION

Owner: KSC2 CONTRACTING LTD.

Address: P.O. Box 237

City: Stettin Lake

Jur: AB Postal/Zip Code T9G 3A0

MVD: 0308-12034

Vehicle

Plate

Jur

CVSA Seat

1 Power Unit

E68882

AB

2 Semi Trailer

42X980

AB

Driver: Brian

Address: Unknown, THURSDAY

Basic Measurements

Auto 1

Tire 1

Lift 1

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

3.18

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

1.14

1

ANY DEFECTS NOTED ON THIS DOCUMENT MAY RESULT IN PROSECUTION

Vehicle Defects

[illegible]

Alameda		CVA- COMMERCIAL VEHICLE INSPECTION REPORT		AB204-1001 Page 1 of 4
INSPECTION LEVEL: 1 (Vehicle) Inspected on <u>09 of February 2020</u> at <u>10:04</u> hours under <u>North West</u> City		Inspector: _____		
INSPECTION RESULT: OUT OF SERVICE				
VEHICLE(S) UNDER OUT OF SERVICE DEFECT RESULT YES/NO ARE CORRECTED FAILURE TO REPORT INDICATED REPAIRS BY 250000 HRS MAY RESULT IN SUSPENSION				
Continued...		ANY REPEATS NOTED ON THIS DOCUMENT MAY RESULT IN PROSECUTION		
VIEW/DEFECT	DESCRIPTION	ACT/SECTION	FVI/ASSESSMENT/NOTES	REPAIR/ALTERNATIVE
1 Brake Systems	Brake fluid level above minimum of performance. Amount 6.75 lbs. was contained. Given the vehicle's age and having only been tested and fixed.	15A AR 1710000-500 (10/07)		Requires Attention
2 Brake Systems	Brake inspected shows evidence of contamination. MAJOR DEFECT	15A AR 1710000-500 (10/07)		Requires Attention
3 Brake Systems	No mechanical or structural part that is malfunctioning so as to render it unsafe. MAJOR DEFECT	15A AR 1710000-500 (10/07)		Requires Attention
4 Cargo Securement	Good securement system not in proper working condition as per inspection.	15A NSC Standard 10 A20		Requires Attention
5 Cargo Securement	Defective ties of suspended not secured by U-bolts. MAJOR DEFECT	15A NSC Standard 10 A20		Out of Service
6 Cargo Securement	Over 100 lbs. in excess. Indicators that when vehicle on highway. MAJOR DEFECT	15A NSC Standard 10 A20		Requires Attention
7 Emergency Communication System/Warning System	Communication vehicle not properly installed. MAJOR DEFECT	15A AR 1710000-500 (10/07)		Requires Attention
8 Lighting Device (Part 1 Section 9 - OORC only)	Brake lamp not in light and when service brake applied. MAJOR DEFECT	15A AR 1000000-500 (10/07)		Out of Service
9 Tires	Brake lamp not in light and when service brake applied. MAJOR DEFECT	15A AR 1000000-500 (10/07)		Out of Service
NOTES / COMMENTS FOR THE INFORMATION OF THE CARRIER / DRIVER All OORC and Major Defects must be corrected on site. This vehicle has been identified to have brake contamination. A qualified technician needs to determine why the defective brake has excessive brake dust and adjust the appropriate axles. Simply adjusting the brake assembly or replacing it does not remove the problem or control the problem. Brake dust can be the foundation for brake failure. By writing this inspection report you have indicated that this vehicle now has a properly functioning safety system. MAJOR DEFECT (Part 1 Section 9) is listed in NSC Part Inspection Standard 10 has been indicated on this report. Repairs must be made in compliance with the Commercial Vehicle Safety Regulation before proceeding.				
OFFICER: ROBERT KIRBY		City: North West		Time Out: 10:42
REFER TO LAST PAGE OF INSPECTION FOR DETAILS REGARDING COMPLIANCE				
THE CARRIER HAS BEEN ADVISED THAT THE VEHICLE IS OUT OF SERVICE. THE INSPECTION REPORT IS BEING PROVIDED TO THE CARRIER. THE CARRIER IS RESPONSIBLE FOR PROVIDING CARRIER WITH A COPY OF THIS REPORT. DRIVER IS RESPONSIBLE FOR PROVIDING CARRIER WITH A COPY OF THIS REPORT.				

T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2025	Feb 25, 2025		Feb 27, 2025 11:38 AM	Feb 27, 2025 11:38 AM

Line	Task	Parts	Labor	Total
1	✓ rear rh saddle crack	\$0.00	\$0.00	\$0.00
2	✓ middle lh saddle crack	\$0.00	\$0.00	\$0.00
3	✓ rear inside flat LH	\$0.00	\$0.00	\$0.00
4	✓ winch handle #6	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 6, 2025 6:07 PM	Mar 6, 2025 6:07 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> light on	\$0.00	\$0.00	\$0.00
2	✓ Hub Levels <u>Notes</u> top up hubs	\$0.00	\$0.00	\$0.00
3	✓ Saddle cracks <u>Notes</u> front LH crack	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 22, 2025	May 22, 2025		Jul 3, 2025 8:09 AM	Jul 3, 2025 8:09 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Jun 24, 2025	Jun 24, 2025		Jun 25, 2025 6:37 AM	Jun 25, 2025 6:37 AM

Line	Task			Parts	Labor	Total
1	✓ air bag			\$150.00	\$0.00	\$150.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
				Part Cost		\$150.00
				Labor		\$0.00
				Subtotal		\$150.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$150.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Jul 6, 2025	Jul 6, 2025		Jul 6, 2025 12:28 PM	Jul 6, 2025 12:28 PM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Rh WSS unplugged					
2	✓ Front axle rh inside nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Sep 23, 2025		Sep 23, 2025 8:14 AM	Sep 23, 2025 8:14 AM

Line	Task	Parts	Labor	Total
1	✓ Rear rh tires nfg	\$0.00	\$0.00	\$0.00
2	✓ Middle LH outside tire nfg	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Oct 1, 2025	Oct 1, 2025		Oct 2, 2025 6:01 AM	Oct 2, 2025 6:01 AM

Line	Task	Parts	Labor	Total
1	✓ Push down lift axle air bag blown	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Nov 3, 2025	Nov 3, 2025		Nov 3, 2025 5:39 PM	Nov 4, 2025 5:01 PM

Line	Task	Parts	Labor	Total		
1	✓ Loose shock	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LM lower bolt loose					
2	✓ saddle crack	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RHF					
3	✓ Replace shock	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LR shock					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Loose S-cam tube	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RR Scam tube loose-weld					
5	✓ #7 LH slack adjuster	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Aiden Kenny	0.0	\$0.00	\$0.00		
6	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

T42 - 2016 Gerrys

Work Order 2235

Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

CLOSED

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Nov 26, 2025		Nov 26, 2025 4:40 PM	Nov 26, 2025 4:40 PM

Line	Task	Parts	Labor	Total
1	✓ Rh mid outside nfg	\$0.00	\$0.00	\$0.00
2	✓ Rear LH inside nfg	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2025	Dec 13, 2025		Dec 13, 2025 12:16 PM	Dec 13, 2025 12:16 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections Notes replace axle mounting bracket to axle bottom looks broke rh rear scam loose	\$0.00	\$0.00	\$0.00
2	✓ Brakes Notes rh middle shoes nfg	\$0.00	\$0.00	\$0.00
3	✓ Hub Levels Notes rh front low	\$0.00	\$0.00	\$0.00
4	✓ Lights - All Notes license plate light out, middle marker out	\$0.00	\$0.00	\$0.00
5	✓ other Notes lh rear wheel seal leaking	\$0.00	\$0.00	\$0.00
6	✓ Suspension Notes rh rear u bolt loose	\$0.00	\$0.00	\$0.00

T42 - 2016 Gerrys

CLOSED

7	✓ rh front dust cover mia	\$0.00	\$0.00	\$0.00
8	✓ bent mudflap bracket rh side	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
2 week check	Jan 16, 2026	Jan 16, 2026		Jan 16, 2026 3:54 PM	Jan 17, 2026 6:43 AM

Line	Task	Parts	Labor	Total
1	✓ S-cam tube on #7rh needa welded	\$0.00	\$0.00	\$0.00
2	✓ #7lh hub needs oil	\$0.00	\$0.00	\$0.00
3	✓ Both S-cam needs welded on #5 axel	\$0.00	\$0.00	\$0.00
4	✓ Brake needs adjusting on #5 lh	\$0.00	\$0.00	\$0.00
5	✓ Airbag on #5rh needs adjusting	\$0.00	\$0.00	\$0.00
6	✓ Clevis nut on #5lh fucked	\$0.00	\$0.00	\$0.00
7	✓ Saddle crack on #5rh	\$0.00	\$0.00	\$0.00
8	✓ Loose bunk bolt on #5lh	\$0.00	\$0.00	\$0.00
9	✓ Lh side marker on middle of trailer out	\$0.00	\$0.00	\$0.00
10	✓ Mud flap on lh side of trailer	\$0.00	\$0.00	\$0.00
11	✓ #5rh hub needs oil	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2026	Feb 1, 2026		Feb 1, 2026 2:37 PM	Feb 1, 2026 2:37 PM

Line	Task	Parts	Labor	Total		
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RH rear brake tube and bracket broke					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	X039 - CC S cam tube	Kropp Shop		1.0	\$0.00	\$0.00
	S cam tube brackets	Kropp Shop		1.0	\$0.00	\$0.00
	40020216 - Peerless lift axle slack adjuster	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RH middle jam nut backed off, clevis pin tight					
3	✓ Hub Levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LH middle hub cap NFG					
4	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	license plate light out					
5	✓ other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	dust cover MIA front LH, rear RH					

T42 - 2016 Gerrys

6	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

rh front cracked

7	✓ Suspension	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

RH front u bolts loose

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Scheduled	Due	Started	Closed
	Feb 26, 2026		Feb 26, 2026 4:31 AM	Feb 26, 2026 4:31 AM

Line	Task			Parts	Labor	Total
1	✓ FRHO flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Apr 1, 2026	Apr 1, 2026		Apr 1, 2026 2:05 PM	Apr 1, 2026 2:05 PM

Line	Task	Parts	Labor	Total
1	✓ Weld cracked bunk #6rh	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Apr 15, 2026	Apr 15, 2026		Apr 16, 2026 5:45 AM	Apr 16, 2026 5:45 AM

Line	Task	Parts	Labor	Total
1	✓ Fixed right hand mid way marker and both side markers at back of trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T42 - 2016 Gerrys

CLOSED

Serial	Tag	Closed Meters
2L9HS8385GH004042	4ZX993	

Type	Created	Scheduled	Due	Started	Closed
	Jun 16, 2026	Jun 16, 2026		Jun 19, 2026 5:46 AM	Jul 2, 2026 10:26 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Dust cover front right	\$0.00	\$0.00	\$0.00
3	✓ Lift axle king pen inspect	\$0.00	\$0.00	\$0.00
4	✓ Front left scam tube needs welded	\$0.00	\$0.00	\$0.00
5	✓ Axle cover plate missing	\$0.00	\$0.00	\$0.00
6	✓ Abs wires broke	\$0.00	\$0.00	\$0.00
7	✓ Lift axle shock	\$0.00	\$0.00	\$0.00
8	✓ Broken welds on first axle up at suspension hangar	\$0.00	\$0.00	\$0.00
9	✓ License plate light	\$0.00	\$0.00	\$0.00
10	✓ brakes on front left axle	\$0.00	\$0.00	\$0.00
11	✓ brakes on middle left axle	\$0.00	\$0.00	\$0.00
12	✓ brakes on back left	\$0.00	\$0.00	\$0.00
13	✓ scam bushing on front left	\$0.00	\$0.00	\$0.00
14	✓ scam bushings on back right axle	\$0.00	\$0.00	\$0.00
15	✓ leaking quick release valve on lift axle	\$0.00	\$0.00	\$0.00
16	✓ LH service pot leaking	\$0.00	\$0.00	\$0.00

T42 - 2016 Gerrys

CLOSED

17	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00