

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Mar 25, 2024	Mar 25, 2024		Mar 25, 2024 4:42 PM	Mar 25, 2024 4:42 PM

Line	Task	Parts	Labor	Total
1	✓ Air bag	\$150.00	\$0.00	\$150.00

Notes

Back left hand air bag blown

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
8050 air bag	Kropp Shop		1.0	\$150.00	\$150.00
Part Cost					\$150.00
Labor					\$0.00
Subtotal					\$150.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$150.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Apr 10, 2024	Apr 10, 2024		Apr 12, 2024 8:03 AM	May 3, 2024 1:16 PM

Line	Task	Parts	Labor	Total		
1	✓ Cvip inspection	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Wheels off inspection					
2	✓ Replace Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle LH inside/outside NFG					
	Rear LH inside NFG					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ Fender bracket	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Install bracket that was broke off					
4	✓ dolly leg crossmember crack	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Weld cracks on gussets					
5	✓ Top cover on front	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Aluminum plate ontop bolt back down					
6	✓ inspect horse cock for wear	\$0.00	\$0.00	\$0.00		

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

7	✓ install lift axle	\$0.00	\$0.00	\$0.00
8	✓ Lights out	\$0.00	\$0.00	\$0.00

Notes

License plate light out, midship RH marker out, RH signal rear

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
licence plate light	Kropp Shop		1.0	\$0.00	\$0.00
2 wire pigtail	Kropp Shop		2.0	\$0.00	\$0.00
3050A round light	Kropp Shop		1.0	\$0.00	\$0.00

9	✓ stake pocket	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

#6 LH pocket wore out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
peerless stake pocket	Kropp Shop		1.0	\$0.00	\$0.00

10	✓ suspension hanger	\$0.00	\$0.00	\$0.00
----	---------------------	--------	--------	--------

Notes

Front RH NFG

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
suspension hanger peerless	Kropp Shop		1.0	\$0.00	\$0.00
weld alignment collar	Kropp Shop		1.0	\$0.00	\$0.00

11	✓ saddle crack	\$0.00	\$0.00	\$0.00
----	----------------	--------	--------	--------

Notes

Front axle LH beam NFG, RH cracked check U-bolts

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
LH beam	Kropp Shop		1.0	\$0.00	\$0.00
Pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
S-21099 - Teflon washer	Kropp Shop		2.0	\$0.00	\$0.00
U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

12 ✓ suspension hanger crossmember crack \$0.00 \$0.00 \$0.00

Notes

Middle LH side

13 ✓ chafing air lines \$0.00 \$0.00 \$0.00

Notes

Rear tank supply line rubbing on frame

14 ✓ air bag \$0.00 \$0.00 \$0.00

Notes

Rear LH bag bolts MIA

15 ✓ Trailer ABS \$0.00 \$0.00 \$0.00

Notes

NO power to ECU and diagnose codes

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
ABS ECU	Kropp Shop		1.0	\$0.00	\$0.00
K181625 - 6' 90 ABS WSS	Kropp Shop		2.0	\$0.00	\$0.00

16 ✓ install lift axle mud flap \$0.00 \$0.00 \$0.00

17 ✓ Replace Lift axle king pins \$0.00 \$0.00 \$0.00

Notes

bushings wore out of spec for CVIP

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
peerless king pin kit	Kropp Shop		1.0	\$0.00	\$0.00

18 ✓ Trailer Brakes \$0.00 \$0.00 \$0.00

Notes

Back LH axle Shoes/Drum wore out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1064
Trent Court, Nate Vandenberghe

CLOSED

Brake Drum

Kropp Shop

1.0

\$0.00

\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jul 23, 2024	Jul 23, 2024		Jul 23, 2024 3:05 AM	Jul 23, 2024 3:05 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

Lift axle LH outside wire out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
22.5 trailer tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Aug 30, 2024	Aug 30, 2024		Aug 30, 2024 3:37 PM	Aug 30, 2024 3:37 PM

Line	Task	Parts	Labor	Total
1	✓ Landing Gear	\$0.00	\$0.00	\$0.00
	Notes			
	Bent dolly leg bracket			
2	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	Rh rear outside tire wore out			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
			Part Cost		\$0.00
			Labor		\$0.00
			Subtotal		\$0.00
			Tax 1 (0.0%)		\$0.00
			Tax 2 (0.0%)		\$0.00
			Credit		(\$0.00)
			Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Scheduled	Due	Started	Closed
	Oct 8, 2024		Oct 8, 2024 7:00 AM	Oct 8, 2024 7:00 AM

Line	Task	Parts	Labor	Total
1	✓ trailer ABS	\$0.00	\$0.00	\$0.00
	Notes			
	push in WSS RH			
2	✓ Middle axle RH cotter pin missing	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1354
Everett Twin, Trent Court
CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2024	Oct 20, 2024		Oct 20, 2024 2:38 PM	Oct 20, 2024 2:38 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Notes

front RH crack

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1372

Trent Court

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Scheduled	Due	Started	Closed
	Oct 24, 2024		Oct 24, 2024 3:11 PM	Oct 24, 2024 3:11 PM

Line	Task	Parts	Labor	Total
1	✓ Front axle trifunctional bolt loose RH side	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1377

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Scheduled	Due	Started	Closed
	Oct 25, 2024		Oct 25, 2024 5:32 PM	Oct 25, 2024 5:32 PM

Line	Task			Parts	Labor	Total
1	✓ Flat tire RH rear axle inside			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Scheduled	Due	Started	Closed
	Dec 13, 2024		Dec 13, 2024 8:46 PM	Dec 13, 2024 8:46 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	LH rear marker out			
2	✓ other	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Remove Lift axle mudflap			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jan 11, 2025	Jan 11, 2025		Jan 14, 2025 5:00 PM	Jan 14, 2025 5:00 PM

Line	Task			Parts	Labor	Total
1	✓ Front RH, Back RH air bags blown			\$300.00	\$0.00	\$300.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	8050 air bag	Kropp Shop		2.0	\$150.00	\$300.00
2	✓ Rear LH dust cover MIA			\$0.00	\$0.00	\$0.00
				Part Cost		\$300.00
				Labor		\$0.00
				Subtotal		\$300.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$300.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Scheduled	Due	Started	Closed
	Jan 17, 2025		Jan 17, 2025 2:34 PM	Jan 17, 2025 2:34 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	abs light 6 blink			
2	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	low rear axle			
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	middle LH marker out			
4	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	front cracked rear rh cracked			
5	✓ Suspension	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	rear rh air bag bolt			
6	✓ Tires	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	low rh inside low PSI, front lho nfg			

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1580

Nate Vandenberghe

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1619

Unassigned

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jan 28, 2025	Jan 28, 2025		Jan 28, 2025 4:00 PM	Jan 28, 2025 4:00 PM

Line	Task	Parts	Labor	Total		
1	✓ Axle saddle cracks front LH rear RH	\$0.00	\$0.00	\$0.00		
2	✓ Loose u bolts, front LH rear RH	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-21140 - U bolt kit	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 1, 2025 8:15 AM	Feb 1, 2025 8:15 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> 6 blink code	\$0.00	\$0.00	\$0.00
2	✓ Brake Connections <u>Notes</u> rh rear fitting leak, rh front fitting leak	\$0.00	\$0.00	\$0.00
3	✓ Lights - All <u>Notes</u> mid lh marker out	\$0.00	\$0.00	\$0.00
4	✓ other <u>Notes</u> scales inaccurate, found air lines off of rh front air bag loose/ leaking... middle of trailer susp line leaking	\$0.00	\$0.00	\$0.00
5	✓ Tires <u>Notes</u> front rh outside nfg middle lh outside nfg	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1625

Trent Court, Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1654
Nate Vandenberghe, Trent Court

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Feb 3, 2025	Feb 3, 2025		Feb 3, 2025 3:06 PM	Feb 3, 2025 3:06 PM

Line	Task	Parts	Labor	Total
1	✓ move bunk 4,5,6 to 8' (pushed together)	\$0.00	\$0.00	\$0.00
2	✓ Diagnose and repair trailer scales	\$0.00	\$0.00	\$0.00

Notes

adjusted ride height found susp air leaks changed fitting on front of trailer

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Feb 11, 2025	Feb 11, 2025		Feb 11, 2025 10:09 PM	Feb 11, 2025 10:09 PM

Line	Task	Parts	Labor	Total		
1	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Bunk clearance light out LH side					
2	✓ Suspension	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Air lines kinked/cracked on #1,2,3 RH sodey					
3	✓ Midship junction box broke off and destroyed wires open	\$0.00	\$0.00	\$0.00		
4	✓ Front RH brake no stroke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Adjust brakes to 1-1/2"	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:29 AM	Mar 3, 2025 11:29 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00

Notes

Middle RH MIA

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Brakes	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

Middle RH MIA

3	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

RL rig marker out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1746

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 4:31 PM	Mar 6, 2025 4:31 PM

Line	Task			Parts	Labor	Total
1	✓ Middle LH outside flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Apr 7, 2025	Apr 7, 2025		Apr 18, 2025 8:37 PM	Apr 18, 2025 8:37 PM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
3	✓ middle RH marker out	\$0.00	\$0.00	\$0.00		
4	✓ Rear rh bunk marker out	\$0.00	\$0.00	\$0.00		
5	✓ license plate light hanging	\$0.00	\$0.00	\$0.00		
6	✓ 7 wire female plug broke off	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	7 wire female plug	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ lift axle king pins no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	peerless king pin kit	Kropp Shop		1.0	\$0.00	\$0.00
8	✓ LH front axle wheel seal leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
9	✓ LH rear axle brake pot jam nut backed off	\$0.00	\$0.00	\$0.00		
10	✓ Middle RH brake pot push rod bent	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ Rear RH slack adj bushing MIA	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

	Haldex bushing kit	Kropp Shop	1.0	\$0.00	\$0.00	
12	✓ Flat lire Middle inside		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ ABS codes		\$100.00	\$0.00	\$100.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00
14	✓ Front RH trifunctional bolt loose		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Pivot bolt	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ king pin wore out		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	KP100 - 2" king pin 3/8 plate	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$100.00
				Labor		\$0.00
				Subtotal		\$100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$100.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jun 6, 2025	Jun 6, 2025		Jun 6, 2025 10:39 AM	Jun 6, 2025 10:39 AM

Line	Task	Parts	Labor	Total
1	✓ saddle crack	\$0.00	\$0.00	\$0.00

Notes

Rhf saddle crack, gouge, preheat and weld

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jun 7, 2025	Jun 7, 2025		Jun 7, 2025 8:03 AM	Jun 7, 2025 10:32 AM

Line	Task	Parts	Labor	Total		
1	✓ RHI lift axle tire NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	22.5 trailer tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Lift axle steer shock	\$0.00	\$0.00	\$0.00		
	Notes					
	Both sides no good					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	66502 - Lift axle shock	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ Rh rear brakes wore out	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ rh rear outside tire nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ LH rear jam nut loose in brake pot	\$0.00	\$0.00	\$0.00		
6	✓ LH rear adjustment bar loose	\$0.00	\$0.00	\$0.00		
7	✓ rh rear S cam nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	40020216 - Peerless lift axle slack adjuster	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 1906

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jul 7, 2025	Jul 7, 2025		Jul 7, 2025 7:45 AM	Jul 7, 2025 7:45 AM

Line	Task			Parts	Labor	Total
1	✓ Inside lift axle LH tire			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	22.5 trailer tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Front LH inside tire nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Rear inside tire nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jul 7, 2025	Jul 7, 2025		Jul 7, 2025 6:53 AM	Jul 7, 2025 6:53 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

Lift axle LH inner, #6&8 LH inner

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
225 low profile tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Aug 22, 2025	Aug 22, 2025		Aug 22, 2025 3:41 PM	Aug 22, 2025 3:41 PM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00
2	✓ Loose tri functional	\$0.00	\$0.00	\$0.00
3	✓ Broken air bag mounts	\$0.00	\$0.00	\$0.00
4	✓ Licsense plate light	\$0.00	\$0.00	\$0.00
5	✓ Ratio rely valve	\$0.00	\$0.00	\$0.00
6	✓ Broken mudflap hanger	\$0.00	\$0.00	\$0.00
7	✓ ABS codes	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Oct 9, 2025	Oct 9, 2025		Oct 16, 2025 4:20 AM	Oct 16, 2025 4:20 AM

Line	Task	Parts	Labor	Total
1	✓ Front RH trifunctional bolt loose (pivot pin)	\$0.00	\$0.00	\$0.00
2	✓ Rh front air bag base broke off	\$0.00	\$0.00	\$0.00
3	✓ ABS codes	\$0.00	\$0.00	\$0.00
4	✓ licence plate light hanging	\$0.00	\$0.00	\$0.00
5	✓ LH rear middle marker light grommet to replace	\$0.00	\$0.00	\$0.00
6	✓ Middle LH inside tire nfg	\$0.00	\$0.00	\$0.00
7	✓ lift axle rh outside tire showing cords	\$0.00	\$0.00	\$0.00
8	✓ rh lift axle slack adjuster pin MIA	\$0.00	\$0.00	\$0.00
9	✓ #4 wrapper handle bolt MIA	\$0.00	\$0.00	\$0.00
10	✓ LH rear axle slack bushing falling out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Oct 21, 2025	Oct 21, 2025		Oct 21, 2025 4:53 PM	Oct 22, 2025 4:23 PM

Line	Task	Parts	Labor	Total
1	✓ Bag bag bolt MIA	\$0.00	\$0.00	\$0.00
	Notes			
	RHF inner bolt MIA, move airbag base back to normal, install new bolt			
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Oct 30, 2025	Oct 30, 2025		Oct 31, 2025 9:02 PM	Oct 31, 2025 9:02 PM

Line	Task	Parts	Labor	Total
1	✓ Bad pedcock on 3rd axle air tank	\$0.00	\$0.00	\$0.00
2	✓ Tri functional bushing bolt loose	\$0.00	\$0.00	\$0.00
3	✓ Lift axle leak	\$0.00	\$0.00	\$0.00
4	✓ Broken air bag mount	\$0.00	\$0.00	\$0.00
5	✓ Broken s cam tube	\$0.00	\$0.00	\$0.00
6	✓ Left hand tail lights no blinky	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Nov 12, 2025	Nov 12, 2025		Nov 12, 2025 11:08 AM	Nov 12, 2025 11:30 AM

Line	Task	Parts	Labor	Total		
1	✓ Hub Levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front LH wheel seal leaking					
	Front LH low, rear rh low					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Back LH outside marker dim					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4" red light	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	FLO nfg, RMI nfg					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ Wheel seal front left axle	\$0.00	\$0.00	\$0.00		
5	✓ Abs wire fixed middle right	\$0.00	\$0.00	\$0.00		
6	✓ Middle RH hub cap cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	hub cap	Kropp Shop		1.0	\$0.00	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 2248
Aiden Kenny, Trent Court
CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Nov 28, 2025	Nov 28, 2025		Nov 29, 2025 5:53 AM	Nov 29, 2025 5:53 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> rh WSS broke	\$0.00	\$0.00	\$0.00
2	✓ Brake Connections <u>Notes</u> rh lift service line nfg	\$0.00	\$0.00	\$0.00
3	✓ Hub Levels <u>Notes</u> rh mid low (wheel seal dry)	\$0.00	\$0.00	\$0.00
4	✓ Lights - All <u>Notes</u> LH rear outside 2" marker out	\$0.00	\$0.00	\$0.00
5	✓ Suspension <u>Notes</u> lift axle lift air line to bag spice to bag replace, control box 1/4 line leak	\$0.00	\$0.00	\$0.00
6	✓ other <u>Notes</u> Lift axle control box loose,	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 2307

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 2349

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Dec 9, 2025	Dec 9, 2025		Dec 9, 2025 9:56 PM	Dec 9, 2025 9:56 PM

Line	Task	Parts	Labor	Total		
1	✓ Changed tire on middle right hand inside	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Right front trifurcational bolt tightened and welding	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2025	Dec 13, 2025		Dec 13, 2025 6:13 PM	Dec 19, 2025 9:30 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections <u>Notes</u> middle rh s cam tube spinning	\$0.00	\$0.00	\$0.00
2	✓ Hub Levels <u>Notes</u> hub rh low (replace hub gasket)	\$0.00	\$0.00	\$0.00
3	✓ Lights - All <u>Notes</u> lh rear outside marker out	\$0.00	\$0.00	\$0.00
4	✓ cotter pin MIA rh rear axle	\$0.00	\$0.00	\$0.00
5	✓ slack shims	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jan 9, 2026	Jan 9, 2026		Jan 9, 2026 5:36 PM	Jan 9, 2026 5:36 PM

Line	Task	Parts	Labor	Total
1	✓ Fixed right side tail light bar	\$0.00	\$0.00	\$0.00
2	✓ 2 red lights	\$0.00	\$0.00	\$0.00
3	✓ Installed pig tail	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jan 15, 2026	Jan 15, 2026		Jan 15, 2026 12:04 PM	Jan 15, 2026 5:36 PM

Line	Task	Parts	Labor	Total
1	✓ #6 bunk bolts loose	\$0.00	\$0.00	\$0.00
2	✓ Air leak on middle axle	\$0.00	\$0.00	\$0.00
3	✓ Middle centre light at back of trailer missing	\$0.00	\$0.00	\$0.00
4	✓ Abs wire hanging	\$0.00	\$0.00	\$0.00
5	✓ Right hand bunk light out	\$0.00	\$0.00	\$0.00
6	✓ Winch handle	\$0.00	\$0.00	\$0.00
7	✓ #2 bunk bolt loose	\$0.00	\$0.00	\$0.00
8	✓ Leveling valve	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Rapid response levelling valve	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Jan 30, 2026	Jan 30, 2026		Jan 30, 2026 6:41 PM	Jan 30, 2026 6:41 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	6 blink code			
2	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	middle lh pot bracket cracked			
3	✓ Brakes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	LH rear slack shim			
4	✓ Hub Levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#7 LH , #6 RH low			
5	✓ Middle LH outside tire nfg	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Feb 13, 2026	Feb 13, 2026		Feb 13, 2026 5:24 PM	Feb 13, 2026 5:24 PM

Line	Task	Parts	Labor	Total												
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Service line at front of trailer broke															
2	✓ Brakes	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Front axle brake job															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Q plus shoe kit</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00											
3	✓ Lights - All	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	License plate light out															
4	✓ other	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Loose u bolt rh rear															
5	✓ Saddle cracks	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Front rh crack															

Kropp Contracting
Shop

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

Work Order 2546

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	Feb 27, 2026	Feb 27, 2026		Mar 1, 2026 1:30 PM	Mar 1, 2026 1:30 PM

Line	Task	Parts	Labor	Total
1	✓ Brake Connections	\$0.00	\$0.00	\$0.00
	Notes			
	Middle rh s cam looe			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	License plate light mia			
3	✓ Saddle cracks	\$0.00	\$0.00	\$0.00
	Notes			
	Front rh u bolts loose and ceacked			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

Serial	Tag	Closed Meters
2PLB04845FBL17366	6KX721	

Type	Created	Scheduled	Due	Started	Closed
	May 19, 2026	May 19, 2026		May 20, 2026 5:14 PM	May 27, 2026 6:54 AM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ 2nd bunk bolts LH no washer	\$0.00	\$0.00	\$0.00		
4	✓ LH lift axle hub cap nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	hub cap	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Lift axle not working on switch	\$0.00	\$0.00	\$0.00		
6	✓ Lift axle mounting bolts wrong size	\$0.00	\$0.00	\$0.00		
7	✓ # 4 bunk bolts all loose	\$0.00	\$0.00	\$0.00		
8	✓ Front RH beam NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RH beam	Kropp Shop		1.0	\$0.00	\$0.00
9	✓ middle axle brakes NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00
	Brake Drum	Kropp Shop		2.0	\$0.00	\$0.00
	Csk4120 - SCAM tube peerless (some CC)	Kropp Shop		2.0	\$0.00	\$0.00
	2110 wheel seal	Kropp Shop		2.0	\$0.00	\$0.00
10	✓ middle RH adjuster bar MIA	\$0.00	\$0.00	\$0.00		

T366 - 2015 Peerless

Parent: 868 - 2019 Kenworth t800

CLOSED

11	✓ Rear brakes NFG			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q plus shoe kit	Kropp Shop		2.0	\$0.00	\$0.00
12	✓ move back rear bunk			\$0.00	\$0.00	\$0.00
13	✓ rear rh saddle crack			\$0.00	\$0.00	\$0.00
14	✓ middle lh dust cover mia			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Clamp on dust cover	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ rear lh hub low			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2110 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
16	✓ install peerless mudflaps			\$0.00	\$0.00	\$0.00
17	✓ Middle Lh shock nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00
18	✓ Front rh shock nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	S-20126 - Trailer shock	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00