

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	4,429 hr & 196,551 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2024	Mar 11, 2024		Mar 11, 2024 2:55 PM	Mar 11, 2024 2:55 PM

Line	Task			Parts	Labor	Total
1	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
2	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	4,429 hr & 196,551 km

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	Jun 4, 2024	Jun 4, 2024	Jun 4, 2024	Jun 4, 2024 1:40 PM	Jun 6, 2024 10:33 AM

Line	Task	Parts	Labor	Total		
1	✓ change windshield	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	windshield t880	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
3	✓ Change convex mirror	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Both right and left lower					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	convex mirror t880	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
5	✓ Check diff oil level	\$0.00	\$0.00	\$0.00		
6	✓ Check trans oil levels	\$0.00	\$0.00	\$0.00		
7	✓ Check steer hub oil level	\$0.00	\$0.00	\$0.00		
8	✓ Change cam tube studs	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Steer axle LH 2 broken studs					
9	✓ Replace missing/tore mudflaps	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1127

Cam Nadeau

CLOSED

	24" plastic mudflap	Kropp Shop	2.0	\$0.00	\$0.00
	anti sail bracket	Kropp Shop	1.0	\$0.00	\$0.00
10	✓ Wheel seal leaking		\$0.00	\$0.00	\$0.00
<u>Notes</u>					
	LH steer				
11	✓ replace A/C belt		\$0.00	\$0.00	\$0.00
12	✓ replace fan belt		\$0.00	\$0.00	\$0.00
			Part Cost		\$0.00
			Labor		\$0.00
			Subtotal		\$0.00
			Tax 1 (0.0%)		\$0.00
			Tax 2 (0.0%)		\$0.00
			Credit		(\$0.00)
			Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	4,836 hr & 213,578 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 9, 2024	Jul 9, 2024	Jul 9, 2024	Jul 9, 2024 5:45 AM	Jul 9, 2024 5:45 AM

Line	Task	Parts	Labor	Total
1	✓ Change exhaust gasket	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Change 2 gasket behind turbo			
2	✓ Coolant sensor wiring	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Check coolant and sensor wiring, spread pins			
		Part Cost	\$0.00	
		Labor	\$0.00	
		Subtotal	\$0.00	
		Tax 1 (0.0%)	\$0.00	
		Tax 2 (0.0%)	\$0.00	
		Credit	(\$0.00)	
		Total Cost	\$0.00	

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	4,848 hr & 214,037 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 10, 2024	Jul 10, 2024	Jul 10, 2024	Jul 10, 2024 4:36 AM	Jul 10, 2024 4:36 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,132 hr & 228,577 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 19, 2024	Aug 19, 2024		Aug 19, 2024 1:41 PM	Aug 19, 2024 1:41 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,179 hr & 229,370 km

Type	Created	Scheduled	Due	Started	Closed
Service	Aug 23, 2024	Aug 23, 2024	Aug 23, 2024	Aug 23, 2024 7:37 AM	Aug 29, 2024 11:02 AM

Line	Task	Parts	Labor	Total
1	✓ Bent stake <u>Notes</u> Replaced # 4 RH stake with new	\$0.00	\$0.00	\$0.00
2	✓ saddle crack <u>Notes</u> #8 RHS welded	\$0.00	\$0.00	\$0.00
3	✓ Replace tire <u>Notes</u> #6RHS outside, replaced with used tire	\$0.00	\$0.00	\$0.00
4	✓ Add hub oil <u>Notes</u> #5 LHS lift axle hub low	\$0.00	\$0.00	\$0.00
5	✓ Work Light <u>Notes</u> L/h upper work light out, change assembly	\$0.00	\$0.00	\$0.00
6	✓ Check all fluids	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1252
Nate Vandenberghe

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,246 hr & 229,370 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 31, 2024	Aug 31, 2024		Sep 17, 2024 3:45 AM	Sep 17, 2024 3:45 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,318 hr & 236,741 km

Type	Created	Scheduled	Due	Started	Closed
Service	Sep 25, 2024	Sep 25, 2024	Sep 25, 2024	Sep 25, 2024 4:47 AM	Sep 25, 2024 4:47 AM

Line	Task	Parts	Labor	Total
1	✓ Emergency valve leaking	\$0.00	\$0.00	\$0.00

Notes

Replaced with new SEL110800 on trailer

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop


858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1298

Cam Nadeau

CLOSED



858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,318 hr & 236,741 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 25, 2024	Sep 25, 2024		Sep 25, 2024 5:42 PM	Sep 25, 2024 5:42 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,318 hr & 236,741 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 10, 2024	Oct 10, 2024		Oct 12, 2024 10:37 AM	Oct 12, 2024 10:37 AM

Line	Task	Parts	Labor	Total
1	✓ Front steer shocks loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,481 hr & 246,043 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 18, 2024	Oct 18, 2024		Oct 20, 2024 11:06 AM	Oct 20, 2024 11:06 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
2	✓ Tires	\$0.00	\$0.00	\$0.00		

Notes

front drive RH outside flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,485 hr & 246,265 km

Type	Created	Scheduled	Due	Started	Closed
electrical	Oct 23, 2024	Oct 23, 2024	Oct 23, 2024	Oct 23, 2024 8:24 AM	Oct 23, 2024 8:24 AM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00

Notes

Found green broken wire at plug by the DEF tank,

Bypass wire at plug

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,569 hr & 250,203 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 2, 2024	Nov 2, 2024		Nov 2, 2024 2:22 PM	Nov 2, 2024 2:22 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

Set of 12, steer tires at 150km

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00
steer tires	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Steer Tires	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1449

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,665.2 hr & 255,361.6 km

Type	Scheduled	Due	Started	Closed
	Nov 17, 2024		Nov 17, 2024 3:07 PM	Nov 17, 2024 3:07 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1454
Everett Twin

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,675 hr & 255,859 km

Type	Scheduled	Due	Started	Closed
	Nov 18, 2024		Nov 18, 2024 8:08 PM	Nov 18, 2024 8:08 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,755 hr & 259,639 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 29, 2024	Nov 29, 2024		Nov 29, 2024 8:11 PM	Nov 29, 2024 8:11 PM

Line	Task	Parts	Labor	Total
1	✓ Air Compressor	\$0.00	\$0.00	\$0.00

Notes

Found air leak in hub, pinched supply line off and truck built air within a reasonable time, replaced fan hub and tested air build time

100-120PSI too long to build diag.

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
79A9782 - Horton Fan hub	Kropp Shop	EKW	1.0	\$0.00	\$0.00

2	✓ Mirrors	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

RH upper mirror cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
mirror t880	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1507
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,755 hr & 259,639 km

Type	Scheduled	Due	Started	Closed
	Dec 9, 2024		Dec 9, 2024 7:27 PM	Dec 9, 2024 7:27 PM

Line	Task	Parts	Labor	Total
1	✓ LH top work light out	\$0.00	\$0.00	\$0.00
2	✓ Trailer markers out on bunk	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,898 hr & 267,221 km

Type	Scheduled	Due	Started	Closed
	Dec 15, 2024		Dec 15, 2024 6:54 PM	Dec 15, 2024 6:54 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	LH micky mouse light signals not working			
3	✓ Mirrors	\$0.00	\$0.00	\$0.00

Notes

lh mirror cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	5,898 hr & 267,221 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 17, 2024	Dec 17, 2024		Dec 21, 2024 4:30 PM	Dec 21, 2024 4:30 PM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00

Notes

Def line heater 3 no voltage,, broken wire in harness, Rand
i

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1550

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,066 hr & 267,221 km

Type	Scheduled	Due	Started	Closed
	Jan 5, 2025		Jan 5, 2025 4:04 AM	Jan 5, 2025 4:04 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1552

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,076 hr & 267,221 km

Type	Scheduled	Due	Started	Closed
	Jan 5, 2025		Jan 5, 2025 4:51 PM	Jan 5, 2025 4:51 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,376 hr & 290,783 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 2, 2025	Feb 2, 2025		Feb 2, 2025 10:16 AM	Feb 2, 2025 10:16 AM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00
	Notes			
	heater hose leak			
2	✓ Driveline	\$0.00	\$0.00	\$0.00
	Notes			
	front input yoke loose			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1644

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,376 hr & 290,783 km

Type	Scheduled	Due	Started	Closed
	Feb 2, 2025		Feb 2, 2025 6:32 PM	Feb 2, 2025 6:32 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,461 hr & 294,500 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 9, 2025	Feb 9, 2025		Feb 9, 2025 2:43 PM	Feb 9, 2025 2:43 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	K37-1010-100101120 - 1029 water separator	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,515 hr & 297,191 km

Type	Scheduled	Due	Started	Closed
	Feb 14, 2025		Feb 14, 2025 9:33 AM	Feb 14, 2025 9:33 AM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> front drive diff air lines rubbing	\$0.00	\$0.00	\$0.00
2	✓ Frame & Assembly <u>Notes</u> T rail bolts loose	\$0.00	\$0.00	\$0.00
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
4	✓ Lights - All <u>Notes</u> top rh work light out	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,623 hr & 302,662 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:32 AM	Mar 3, 2025 11:32 AM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00
	Notes			
	airline off of air tank leaking (pin hole)			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1779

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,763 hr & 308,566 km

Type	Scheduled	Due	Started	Closed
	Mar 17, 2025		Mar 17, 2025 8:25 AM	Mar 17, 2025 8:25 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1818

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,838 hr & 308,566 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 29, 2025	Mar 29, 2025		Apr 6, 2025 6:08 AM	Apr 6, 2025 6:08 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	6,841 hr & 312,073 km

Type	Scheduled	Due	Started	Closed
	May 4, 2025		May 4, 2025 1:44 PM	May 4, 2025 1:44 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ change diff filters	\$0.00	\$0.00	\$0.00
4	✓ Replace Belt	\$0.00	\$0.00	\$0.00
Notes				
Ac and fan				
5	✓ Check fluids	\$0.00	\$0.00	\$0.00
6	✓ Air filters	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,004 hr & 321,332 km

Type	Created	Scheduled	Due	Started	Closed
	May 26, 2025	May 26, 2025		May 26, 2025 7:02 PM	May 26, 2025 7:02 PM

Line	Task	Parts	Labor	Total
1	✓ Loose exhaust stack	\$0.00	\$0.00	\$0.00

Notes

Remove heat shield to inspect. Found clamp not attached properly to exhaust, reposition clamps and reinstall heat shield

Technician	Hours	Rate	Cost
Everett Twin	0.0	\$0.00	\$0.00
Part Cost			\$0.00
Labor			\$0.00
Subtotal			\$0.00
Tax 1 (0.0%)			\$0.00
Tax 2 (0.0%)			\$0.00
Credit			(\$0.00)
Total Cost			\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1899

Unassigned

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,080 hr & 323,548 km

Type	Scheduled	Due	Started	Closed
	Jun 6, 2025		Jun 6, 2025 7:21 AM	Jun 6, 2025 7:21 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,236 hr & 335,229 km

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	Jun 18, 2025	Jun 18, 2025		Jun 18, 2025 4:40 AM	Jun 25, 2025 1:51 PM

Line	Task	Parts	Labor	Total
1	✓ change windshield	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
3	✓ S cam u-bolts	\$0.00	\$0.00	\$0.00
	Notes			
	All loose			
4	✓ #4 roof light	\$0.00	\$0.00	\$0.00
	Notes			
	LED not working			
5	✓ Beacon	\$0.00	\$0.00	\$0.00
	Notes			
	Both beacons not working			
6	✓ S-Cam U-bolts loose	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1923

Everett Twin

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,212 hr & 333,956 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 20, 2025	Jun 20, 2025		Jun 20, 2025 7:59 PM	Jun 20, 2025 7:59 PM

Line	Task	Parts	Labor	Total
1	✓ Glue driver side fender back on	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,225 hr & 334,592 km

Type	Scheduled	Due	Started	Closed
	Jun 23, 2025		Jun 23, 2025 7:01 PM	Jun 23, 2025 7:01 PM

Line	Task	Parts	Labor	Total
1	✓ Lights inop	\$0.00	\$0.00	\$0.00

Notes

LH upper work light, splice broken wire

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,236 hr & 335,229 km

Type	Scheduled	Due	Started	Closed
	Jun 25, 2025		Jun 25, 2025 5:58 PM	Jun 25, 2025 5:58 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ RHS exhaust stack loose	\$0.00	\$0.00	\$0.00
---	---------------------------	--------	--------	--------

Notes

Adjust exhaust and tighten clamps, tack weld exhaust on, has come loose 3 other times

2	✓ Cab clearance light INOP	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

Notes

New light

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,236 hr & 335,229 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 1, 2025	Jul 1, 2025		Jul 1, 2025 3:27 PM	Jul 1, 2025 3:27 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,260 hr & 335,350 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 3, 2025	Jul 3, 2025		Jul 3, 2025 8:08 AM	Jul 3, 2025 8:08 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 1985

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,417 hr & 347,020 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 21, 2025	Jul 21, 2025		Jul 21, 2025 4:19 AM	Jul 21, 2025 4:19 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,477 hr & 351,115 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 25, 2025	Jul 25, 2025		Jul 25, 2025 3:34 PM	Jul 25, 2025 3:34 PM

Line	Task	Parts	Labor	Total
1	✓ Top LH mM light out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,479 hr & 351,116 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 28, 2025	Jul 28, 2025		Jul 28, 2025 5:04 PM	Jul 28, 2025 5:04 PM

Line	Task			Parts	Labor	Total
1	✓ Cab filter(s)			\$30.00	\$0.00	\$30.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF55839 - T880 primary cab filter	Kropp Shop		1.0	\$30.00	\$30.00
	AF56102 - T880 secondary cab filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Lights INOP.			\$0.00	\$0.00	\$0.00

Notes

RH upper work light inop. Splice broken wire and test light function

Part Cost	\$30.00
Labor	\$0.00
Subtotal	\$30.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$30.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2037

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,516 hr & 353,433 km

Type	Scheduled	Due	Started	Closed
	Aug 5, 2025		Aug 5, 2025 5:13 AM	Aug 5, 2025 5:13 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,592 hr & 358,508 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 18, 2025	Aug 18, 2025		Aug 18, 2025 4:07 AM	Aug 18, 2025 4:07 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,602 hr & 359,051 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 18, 2025	Aug 18, 2025		Aug 18, 2025 2:16 PM	Aug 18, 2025 2:16 PM

Line	Task	Parts	Labor	Total
1	✓ Air compressor discharge line leaking	\$0.00	\$0.00	\$0.00
2	✓ Rear transmission support wear pads wore out,	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,660 hr & 362,853 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 26, 2025	Aug 26, 2025		Aug 26, 2025 2:08 PM	Aug 26, 2025 2:08 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
2	✓ Top LH Mickey Mouse light marker out			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Mirror cracked, replace			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,763 hr & 369,551 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 10, 2025	Sep 10, 2025		Sep 10, 2025 4:39 PM	Sep 10, 2025 5:11 PM

Line	Task	Parts	Labor	Total
1	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00

Notes

#1 output loose

2	✓ U joint NFG	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
SPL170-4x - SPL170 U joint	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2120

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,782 hr & 369,991 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 14, 2025	Sep 14, 2025		Sep 14, 2025 6:41 PM	Sep 14, 2025 6:41 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,826 hr & 373,617 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 18, 2025	Sep 18, 2025		Sep 18, 2025 5:46 PM	Sep 18, 2025 5:46 PM

Line	Task	Parts	Labor	Total
1	✓ T rail bolts loose	\$0.00	\$0.00	\$0.00
2	✓ 7 wire lift axle plug nfg	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2178

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,903 hr & 378,106 km

Type	Scheduled	Due	Started	Closed
	Oct 4, 2025		Oct 4, 2025 9:47 AM	Oct 4, 2025 9:47 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,903 hr & 378,106 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 6, 2025	Oct 6, 2025		Oct 6, 2025 3:43 PM	Oct 6, 2025 3:43 PM

Line	Task			Parts	Labor	Total
1	✓ Steer Tires			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ ABS codes			\$100.00	\$0.00	\$100.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K181625 - 6' 90 ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00
3	✓ 4" exhaust clamp off turbo leaking			\$0.00	\$0.00	\$0.00
				Part Cost		\$100.00
				Labor		\$0.00
				Subtotal		\$100.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$100.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,991 hr & 382,050 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 3, 2025	Nov 3, 2025		Nov 3, 2025 11:37 AM	Nov 4, 2025 6:33 PM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ S cam tube loose	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LM S cam u bolt loose					
3	✓ Worklight INOP	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Cab filter	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Blow out cab filters					
5	✓ Replace missing/tore mudflaps	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	anti sail bracket	Kropp Shop		1.0	\$0.00	\$0.00
	24" plastic mudflap	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Herbs warranty- replace turbo actuator, re tip injectors, new dpf	\$0.00	\$0.00	\$0.00		
7	✓ Lift axle switch not working	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Refer WO 2237					

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2232
Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	7,992 hr & 382,050 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 4, 2025	Nov 4, 2025		Nov 4, 2025 5:04 PM	Nov 4, 2025 6:34 PM

Line	Task	Parts	Labor	Total
1	✓ Spare switch INOP	\$0.00	\$0.00	\$0.00

Notes

Fuse blown, replace fuse and inspect 7-wire harness for marks/damage/blemishes. Unable to find damaged harness. Perform wiggle test and found short. Replace approx 6ft of 7 wire plug for lift axle/clam dumps and 7 wire male/female plug. Re-tape airlines/cords together

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
7 wire trailer cord	Kropp Shop		1.0	\$0.00	\$0.00
7 wire male plug	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2242

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,012 hr & 383,074 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 9, 2025	Nov 9, 2025		Nov 9, 2025 7:43 PM	Nov 9, 2025 7:43 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,057 hr & 385,541 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 18, 2025	Nov 18, 2025		Nov 18, 2025 12:51 PM	Nov 18, 2025 12:51 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,294 hr & 397,221 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 9:43 AM	Dec 14, 2025 11:06 AM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	air dryer heater re wire					
2	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	power steering level low					
3	✓ Engine	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	check engine light on					
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
5	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	top rh work light out					
6	✓ Other	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh side front mudflap anti sail loose					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	anti sail bracket	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ Steering System	\$0.00	\$0.00	\$0.00		

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Notes

bolt can wait till spring tube not loose- TC

rh Steer s cam mount bolt MIA, check toe looks like bar is bent

8	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

flat front drive inside LH

9	✓ loose leveling rod rear	\$0.00	\$0.00	\$0.00
---	---------------------------	--------	--------	--------

10	✓ back of bellows exhaust leak	\$0.00	\$0.00	\$0.00
----	--------------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
90-0012 - 4" v clamp	Kropp Shop		1.0	\$0.00	\$0.00
2866636 - 4" exhaust gasket	Kropp Shop		1.0	\$0.00	\$0.00

11	✓ coolant leak ontop of rear end of EGR cooler area	\$0.00	\$0.00	\$0.00
----	---	--------	--------	--------

12	✓ rh stack bushing NFG	\$0.00	\$0.00	\$0.00
----	------------------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2388

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,294 hr & 397,221 km

Type	Scheduled	Due	Started	Closed
	Dec 17, 2025		Dec 17, 2025 4:23 AM	Dec 17, 2025 4:23 AM

Line	Task	Parts	Labor	Total
1	✓ Air governor line broke off	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,461 hr & 405,428 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 8, 2026	Jan 8, 2026		Jan 8, 2026 6:00 AM	Jan 8, 2026 6:00 AM

Line	Task	Parts	Labor	Total												
1	✓ Oil change	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>LF14000 - Cummins oil filter</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00											
2	✓ Drive brakes not holding on hill	\$0.00	\$0.00	\$0.00												
3	✓ Def code: def pump speed pump voltage erratics	\$0.00	\$0.00	\$0.00												

Notes

Broken/green wire by LH steer fender

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,461 hr & 405,428 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 15, 2026	Jan 15, 2026		Jan 17, 2026 6:42 AM	Jan 17, 2026 6:42 AM

Line	Task	Parts	Labor	Total		
1	✓ Fix bent work light right top	\$0.00	\$0.00	\$0.00		
2	✓ Tie up airlines on front differential	\$0.00	\$0.00	\$0.00		
3	✓ Left micky no blinky	\$0.00	\$0.00	\$0.00		
4	✓ Cab filters plugged	\$30.00	\$0.00	\$30.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF55839 - T880 primary cab filter	Kropp Shop		1.0	\$30.00	\$30.00
	AF56102 - T880 secondary cab filter	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
		Part Cost				\$30.00
		Labor				\$0.00
		Subtotal				\$30.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$30.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,618 hr & 413,055 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2026	Feb 1, 2026		Feb 1, 2026 8:27 PM	Feb 1, 2026 8:27 PM

Line	Task	Parts	Labor	Total
1	✓ Check all fluid levels <u>Notes</u> power steering level low	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> lh marker light on headache rack out	\$0.00	\$0.00	\$0.00
3	✓ Steering System <u>Notes</u> steering shaft u joint nfg	\$0.00	\$0.00	\$0.00
4	✓ Wheels & Rims <u>Notes</u> rh rear outside rim cracked	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2525

Aiden Kenny

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,670 hr & 415,824 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 7, 2026	Feb 7, 2026		Feb 7, 2026 5:36 PM	Feb 7, 2026 5:37 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2529

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,689 hr & 416,706 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 11, 2026	Feb 11, 2026		Feb 11, 2026 6:36 PM	Feb 11, 2026 6:36 PM

Line	Task	Parts	Labor	Total
1	✓ Engine light	\$0.00	\$0.00	\$0.00
2	✓ Broken brake pot front right	\$0.00	\$0.00	\$0.00
3	✓ Front left out of adjustment	\$0.00	\$0.00	\$0.00
4	✓ Broken brake pot back left	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2569

Aiden Kenny

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,742 hr & 419,107 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 24, 2026	Feb 24, 2026		Feb 24, 2026 10:27 AM	Feb 24, 2026 10:27 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00

Notes

front diff lh air lines rubbing

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,742 hr & 420,312 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2026	Feb 25, 2026		Feb 25, 2026 6:13 PM	Feb 25, 2026 6:13 PM

Line	Task			Parts	Labor	Total
1	✓ Middle LH outside drive flat			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,742 hr & 420,312 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 13, 2026	Mar 13, 2026		Mar 13, 2026 8:38 AM	Mar 13, 2026 8:38 AM

Line	Task	Parts	Labor	Total		
1	✓ Mux solenoid bank not functioning	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5603-02-020 - Mux solenoid bank 2	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,943 hr & 428,414 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 20, 2026	Mar 20, 2026		Mar 24, 2026 10:44 AM	Mar 25, 2026 7:39 AM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> Front left drive air lines chaffing	\$0.00	\$0.00	\$0.00
2	✓ Belts and Hoses <u>Notes</u> Lower rad hose leaking	\$0.00	\$0.00	\$0.00
3	✓ Brake Accessories <u>Notes</u> Brake pot nut lose front right hand	\$0.00	\$0.00	\$0.00
4	✓ Check all fluid levels <u>Notes</u> Power steering	\$0.00	\$0.00	\$0.00
5	✓ Exhaust <u>Notes</u> Chaffing on tranny cooler	\$0.00	\$0.00	\$0.00
6	✓ Front Axle <u>Notes</u> Broken bolts on scam bracket RH	\$0.00	\$0.00	\$0.00
7	✓ Lights - All	\$0.00	\$0.00	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Notes

Right hand top work light, micky mouse light grommet nfg

8	✓ Other	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

Needs DEF

9	✓ Steering System	\$0.00	\$0.00	\$0.00
---	-------------------	--------	--------	--------

Notes

Power steering leaks

10	✓ Oil change	\$0.00	\$0.00	\$0.00
----	--------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00

11	✓ diagnose Check engine light	\$0.00	\$0.00	\$0.00
----	-------------------------------	--------	--------	--------

12	✓ Fifth wheel cracked	\$0.00	\$0.00	\$0.00
----	-----------------------	--------	--------	--------

13	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
----	----------------------------	--------	--------	--------

14	✓ Adjust 5th wheel	\$0.00	\$0.00	\$0.00
----	--------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	8,943 hr & 428,414 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 16, 2026	Apr 16, 2026		Apr 16, 2026 6:04 AM	Apr 16, 2026 6:04 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Cab lights not working, headache rack markers not working	\$0.00	\$0.00	\$0.00
---	---	--------	--------	--------

Notes

Fuse blown, found short in headache rack

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	9,101 hr & 436,700 km

Type	Created	Scheduled	Due	Started	Closed
	May 13, 2026	May 13, 2026		May 21, 2026 5:18 PM	May 21, 2026 5:18 PM

Line	Task	Parts	Labor	Total		
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
3	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ change belts	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	ac belt	Kropp Shop		1.0	\$0.00	\$0.00
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ check all fluid levels	\$0.00	\$0.00	\$0.00		
6	✓ change air filter	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filter T880	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ Front rh steer scam tube bolts broke	\$0.00	\$0.00	\$0.00		
8	✓ middle Lh drive s cam u bolt	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2-1/2 u bolt	Kropp Shop		1.0	\$0.00	\$0.00
9	✓ front rh drive brake pot mounted loose	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

10	✓ air lines rubbing on air dyer guard			\$0.00	\$0.00	\$0.00
11	✓ front diff Lh brake pot supply line rubbing on diff			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	hab 6 28 fs - Rubber air brake supply	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ Tie up hyd clutch line to brackets			\$0.00	\$0.00	\$0.00
13	✓ Front t rail bolts loose			\$0.00	\$0.00	\$0.00
14	✓ Power steering low			\$0.00	\$0.00	\$0.00
15	✓ Discharge line clamp broke			\$0.00	\$0.00	\$0.00
16	✓ Water on fuel plug hanging			\$0.00	\$0.00	\$0.00
17	✓ check engine light on			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5492073 - Dfn pressure sensor	Kropp Shop		1.0	\$0.00	\$0.00
18	✓ Fuel tank gaskets leaking			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Fuel cap gasket	Kropp Shop		2.0	\$0.00	\$0.00
19	✓ bottom rh work light			\$0.00	\$0.00	\$0.00
20	✓ rh headlight housing full of shit			\$0.00	\$0.00	\$0.00
21	✓ coolant leak by heater core			\$0.00	\$0.00	\$0.00
22	✓ cab air filters			\$30.00	\$0.00	\$30.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF55839 - T880 primary cab filter	Kropp Shop		1.0	\$30.00	\$30.00
	AF56102 - T880 secondary cab filter	Kropp Shop		1.0	\$0.00	\$0.00
23	✓ rh wiper falling off windshield			\$0.00	\$0.00	\$0.00
24	✓ Rh stack handle			\$0.00	\$0.00	\$0.00
25	✓ adjust 5th wheel			\$0.00	\$0.00	\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

26	✓ Lh mirror glass			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
27	✓ middle marker out in headache rack			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3050 - 2" red marker light	Kropp Shop		1.0	\$0.00	\$0.00
28	✓ Red glad hand rubber mia			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	glad hand rubber	Kropp Shop		1.0	\$0.00	\$0.00
29	✓ Rear spring pins wore out			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	B13-1002 - Spring pin bushing (T800,T880)	Kropp Shop		4.0	\$0.00	\$0.00
	B65-6008 - Rear spring pin (T800,T880)	Kropp Shop		4.0	\$0.00	\$0.00
30	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
31	✓ middle diff wishbone nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$30.00
Labor	\$0.00
Subtotal	\$30.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$30.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	9,321 hr & 446,434 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 7, 2026	Jul 7, 2026		Jul 7, 2026 4:55 AM	Jul 7, 2026 4:55 AM

Line	Task			Parts	Labor	Total
1	✓ Replace steady bearing			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	SPL250 Strap - SPL 250 Strap Kit	Kropp Shop		2.0	\$0.00	\$0.00
	Steady bearing	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2779

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	9,376 hr & 446,434 km

Type	Scheduled	Due	Started	Closed
	Jul 31, 2026		Jul 31, 2026 6:10 AM	Jul 31, 2026 6:10 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

Work Order 2781

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	9,549 hr & 446,434 km

Type	Scheduled	Due	Started	Closed
	Jul 31, 2026		Jul 31, 2026 8:36 AM	Jul 31, 2026 8:36 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

858 - 2023 Kenworth T880

Parent: T809 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EXXPJ999794	A46135	9,637 hr & 459,529 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 8, 2026	Aug 8, 2026		Aug 8, 2026 5:13 AM	Aug 8, 2026 5:13 AM

Line	Task	Parts	Labor	Total
1	✓ Battery	\$0.00	\$0.00	\$0.00

Notes

Change 1 battery. Shorted to ground

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00