

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	8,529 hr & 384,681 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 16, 2024	Mar 16, 2024		Mar 16, 2024 1:13 PM	Mar 16, 2024 1:13 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

greased t413

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	8,760 hr & 395,449 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 22, 2024	Apr 22, 2024		Apr 22, 2024 12:10 PM	Apr 25, 2024 6:21 AM

Line	Task	Parts			Labor	Total
1	✓ Grease truck and trailer	\$0.00			\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		4.0	\$0.00	\$0.00
2	✓ Oil change	\$0.00			\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ change rear plywood	\$0.00			\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	plywood sheet	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ brake pot	\$0.00			\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ middle drive wishbone bolts	\$0.00			\$0.00	\$0.00
6	✓ loose yoke on diff	\$0.00			\$0.00	\$0.00
	Notes					
	front diff output middle diff input					
7	✓ change diff filters	\$0.00			\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	LF3311 - Rockwell diff filter	Kropp Shop	2.0	\$0.00	\$0.00	
8	✓ broken exhaust clamp by bellows		\$0.00	\$0.00	\$0.00	
9	✓ RH steer wheel seal		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5327 wheel seal	Kropp Shop		1.0	\$0.00	\$0.00
	80 w 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00
10	✓ replace fan belt		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ replace air filters		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filter T880	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ change windshield		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	windshield t880	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ RH stack bushing		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
14	✓ RH convex mirror cracked		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	convex mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ T rail bolts loose		\$0.00	\$0.00	\$0.00	
16	✓ Loose fender LH drive		\$0.00	\$0.00	\$0.00	
17	✓ grease 5th wheel saddles		\$0.00	\$0.00	\$0.00	

Notes

Replaced LH grease nipple

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

18	✓ Change cab air filters			\$30.00	\$0.00	\$30.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF55839 - T880 primary cab filter	Kropp Shop		1.0	\$30.00	\$30.00
19	✓ DPF cleaning			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	cleaned DPF	Kropp Shop		1.0	\$0.00	\$0.00
	Cleaned DOC	Kropp Shop		1.0	\$0.00	\$0.00
	5417859 - Cummins Can gaskets	Kropp Shop		1.0	\$0.00	\$0.00
	2880215 - DOC inlet gasket 5"	Kropp Shop		1.0	\$0.00	\$0.00
20	✓ DEF codes			\$0.00	\$0.00	\$0.00

Notes

diff pressure code, dpf cleaning required

intake temp short code broken wire on inlet temp sensor

Part Cost	\$30.00
Labor	\$0.00
Subtotal	\$30.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$30.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	8,786 hr & 396,384 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 29, 2024	Apr 29, 2024		Apr 29, 2024 6:16 AM	Apr 29, 2024 6:16 AM

Line	Task			Parts	Labor	Total
1	✓ RH stack pin broke			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	8,906 hr & 402,491 km

Type	Created	Scheduled	Due	Started	Closed
	May 21, 2024	May 21, 2024		May 23, 2024 6:47 AM	May 23, 2024 6:47 AM

Line	Task	Parts	Labor	Total
1	✓ Transmission blown, remove and replace	\$0.00	\$0.00	\$0.00

Notes

Used 848 grader tranny

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
RTLO-18918B - Transmission	Kropp Shop		1.0	\$0.00	\$0.00
309701-25 - Eaton solo clutch	Kropp Shop		1.0	\$0.00	\$0.00
CD-50 - Transmission oil	Kropp Shop		1.0	\$0.00	\$0.00
Read support bar wear pads t880	Kropp Shop		2.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1120

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	8,906 hr & 402,491 km

Type	Scheduled	Due	Started	Closed
	May 27, 2024		May 27, 2024 7:14 AM	May 27, 2024 7:14 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	9,197 hr & 415,717 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 10, 2024	Jul 10, 2024		Jul 10, 2024 3:06 PM	Jul 10, 2024 3:06 PM

Line	Task			Parts	Labor	Total
1	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
2	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1182
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	9,197 hr & 415,717 km

Type	Scheduled	Due	Started	Closed
	Jul 12, 2024		Jul 12, 2024 7:27 AM	Jul 12, 2024 7:27 AM

Line	Task	Parts	Labor	Total
1	✓ Clean out rad, truck running hot	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	9,619 hr & 435,275 km

Type	Created	Scheduled	Due	Started	Closed
electrical	Aug 9, 2024	Aug 9, 2024	Aug 9, 2024	Aug 9, 2024 3:47 PM	Aug 28, 2024 7:42 PM

Line	Task	Parts	Labor	Total
1	✓ Headlight not working <u>Notes</u> Changed low beam led	\$0.00	\$0.00	\$0.00
2	✓ Broken door stop <u>Notes</u> LH drivers door	\$0.00	\$0.00	\$0.00
3	✓ Oil change	\$0.00	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
5	✓ Auxiliary transmission gears broke	\$0.00	\$0.00	\$0.00
6	✓ Middle drive LH shock broke off	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	9,561 hr & 433,003 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 19, 2024	Aug 19, 2024		Aug 19, 2024 3:09 PM	Aug 19, 2024 3:09 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ brake pot	\$0.00	\$0.00	\$0.00

Notes

Front LH drive

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	9,580 hr & 434,230 km

Type	Created	Scheduled	Due	Started	Closed
Tire	Aug 21, 2024	Aug 21, 2024	Aug 21, 2024	Aug 21, 2024 6:09 AM	Aug 21, 2024 10:41 AM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00

Notes

#7LHS inside tire replace

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,002 hr & 454,816 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 16, 2024	Oct 16, 2024		Oct 16, 2024 6:48 PM	Oct 16, 2024 6:48 PM

Line	Task			Parts	Labor	Total
1	✓ LH mirror cracked			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1350

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,002 hr & 454,816 km

Type	Scheduled	Due	Started	Closed
	Oct 20, 2024		Oct 20, 2024 9:38 AM	Oct 20, 2024 9:38 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Steer Tires	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1370

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,420 hr & 455,758 km

Type	Scheduled	Due	Started	Closed
	Oct 24, 2024		Oct 24, 2024 8:43 AM	Oct 24, 2024 8:43 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1371

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,420 hr & 455,758 km

Type	Scheduled	Due	Started	Closed
	Oct 24, 2024		Oct 24, 2024 8:44 AM	Oct 24, 2024 8:44 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1403
Nate Vandenberghe, Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,420 hr & 460,655 km

Type	Scheduled	Due	Started	Closed
	Nov 2, 2024		Nov 2, 2024 7:39 PM	Nov 2, 2024 7:39 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> middle axle chafing	\$0.00	\$0.00	\$0.00
2	✓ Brake Accessories <u>Notes</u> rh scam bracket rear axle	\$0.00	\$0.00	\$0.00
3	✓ Rear End <u>Notes</u> rear diff wishbone nfg	\$0.00	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1451

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,420 hr & 460,655 km

Type	Scheduled	Due	Started	Closed
	Nov 17, 2024		Nov 17, 2024 3:08 PM	Nov 17, 2024 3:08 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,420 hr & 474,814 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 25, 2024	Nov 25, 2024		Nov 25, 2024 4:37 PM	Nov 25, 2024 4:37 PM

Line	Task			Parts	Labor	Total
1	✓ LH signal out on hood			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4157 bulb	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1470
Everett Twin, Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,420 hr & 474,814 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 28, 2024	Nov 28, 2024		Nov 29, 2024 11:04 AM	Nov 29, 2024 11:04 AM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00

Notes

Flat tire on trailer not truck

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,566 hr & 485,318 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 13, 2024	Dec 13, 2024		Dec 14, 2024 10:10 AM	Dec 14, 2024 10:10 AM

Line	Task			Parts	Labor	Total
1	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Lights - All			\$0.00	\$0.00	\$0.00
	<u>Notes</u>					
	Mickey mouse light short					
3	✓ Mirrors			\$0.00	\$0.00	\$0.00
	<u>Notes</u>					
	lh convex broke					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	convex mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,566 hr & 485,318 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 17, 2024	Dec 17, 2024		Dec 17, 2024 10:50 PM	Dec 17, 2024 10:50 PM

Line	Task	Parts	Labor	Total
1	✓ No heat in cab	\$0.00	\$0.00	\$0.00

Notes

Cleaned out blower fan checked blending valve and heat works

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1569

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,822 hr & 498,144 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 14, 2025	Jan 14, 2025		Jan 14, 2025 4:04 PM	Jan 14, 2025 4:04 PM

Line	Task	Parts	Labor	Total
1	✓ LH mirror NFG	\$0.00	\$0.00	\$0.00
2	✓ LH middle brake pot NFG	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,862 hr & 500,193 km

Type	Scheduled	Due	Started	Closed
	Jan 17, 2025		Jan 17, 2025 6:01 PM	Jan 17, 2025 6:01 PM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	acc drive belt			
2	✓ Driveline	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	1st diff output yoke loose			
3	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	lh t rail bolt			
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
5	✓ Oil change	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1611

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,862 hr & 500,193 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 25, 2025	Jan 25, 2025		Jan 25, 2025 9:21 AM	Jan 25, 2025 9:21 AM

Line	Task	Parts	Labor	Total		
1	✓ RH rear drive air bag blown	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	9501 - drive airbag	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1614

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	10,957 hr & 504,582 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 26, 2025	Jan 26, 2025		Jan 26, 2025 2:02 PM	Jan 26, 2025 2:02 PM

Line	Task	Parts	Labor	Total
1	✓ 5rh air bag	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	11,009 hr & 506,764 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 1, 2025 10:06 AM	Feb 1, 2025 10:06 AM

Line	Task	Parts	Labor	Total
1	✓ Defroster	\$0.00	\$0.00	\$0.00

Notes

blows cold on defrost... recirc blows heat change HAVAC module

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
f21-1047-10012 - t880 HVAC control	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Front Axle	\$0.00	\$0.00	\$0.00
---	--------------	--------	--------	--------

Notes

RH steer shock nfg

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
65175 - t880 steer shock	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	11,143.7 hr & 512,178 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 12, 2025	Feb 12, 2025		Feb 12, 2025 8:14 PM	Feb 12, 2025 8:14 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00
	Notes			
	RH front drive pot line leaking			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	11,344 hr & 522,296 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 3, 2025 11:45 AM	Mar 3, 2025 11:45 AM

Line	Task	Parts	Labor	Total		
1	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front diff low					
2	✓ Driveline	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	middle diff output yoke loose					
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
4	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	top rh work light out					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Parking Brake	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	front RH pot NFH					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Rear End	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rear diff wishbone loose bolts					

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 1718

Everett Twin

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	11,408 hr & 525,013 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 8, 2025	Mar 8, 2025		Mar 8, 2025 6:53 PM	Mar 8, 2025 6:53 PM

Line	Task	Parts	Labor	Total		
1	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	K37-1029 - Water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	11,701 hr & 537,464 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 25, 2025	Apr 25, 2025		Apr 25, 2025 7:49 AM	Apr 25, 2025 10:31 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ Check transmission oil level	\$0.00	\$0.00	\$0.00
3	✓ ABS codes	\$0.00	\$0.00	\$0.00

Notes

broken wire on LH rear drive, RH rear drive, and LH middle

4	✓ stability control system codes	\$0.00	\$0.00	\$0.00
5	✓ check diff level	\$0.00	\$0.00	\$0.00
6	✓ Check engine light on	\$0.00	\$0.00	\$0.00

Notes

3133 outlet pressure voltage high...

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5492073 - Dfn pressure sensor	Kropp Shop		1.0	\$0.00	\$0.00

7	✓ High pressure return line leaking	\$0.00	\$0.00	\$0.00
8	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
9	✓ replace air filters	\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
air filter T880	Kropp Shop		1.0	\$0.00	\$0.00

10	✓ replace fan belt	\$0.00	\$0.00	\$0.00
11	✓ Replace cab filters	\$30.00	\$0.00	\$30.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	AF55839 - T880 primary cab filter	Kropp Shop		1.0	\$30.00	\$30.00
	AF56102 - T880 secondary cab filter	Kropp Shop		1.0	\$0.00	\$0.00
12	✓ change diff filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
13	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
Part Cost						\$30.00
Labor						\$0.00
Subtotal						\$30.00
Tax 1 (0.0%)						\$0.00
Tax 2 (0.0%)						\$0.00
Credit						(\$0.00)
Total Cost						\$30.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	11,739 hr & 539,241 km

Type	Created	Scheduled	Due	Started	Closed
electrical	May 8, 2025	May 8, 2025		May 8, 2025 5:13 AM	May 8, 2025 5:18 AM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ DEF codes	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

Scan and diagnose codes

2	✓ DEF Pump	\$0.00	\$0.00	\$0.00
---	------------	--------	--------	--------

Notes

Failed pump, will not prime

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5506956RX - Pump, doser	Kropp Shop	EKW	1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,200 hr & 543,597 km

Type	Created	Scheduled	Due	Started	Closed
Service	May 20, 2025	May 20, 2025		May 20, 2025 5:07 AM	May 20, 2025 5:07 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,200 hr & 558,594 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jun 18, 2025	Jun 18, 2025		Jun 18, 2025 9:51 AM	Jun 23, 2025 5:51 PM

Line	Task	Parts	Labor	Total		
1	✓ No Diff lock	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Blown MUX fuse					
2	✓ Replace tire	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Replace #1 LHS steer axle tire, with a matched takeoff 15/32 tread left					
3	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	#1input loose					
4	✓ Chassis node shorted	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5603-01-020 - Base 1 kit (node for EOA solenoids)	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,367 hr & 573,404 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 24, 2025	Jul 24, 2025		Jul 24, 2025 5:49 AM	Jul 24, 2025 5:49 AM

Line	Task	Parts	Labor	Total
1	✓ Blower motor making noise	\$0.00	\$0.00	\$0.00

Notes

Vibrating, clean out the housing

2	✓ Change cab air filters	\$30.00	\$0.00	\$30.00
---	--------------------------	---------	--------	---------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
AF55839 - T880 primary cab filter	Kropp Shop		1.0	\$30.00	\$30.00
AF56102 - T880 secondary cab filter	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$30.00
Labor	\$0.00
Subtotal	\$30.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$30.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2011
Sam Hawksley, Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,390 hr & 574,865 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 28, 2025	Jul 28, 2025		Jul 28, 2025 5:39 AM	Jul 28, 2025 5:39 AM

Line	Task	Parts	Labor	Total		
1	✓ Water pump core leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5719751 - X15 water pump core	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,390 hr & 574,865 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 31, 2025	Jul 31, 2025		Aug 1, 2025 9:56 AM	Aug 1, 2025 9:56 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Loose brake pot bolt axel 4 rh	\$0.00	\$0.00	\$0.00
3	✓ Adjust brakes	\$0.00	\$0.00	\$0.00
4	✓ Engine lights	\$0.00	\$0.00	\$0.00
5	✓ Hood shock rh side	\$0.00	\$0.00	\$0.00
6	✓ Loose t rail bolt	\$0.00	\$0.00	\$0.00
7	✓ Broken bungee	\$0.00	\$0.00	\$0.00
8	✓ Loose exhust clamp	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,564 hr & 585,244 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 18, 2025	Aug 18, 2025		Aug 18, 2025 4:07 AM	Aug 18, 2025 4:07 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,746 hr & 595,660 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 2, 2025	Sep 2, 2025		Sep 3, 2025 2:03 PM	Sep 3, 2025 2:03 PM

Line	Task			Parts	Labor	Total
1	✓ Steer Tires			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ Exhaust leak			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4" exhaust hanger clamp	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Batteries NFG			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Group 31S battery	Kropp Shop		4.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2097

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,746 hr & 595,660 km

Type	Scheduled	Due	Started	Closed
	Sep 3, 2025		Sep 3, 2025 2:06 PM	Sep 3, 2025 2:06 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2118

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,841 hr & 601,846 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 14, 2025	Sep 14, 2025		Sep 14, 2025 6:40 PM	Sep 14, 2025 6:40 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,851 hr & 602,441 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 15, 2025	Sep 15, 2025		Sep 15, 2025 5:39 PM	Sep 15, 2025 5:40 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Window switch INOP	\$0.00	\$0.00	\$0.00
---	----------------------	--------	--------	--------

Notes

Found open circuit from door harness to window switch

2	✓ Scale line leaking	\$0.00	\$0.00	\$0.00
---	----------------------	--------	--------	--------

Notes

Replace both scale line fittings

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,855 hr & 602,469 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 16, 2025	Sep 16, 2025		Sep 16, 2025 7:01 PM	Sep 16, 2025 7:01 PM

Line	Task			Parts	Labor	Total
1	✓ Front diff piled up			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Rockwell diff	Kropp Shop		1.0	\$0.00	\$0.00
	75 W 90 gear oil	Kropp Shop		20.0	\$0.00	\$0.00
	Axle gasket	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ Front rh inside drive nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,864 hr & 603,056 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 17, 2025	Sep 17, 2025		Sep 17, 2025 3:16 PM	Sep 17, 2025 3:17 PM

Line	Task	Parts	Labor	Total
1	✓ Loose Scam U-bolt	\$0.00	\$0.00	\$0.00

Notes

RM, RR, LR & LM

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
MC-250 - 2.5" exhaust clamp	Kropp Shop		3.0	\$0.00	\$0.00

2	✓ Reseal power divider	\$0.00	\$0.00	\$0.00
---	------------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	12,909 hr & 605,637 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 21, 2025	Sep 21, 2025		Sep 22, 2025 8:16 AM	Sep 22, 2025 8:16 AM

Line	Task	Parts	Labor	Total		
1	✓ Rh rear drive inside flat	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		2.0	\$0.00	\$0.00
2	✓ Front power divider reseal (et warranty)	\$0.00	\$0.00	\$0.00		
3	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		11.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,004 hr & 610,214 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 2, 2025	Oct 2, 2025		Oct 2, 2025 2:12 PM	Oct 2, 2025 2:44 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Air filters	\$0.00	\$0.00	\$0.00
---	---------------	--------	--------	--------

Notes

Blow out air filter

2	✓ Lift axle MUX solenoid NFG	\$0.00	\$0.00	\$0.00
---	------------------------------	--------	--------	--------

Notes

Swap lift axle solenoid airline to PTO MUX solenoid, reprogram ECM to use same switch

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,004 hr & 610,214 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 3, 2025	Oct 3, 2025		Oct 3, 2025 6:35 AM	Oct 3, 2025 6:35 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,177 hr & 619,318 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 28, 2025	Oct 28, 2025		Oct 29, 2025 7:31 AM	Oct 31, 2025 9:07 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ Rear r-12 valve broken	\$0.00	\$0.00	\$0.00
3	✓ Rad leaking	\$0.00	\$0.00	\$0.00
4	✓ Water pump pipe leaking	\$0.00	\$0.00	\$0.00
5	✓ Cab heat weak	\$0.00	\$0.00	\$0.00
6	✓ Breather tubes tore off	\$0.00	\$0.00	\$0.00
7	✓ Grease 5th wheel riser	\$0.00	\$0.00	\$0.00
8	✓ Exhaust clamp and gasket on bellows pipe	\$0.00	\$0.00	\$0.00
9	✓ Topped up diff	\$0.00	\$0.00	\$0.00
10	✓ Replaced coolant reservoir	\$0.00	\$0.00	\$0.00
11	✓ New right hand convex mirror	\$0.00	\$0.00	\$0.00
12	✓ Fixed tail light bar	\$0.00	\$0.00	\$0.00
13	✓ Grease fifth wheel and free up frozen grease zirks	\$0.00	\$0.00	\$0.00
Technician		Hours	Rate	Cost
Everett Twin		0.0	\$0.00	\$0.00
14	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2218
Sam Hawksley, Aiden Kenny

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,177 hr & 619,318 km

Type	Scheduled	Due	Started	Closed
	Nov 21, 2025		Nov 21, 2025 8:31 PM	Nov 21, 2025 8:31 PM

Line	Task	Parts	Labor	Total		
1	✓ Bellows pipe cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Rear headache rack markers not working	\$0.00	\$0.00	\$0.00		

Notes

Sammy found loose wire end in junction box

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,483 hr & 635,769 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 30, 2025	Nov 30, 2025		Nov 30, 2025 5:41 AM	Nov 30, 2025 5:41 AM

Line	Task	Parts	Labor	Total		
1	✓ Battery	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	battery box bolt MIA					
2	✓ Driveline	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	trans output yoke loose					
3	✓ Exhaust	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	RH stack loose					
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
5	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lh rear lightbar out					
6	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ Parking Brake	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	center drive lh s cam u bolt					

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

8	✓ Steering System	\$0.00	\$0.00	\$0.00
---	-------------------	--------	--------	--------

Notes

LH drag link

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
346-632 - T880 LH drag link (283/284)	Kropp Shop		1.0	\$0.00	\$0.00

9	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

lh mid drive outside low

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,177 hr & 619,318 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 8, 2025	Dec 8, 2025		Dec 9, 2025 9:58 PM	Dec 9, 2025 9:58 PM

Line	Task	Parts	Labor	Total
1	✓ Middle left outside drive	\$0.00	\$0.00	\$0.00
2	✓ Tightened loose rad	\$0.00	\$0.00	\$0.00
3	✓ Right hand work light missing	\$0.00	\$0.00	\$0.00
4	✓ Tightened micky mouse light bracket	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,634 hr & 642,557 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 5:58 PM	Dec 14, 2025 5:58 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines Notes loose levelling valve, inspect leveling valves	\$0.00	\$0.00	\$0.00
2	✓ Belts and Hoses Notes inspect coolant lines on def pump	\$0.00	\$0.00	\$0.00
3	✓ Check all fluid levels Notes low coolant	\$0.00	\$0.00	\$0.00
4	✓ Generator Notes alternator loose	\$0.00	\$0.00	\$0.00
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
6	✓ Lights - All Notes rear skirt light wires hanging, right hand bottom work light	\$0.00	\$0.00	\$0.00
7	✓ Mirrors Notes right hand mirror	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2374
Terren Page, Sam Hawksley
CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2396
Trent Court, Sam Hawksley
CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,653 hr & 643,146 km

Type	Scheduled	Due	Started	Closed
	Dec 20, 2025		Dec 20, 2025 11:00 AM	Dec 20, 2025 11:00 AM

Line	Task	Parts	Labor	Total
1	✓ No heat	\$0.00	\$0.00	\$0.00
2	✓ Change hvac box... temp door stripped	\$0.00	\$0.00	\$0.00
3	✓ Change heater core	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2404

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,716 hr & 646,262 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 29, 2025	Dec 29, 2025		Dec 29, 2025 10:36 AM	Dec 29, 2025 10:36 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,827 hr & 651,907 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 9, 2026	Jan 9, 2026		Jan 9, 2026 5:38 PM	Jan 9, 2026 5:38 PM

Line	Task	Parts	Labor	Total		
1	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Change out compressor line as it was plugged up	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,838 hr & 652,289 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 12, 2026	Jan 12, 2026		Jan 12, 2026 7:15 PM	Jan 12, 2026 7:15 PM

Line	Task	Parts	Labor	Total		
1	✓ D rate	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Doser lost communication code, broken wire in harness at “Y”					
2	✓ Lose yoak on transmission	\$0.00	\$0.00	\$0.00		
3	✓ Check diff breather on first diff	\$0.00	\$0.00	\$0.00		
4	✓ Chaffed air lines on diff	\$0.00	\$0.00	\$0.00		
5	✓ Power steering cap	\$0.00	\$0.00	\$0.00		
6	✓ Intake nox sensor code	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3687930RX - Inlet NOX sensor	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Subtotal	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2467

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,838 hr & 652,289 km

Type	Scheduled	Due	Started	Closed
	Jan 18, 2026		Jan 18, 2026 2:49 PM	Jan 18, 2026 2:49 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2476
Sam Hawksley, Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	13,948 hr & 658,114 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 23, 2026	Jan 23, 2026		Jan 23, 2026 5:44 PM	Jan 23, 2026 5:44 PM

Line	Task	Parts	Labor	Total
1	✓ tranny oil milky	\$0.00	\$0.00	\$0.00

Notes

by pass tranny cooler, and replaced with new cd50, test drove and passed

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,033 hr & 662,802 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2026	Jan 31, 2026		Jan 31, 2026 3:18 PM	Jan 31, 2026 4:54 PM

Line	Task	Parts	Labor	Total
1	✓ Battery <u>Notes</u> battery box bolt MIA	\$0.00	\$0.00	\$0.00
2	✓ Brake Accessories <u>Notes</u> s cam u bolt RH	\$0.00	\$0.00	\$0.00
3	✓ Clutch <u>Notes</u> clutch fluid low	\$0.00	\$0.00	\$0.00
4	✓ Defroster <u>Notes</u> blower motor vibrating	\$0.00	\$0.00	\$0.00
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
6	✓ LH 1/4 fender broke	\$0.00	\$0.00	\$0.00
7	✓ Top rh mm marker out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2497

Sam Hawksley

CLOSED

Total Cost

\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2532

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,157 hr & 668,999 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 11, 2026	Feb 11, 2026		Feb 11, 2026 6:38 PM	Feb 11, 2026 6:41 PM

Line	Task	Parts	Labor	Total
1	✓ Lose tranny yolk	\$0.00	\$0.00	\$0.00
2	✓ Missing work light on top right	\$0.00	\$0.00	\$0.00
3	✓ Coolant hose	\$0.00	\$0.00	\$0.00
Notes				
Top rad elbow				
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
5	✓ Top rad hose tore	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,286 hr & 675,530 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 23, 2026	Feb 23, 2026		Feb 24, 2026 10:27 AM	Feb 24, 2026 10:27 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes <u>Notes</u> tractor abs	\$0.00	\$0.00	\$0.00
2	✓ Air Compressor <u>Notes</u> discharge line loose	\$0.00	\$0.00	\$0.00
3	✓ Air Lines <u>Notes</u> blue glad hand spring missing	\$0.00	\$0.00	\$0.00
4	✓ Body <u>Notes</u> rh step loose	\$0.00	\$0.00	\$0.00
5	✓ Brake Accessories <u>Notes</u> #3,#4 lh and rh scam bolts loose	\$0.00	\$0.00	\$0.00
6	✓ Check all fluid levels <u>Notes</u> engine oil level low	\$0.00	\$0.00	\$0.00
7	✓ Other	\$0.00	\$0.00	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Notes

glove box

8	✓ Radiator	\$0.00	\$0.00	\$0.00
---	------------	--------	--------	--------

Notes

loose rad mount rh

9	✓ Steering System	\$0.00	\$0.00	\$0.00
---	-------------------	--------	--------	--------

Notes

power steering cap mia

10	✓ Suspension System	\$0.00	\$0.00	\$0.00
----	---------------------	--------	--------	--------

Notes

bend lh leveling rod

11	✓ Wheels & Rims	\$0.00	\$0.00	\$0.00
----	-----------------	--------	--------	--------

Notes

#3 LH outside rim cracked

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2578

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,286 hr & 675,530 km

Type	Scheduled	Due	Started	Closed
	Feb 25, 2026		Feb 25, 2026 6:57 AM	Feb 25, 2026 6:57 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,315 hr & 676,959 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2026	Feb 25, 2026		Feb 25, 2026 3:19 PM	Feb 25, 2026 3:19 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2615

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,315 hr & 676,959 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 4, 2026	Mar 4, 2026		Mar 4, 2026 8:36 PM	Mar 4, 2026 8:36 PM

Line	Task	Parts	Labor	Total
1	✓ Repaired shorted plug on def line heater 1	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,538 hr & 685,275 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 13, 2026	Mar 13, 2026		Mar 13, 2026 6:11 PM	Mar 13, 2026 6:11 PM

Line	Task	Parts	Labor	Total
1	✓ Air Compressor	\$0.00	\$0.00	\$0.00
	Notes Discharge line rubbing on fuel filter housing, p clip on engine mount loose			
2	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes Top rh work light			
3	✓ Rear End	\$0.00	\$0.00	\$0.00
	Notes Middle diff output yoke loose			
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,696 hr & 693,976 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 6, 2026	Apr 6, 2026		Apr 6, 2026 7:30 PM	Apr 6, 2026 7:30 PM

Line	Task			Parts	Labor	Total
1	✓ Transmission failure			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	RTLO-18918B - Transmission	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,742 hr & 696,466 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 12, 2026	Apr 12, 2026		Apr 12, 2026 11:05 AM	Apr 12, 2026 11:05 AM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

Work Order 2683

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,764 hr & 697,710 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 14, 2026	Apr 14, 2026		Apr 22, 2026 5:55 PM	Apr 22, 2026 5:55 PM

Line	Task	Parts	Labor	Total
1	✓ Changed tranny cooler	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX6NJ980026	U68442	14,878 hr & 701,800 km

Type	Created	Scheduled	Due	Started	Closed
	May 5, 2026	May 5, 2026		May 7, 2026 6:36 AM	May 13, 2026 1:11 PM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ Air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filter T880	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ A/c not working	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Ac compressor	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ back headache rack box loose	\$0.00	\$0.00	\$0.00		
7	✓ Lh mirror	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	convex mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
8	✓ ABS codes	\$0.00	\$0.00	\$0.00		
9	✓ Air discharge line loose	\$0.00	\$0.00	\$0.00		
10	✓ Middle axle wishbone nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

	48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
11	✓ Lower rad stack bushings mia			\$0.00	\$0.00	\$0.00
12	✓ Top rad hose u bolt mia			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2-1/2 u bolt	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ middle drive diff lock oil leak			\$0.00	\$0.00	\$0.00
	<u>Notes</u>					
	Banjo seal broke, mount bolts loose remove and reseal					
14	✓ middle diff filter cover mia			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	diff cover	Kropp Shop		1.0	\$0.00	\$0.00
15	✓ front diff input yoke loose			\$0.00	\$0.00	\$0.00
16	✓ middle diff output yoke loose			\$0.00	\$0.00	\$0.00
17	✓ wrap umbilical cord			\$0.00	\$0.00	\$0.00
18	✓ Skirt light tail lights out			\$0.00	\$0.00	\$0.00
19	✓ top rh red oval Mickey Mouse light mia			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	6050 - Oval Red light	Kropp Shop		1.0	\$0.00	\$0.00
20	✓ rh beacon out			\$0.00	\$0.00	\$0.00
	<u>Notes</u>					
	Plugged back in unplugged in roof					
21	✓ lh king pin nfg			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	King pin kit	Kropp Shop		1.0	\$0.00	\$0.00
22	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00

283 - 2022 Kenworth T880

Parent: T413 - 2018 Cross Country Cross Country Mfg.

CLOSED

23	✓ Drive tires (set of 12)			\$0.00	\$0.00	\$0.00														
24	✓ match lh steer with rh			\$0.00	\$0.00	\$0.00														
25	✓ Front axle wishbone nfg			\$0.00	\$0.00	\$0.00														
<table> <tr> <th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th colspan="2">Cost</th></tr> <tr> <td>48100511 - Neway wishbone bushing kit</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td colspan="2">\$0.00</td></tr> </table>							Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost		48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost															
48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00															
26	✓ front axle diff breather tube tore off			\$0.00	\$0.00	\$0.00														
27	✓ Middle rh drive brake pot spring broken			\$0.00	\$0.00	\$0.00														
<table> <tr> <th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th colspan="2">Cost</th></tr> <tr> <td>3030 brake pot</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td colspan="2">\$0.00</td></tr> </table>							Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost		3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost															
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00															
28	✓ S cam u bolts loose middle axle			\$0.00	\$0.00	\$0.00														
29	✓ Rear axle drive shocks nfg			\$0.00	\$0.00	\$0.00														
<table> <tr> <th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th colspan="2">Cost</th></tr> <tr> <td>drive shock</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td colspan="2">\$0.00</td></tr> </table>							Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost		drive shock	Kropp Shop		2.0	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost															
drive shock	Kropp Shop		2.0	\$0.00	\$0.00															
30	✓ Drums on all drives but rear Lh			\$0.00	\$0.00	\$0.00														
<table> <tr> <th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th colspan="2">Cost</th></tr> <tr> <td>Brake Drum</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td colspan="2">\$0.00</td></tr> </table>							Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost		Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00	
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost															
Brake Drum	Kropp Shop		1.0	\$0.00	\$0.00															
				Part Cost	\$0.00															
				Labor	\$0.00															
				Subtotal	\$0.00															
				Tax 1 (0.0%)	\$0.00															
				Tax 2 (0.0%)	\$0.00															
				Credit	(\$0.00)															
				Total Cost	\$0.00															